

GENERAL INDEX

TO THE FOUR VOLUMES OF

Ore Dressing

 \mathbf{BY}

ROBERT H. RICHARDS, S.B., LL.D.

Professor of Mining Engineering and Metallurgy at the Massachusetts Institute of Technology, Boston, Mass., U. S. A.

1909 McGRAW-HILL BOOK COMPANY NEW YORK 6221 PS1 V

SELLECTORS SCHOOL AND THE COMMENT OF THE COMMENT OF

A GENERAL GUIDE TO ALL FOUR VOLUMES.

Pages 1-643, Vol. I: 644-1197, Vol. II;	1199-1610, Vol. III; 1611-2052, Vol. IV.
A · · ·	Action of jaw and spindle breakers
Aachen, wash trommel at	Rittinger table
Aaron, C. H., gold amalgamation	steam stamps
gravity stamps 226	trommels
leaching gold and silver xix losses in gold milling	Vanners
losses in gold milling	Actions in crushing
leaching	Adalbert Works, hand picking at
leaching 1167 testing gold ores by chlorination 1173 Abadie, E. R., gravity stamps 224 North Star gold stamp mill at Grass Valley,	Adalbert Works, hand picking at 49. Adams, J. M., amalgamating pans 290, 29 amalgam at the Owyhee silver mill 78.
Abadie, E. R., gravity stamps	amalgam at the Owyhee silver mill 78
North Star gold stamp mill at Grass Valley,	dimension of Black Hill traps 77: end and side-shake vanners 655, 65
California	end and side-snake vanners
plates at the North Star mill 787	form of riffles in mercury traps
A Bartlett mill xxvii Abbé Engineering Company. Abbé spiral feed 1323 tube mill 1280, 1298 at Guanajunto, capacity of 1280, 1298	impurities in amalgam 25
Abbé Engineering Company. Abbé spiral feed 1328	life of retorts 789
tube mill	pointed boxes
sizing test of feed and discharge 1291	
mills	splash plates 734 splash plates 738 Adams, W. J., amalgamated plates 789, 744 amalgamation 787, 1176 amalgamation and gold mills xi mercury traps 777 vanners
mills	amalgamation 787 1175
Absorption of amalgam by plates	amalgamation and gold millsxix
mercury by amalgamating plates	mercury traps 772
details of stroke	vanners
details of stroke	Adhesion 830
cam and gravity in Stutz coal jig 537	in dry concentration 826
cam and spring 537	of minerals, effect of
disc motion	separation by
for jigs	Adjustment of Blake breakers
hammer and spring on Collom jigs	Card concentrator 1483
on Wilfley table	Comet breaker
Accessory apparatus	Frue vanner for testing
Accounting, mine	Gates breaker 89
Accounts and reports	gravity stamps
Accuracy of machine sampling	gyratory breakers
Acids, action of on mercury 780	
for cleaning mercury	machines
Acids used in settling tests	Mechernich magnetic separators at Mill 185 1786
on amalgamated plates	EDFOW OR 1109
effect of	travel, slope, and water on vanners 660
in amalgamation 751	spindle breakers 47 vanners 653, 663, 658, 658
on amalgamated plates	Willey table head motion
jig tanks	Advantages and disadvantages of various crushing
plates 749 screens 178	macunes 818
neutralized	
neutralized 173 Acme concentrator. L. H. L. Huddart 2023	action of jaw breaker 55 action of spindle breaker 55 air versus water concentration 225
E. Walker 2023 guide for gravity stamps 154, 155 ore feeders at Mill 100 1624	action of spindle breaker
guide for gravity stamps	air versus water concentration 825
table	200
table	concentration over smelting
Action of air jig 822	electric nower
Deit tables	Elmore oil process
breakers compared	mici-pressing plants as against decantation
bumping belt tables	plants
tables 682	gravity stamps
centrifugal force 827	hand breaking 12
classifiers	hand figs
crushing machines	hand picking. 480, 487 helicoid conveyor over older types . 1582
gravity stamps	high-speed rolls
jaw breakers	high-speed rolls 88 large breakers 49
	TO THE PERSON OF

Pages 1-643, Vol. I.

Advantages of large motors	Albertite, specific gravity of
machine feeding 1110	1188 Albite, specific gravity of 1188 Albite, specific gravity of 1188 Alden breaker 1055 Alden breaker 59 61 Alexandria Coal Co., washing plant 1178 Alica mill
magnetic concentration	Alburtis, Pennsylvania, mill at
mercury wells 771 Muntz metal plates 750	Alexandria Coal Co. washing plant
Parsons & Fisher jig	
midsing in the mine	Alignment of rolls
pipe and plug jig spigot	Alkali to prevent sickening of mercury 751 Alkard coal washing methods 2018
removing dust before washing coal 817	Allard coal washing methods
riffle tables	Alleghany Iron Co. Alleghany Iro
rock breaker at mine 1109 rolls of large diameter 83	Stone single-roll crusher at
sectional mills	Allen, Robert, West Australia metallurgical practice 1323
separate treatment of mine fines 1111	Thirdy artiff, continuing the minimum of the continuing the contin
side hill site for mills	hand picking at 492
silver combination mills	magnetic separation at 834 mill at 1178
sliding block mechanism 535	roasting for friability at
A-frames for gravity stamps	magnetism at 814
Africa, milling at the Simmer & Jack, G. O.	pricking at 487 roasting for friability at 588 magnetism at 814 sizes of ore hand picked at 487 Allis, E. P., Co., amalgamating pan 243, 244, 245, 246,
Siding block mechanism 535	Ains, E. P., Co., amaigamating pan 243, 244, 245, 246, 247, 249
Agassiz A Viii	247, 248 246, 247, 248 247, 248 24
Aggregation affecting separation	edge runner mill
of minerals, effect of	mechanical batea
Agitation	on design of cams 197
in kieves	stamp tappets
ratio on vanners	stamp mortar
use made of, in mills 890 Agitator for bottle tests 1157 Agitators for amalgamation 780	Allis, E. P., on shoe shanks 181
Agitator for bottle tests	atom historia
Agitators for amalgamation	stems 187 rolls 76, 111 at Mill 136 776, 111
for clay	at Mill 136
Aikinite, specific gravity of	speed
Air blast, continuous	runa-comment continuity, an unproved frommer 1300
dry blanket	annular picking table
panning	Ayton thick-pulp extractor 1408 ball mills, regards work, cost, etc. 2016
for emery	Challenge feeder 1577
Hochstedt apparatus	Challenge feeder
on horizontal belt	COPPURATED FORM
bubbles affecting separation	costs of breaking ore 1222 Frue vanners at Mill 127
on free settling	Mill 170
classifier at Engis 817	Gates ore breakers 1000
concentration, bibliography for	rock and ore breakers 1999
by	tube and ball mills 1323
concentrators, classification of	
continuous blast 918	Hancock jig 1440, 1459 improved Wolf Tongue classifier 1487
gaps, ampere turns required for	Lamb automatic tailings sampler 1574, 1609
gaps, ampere turns required for 795 hoists, Pilling 1608 jigs 640, 816, 820 Hooper-Paddock 820	Richards' shallow-pocket hindered settling clas-
Hooper-Paddock 990	
Kromxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx	rolls 1137, 1244 at mills 1707, 1724, 1750, 1751, 1752, 1854, 1866, 1867, 1877, 1878, 1885, 1898, 1913 simple steam stamp at Mill 182 1909
pressure and gravity jig mechanism 537 separator, Clarkson-Stanfield 820, 828 Mumford & Moodie 818	1860, 1867, 1877, 1878, 1885, 1898, 1913
separator, Clarkson-Stanfield820, 828	simple steam stamp at Mill 182
Pone-Henneberg 210 000	
Pape-Henneberg	stamps at Mill 100 1624 steam stamp 2011
Suction used in aghestos dressing 217	
versus water for concentration	
Versus water for concentration 825	toothed rolls 1242 vanners at Mill 136 2739 Allis Corliss engine 994, 997, 1000, 1003 pump 994, 997, 1000, 1003
Akins & Evans concentrator 2022	Allie Corlies angles
2261011 Citil 11111 [30]	bumb 604 607 1000 1009
table of sizes caracities emeads weights ato 1909	reliance rolls
Aktien Company, new mill of 1924	reliance rolls
Alabama graphite mills 1075 hematite, cost of concentrating 1135	122, 123, 124, 125, 126, 127, 128 181, 188, 142
	Valve motion 124
iron ore concentration 1176 magnetic concentration of833, 835, 836	Allouez Copper mine, hand picking at 402
magnetic concentration of833, 835, 836	Allison Rand mine 2044 Allouez Copper mine, hand picking at 492 mill 1089, 1107, 1109, 1174 cost of stamping 142
Alaska, cost of producing gold in 1075 1076 1077	cost of stamping
dredging in	Alma Emmons sludge will
stamp mill practice at Douglas Island 2039	Alpha DeLaval separator
Treadwell Gold Mining Co 1181	120 120
amargam squeezer used by 781	tube mills
mill	cyunder
	tube mill
heavy etampe	table of sizes, power, etc. 1280, 1294
H. Watson 2048	Altenberg classifier
H. Watson 2043 mortar blocks 148 Albany compound for greasing guides 156	bibliography of 294 tube mili 1280, 1294 table of sizes, power, etc. 1296 Altenberg classifier 416, 475, 478 mine, wash trommel at 331 Saxony, calcining ore for friability at 998 mili at 1088 1173
grease	ouxony, calcining ore for friability at 9
A	mili at 1086, 1178

Pages 1199–1610, Vol. III.	IND	EX. Pages 1611–2052, Vol. IV.
Alternate polarity in magnetic separation Alternating current in magnetic separation Althans, E., Ball stamp Blake, Marsden and Alden breakers buddles, slime, and percussion tables Dingey mill German and California stamps Krom's rolls and coal rolls on breakers ore dressing Pheenix and Sholl pneumatic stamps Aluminum amalgam atomic weight of bronze cloth screen plate screens specific gravity of Alum used in settling kaolin tests County, California, mill at cost of milling mill, screens mills, plates in stamp mills mill, stamps in Amalgam absorbed by plates amount of bullion in bullion contents of cleaning of distribution of from plates	708 835 61 7293 2303 112 61 1186 1430 1184 1174 1184 1149 11147 1184 1174 7826 228 7661 7780 7764	Amalgamating pan dies E. P. Allis Co. 244, 245, 246, 247, 249 for testing 1157 pan, frame, bottom, and central cone. 241 Fraser & Chalmers 244, 245, 246, 247, 249 in Lyon mill 241, 243, 244, 246 loss of mercury in 241, 243, 244, 246 loss of mercury in 241, 243, 244, 246 loss of mercury in 249 Risdon Iron Works 244, 245, 246, 247, 249 shafts and gears 244, 245, 246, 247, 249 shafts and gears 244, 245, 246, 247, 249 shafts and gears 244 size of stuff treated by spider, driver, cap, lubrication, and grinding. 247 steam pipe and steam jacket 244 tank and Boss systems 248 temperature of 248 Union Iron Works 243, 244, 245, 246, 247, 249 weight of spider and driving cone in 247 wings, muller, shoes, and pulp current 245 tables, back deflectors for 151 Krupp 788 shaking 1513 Amalgamation 780, 892, 1512 agilators for 780 an improved process for A. C. Beatty 2024 apparatus for 787 bottle amalgamation for testing 1996 combination process of 248 description of a new machine for 2025 effect of arsenic on 1654
fineness of general discussion of, Leon de Mortillet gold	2025 731 762 762 768 1512 1512 1512 2024 251 762 2024 251 730 1518 2024 1519 730 11517 730 11517 747 756 81 2024 1519 758 1512 758 178 178 178 178 178 178 178 178 178 17	solutions of salts 767
absorption of mercury by amount of drop at Mill 98. at Mill 98, details of clean up details of in the mills distributors and collectors used on dressing of. W. H. Kritzer for testing heavily silver plated. F. W. Cindel inside material for Muntz metal for on Wilfley table quality of copper for	622 1618 737 743 2024 1156 178 1514 1512 747 1512 744 6 2024 1173 2024	Settlers for

American Developing and Mining Company mili XXVII, 1028	
	varia
gold stamp mills	Andrews dredging pump 869 Angels, California stamps at 228 Camp, California, arrastra at 1034 mills at 1024, 1033, 1034, 1038 shoes and dies at 183 stamps at 224 Angel props in launders 270
Process Company driers 1597 1609	mills at 1024 1032 1034 1039
rock breaker	shoes and dies at
Screen gauge	stamps at
steam stamp 2011	of friction
Steel Mfrs. Association on screen gauges 173	
wire gauges 227 Zinc Extraction Co., international separators at 1535	of nip, formula
Lead & Smelting Co., Huff electrostatic sepa-	how affected
rator	of rolls
Americus Zinc and Lead Mining Company, separa-	In trommels
tion of zinc blende and barytes 1565 Amicus mill, milling cost at	Anietced by speed 94
Ammeberg, heating ore for friability	Angleur, double discharge on jigs at 584
Heberli mills at	Anhydrite, specific gravity of
jig at 641 bed at 574	Ankerite specific gravity of
bed at	Anna mill 1177
picking at 492	1090
removal of slimes by classifier 373 screening at 373	stamp mill, spitzlutten at
separation of pyrite and blende at	Annealing copper plate 747 graphite crucibles 784
Sieve scale at	graphite crucibles 784
Utsch jig at	iron for permeability 792 Annular picking table 490
Amortization of capital	Allis-Chaimers type
Amount and temperature of water for gravity stamps 221	Krupp type
of mercury fed to stamps 203 throw of jigs 594	vortex classifier
Amperes. See also Power	Anorthite, specific pravity of 1100
Amphibola specific gravity of	Anthony, W. A. Edison, Buchanan, and Wetherill
Ampere turns for magnets. 794 Amphibole, specific gravity of 1188 A. M. W. mill, Leadville, milling at the. A. W.	separators
Warwick	hindered settling test on 0.17 coo
Amygdaloid ore, mills for 990	settling velocity of
coal washer	
Warwick	Antidote for mercury 780 Antimony amalgam 730 atomic weight of 1188
Copper Mining Co. 1836	atomic weight of
1000	ore concentrated by Hooper air jig.
Huntington milis screens at	Antique Anti
plant of 2027	settling velocity of
H. O. Hofman 1922	Antiquia Colombia amalgamated plates at 740
rolls at mills	Anvil blocks for Nordberg steam stamp 1247
Analotte, specific gravity of	Anzin Company, air blast for coal dust
Analyses of Cammett table products 678 of canvas table products 701, 702 crude ore and concentrates at Mill 167. 1858, 1859 Lubrit table products 879	using air blast
Crude ore and concentrates at Mill 1671858, 1859	Apatite, mill for 1059 specific gravity of 1188
Lunrig table products	
mill products. See individual mills in Chan-	used in making phosphate
mill products. See individual mills in Chap- ter XX	Apophyllite, specific gravity of
products at Mill 162	Apophyllite, specific gravity of 1188 Apparatus, accessory 842 used for amplemation 721
products at Mill 162	Apophyllite, specific gravity of 1188 Apparatus, accessory 842 used for amplemation 721
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 200	Apophyllite, specific gravity of 1188 Apparatus, accessory 842 used for amplemation 721
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 676 magnetic separation 802 902 904 900 010	Apophyllite, specific gravity of 1188
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 676 magnetic separation 802 902 904 900 010	Appolyllite, specific gravity of 1188
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 676 magnetic separation 802 902 904 900 010	Appopulation Applements A
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 676 magnetic separation .802, 803, 804, 809, 810, 813 Parsons table 669 pneumatic belt concentrator 818 Richards annular classifier 466	Apophyllite, specific gravity of 1188
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 676 magnetic separation 802, 803, 804, 809, 810, 813 Parsons table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 815 slime table 1172	Appopulation Apparatus A
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 676 magnetic separation 802, 803, 804, 809, 810, 813 Parsons table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 815 slime table 1172 roasted products 1172	Appopulation Apparatus A
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 682 Hallett table 682 nagnetic separation 802, 803, 804, 809, 810, 813 Parsons table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 815 slime table 1172 roasted products 814 vanner products 650, 664	Appopulation Apparatus A
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 682 Hallett table 682 nagnetic separation 802, 803, 804, 809, 810, 813 Parsons table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 816 slime table 1172 roasted products 814 vanner products 650, 664 Wilfley table products 650, 664 Analysis by specific gravity tests	Appopulation Apparatus A
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 676 magnetic separation. 802, 803, 804, 809, 810, 813 Parsons table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 815 slime table 1172 roasted products 814 vanner products 814 vanner products 650, 664 Analysis by specific gravity tests 1159 for minerals 1150	Appopulation Apparatus A
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 682 Hallett table 669 magnetic separation 802, 803, 804, 809, 810, 813 Farsons table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 815 slime table 1172 roasted products 814 vanner products 650, 604 Wilfley table products 650, 604 Mulfley table products 155 for minerals 1162 of Butte ore 135 Morison's curves of velocity of severe	Apophyllite, specific gravity of 1188
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 676 magnetic separation 802, 803, 804, 809, 810, 813 Parsons table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 815 slime table 1172 roasted products 814 vanner products 814 vanner products 650, 664 Wilfley table products 650, 664 Milfley table products 1159 for minerals 1162 of Buttle ore 1159 Morison's curves of velocity of stamps 215 Morison's curves of velocity of stamps 215 products of disintegration and screening 830	Apophyllite, specific gravity of 1188
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 682 Hallett table 682 Hallett table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 815 slime table 1172 roasted products 814 vanner products 650, 664 Wilfley table products 650, 664 Wilfley table products 1159 for minerals 1162 of Butte ore 136 Morison's curves of velocity of stamps 216 products divisintegration and screening 830 of dry separation 820	Apophyllite, specific gravity of 1188
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 682 Hallett table 682 Hallett table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 816 slime table 1172 roasted products 814 vanner products 650, 664 Wilfley table products 650, 664 Wilfley table products 1159 for minerals 1162 of Butte ore 135 Morison's curves of velocity of stamps 215 products of disintegration and screening 830 of dry separation 820 Krom air jig 824	Apply Appl
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 682 Hallett table 682 Hallett table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 816 slime table 1172 roasted products 814 vanner products 650, 664 Wilfley table products 650, 664 Wilfley table products 1159 for minerals 1162 of Butte ore 135 Morison's curves of velocity of stamps 215 products of disintegration and screening 830 of dry separation 820 Krom air jig 824	Apply Appl
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 682 Hallett table 682 Hallett table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 816 slime table 1172 roasted products 814 vanner products 650, 664 Wilfley table products 650, 664 Wilfley table products 1159 for minerals 1162 of Butte ore 135 Morison's curves of velocity of stamps 215 products of disintegration and screening 830 of dry separation 820 Krom air jig 824	Apply Appl
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 676 magnetic separation 802, 803, 804, 809, 810, 813 Parsons table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 815 slime table 1172 roasted products 5650, 664 Wilfley table products 674 Analysis by specific gravity tests 1159 for minerals 1162 of Buttle ore 135 Morison's curves of velocity of stamps 215 products of disintegration and screening 830 of dry separation 820 Krom air jig 824 magnetic separation 802 oil process 832 Paddock air jig 823 separated by decrepitation 829 See Assaving 829	Apply Appl
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 676 magnetic separation 802, 803, 804, 809, 810, 813 Parsons table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 815 slime table 1172 roasted products 814 vanner products 650, 664 Wilfley table products 650, 664 Mulfley table products 1159 for minerals 1162 of Butte ore 1159 for minerals 1162 Morison's curves of velocity of stamps 215 products of disintegration and screening 830 of dry separation 324 magnetic separation 802 Krom air jig 824 magnetic separation 802 Paddock air jig 832 Faddock air jig 832 See Assaying.	Appopulation Apparatus Accessory Apparatus Accessory Aga
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 676 magnetic separation 802, 803, 804, 809, 810, 813 Parsons table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 815 slime table 1172 roasted products 814 vanner products 650, 664 Wilfley table products 650, 664 Mulfley table products 1159 for minerals 1162 of Butte ore 1159 for minerals 1162 Morison's curves of velocity of stamps 215 products of disintegration and screening 830 of dry separation 324 magnetic separation 802 Krom air jig 824 magnetic separation 802 Paddock air jig 832 Faddock air jig 832 See Assaying.	Appopulation Apparatus Accessory Apparatus Accessory Aga
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 676 magnetic separation 802, 803, 804, 809, 810, 813 Parsons table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 815 slime table 1172 roasted products 814 vanner products 650, 664 Wilfley table products 650, 664 Mulley table products 1159 for minerals 1162 of Butte ore 1159 for minerals 1162 Morison's curves of velocity of stamps 215 products of disintegration and screening 830 of dry separation 324 magnetic separation 802 Krom air jig 824 magnetic separation 802 Paddock air jig 832 Faddock air jig 823 separated by decrepitation 829 See Assaying.	Appopulation Apparatus Accessory Apparatus Accessory Aga
products at Mill 162 1847 of Anchor mill ore 815 Ball-Norton magnet 798 Golden gate table 682 Hallett table 676 magnetic separation 802, 803, 804, 809, 810, 813 Parsons table 669 pneumatic belt concentrator 818 Richards annular classifier 406 roasting for magnetism 815 slime table 1172 roasted products 5650, 664 Wilfley table products 674 Analysis by specific gravity tests 1159 for minerals 1162 of Buttle ore 135 Morison's curves of velocity of stamps 215 products of disintegration and screening 830 of dry separation 820 Krom air jig 824 magnetic separation 802 oil process 832 Paddock air jig 823 separated by decrepitation 829 See Assaving 829	Apophyllite, specific gravity of 1188 Apparatus, accessory 342 used for amalgamation 731 Appendix 1187, 1999 bibliography for 1173 Appleby, C. 2 Appliances for elevating ore and water 559 Application of magnets 790 riffles 723 Application of magnets 790 riffles 723 Apron distributors 557 for feeding slime tables 689 jugs 549 plates 740 Aragonite, specific gravity of 1188 Aradian mill 131 Archer breaker 770 Archimedes acrew dredge 1009 Arc lamp at Mill 152 1031 lights 1100 Area of amalgamated plates 744 discharge for stamps 209 steam stamps 129 sorting column 403 Argall, Philip. Capacity for rolls 1226 cylindrical driers 880, 1600 and driving of ces 880, 1600

	11 Dille ideas on a modern fine quiching plant	2018	Aspen, Colorado, rock house at	485
£	argall, Philip, ideas on a modern fine crushing plant.	639	Applied floor in mile	1000
	jig		Asphalt floors in mills Asphaltum, specific gravity of Asphalt varnish used in electroplating	1100
	journal pressure in rolls	97	Aspnaitum, specific gravity of	770ů
	imit of economical sizing modern crushing and grinding machinery multi-tubular drier at Mill 143	1366	Asphalt varnish used in electroplating	754
	modern crushing and grinding machinery	1278		
	multi tuhular drier at Mill 143	1770	Assay olice for mill of tailings at Mill 48 Assays and sizing test of feed and products of Huntington mills	1160
	- Oll-in County mills	1047	for mill	รีกิซีซี
	on Gilpin County mills	10.10	of to History at Mill 40	7000
	rules for sampling	848	or tallings at will 48	190
	roll shells	69	Assays and sizing test of feed and products of Hunt-	
			ington mills	1817
	ore dressing in British Columbia	2012	of jig tailings mill products Mill 142	807
	ore dressing in British Columbia	1000	mill manifesta Mill 140	1707
	duestion of hole us. mesh	1900	min products with 142	1101
	rolls	1400	minerals	1162
	for dry crushing	1224	products at Mill 129 1	1718
	compling and dry graching in Colorado	1244	of Paddock air jig	823
	for dry crushingsampling and dry crushing in Colorado	1000	atamas mala	011
	of ores	TOOR	stamp pulp	211
	screens kind speeds and cost of screening	1000	tailings	218
	settlement of slimes	1417	zinc mill products	1169
	settling of roasted slimes	1419	See also Analyses.	
	Scening of Todated States	1004	Ataonna Chili mill at	1182
	speed for rolls and speed curves	1000		
			min, Taitai, Chin. S. Fl. Loram	2033
	use of Vezin sampler	1572	Atacamite separated by screening	830
Δ	reentite specific gravity of	1188	specific gravity of	1188
- X	use of Vezin sampler argentite, specific gravity of argon, atomic weight of	1188	specific gravity of	
- 4	irgon, atomic weight of	007	TO N. 17-11	2034
P	rithmetical ratio for sieve scale	907	Addition of Control of the Control o	AUGR
A	rizona and Sonora. D. E. Woodbridge	1928	E. N. Fell Atkinson, A. S. Lake Superior milling practice	1410
	concentration at Humboldt. A. H. Hamilton .	2038		1183
	in B' El Propert	2037	cost of breaking at	51
	of copper in. F. H. Probert2033,	2041	crushing at	57
	or copper in. F. ri. Propert	2017	truming at a contract of the c	
	concentrators in. A. Morison	2042		1191
	Copper Company. D. E. Woodbridge	1923	steam stamping	142
	Limited	1868	details of cylinders of steam stamps	126
	mill of A Morison	2041	Evans classifier in	895
	and of lines for alines sottling	1416	launders at	878
	use of lime for slime settlingdistricts. Cost of producing copper in 1953,	1084		
	districts. Cost of producing copper in 1908,	1904,	screen for stamp.	121
		1955	slime tables at steam stamps	697
	gasoline engines in	1184	steam stamps	185
	milling at Moure	2042	Mining Co.	1181
	Thinking at Midwig in TN TV VV- Abeldee	0030	Atlan andra	
	milling at Mowry milling practice in. D. E. Woodbridge	2000	Atlas engine Atlan district, B. C., dredging in the	902
	mills in	2043	Atlin district, B. C., dredging in the	2087
	slime treatment in	1411	Atmosphere, weight of	1188
	stamp mill type of settling tanks at Morenci rminius Chemical Company	1175	Atmospheric discharge for figs	582
	tune of cattling tanks at Movensi	1719	stamp Atomic weights, table of Attoching illy stamps	140
	type of setting tanks at typorence.	1010	About a contain a contain and the contain and	00 F F
Α	rminius Chemicai Company	1919	Atomic weights, table or	TINN
	mill	1913	Attaching jig screens	539
Α	mill	640	Attachment of jig plunger to connecting rods	529
	double-cone classifier	426	screens in trommels	855
	on making bed material for jigs	574	Attendance received by American Decreas Communica	000
	ou making bed material for jigs		Attendance required by American Process Company	1800
	spitalutte. Hopper-shaped unwaterer	476		1599
Λ	rrangement of holes in screens	168	Blake breaker at Mill 186	1917
	trommels machinery in a modern mill. A. Harvey	384	Gates breaker at Mill 159	1828
	machinery in a modern mill. A. Harvey	2048	Pleace amalgamator at Mill 114	1668
	machines	891	rotary drier at Mill 186	1917
	100g		steems steems at Mill 100	1010
	mills	1107	steam stamps at will 102	$\frac{1912}{1525}$
	plates	, 742	Wettern magnetic separation	1020
	screen holes	369	Wilfley roasting furnace	1548
	trommely	364	Attraction of various substances by magnets	700
А	rrestra 239	2 237	Attrition causing slimes	1121
•	hibliomaphy of	990		7777
	arrastra 232 bibliography of 232 description of the A. Lakes discussion of construction. E. L. Ballou	0019	Atwood amalgamator	775
	description of the. A. Lakes	2013	Atwood, M. Microscopic examination of pulp	228
	discussion of construction. E. L. Ballou	2016	Augite, strength of	301
	mill	1039	Aultman balanced shaking screen	2018
	value of the. M. F. Leech	2014	jaw breaker	2009
A	rrastras, number used	231	Aprilerous antimony are concentration of an	กิตกอ
Ā	reenic amalgam	780	Announ will time at	41.19
-	rsenic amalgam atomic weight of	1100	related borns at	477
	in anothers	1100	Aurora mill, jigs at pointed boxes at Austin gyratory breaker Austin, L. S., Anaconda Copper Company in 1905 Delster concentrator at the Baltic mill	417
	in amalgam	707	Austin gyratory breaker	2000
	in amalgam specific gravity of rsenolite, specific gravity of	1188	Austin, L. S., Anaconda Copper Company in 1905	1922
Α	rsepolite, specific gravity of	1188	Delater concentrator at the Baltic mill	ฉักฉิลิ
74	rsenopyrite, hindered settling test on616	617	Washoe Plant of the Anaconda Copper Com-	MUMU
	remobilitie muncied serving test on	, 017	washoe Frant of the Anaconda Copper Com-	
H		829	pany	2013
А	roasted for porosity		Austin Manufacturing Company. Cost of breaking	
А	roasted for porosity settling velocity of	, 469		1222
	roasted for porosity settling velocity of	, 469 1188	ore	
	roasted for porosity settling velocity of	, 469 1188 1105	Austin gyratory breakers	
Ą	rresian well for water	1109	Austin gyratory breakers	1222
Ą	spector board used in retorting	781	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system	$\frac{1222}{291}$
Ą	spector board used in retorting	781	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system at the Harshaw mill	1222 291 290
Ą	sbestos board used in retorting covering for steam pipes dressing	781 1091 1182	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system at the Flarshaw mill Boss tubular classifier at Harshaw mill	1222 291 290 478
Ą	rtesian well for water subsets board used in retorting covering for steam pipes dressing	781 1091 1182	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system at the Flarshaw mill Boss tubular classifier at Harshaw mill	1222 201 200 478 224
Ą	rtesian well for water subsets board used in retorting covering for steam pipes dressing	781 1091 1182	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system at the Flarshaw mill Boss tubular classifier at Harshaw mill	1222 201 200 478 224
Ą	rtesian well for water subsets board used in retorting covering for steam pipes dressing	781 1091 1182	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system at the Flarshaw mill Boss tubular classifier at Harshaw mill	1222 291 290 478
Ą	rtesian well for water subsets board used in retorting covering for steam pipes dressing	781 1091 1182	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system at the Harshaw mill Boss tubular classifier at Harshaw mill gravity stamps grizzlies in the Harshaw mill milling at Harshaw and Charleston mills, Ari-	1222 291 290 478 224 385
Ą	tressan Well for water sbestos board used in retorting covering for steam pipes dressing	781 1091 1182 1916 2046 2041 1568	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system at the Harshaw mill Boss tubular classifier at Harshaw mill gravity stamps grizziles in the Harshaw mill milling at Harshaw and Charleston mills, Arizons	1222 201 200 478 224 885
A	subestos board used in retorting covering for steam pipes dressing	781 1091 1182 1916 2046 2041 1568	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system at the Harshaw mill Boss tubular classifier at Harshaw mill gravity stamps grizziles in the Harshaw mill milling at Harshaw and Charleston mills, Arizons	1222 201 200 478 224 885 1174 251
A	subestos board used in retorting covering for steam pipes dressing	781 1091 1182 1916 2046 2041 1568	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system	1222 201 200 478 224 885
A	subestos board used in retorting covering for steam pipes dressing	781 1091 1182 1916 2046 2041 1568	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system. at the Harshaw mill Boss tubular classifier at Harshaw mill gravity stamps grizzlies in the Harshaw mill milling at Harshaw and Charleston mills, Arizona on impurities in amalgam settlers and retorts at the Harshaw mill wear of amalgamating pans.	1222 201 200 478 224 885 1174 251 787
A	tressan Well for water sbestos board used in retorting covering for steam pipes dressing	781 1091 1182 1916 2046 2041 1568 2036 2034 1402	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system. at the Harshaw mill Boss tubular classifier at Harshaw mill gravity stamps grizzlies in the Harshaw mill milling at Harshaw and Charleston mills, Arizona on impurities in amalgam settlers and retorts at the Harshaw mill wear of amalgamating pans.	1222 201 200 478 224 885 1174 251 787 249
A	covering for steam pipes dressing 817, 838, 1079, 1178, in Quebec R. Stokes methods of treating. E. B. Wilson milling of. F. Cirkel E. S. Regelman in Canada. F. Cirkel ascending-current cones or cylinders asches used in preparing amalgamated plates	781 1091 1182 1916 2046 2041 1568 2036 2034 1402 756	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system. at the Harshaw mill Boss tubular classifier at Harshaw mill gravity stamps grizzlies in the Harshaw mill milling at Harshaw and Charleston mills, Arizona on impurities in amalgam settlers and retorts at the Harshaw mill wear of amalgamating pans.	1222 201 200 478 224 385 1174 251 787 249 1065
A	covering for steam pipes covering for steam pipes dressing	781 1091 1182 11916 2046 2041 1568 2034 1402 756 781	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system. at the Harshaw mill Boss tubular classifier at Harshaw mill gravity stamps grizziles in the Harshaw mill milling at Harshaw and Charleston mills, Arizona on impurities in amalgam settlers and retorts at the Harshaw mill wear of amalgamating pans Austinville, Virginia, mill at New Century jig at	1222 201 200 478 224 385 1174 251 787 249 1008 1446
A	tressan well for water subestos board used in retorting covering for steam pipes dressing 817, 838, 1079, 1178, in Quebec R. Stokes methods of treating. E. B. Wilson milling of. F. Cirkel E. S. Regelman in Canada. F. Cirkel scending-current cones or cylinders subes used in preparing amalgamated plates retorts subjectified.	1105 1781 1182 1916 2046 2041 1568 2034 1402 756 2047	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system. at the Harshaw mill Boss tubular classifier at Harshaw mill gravity stamps grizzlies in the Harshaw mill milling at Harshaw and Charleston mills, Arl- zona on impurities in amalgam settlers and retorts at the Harshaw mill wear of amalgamating pans. Austiaville, Virginia, mill at New Century jig at zinc over from	1222 201 200 478 224 385 1174 251 787 249 1065 1446
A	covering for steam pipes covering for steam pipes dressing	1105 1091 1091 1182 1916 2046 2041 1568 2034 2034 1402 756 2047 1091	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system. at the Harshaw mill Boss tubular classifier at Harshaw mill gravity stamps grizzlies in the Harshaw mill milling at Harshaw and Charleston mills, Arl- zona on impurities in amalgam settlers and retorts at the Harshaw mill wear of amalgamating pans. Austiaville, Virginia, mill at New Century jig at zinc over from	1222 201 200 478 224 385 1174 251 787 249 1065 1446
A	tresan Well for Water sibestos board used in retorting covering for steam pipes dressing	781 1091 1182 1916 2046 2046 2036 2034 1402 781 2047 1091	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system. at the Harshaw mill Boss tubular classifier at Harshaw mill gravity stamps grizzlies in the Harshaw mill milling at Harshaw and Charleston mills, Arl- zona on impurities in amalgam settlers and retorts at the Harshaw mill wear of amalgamating pans. Austiaville, Virginia, mill at New Century jig at zinc over from	1222 201 200 478 224 385 1174 251 787 249 1065 1446
A	tresan Well for Water sibestos board used in retorting covering for steam pipes dressing	781 1091 1182 1916 2046 2046 2036 2034 1402 781 2047 1091	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system. at the Harshaw mill Boss tubular classifier at Harshaw mill gravity stamps grizzlies in the Harshaw mill milling at Harshaw and Charleston mills, Arl- zona on impurities in amalgam settlers and retorts at the Harshaw mill wear of amalgamating pans. Austiaville, Virginia, mill at New Century jig at zinc over from	1222 201 200 478 224 385 1174 251 787 249 1065 1446
A	covering for steam pipes covering for steam pipes dressing	781 1091 1182 1916 2046 2046 2036 2034 1402 781 2047 1091	Austin gyratory breakers Austin, W. L. amalgamating pan, Boss system. at the Harshaw mill Boss tubular classifier at Harshaw mill gravity stamps grizziles in the Harshaw mill milling at Harshaw and Charleston mills, Arizona on impurities in amalgam settlers and retorts at the Harshaw mill wear of amalgamating pans Austinville, Virginia, mill at New Century jig at	1222 201 200 478 224 385 1174 251 787 249 1065 1446

	·
Australia details of stamps	Dall william to the second of the first
Australia, details of stamps	Ball mills, Ferraris, capacities of
der concentration in 007 006	table of sizes, power, weights, etc 130
dreuging in	fine grinding
paining in	for clays
riancock jig in	Gates1280, 130
mercury wells and rifles in	table of sizes, capacities, power, weights,
metallurgical practice in West. R. Allen 1323	etc 130
mill practice in. W. T. Saunders 2039	general notes on
Western. R. Stokes	Humboldt Engineering Works Company 131
plates in 788	in Australia, capacity, speed of
stamp mills in	
Stamp mills in 1180	Krupp 123
treatment of lead zinc ores in V E S I over 2024	number used
low-grade copper ore in T T Main 2002	operation of H. Fischer
low-grade copper ore III. J. J. Muli 2039	sizing test of ball mill pulp
ore at the nucknow gold neid. A. R.	on 2017
Canning	using rollers. E. Poetgens 1836
water used in stamp mills 222 Australian gold mills. 1110, 1119 Metal Company's mill, Ullrich magnetic separ-	versus rolls at Mill 159
Australian gold mills	stamps as slime malroys at Mill 105
Metal Company's mill Illrich magnetic senar-	man of stall belle in
ators at. 1535 practice, grinding pans in 1283 Austria, chromite mill in 1073	wear of steel balls in 2017
practice minding none in	wet
Austria chromita mill in	with dust separator
Austra, Chromite min in	a fines separator 2028
	with dust separator 2017 a fines separator 2028 Ball-Norton magnetic separators 797, 1527, 1568, 1527
mills in 1177 Austrian graphite mill, kieves in 727 Author's text on itsers to in 1727	at Mill 158 1822, 1824, 1825, 1822 drum-type at Mill 158 1822, 1824, 1825, 1822 drum-type at Mill 158 1821, 2028
Austrian graphite mill, kieves in	helt-type at Mill 158 1999 1994 1995 1990
Author's tests on jigging mixed sizes	drum tune et Mill 150 1022, 1024, 1029, 1022
suction	drum-type at 14111 100
Automatic discharges on jigs 553 576 577 583 504	results at Fort Henry on a
stay how for	results at Port Henry on a 2028 type 'M' at Mill 158 1822, 1823, 1825, 1826 Ballou, E. L. Stamping and concentration on sulphide gold ore
feeders 050 off ore ore	Ballou, E. L. Stamping and concentration on
Author's tests on jugging mixed sizes 630 Suction 627 Automatic discharges on jigs 553, 576, 577, 583, 584 stay box for 558, 856, 855, 856 ore feeders 853, 854, 855, 856 ore feeders 1578 samplers Vezin-type at Mill 167 1857, 1858 at Mill 172 1873, 1874 tripper at Mill 174 1883 Avery automatic scales at Mill 105 1635 Avoirdupols weights, equivalents of 1187 Axinite, specific gravity of 1180	Statistics of the state of the
complem Veria toward 3 200 de	Ball's revolving knife buddle 292 294
samplers vezin-type at Mill 1671857, 1858	Ball steam stamps
at Mill 172	123 124 126 127 128 130 121 120 122 124 140
tripper at Mill 174	220, 221, 220, 121, 120, 100, 101, 102, 103, 134, 142,
Avery automatic scales at Mill 105	
Avoirdupois weights, equivalents of 1197	valve motion
Axinite, specific gravity of	Bally balanced cam
Avton intermittent pulp thickener	Baltic mill, Redridge, Michigan. E. D. McDermott 2040
thick pulp extractor	Baltic mill, Redridge, Michigan, E. D. McDermott 2040
of Fi Pote will	W. McDermorr 90/1
Axinite, specific gravity of 1187 Axinite, specific gravity of 1189 Ayton intermittent pulp thickener 2020 thick pulp extractor 1419 at E Bote mill 1408 Azurite, specific gravity of 1408	Baltic mill, Redridge, Michigan 2044
Azurite, specific gravity of	Mining Company
	conner hand book
В	Banking in stemp moster
D 111	Transpired
Babbitting rolls 73 Babbit metal for bearings 1098 effect on mercury 1098	Borbs or research
Babbitt metal for bearings	Banks on vanners
effect on mercury	Dank, thickness of, in trommels
Pobasik & Will 1	
	Danner mine, concrete mortar block
	Barber, G. M. Grüson ball mill at Atacama Chili
	Barber, G. M. Grüson ball mill at Atacama, Chili 1182 Barbour, T. J. Dredring in California
Back plates, disadvantages of	Barber, G. M. Grüson ball mill at Atacama, Chili 1182 Barbour, T. J. Dredging in California 1182 Bardwell, E. S. Free-settling velocities 1491
Back plates, disadvantages of	Barber, G. M. Grüson ball mill at Atacama, Chili 1182 Barbour, T. J. Dredging in California 1182 Bardwell, E.S. Free-settling velocities 1421 sorting tuple for testing
Back plates, disadvantages of 910, 1090 Back plates, disadvantages of 178 Bacon, Earl C. viii rolls at Mill 152 1807 Bad-Ems. Prussia mill at 1807	Barber, G. M. Grüson ball mill at Atacama, Chili 1182 Barbour, T. J. Dredging in California 1182 Bardwell, E. S. Free-settling velocities 11421 sorting tube for testing 1988
Back plates, disadvantages of 910, 1090	Baltic mill, Redridge, Michigan 2044 Mining Company 1895 copper hand book 1925 Banking in stamp mortar 215 prevention 218 Banks on vanners 652, 656, 662 Bank, thickness of, in trommels 378, 380 Banner mine, concrete mortar block 148 Barber, G. M. Grüson ball mill at Atacama, Chili 1182 Bardwell, E. S. Free-settling velocities 1421 Bardwell, E. S. Free-settling velocities 1421 sorting tube for testing 1988 Barge with log washers 326
Back plates, disadvantages of 910, 1090 Bacon, Earl C. 178 Bacon, Earl C. viii rolls at Mill 152 1807 Bad-Ems, Prussia, mill at 1177 Badoureau, A. Free settling in water 477 Baffle board in mercury wells 720	148
Back plates, disadvantages of 910, 1090 Bacon, Earl C. viii rolls at Mill 152 1807 Bad-Ems, Prussia, mill at 1177 Badoureau, A. Free settling in water 477 Baffle board in mercury wells 768 settling tank 450	148
1090 1090	148
1090 1090	148
1090 1090	Barber, G. M. Grüson ball mill at Atacama, Chili 1182 Barbour, T. J. Dredging in California 1182 Bardwell, E. S. Free-settling velocities 1421 sorting tube for testing 1988 Barge with log washers 326 Barite, angle of nip to crush 94 decrepitation of 829 dressing at Long Island. E. K. Judd 2027 methods used in dressing. E. Higgins, Jr. 2026 specific gravity of 1189
1090 1090	148
1090 1090	decrepitation of 829 dressing at Long Island. E. K. Judd 2027 methods used in dressing. E. Higgins, Jr. 2026 specific gravity of 1189 washing 1173
1090 1090	decrepitation of 829 dressing at Long Island. E. K. Judd 2027 methods used in dressing. E. Higgins, Jr. 2026 specific gravity of 1189 washing 1173
1090 1090	decrepitation of 829 dressing at Long Island. E. K. Judd 2027 methods used in dressing. E. Higgins, Jr. 2026 specific gravity of 1189 washing 1173
1090 1090	decrepitation of 829 dressing at Long Island. E. K. Judd 2027 methods used in dressing. E. Higgins, Jr. 2026 specific gravity of 1189 washing 1173
1090 1090	Barite, angle or hip to crush 94
Back plates, disadvantages of 910, 1090 Bacon, Earl C. vii Bacon, Earl C. vii rolls at Mill 152 tii Bad-Ems, Prussia, mill at 1177 Baddoureau, A. Free settling in water 477 Baffle board in mercury wells 768 settling tank 459 plates in distributors 857 driers 882 to settle dust 1099 Bag room for dust 883 Bailey, G. E. Gold stamp mills 1183 Baize for tables 703 tables on dredges 1012 Baker, G. W. Blake breaker 58 on breakers 58	Barite, angle or hip to crush 94
Back plates, disadvantages of 910, 1090 Bacon, Earl C. vii Bacon, Earl C. vii rolls at Mill 152 tii Bad-Ems, Prussia, mill at 1177 Baddoureau, A. Free settling in water 477 Baffle board in mercury wells 768 settling tank 459 plates in distributors 857 driers 882 to settle dust 1099 Bag room for dust 883 Bailey, G. E. Gold stamp mills 1183 Baize for tables 703 tables on dredges 1012 Baker, G. W. Blake breaker 58 on breakers 58	Barite, angle or hip to crush 94
Back plates, disadvantages of 178	Barite, angle or hip to crush 94
Back plates, disadvantages of 178	Barrie, angle or hip to crush 94
Back plates, disadvantages of 178	Barlet, angle or hip to crush 94 decrepitation of 829 dressing at Long Island. E. K. Judd 2027 methods used in dressing. E. Higgins, Jr. 2026 specific gravity of 1189 washing 1173 Tennessee. E. K. Judd 2027 Barium, atomic weight of 1188 Barlor, J. C. Sampling of concentrating tables 2032 Barnaby, G. A. Free-settling velocities 1421 Barnhardtite, specific gravity of 1189 Barnhardt, G. A., on Griffin mill 284 Barrel for clean-up 284, 264 Barrels for shipping concentrates 1112, 1113 Barren Springs, Virginia, iron ore from 809
Back plates, disadvantages of 178	Barlet, angle or hip to crush 94 decrepitation of 829 dressing at Long Island. E. K. Judd 2027 methods used in dressing. E. Higgins, Jr. 2026 specific gravity of 1189 washing 1173 Tennessee. E. K. Judd 2027 Barium, atomic weight of 1188 Barlor, J. C. Sampling of concentrating tables 2032 Barnaby, G. A. Free-settling velocities 1421 Barnhardtite, specific gravity of 1189 Barnhardt, G. A., on Griffin mill 284 Barrel for clean-up 284, 264 Barrels for shipping concentrates 1112, 1113 Barren Springs, Virginia, iron ore from 809
Back plates, disadvantages of 178	Barlet, angle or hip to crush 94 decrepitation of 829 dressing at Long Island. E. K. Judd 2027 methods used in dressing. E. Higgins, Jr. 2026 specific gravity of 1189 washing 1173 Tennessee. E. K. Judd 2027 Barium, atomic weight of 1188 Barlor, J. C. Sampling of concentrating tables 2032 Barnaby, G. A. Free-settling velocities 1421 Barnhardtite, specific gravity of 1189 Barnhardt, G. A., on Griffin mill 284 Barrel for clean-up 284, 264 Barrels for shipping concentrates 1112, 1113 Barren Springs, Virginia, iron ore from 809
Back plates, disadvantages of 910, 1090 Back plates, disadvantages of 178 Bacon, Earl C. viii rolls at Mill 152 viii rolls at Mill 152 viii Bad-Ems, Prussia, mill at 1177 Baddoureau, A. Free settling in water 477 Baffle board in mercury wells 768 settling tank 459 plates in distributors 857 driers 887 driers 882 to settle dust 1099 Bag room for dust 883 Bailey, G. E. Gold stamp mills 1183 Baize for tables 7703 tables on dredges 1012 Baker, G. W. Blake breaker 58 con breakers 58 Krom jig 58 Krom's improvements on Cornish rolls 110 Balancing of shaking screens 342 Balol mill 232 Balancing of shaking screens 342 Baliol mill 881 Ballarat, amalgamated plates et 1184	Barlet, angle or hip to crush 94 decrepitation of 829 dressing at Long Island. E. K. Judd 2027 methods used in dressing. E. Higgins, Jr. 2026 specific gravity of 1189 washing 1173 Tennessee. E. K. Judd 2027 Barium, atomic weight of 1188 Barlor, J. C. Sampling of concentrating tables 2032 Barnaby, G. A. Free-settling velocities 1421 Barnhardtite, specific gravity of 1189 Barnhardt, G. A., on Griffin mill 284 Barrel for clean-up 284, 264 Barrels for shipping concentrates 1112, 1113 Barren Springs, Virginia, iron ore from 809
Back plates, disadvantages of 178	Barlet, angle or hip to crush 94 decrepitation of 829 dressing at Long Island. E. K. Judd 2027 methods used in dressing. E. Higgins, Jr. 2026 specific gravity of 1189 washing 1173 Tennessee. E. K. Judd 2027 Barium, atomic weight of 1188 Barlor, J. C. Sampling of concentrating tables 2032 Barnaby, G. A. Free-settling velocities 1421 Barnhardtite, specific gravity of 1189 Barnhardt, G. A., on Griffin mill 284 Barrel for clean-up 284, 264 Barrels for shipping concentrates 1112, 1113 Barren Springs, Virginia, iron ore from 809
Back plates, disadvantages of 178	Barlet, angle or hip to crush 94 decrepitation of 829 dressing at Long Island. E. K. Judd 2027 methods used in dressing. E. Higgins, Jr. 2026 specific gravity of 1189 washing 1173 Tennessee. E. K. Judd 2027 Barium, atomic weight of 1188 Barlor, J. C. Sampling of concentrating tables 2032 Barnaby, G. A. Free-settling velocities 1421 Barnhardtite, specific gravity of 1189 Barnhardt, G. A., on Griffin mill 284 Barrel for clean-up 284, 264 Barrels for shipping concentrates 1112, 1113 Barren Springs, Virginia, iron ore from 809
Back plates, disadvantages of 178	Barlet, angle or hip to crush 94 decrepitation of 829 dressing at Long Island. E. K. Judd 2027 methods used in dressing. E. Higgins, Jr. 2026 specific gravity of 1189 washing 1173 Tennessee. E. K. Judd 2027 Barium, atomic weight of 1188 Barlor, J. C. Sampling of concentrating tables 2032 Barnaby, G. A. Free-settling velocities 1421 Barnhardtite, specific gravity of 1189 Barnhardt, G. A., on Griffin mill 284 Barrel for clean-up 284, 264 Barrels for shipping concentrates 1112, 1113 Barren Springs, Virginia, iron ore from 809
Back plates, disadvantages of 178	Barlet, angle or hip to crush 94 decrepitation of 829 dressing at Long Island. E. K. Judd 2027 methods used in dressing. E. Higgins, Jr. 2026 specific gravity of 1189 washing 1173 Tennessee. E. K. Judd 2027 Barium, atomic weight of 1188 Barlor, J. C. Sampling of concentrating tables 2032 Barnaby, G. A. Free-settling velocities 1421 Barnhardtite, specific gravity of 1189 Barnhardt, G. A., on Griffin mill 284 Barrel for clean-up 284, 264 Barrels for shipping concentrates 1112, 1113 Barren Springs, Virginia, iron ore from 809
Back plates, disadvantages of 178	Barlet, angle or hip to crush 94 decrepitation of 829 dressing at Long Island. E. K. Judd 2027 methods used in dressing. E. Higgins, Jr. 2026 specific gravity of 1189 washing 1173 Tennessee. E. K. Judd 2027 Barium, atomic weight of 1188 Barlor, J. C. Sampling of concentrating tables 2032 Barnaby, G. A. Free-settling velocities 1421 Barnhardtite, specific gravity of 1189 Barnhardt, G. A., on Griffin mill 284 Barrel for clean-up 284, 264 Barrels for shipping concentrates 1112, 1113 Barren Springs, Virginia, iron ore from 809
Back plates, disadvantages of 178	Barte, angle or hip to crush
Back plates, disadvantages of 178	Barte, angle or hip to crush
Back plates, disadvantages of 178	Barter Agree of hip to crush 94
Back plates, disadvantages of 178	Barter Agree of hip to crush 94
Back plates, disadvantages of 178	Barter Agree of hip to crush 94
Back plates, disadvantages of 178	Barter Agree of hip to crush 94
Back plates, disadvantages of 178	Barter Agree of hip to crush 94
Back plates, disadvantages of 178	Barter Agree of hip to crush 94
Back plates, disadvantages of 178	Barter August A
Back plates, disadvantages of 178	Barter August A
Back plates, disadvantages of 178 Bacon, Earl C. viii rolls at Mill 152 1807 Badoureau, A. Free settling in water 1177 Baffle board in mercury wells 768 settling tank 459 plates in distributors 857 driers 857 driers 852 to settle dust 1099 Bag room for dust 1838 Bailey G. E. Gold stamp mills 1183 Bailez for tables 703 tables on dredges 703 tables on dredges 703 tables on dredges 1012 Baker, G. W. Blake breaker 58 on breakers 58 Krom jig 858 Krom jig 8588 Krom jig 8588 Krom jig 8588 Krom jig 8588 Balley G. Sturtevant 1232 Balancing of shaking screens 342 Balch magnetic separator 334 Baliol mill 1184 Ballarat, amalgamated plates at 745 plates at 785 plates at 785 plates at 226 Victoria, mills at 1180 Ball, C. M. Ball-Norton separator 833, 1175 Cummings mill 292 stamps at 226 Victoria, mills at 1180 Ball mills 2182 Ball mills 2183 Ball mills 223, 266, 1285 Allis-Chalmers 1323 analgamanton 1156 an article on the 1156 an article on the 1156 art 1829, 1830, 1914 best size of facel for U. 1828, 1829, 1830, 1914 best size of facel for U. 1828, 1829, 1830, 1914 best size of facel for U. 1828, 1829, 1830, 1914 best size of facel for U. 1828, 1829, 1830, 1914 best size of facel for U. 1828, 1829, 1830, 1914 best size of facel for U. 1828, 1829, 1830, 1914 best size of facel for U. 1828, 1829, 1830, 1914	Barter August A
Back plates, disadvantages of 178 Bacon, Earl C. viii rolls at Mill 152 1807 Badoureau, A. Free settling in water 1177 Baffle board in mercury wells 768 settling tank 459 plates in distributors 857 driers 857 driers 852 to settle dust 1099 Bag room for dust 1838 Bailey G. E. Gold stamp mills 1183 Bailez for tables 703 tables on dredges 703 tables on dredges 703 tables on dredges 1012 Baker, G. W. Blake breaker 58 on breakers 58 Krom jig 858 Krom jig 8588 Krom jig 8588 Krom jig 8588 Krom jig 8588 Balley G. Sturtevant 1232 Balancing of shaking screens 342 Balch magnetic separator 334 Baliol mill 1184 Ballarat, amalgamated plates at 745 plates at 785 plates at 785 plates at 226 Victoria, mills at 1180 Ball, C. M. Ball-Norton separator 833, 1175 Cummings mill 292 stamps at 226 Victoria, mills at 1180 Ball mills 2182 Ball mills 2183 Ball mills 223, 266, 1285 Allis-Chalmers 1323 analgamanton 1156 an article on the 1156 an article on the 1156 art 1829, 1830, 1914 best size of facel for U. 1828, 1829, 1830, 1914 best size of facel for U. 1828, 1829, 1830, 1914 best size of facel for U. 1828, 1829, 1830, 1914 best size of facel for U. 1828, 1829, 1830, 1914 best size of facel for U. 1828, 1829, 1830, 1914 best size of facel for U. 1828, 1829, 1830, 1914 best size of facel for U. 1828, 1829, 1830, 1914	Barric, angle of hip to crush
Back plates, disadvantages of 178 Bacon, Earl C. viii rolls at Mill 152 1807 Bacon, Earl C. viii rolls at Mill 152 1807 Bad-Ems, Prussia, mill at 1177 Baffle board in mercury wells 768 settling tank 459 plates in distributors 857 driers 852 settling tank 1099 Bag room for dust 1099 Bag room for dust 1999 Baley G. E. Gold stamp mills 1183 Bailey G. E. Gold stamp mills 1183 Baize for tables 703 tables on dredges 703 tables on dredges 1012 Baker, G. W. Blake breaker 58 on breakers 58 Krom jig 838 Krom's improvements on Cornish rolls 110 Balanced rolls, Sturtevant 1232 Balancing of shaking screens 342 Balch magnetic separator 834 Balch magnetic separator 834 Balch magnetic separator 834 Balch mill 1184 Ballarat, amalgamated plates at 745 plates at 785 plates at 785 plates at 220 stamps at 120 Victoria, mills at 1180 Ball, C. M. Ball-Norton separator 833, 1175 Cummings mill 292 equations for concentration 1976 on power used for crushing 309 Ball mills 1156 an article on the 2014 as re-grinding machines 1322, 1332 at mills 1132 bets size of feed for. H. J. Brooke 1323 bibliography for 293	Barte, angle or hip to crush
Back plates, disadvantages of 178 Bacon, Earl C. viii rolls at Mill 152 1807 Bacon, Earl C. viii rolls at Mill 152 1807 Bad-Ems, Prussia, mill at 1177 Baffle board in mercury wells 768 settling tank 459 plates in distributors 857 driers 852 settling tank 1099 Bag room for dust 1099 Bag room for dust 1999 Baley G. E. Gold stamp mills 1183 Bailey G. E. Gold stamp mills 1183 Baize for tables 703 tables on dredges 703 tables on dredges 1012 Baker, G. W. Blake breaker 58 on breakers 58 Krom jig 838 Krom's improvements on Cornish rolls 110 Balanced rolls, Sturtevant 1232 Balancing of shaking screens 342 Balch magnetic separator 834 Balch magnetic separator 834 Balch magnetic separator 834 Balch mill 1184 Ballarat, amalgamated plates at 745 plates at 785 plates at 785 plates at 220 stamps at 120 Victoria, mills at 1180 Ball, C. M. Ball-Norton separator 833, 1175 Cummings mill 292 equations for concentration 1976 on power used for crushing 309 Ball mills 1156 an article on the 2014 as re-grinding machines 1322, 1332 at mills 1132 bets size of feed for. H. J. Brooke 1323 bibliography for 293	Barter April Barter Ba
Back plates, disadvantages of 178 Bacon, Earl C. viii rolls at Mill 152 1807 Bacon, Earl C. viii rolls at Mill 152 1807 Bad-Ems, Prussia, mill at 1177 Baffle board in mercury wells 768 settling tank 459 plates in distributors 857 driers 852 settling tank 1099 Bag room for dust 1099 Bag room for dust 1999 Baley G. E. Gold stamp mills 1183 Bailey G. E. Gold stamp mills 1183 Baize for tables 703 tables on dredges 703 tables on dredges 1012 Baker, G. W. Blake breaker 58 on breakers 58 Krom jig 838 Krom's improvements on Cornish rolls 110 Balanced rolls, Sturtevant 1232 Balancing of shaking screens 342 Balch magnetic separator 834 Balch magnetic separator 834 Balch magnetic separator 834 Balch mill 1184 Ballarat, amalgamated plates at 745 plates at 785 plates at 785 plates at 220 stamps at 120 Victoria, mills at 1180 Ball, C. M. Ball-Norton separator 833, 1175 Cummings mill 292 equations for concentration 1976 on power used for crushing 309 Ball mills 1156 an article on the 2014 as re-grinding machines 1322, 1332 at mills 1132 bets size of feed for. H. J. Brooke 1323 bibliography for 293	Barte, angle or hip to crush
Back plates, disadvantages of 178 Bacon, Earl C. viii rolls at Mill 152 1807 Bacon, Earl C. viii rolls at Mill 152 1807 Bad-Ems, Prussia, mill at 1177 Baffle board in mercury wells 768 settling tank 459 plates in distributors 857 driers 852 settling tank 1099 Bag room for dust 1099 Bag room for dust 1999 Baley G. E. Gold stamp mills 1183 Bailey G. E. Gold stamp mills 1183 Baize for tables 703 tables on dredges 703 tables on dredges 1012 Baker, G. W. Blake breaker 58 on breakers 58 Krom jig 838 Krom's improvements on Cornish rolls 110 Balanced rolls, Sturtevant 1232 Balancing of shaking screens 342 Balch magnetic separator 834 Balch magnetic separator 834 Balch magnetic separator 834 Balch mill 1184 Ballarat, amalgamated plates at 745 plates at 785 plates at 785 plates at 220 stamps at 120 Victoria, mills at 1180 Ball, C. M. Ball-Norton separator 833, 1175 Cummings mill 292 equations for concentration 1976 on power used for crushing 309 Ball mills 1156 an article on the 2014 as re-grinding machines 1322, 1332 at mills 1132 bets size of feed for. H. J. Brooke 1323 bibliography for 293	Barte, angle or hip to crush
Back plates, disadvantages of 178	Barter April Barter Ba
Back plates, disadvantages of 178 Bacon, Earl C. viii rolls at Mill 152 1807 Bacon, Earl C. viii rolls at Mill 152 1807 Bad-Ems, Prussia, mill at 1177 Baffle board in mercury wells 768 settling tank 459 plates in distributors 857 driers 852 settling tank 1099 Bag room for dust 1099 Bag room for dust 1999 Baley G. E. Gold stamp mills 1183 Bailey G. E. Gold stamp mills 1183 Baize for tables 703 tables on dredges 703 tables on dredges 1012 Baker, G. W. Blake breaker 58 on breakers 58 Krom jig 838 Krom's improvements on Cornish rolls 110 Balanced rolls, Sturtevant 1232 Balancing of shaking screens 342 Balch magnetic separator 834 Balch magnetic separator 834 Balch magnetic separator 834 Balch mill 1184 Ballarat, amalgamated plates at 745 plates at 785 plates at 785 plates at 220 stamps at 120 Victoria, mills at 1180 Ball, C. M. Ball-Norton separator 833, 1175 Cummings mill 292 equations for concentration 1976 on power used for crushing 309 Ball mills 1156 an article on the 2014 as re-grinding machines 1322, 1332 at mills 1132 bets size of feed for. H. J. Brooke 1323 bibliography for 293	Barte, angle or hip to crush
Back plates, disadvantages of 178	Barte, angle or hip to crush

ORE DRESSING.

Pages 1-643, Vol. I.

Ball mills, Ferraris, capacities of table of sizes, power, weights, etc. fine grinding for clays Gates table of sizes, capacities, power, we etc.		100
ban mins, rerraris, capacities of	• • • •	. 130
table of sizes, power, weights, etc	• • • •	. 130
nne grinding	• • • •	. 201
for clays		. 201
Gates	. 128	0, 130
table of sizes, capacities, power, we	eight	s,
etc		. 130
general notes on		. 130
Humboldt Engineering Works Company		. 131
in Australia, capacity, speed of		. 202
Krupp number used operation of. H. Fischer sizing test of ball mill pulp		. 123
number used		. 34
operation of. H. Fischer		. 130
sizing test of ball mill pulp		. 131
on using rollers. E. Poetgens versus rolls at Mill 159 stamps as slime makers at Mill 185		201
using rollers. E. Poetgens		. 1830
versus rolls at Mill 159	• • • •	1916
stamps as slime makers at Mill 185	• • • •	1303
wear of steel balls in		2017
wet		2014
with dust separator		0017
a fines canamaton	• • • •	2017
Ball-Norton magnetic consenters 707 1507	:::::	2028
o+ Mill 150	1909	, 1027
wear of steel balls in wet with dust separator a fines separator a fines separator separator a fines separator a fines separator at Mill 158 belt-type at Mill 158 results at Port Henry on a type 'M' at Mill 158 Ballou, E. L. Stamping and concentration sulphaide gold ore Ball's revolving knife buddle Ball steam stamps 114, 118, 119, 120, 123, 124, 126, 127, 128, 130, 131, 132, 133, valve motion	:::::	1826
Dent-type at 1911 158 1822, 1824,	1825	, 1822
drum-type at 19111 198	1821,	, 2028
results at Port Henry on a		2028
Type M at Mill 158 1822, 1823, 1	825,	1826
Ballou, E. L. Stamping and concentration	on	
sulphide gold ore		1184
Ball's revolving knife buddle	. 328	3. 334
Ball steam stamps 114, 118, 119, 120,	121	. 122.
123, 124, 126, 127, 128, 130, 131, 132, 133	134	142
		143
valve motion		123
Bally balanced cam		226
cam		228
Baltic mill, Redridge, Michigan, E. D. McDerr	nott	2040
W. McDermott	11000	2041
Baltic mill, Redridge, Michigan	• • • •	2044
Mining Company		1008
copper hand book	• • •	1005
Banking in stamp mortar	• • •	015
valve motion Bally balanced cam cam Baltic mill, Redridge, Michigan. E. D. McDernott Baltic mill, Redridge, Michigan Baltic mill, Redridge, Michigan Mining Company copper hand book Banking in stamp mortar prevention Banks on vanners Banks on vanners Banks thickness of, in trommels Banner mine, concrete mortar block Barbert, G. M. Grüson ball mill at Atacama, Chi Barbour, T. J. Dredging in California Bardwell, E. S. Free-settling velocities sorting tube for testing Barge with log washers Barite, angle of nip to crush decrepitation of dressing at Long Island. E. K. Judd methods used in dressing. E. Higgins, Jr. specific gravity of washing in Tennessee. E. K. Judd	• • •	010
Banks on vanners	OFO	218
Bank, thickness of in trommele	000	, 002
Banner mine concrete morter block	3/8	, 380
Barber G. M. Grison bell will at Atana		148
Barbour T I Dredging in Colifornia	ш.	1182
Bardwell E S Free settling velocities	• • •	1182
sorting tube for testing velocities	• • •	1421
Barge with log washers	• • •	1888
Barite angle of nin to small		326
decrepitation of	• • •	94
dressing at Lang Taland Talan		829
methods used in Justine. E. K. Judd	• • •	2027
specific greater of dressing. E. Higgins, Jr.	• • • •	2026
specific gravity of		1189
wasning		1173
washing in Tennessee. E. K. Judd Barium atomic weight of	:	2027
Barlon, atomic weight of		1188
Barrior, J. C. Sampling of concentrating tables .	:	2032
Barnaby, G. A. Free-settling velocities		1421
Darmardine, specific gravity of		1189
Darmart, G. A., on Griffin mill		284
parrei for clean-up	284	264
parrels for shipping concentrates	12	าวีาัสิ
Barren Springs, Virginia, iron ore from	,	800
Dar rittles	721	724
screens	,	336
in Tennessee. E. K. Judd Barium, atomic weight of Barlor, J. C. Sampling of concentrating tables Barnaby, G. A. Free-settling velocities Barnhartite, specific gravity of Barnhart, G. A., on Griffin mill Barrel for clean-up Barrels for shipping concentrates. 11 Barren Springs, Virginia, iron ore from Bar riffles screens Barry tube mill lining Bars for supporting jig sieves Barth, C. Krom's rolls vs. stamps stamps and rolls stamps and rolls	٠.,	2014
pars for supporting jig sieves	• • •	520
Barth, C. Krom's rolls us stamps	• • •	000
stamps and rolls		119

Pages 644-1197, Vol. II.

Pages 1199–1610, Vol. III.	IND	EX.	Pages 1611-2052, Vol. IV.	
Bartlet, J. C., table	. 2023 . 1767 . 1036 . 61	breakers capacity and waddrum separator a finest size jigged hand and machi		
bumping circular table rotary percussion tables at Mill 150 rotary percussion table, the round table Barus, C. Settling in liquids settling of very fine particles in liquids	. 2022 . 1186	on number of sic ore dressing in S	ves for jigs 641 500 Saxony, The Harz, and Rhenish 1176 ine at Himmelfurst mine 837	•
tests on clay particles Barytes and zinc blende, separation of by decrepita tion Basalt, strength of	. 1565 . 301	hydraulic class Schranz breaker Schranz mill	at Friedrichssegen. Meinecke ifier, Meinecke spitzlutte 477 60 200 and Linkenbach slime tuble 728	•
Base metals, effect on mercury in bullion Basin Reduction Company washers for clay Batea	. 785 . 1848 5, 1076 . 1152	trommels. Schn value of hand pi Bellevue coal washer, Bell, R., Concentrati	nidt spiral sieve	
belt for vanners mechanical Bath for silver plating Batopilas, amalgamating pans at Mexico, Silver Mill at	. 083 . 755 . 291 . 1174	Grasshopper Bell, Robert N. Not Belpair boilers Belt and pulley for tr	Snake River, Idaho 2036 Creek 2041 te on Triplex rolls 1942 commels 356	
Battens for mills Battery, Boss standard cloth, brass and iron construction frame contileyor, I. C. Boss	. 1088 . 1267 . 171 . 2012	Blasdel	4ill 41 650	1
M. P. Boss description of a screens at Mill 96 Foote screen gun-metal at Mill 185	. 2012 . 1618	at mills 1709, 1710, 1764, 1768,	. 1031, 1670, 1690, 1691, 1700, 1708, 1708, 1735, 1750, 1759, 1700, 1702, 1703, 1709, 1771, 1772, 1828, 1851, 1853, 1808, 1809, 1878, 1913	
standard ten-stamp water, the temperature of the Baugh's mill of cone type Baum jig coal jig 5.	. 2012 . 2012 . 292	elevators		
advantages of air pressure and gravity disadvantages discharge	. 537 . 519 . 519 . 581	Brunton tab Castelnau ta Ferraris tabl Uren table.	le	
mechanism washing-plant. Barnsley, Eng. Herne coal washing jig Bauschinger, J. Strength of stone. Bauxite, specific gravity of	. 2051 . 2021 . 316 . 1189	Loring percussion table rope and plate concerns		
Bavaria, graphite dressing in Baxter breaker Bayliss, R. T. Amalgam on plates on Blanton cams Bay State Mining Company mill xxvi	. 787 . 194 . 1023	Dunlap perfec	t clay screen 3358 1367 3669 or 728 s	
Bazin's amalgamator Beach Glen Tron ore concentrated by magnets 8 Beakers for settling tests Bearings for cam shaft	02, 803 - 1146 90, 191	Belting used on amal	gamated plates	
Utah the mill of the Utah Copper Co., Garfield, Utah. Beatty, A. C. An improved amalgamation process Beaumont, W., on breakers.	. 2038 . 2045 . 2024 . 59	corrugated corrugated versu.	197 1585 For belts in Wetherill magnetic 1523 647 5 plain 650	
Cole's stone breaker Becker Foundry & Machine Co. Becker, G. F. and S. F. Emmons. Amalgamatin pans amalgamation	. 80 g . 201 . 789	"crack-proof" vi for gravity stamp for hand picking for mills	rs (1508) unner belt (1508) s 197 , speed and capacity of 1438 1093	
arrastra edge runners Becket Foundry & Machine Co., rolls Becket and McDowell geared rolls at Mill 183 Bedding for jigs	. 295 . 76	link magnetic separat	860 ors with 864 is of 048 d picking 1435 ng belts at Mill 137 1438 q and picking 1438, 2021	
Bedding for igs Flarz jigs at Mill 183 Bed of hand jig of jigs effect of material for		Spadone concent	rator belt 1503	
size of grains for tests on on concentrators, depth of on vanners, thickness of proper condition of, on ligs	. 575 . 680 . 1510 . 660 . 595	rear amend temine	proper speed for 1524 d plates at 745, 762 tt 1180 e at. H. C. Boydell 2044 ts in 180 180 180 180 180 180 180	
thickness of, on fine concentrators Beguelin mine, Blake breaker at Belgium, jigs in mills in 117 phosphate dressing in	644	shoes and dies at stamps at Benedict, W. de L. washing plant	788 183 226 Log washer in South Carolina 1180 335	
Bell discharge for jigs	. 582 O	on wash tromme	ls 333	r

Pages 1-643, Vol. I.	ORE	DRESSING.	Pages 644-1197, Vol. II.
Benson mines, magnetic separation at Berdan's amalgamating pan Berenger and Stingls slime tank		798 Bilharz, O. <i>spital ut</i> 291 test of jaw and 407 wash trommels	428 Blake breakers 428
Berlin, tests on strength of stone at Berrigan centrifugal separator		01 Wengtelin La	rate Evenness Change and 332
Bertha Zinc Co., mill	13	80 Rieve typer	lin 518
Works Berthelet inclined screen Berthierite, specific gravity of	20	18 improved Rittin	over spitzlutte 475
Bertrand mill, rolls at		10 spitslutte	5 Sieve power jig 503
Beryl, specific gravity of Bessemer steel for shoes and dies Bessie mill, Argall 4-tube drier at	1	89 table 85 capacity of 00 at mills	669
Bethune Mining Co., France, surface equipment coal washing at the	it for	Billek, J. Concents Maiern	669 504 504 504 789, 1799, 1791 ration on galena-blende-pyrite at and mill at Maiern, Austria 493 at Maiern, Siemens and Halsha
Bettel, W. Delinition of slimes	18	97 picking in mine	and mill at Maiern, Austria 493
Beuthen, mill at Upper Silesia, mill at Bevel gears	10	87 separators .	2 886
Bibliography for adhesion amalgamation	8	39 Bingham, Utah, mil 87 milling the ores	for steam stamps
appendix breakers and hammers	11	73 Binkley, George E. 57 Bins	or steam stamps 129 1 1 20 1 1 20 1 20 20 20 20 20 20 20 20 20 20 20 20 20
centrifugal separation	8	39 at mills 17- 75 concentrate dry	12, 1743, 1760, 1761, 1762, 1763, 1857
classifiers and laws of classifying decrepitation disintegrating and screening	8	39 discharge chute 39 drier, at Mill 10	in
dust chambers and bag houses elevators and conveyors feeders and distributors		85 filter 84 for concentrates	1625
gravity stamps			e mine, drawings of the ore 2032 cities. See individual mills in
hand picking jigs and laws of jigging kieves	4	39 Stamp	100
launders	8	with steam pipe in Biotite, separation fr	on molyklenite by magnet 1880
laws of classifying by free settling in wat crushing	9	Birkinbine, J., and	A. Edison. Blake system
jigging	mag-	Edison serse	rators
netism mills and general milling pneumatic concentration	117		
prenumary crushing	,	Conking separa	at Atlantic will
washers pulverizers pumps	28	magnetic concen	ntic mill 57 tration 1175
		7 Lake Superior	nac mit 87 tration 1175 ic mill, Lake Superior 1175 1175 1194 76 172
roasting for friability roasting for porosity rolls		9 Iron foundry .	76
sampling screening	88	4 Bismuth amalgam .	730
vanners, tables, riffles, and kieves	14	 Bismuthinite, specific Bismuth removed fro 	772 730 730 730 730 8 gravity of 1189 m mercury 786 f 1189 f 1189 f 1189 f Dodge type 31 at 1035, 1048 at 57
weathering Bigelow patent breaker Bilharz cobbing magnet	200	9 specific gravity o Bituminous coal, spec	f 1189
O. and E. W. Neubert Dressing at Fall	153	Blackhawk breaker of Colorado, mill at	f Dodge type
Saxony Bilharz, O.	117	4 cost of gold milli	at
Bilharz, O. Altenberg classifier and Rittinger spitalutte Ball stamps Bilharz belt table		district, South Da	ng in
hydraulic classifier sinhon generator Alteri	72	orivalina in	1977, 1978
ilg	471	mills in	
movable sieve jigs table, Frue vanner, slime table, and buddle.	727	stamps in	
versus Rittinger spitshute Blake, Kley, Gates, and McCully breakers Carnall and Crickboom wash trommels Carr disinterator	470	Black Pine, Montana,	ilde mill in the. E. B. Sawyer, 2044 mill at 1175
Carr disintegrator Dingey mill	298	by U. S. G. S., ir	
Carr disintegrator Carr disintegrator Dingey mill edge runners general milling gravity stamps	295	concentration by	treating
gravity stamps Griffin roller mill grizzlies, riddles, and trommels Grüson ball mill Heberli mill	228 297	D. T. Day, R	. H. Richards 2088
grizzlies, riddles, and trommels Grüson ball mill	384	Leighton separate	w. Brazenati
Heberwäsche, Harz jig, Bilharz jig	292	problem of the.	224 237 135 136 137 136 137
Huntington mill at Freiberg, Saxony1	182, 1185 296	treatment of	2034 2028 an
Pape-Henneberg separator and Krom jig	2034 837	Californi Blacksmith shop for m	n 2027
picking houses Rittinger's principles	837 492	Blades in centrifugal p Blaisdell aerators at M	in 2025 a 2027 iil 1087 sumps 869 iil 109 1650 statibute 1400
Grüson ball mill Heberi mill Heberwäsche, Harz jig, Bilharz jig Himmelfahrt mill at Freiberg, Saxony 1 Huntlington mill milling in Missouri Pape-Henneberg separator and Krom jig dry concentration picking houses Rittinger's principles Schwarzmann's rolls	1175	centrifugal sand d Company. Blaisc	istributor 1602 lell mechanical ore machinery 1609
		10	The second secon

Pages 1199–1610, Vol. III.	INDE	EX.	Pages 1611-2052, Vol.	. IV.
Pages 1199—1610, Vol. III. Blaisdell distributor excavator at mills 1670, mechanical mixer sand distributor slime agliator system of mechanical ore handling Blake breakers of mechanical ore handling 13, 55–61, at mills 1617, 1618, 1621, 1624, 1724, 1737, 1749, 1769, 1792, 1802, 1821, 1823, 1824, 1837, 1853, 1832, 1833, author's tests on samples crushed in Carterville Foundry & Machine Works Case laboratory breaker of the Denver Fire Clay Company comparative wear of metals in jaws compared with Dodge Gates Denver Engineering Works Company design of details of from the mills sizes EII Whitney Farrel Foundry and Machine Company for testing Gates Iron Works horse-power required Humboldt Engineering Company information on 18, Krupp rock lead ore crushed in lever type life of wearing parts of at Mill 139 National Drill and Manufacturing Company's New Century Blake operation of Surtevant roll-jaw toggles used for pounding blocks Von Reytt's tests Von Reytt's tests Von Reytt's tests Wear of 2, Blake-Denison continuous weighers Weigher Company, Blake-Denison Weighing machine at mills 18, 1832, Blake double jaw breaker at Mill 188 Blake, L. I. Blake-Morscher separators electrostatic separation Blake-Marschen line breaker breaker at Mill 185 Blake-Morscher electrostatic separators electrostatic separation magnetic separation Blake breaker Or Separator, McA. Johnson at Mill 140 teatment of milling at Mill 131 Blake multiple jaw breaker or Chateaugay Ore and Iron Company, N. Y. rock breaker red Montana Zinc Company, N. Y. rock breaker wearing parts for breakers W. P. Amalgamation Blake breaker wearing parts for breakers W. P. Amalgamation Blake magnetic separator breakers Howland's stamp battery stamp mills in California, Australia, and Brazil. German over- flow battery, Rittinger stay battery Hute & Geyler's settling cylinder, Hundt's sett- ling tub and Rittinger's setsrad. jigs pivoting of jaw reverberatory furnace designed by separating ploende and pyrite separating processes sliver milling at Butte, Montana two-stam	1600 1600 1808 1600 1808 1600 1203 1201 1201 1201 1201 1203 1303	Blanding, L. Amalga Blandy, J. F. Ball str pneumatic stamp Blanket concentrating for mortar blocks tables on dredges under amalgamate used dry for conce in sweating plate Blanks for accounts Blanton cams Blasted vanner belt Blasting in the mine Bleaching powder Bleichert aerial tramwa wire tramway Bleischarley mill, Silesi mine, mill at Bleichert aerial tramwa wire tramway Bleischarley mill, Silesi mine, mill at Blende and pyrite sepa roasting am separation siderite separate crushed by rolls jigs in Missouri, c mill for ore, roasting of test on weight of separated by decre from pyrite quartz separation at Amn weight of, Bleyberg, double disch sieve scale at Blinding of screens Blisters on amalgamate Block corundum system of selecting Block 10 mine Blomeke, C. Advanta apparatus in Gern ball mills Bartsch, Schranz system of selecting Block 10 mine Blömeke, C. Advanta apparatus in Gern ball mills Bartsch, Schranz tables onreand Schra Gröppel concentra hand picking at R ing table Himmelfahrt ore c Saxony separator in Aurora and D Kåvån-Rittinger, tables labor for jigs magnetic separatic in Hungary separator new jig screen ore dressing at Ba Beuthen, Sile Clausthal Lintorf Silberau, Len red Groppel sole schranz mill separation side plunger eccer slives at the Hil	Pages 1611—2052, Vol. mation tables at Mill 118	7892 14437 1678 1678 1678 1678 1668 1678 1668 1680 1680 1680 1680 1680 1680 168
Wimmer's, Rittinger's, Harz, and Huet and Geyler's jigs	643 11	Stein, Schranz, an	d Rittinger tables	. 728 728


Pages 1-643, Vol. I.

ORE DRESSING. Pages 644-1197, Vol. II. Braun, Company, F. W. Sample grinders 1323 jig 641 double discharge on 584 sample grinder 1279, 1284 solution 1156 Bray coal screen 1156 Brazil, mining in. W. Maude 2018 stamps in 227, 229 Brazing of amalgamated plates 735 Breakers, action of 188 Breakers, action of 188 Alden type 59, 61 Allis-Chalmers, Gates type 1222 American rock 1222 Archer type 57, 58, 60

Breaking before stamping in California 1619	Bromilow magnetic separator
by hammers	Bromine, atomic weight of
with or without hand picking	Bromly, A. H. Weight of ore crushed for cyaniding 1107
cost of 50	Bromyrite, specific gravity of 1189 Bronze for jig screens 545 screens 355
at Mill 162 1222	Bronze for ijg screens
crushing, comminuting	screens 045
details of cost	screens
for hand picking 1435 general considerations about 47 hand and machine compared 12, 56	Screens 355
general considerations about 47	Brooke H I Post size of facility 1 31 311
hand and machine compared 19 56	Brookfold Mining C. 1323
pieces for breakers	Prodite marife 1166
Breast water wheels	Brookite, Specific gravity of
Breccia, andesitic, crushed at Florence, Colorado 1030	brooklyn Chrome Steel Works
Breccia, andesitic, crushed at Florence, Colorado 103 Breckenridge, Colorado, ore crushed in Griffin mill . 284	broom for amalgamated plates
Breiniger, Colorado, ore crusted in Grimti mili . 204	buddles705, 707
Breinigerberg mill, jigs in	canvas tables
mine, fig eccentrics at	German sweeping table 704
Breinigerberg mill, jigs in 597 mine, jig eccentrics at 532 Brennan and Young 1055 breaker 59	Brough, B. H. Concentration at Svärto, Sweden 1185
breaker 59	magnetic concentration plants in Sweden 1170
Diake type	Wenstrom separator and plant at Svärto, Sweden. 834
Blake type. 21 Brewer, W. M. Log washer plant in Alabama 1180 settling in liquids 1183	Broughton Asbestos Company magnet, the 1532
setting in inquids	Brown & Sharpe 1105
_ spray pape for trommer	gauge 1194
Brewster, New York, mill at	screen gauge 179
Briart bar screen	breaker
movable grizzly bars 386 Brick and stone for mills 1088	coal, specific gravity of
Drick and stone for mills 1088	F., Importance of fine grinding 1322
Bridgman, H. L. Bridgman mechanical samplers 884	R. G. Details regarding Frenier and number 1507
	plates and traps at Bodie California 700
DINK, G. G. Action of sands in classifiers and line 2020	Wenstrom separator and plant at Svärto, Sweden. 834 Broughton Asbestos Company magnet, the 1532 Brown & Sharpe 1105 gauge 1194 screen gauge 172 breaker 45 coal, specific gravity of 1189 F., Importance of fine grinding 1323 R. G. Details regarding Frenier sand pumps 1587 plates and traps at Bodle, California 788 pumps for handling pulp 1610
investigations of suction in figging	plates and traps at Bodie, California 788
SLUGV OF 110'S 1489	spindle breaker
Drinje's preaker	Browne hydrometric conical sizer
Brink & Hübner disintegrator236, 284	sizing of products of
bibliography for	Brownell Frue vanner
capacity of, at Mannheim 286 Brinsmade, R. B. Concentration in Southwest Mis-	vanner belt
Brinsmade, R. B. Concentration in Southwest Mis-	Browning crane hoist at Mill 165
souri	F. D. Plates in Providence mill 1852
	stamps at Providence mill Navada City Cali
pyrite milling in New York	fornia
pyrite milling in New York 2027 the Combination Mountain mill, Montana 2042	Brucite, specific gravity of
	Fornia
Missouri 2042	bibliography for 293
Union mill, Gratz, Kentucky 2038 Briquetting iron concentrates. 1054	
ore	
Britannia Beach. Hancock jig at	
ore 1054 Britannia Beach. Hancock jig at 1441 Copper Company, B. C., the mill of the, R. Stokes 2046	
R. Stokes 2046 United mill, acid water 173	
United will and much	principles of sampling
amalgamated plates in	rock nouse 485
amalgamation in	roll snims 74
amalgamated plates in 745 amalgamation in 768 British Columbia, concentration at. R. Bell 2034 concentration in the Kootenay district. E. R.	rock house 485 roll shims 74 sampler 847, 1572, 2032 requisites to accuracy when points
concentration in the Kootenay district. E. R.	requisites to accuracy when using 1575 sampling 850, 884 Brush for dressing amalgamated plates 756, 760 Brussels carpet in sluiges
Woakes 2034	Brush for dressing amelianus 1
history of 1009	Brussels carnet in sluices
18.60ry of mining in. H. M. Lamb 2035	for tables
ilgring for a significant state of the signifi	
milling at Duntal In	Bruyn slime separator 750
mills at Roseberry. A. W. Dyer 2035	Bryan mills at Mill 179 1070 1000 1000 2020
notes on T. T. 2034	Bruyn slime separator
milling at the Class at the Cla	data on D W C Nolon
notes on. L. Jordan 2034 milling at the Slocan district. S. S. Fowler 2034 ore dressing in the Slocan district. P. A. well P. A. S. Fowler 2034	bibliography for
ore dressing in the Slocan district. S. S. Fowler. 2034 British imperial wire gauge	number used 2016
Brittain, D. Milling the sheet are at 7 1195	sizing tests on. F P Probert
Brittleness of minerals, effect of	
under crushing force	
under crushing force 1611 use of made, in mills 891 Brodie breaker 891	
Brodie breaker 60	versus high-speed rolls 273 Huntington mill 1309 rolls, F. P. Probert 273
Broken Hill, Collom jig at	Huntington mill
concentration at. D. Clark	rolls. F. P. Probert
at. T. J. Greenway 2040	stamps
	Bryan roller mill. 273 quartz mill, dimensions of 284, 271 guartz mill, dimensions of 272 Bryant, W. G. Discussion of design is nim 272
	quartz mill, dimensions of
DeBavay flotation process at	Bryant, W. G. Discussion of design of Blake
Hancock jig at 1562 Hancock jig at 504 jigs at 543 metallurgy at 643	breakers . Discussion of design of Blake breakers . 1201 Buchal, L. Pointed boxes at Przibram . 1201 rope driver for stamps at Przibram . 478
matally at 643	rope driver for at Doxes at Przibram 478
metallurgy at 643 milling practice. G. Delprot 1568	rope driver for stamps at Przibram
R Stokes G. Delprat 2038	stamps at Przibram
milling practice 2046	at mile
milling practice. G. Delprat 1568 milling practice 2038 R. Stokes 2046 milling practice 2039, 2047 mills at 1208	table of movements of old
mills at 2039, 2047 mills at 2039, 2047 mills at 1136, 1182 ore dressing at. G. D. Delprat 1136, 1182 Potter and Delprat flotation processes at 1561 Proprietary Company, report of the	Buchanan breaker 229 Buchanan breaker 59, 61 at mills 1818, 1891, 1913 C. G. Magnetic concentration 23
Potter and Delpost dates:	C. G. Magnetic concentration 1178 granulator 59 magnetic separator 803, 2028 rock breaker 803, 2028
Proprietary Company, report of the	magnetic general 59
Sengration of colone and it is	rock breaker
stamps at	of Risks turns
steam stamps at	
Broken on mild.	rolls at mills
Mater used at 142	universal breaker 1819, 1897 Buckbee, A., on silver milling 50 1040
	nuckbee, A., on silver milling
14	2010

Pages 1199–1610, Vol. III.	IND	EX.	Pages 1611–2052, Vol. IV.
Bucket conveyor dredge 10 elevators sample Buckets, elevator, materials for for elevators Buckeye engine 910, 18 Bucking board King's 12 samples Buckskin for squeezing amalgam Buckstaves for gravity stamps Bucyrus dredge 10 Buddle jig Buddles bilbiography for building 14 convex Cornish, at Mill 185 Dodd	290 08, 1011 862 864 864 864 864 1137 157 157 158 158 151	Butte, Mon Reduct mills Wild Butters' and distributo Butters, Ch Gyan figur re-gr rules valur filter be pan, bi patent vacuun Bittgraphaci	tana, ores, sizing tests on 1840 ion Works 1849 ey table at xxvii, 987 ey table at 674 if Mein pulp distributor at Mill 117 1670 rs at Mill 106 rs at Mill 106 rs, 1041 as, Congulation, concentration, and settling of slimes 1184 diding at El Oro 1924, 2040 es on sampling 852 inding tests on sands 2014 for sampling 849 ble tube mill experiences in El Oro 2016 briggraphy of 293 amalgamating pan 233 a filter boxes at Mill 102 1630 h, P. Glass jig 1181 sting jigs 1181 at general axes
rectangular round concave convex	706	poini	ed boxes 478
tye Buffalo Hump Mining Co., mill	707 954	separat Byron Jack	lic classifiers 476 or (classifier) 447 son centrifugal pumps at Mill 103 . 1632, 1633, 1662, 1673
Tiger and Poorman Branch mill Buffer for feeding gravity stamps Burbee, E. E. School laboratory work, a free mi	199		C
Bugbee, E. E. School laboratory work, a free ming gold ore Buhrstone mill	2048 232, 252	Cabarceno,	Spain, mill at
versus Griffin mill	291	Wash tr	Newhouse Utah 1924
Building buddles	685, 704	Cadmium a	A. Palmer
for mills	86, 1087	specific Caesium, at	weight of 1188 gravity of 1189 omic weight of 1188
Bulkley condenser Builfrog cyanide mill. E. R. Ayres Bullion Beck and Champion Mining Company m	2038 ill .xxvi,	districts .	omic weight of
Bullion contents of amalgam	926 783	ton mills	Comparison of stamps and Hunting- 1262 on of slime
fineness of Bull jigs at Mill 121 Bumping ore feeder	1685	test of Calamine n	on of slime
Bumping ore feeder tables	64, 1497 740	specific	gravity of
Bartsch compared depth of bed	682	An in	or friability 9 nmeberg, Sweden 9 North Carolina 9 th or without quenching with water 9
details of in the mills end-bump tables	682	for mar	gnetism
Hendy concentrator principle of	683	specific	gravity of
Mining and Concentrating Company mil	l xxvi	chloride	omic weight of
Burdon, J. A., Brunton belt concentrator Burgan classifier, The A. L. Burke, Idaho, mill at	1371	Calculation	e, removal of by heat
Burlap filter	879	of class	ifier
for filtering dust tables on dredges Burlingame, E. E., figures on sampling	852	midd	lings into finished products
rules for sampling Burnett and Newbegin coal washer Burt E definition of slime		crı	shing efficiency of tube mills
Burt, E., definition of slime. fine grinding at El Oro milling at El Oro Burt filter presses at Mill 118 Burthé, P. L. Gravity stamps silver milling in the United States	2013	costs of	f fine grinding
Burt filter presses at Mill 118 Burthé, P. L. Gravity stamps	1678 224	discussi lime in	ion of fine grinding
Varney pan Buss patent Luhrig slimer slime table. E. Walker	1176	use of l	illing grinding in South Africa 2014 lime in silme settling 1416
slime table. E. Walker tables at Mill 185	2022	conveyors	1416
tables at Mill 185 Butte and Boston Consolidated Mining Companie mill, cost of die, etc., at		Caledonia n	onveyor
Huntington mill in Huntington mill in Mining Company, mill Reduction Works, test on ore at Butte, Montana, concentration at. C. W. Good	281 cvi, 976	amal comp	gam in
Butte, Montana, concentration at. C. W. Good cost of milling at	ale 2035	dies	Is of screen in 170 used in 180 ensions of mortars in 165
hammers used	10	finen	ess of bullion in
iir losses ot	840	mort mo	ar
launders at	.75, 1176 1419	mort rate	ars
ores, concentration of. C. W. Goodale crushed by rolls by steam stamps	** 110	scree	ing cost in
	100		TOT THE STREET STREET,

Calico California annal	rages 644-1197, V
Calico, California, amalgamating pan at 2: California, chromite mill in 10: concentration of auriferious sulphides in 20: cost of gold milling in 20:	00 40 15
	"Camel Brand" elevator belting at Mill 175 Cameron pump Cameron pump Camet table Campbell coal washing table. C. R. Claghorn Washer Camp Bird mill
Concentration of auriferious sulphides in 200	Cameron pump
producing gold in	Campbell and
dredging in	77 Washing table. C. R. Claghorn
gold milling in Newada	9 Camp Bird and
gold mills in Tyevada county. H. F. Brown 204	77 Campoeli coal washing table. C. R. Claghorn Washer Camp Bird mill Ouray, Colo. S. L. Goodale T. H. Woods, G. D. Doveton Camroux breaker Came
gold mills modern prosition 1177, 1178, 118	Juray, Colo. S. L. Goodale
gravity stamps practice in	9 Compour L. H. Woods, G. D. Doveton
milling practice of William 13	Gamroux breaker Cams
mill number and being 204	8 Cams
mills in	Bally balanced 191 Blanton and other self-tightening Boss cam key
number of pulverisons in	2 Barran and other self-tightening
silver mill Neveda 23	Boss cam key Canda cams for gravity stamps
silver mill, Nevada	Canda cams for gravity stamps design of
stamps	design of for gravity stamps
silver mill, Nevada 23 stamp mill 117 stamps 144, 204 in 225, 236 origin of 220, 226	for gravity stamps friction and lubrication of inscribing circles and clearances
origin of	iriction and lubrication of
Tierras Colonal 2019	inscribing circles and clearances lateral thrust of
Colorado and steam stamps	lateral thrust of right and left hand self-tightening
Suggestion for willis	right and left hand
system for milling of gold ores. N. H. Storms 2024	self-tightening stamp mill cam
of stamp milling 224, 227	stamp mill cam
suggestion for milling of gold ores. N. H. Storms 2034 system	starting terms starting mill cam table of details of
Callon, J. Comparison of different 1362, 1366	Canada, chromite mill in
Englis machine and Krom jig. 837 Englis machine and Krom jig. 837 Englis, Thirlon, and Dorr hydraulic classifications.	Corundum Co., mill
Engis machine and Krom jig	Cananea, concentration at D P viz 1078,
Engis, Thirion, and Dorr hydraulic classifiers. Siphon separator	Consolidated Copper Company
Siphon separator	stamp mill cam table of details of Canada, chromite mill in Corundum Co., mill Cananea, concentration at. D. E. Woodbridge Consolidated Copper Company power tests at.
gravity stamps	Sonora, Mexico mill of the
hammers and breakers	ore dressing at. D. F. Woodbard. O. P. Finley 2
jaw breaker	type Blake breaker at Mill 181
Engis, Thirion, and Dorr hydraulic classifiers. Siphon separator gravity stamps 475 hammers and breakers 223 jaw breaker 55 lectures on mining 55 mill schemes 127 movable sixty 127	power tests at. Sonora, Mexico, mill of the. O. P. Finley ore dressing at. D. E. Woodbridge type Blake breaker at Mill 151 Canby dust separator at Mill 151 R. C., separation of mixed substice.
mill schemes xix movable sieve hand and machine jigs, Harz jigs 639 percussion tables, buddles slime that jigs 639	
percussion and machine jigs, Harz jige 620	Stiffen Charle 11 1
percussion tables, buddles, slime tables, and	Sutton-Steele dielectric separators 2
kieves 727 sieve scale, trommels 109 value of hand picking 492 Callow cones 492	Canda cama
Sieve scale, trommels 109	at Mill 143
value of hand picking 384	at Mill 143. 1 stamp mill cam 1 steel jaw-plates for Blake breakers at Mill 139 1 cat Mill 166
Callow cones	steel law-plates for Plates bearings and the state of the
	at Mill 166 Diaker of cakers at Mill 139 . 18
Callow cones. 492 at mills	Camisteo district, Minnesota, washing iron over 18
On Coeur d'Alone 1-	Canisteo district, Minnesota, washing iron ores in 18 Cannon ball mills, number used 2 Canon, Arizona, gasoline engines at 10 Cantilever crane at Mill 171 for removing tailings 18 Malleable Toron denders 10 Cantilever crane at Mill 171 for removing tailings 18
test on Butte copper slimes 1404 J. M. Callow traveling belt screen 2404	Cantilever and, gasoline engines at.
J. M. Callow fraveling bulk	Canton flannel to Mill 171 for removing tailings
	Canton flannel tables on dredges . 18 Malleable Iron Company, iron balls for its in 10
pulp-thickening and settling tapks at Milliam 2020	
screens at mills 1661 1662 1664 1607 14 1662	
pulp-thickening and settling tanks at Mill 114. 1662 screens at mills 1661 1602 1604, 1687 1689 1725, capacity of to various meshes	Delts
capacity of to various meshes	Alexantes half
water in feed to	Cevator bet at Mill 125 136 for squeezing amalgam 177 plant . 1017, 1021, 1029, 1035, 1037, 1038, 1101, 111 at Garnet, Montana P. S. Mussigbrod 206 failure of 112 results at Mill Co. 102
water in reed to 1360 settling tanks at mills 1689, 1711, 1712 slime and water cones 1689, 1711, 1712	plant 1017, 1021, 1020, 100
slaughter cones	at Garnet, Montage, 1029, 1038, 1037, 1038, 1101, 111
system of tanks at mills 1662 1697 1690	cost of 208
slime and water cones 1689, 1711, 1712 sloughing-off tanks at mills 1662, 1687, 1689 system of ore concentration. J. M. Callow 2045 tanks 2045	failure of
at mills. 1683, 1684 1846 1849 1849 1849, 2020	
at mills . 1683, 1684, 1846, 1848, 1851, 1852, 1867,	200 failure of 112 results at Mill 101 102 test 162 shield for stamps 116
99 Vin ~ 60 1 . 3 min . 1000	shield for stamps 116
traveling helt screen	surface for slime tables
1848 1848	test 102 shield for stamps 116 surface for slime tables 69 sweeps for buddles 705, 701 at mills 700, 1037, 1464, 150 bibliography for 1696, 1755, 177 details of, in mills 705 for testing 705
Calumet and Hecla jigs at (C	700 1097 1464, 701
Jes at. (See also Mill 177.)	biblion 1804, 150'
mill 1440, 1446 Huntington mill in 142, 990, 1184 Krause stamp 281	details as in the contract of
Huntington mill :	Statistics
Krause stamp 281 mortar housing lining for stamp 141	for testing 700 new Dimmick patent slime table 1155 on dredges 1507
mortar housing lining silling silling 141	on dredges patent slime table
mortar housing lining for stamp 141 steam stamps 120 Mining Company 120	on dredges patent sume table 1507 vanner belt 1012 versus rubber for vanner belts 650 Capacities and speeds of picking tables and belts 1438 of Abbé tube mills at Mill 101 1438 air classifiers at Engis 816
Steam stamps	Der sue mubbane s
copper handbook	Capacities and another vanner belts
mill 1925	of Abba tube and picking tables and belts 1429
1925	air classifiers at Mill 101
sand wheel	Akron Chili milla di 1998
sand wheel 259 type Chili mills at Mill 177 1893, 1894	air classifiers at Engis 1026 Akron Chili mills, table of 179 Allis-Chalmers rolls at Mill 179 Suspended frame vanners 1898
classifier	Slispended from 1808
at Mill 166	toothed and and and 1509
Michigan, mill at 1855 mill 990	Alsing cylindom 1949
mill 990 or Richards-Coggin classifier 1892	
tables at Mill 177	American Process Company's 4.4
Cam and gravity for its many 1804	Argall driero 1500
min 9990 or Richards-Coggin classifier 1892 tables at Mill 177 1367 Cam and gravity for jig mechanism 1894 in Stutz jigs 506, 537	9rmet 901 1000
and Spring the mooks	
shatt for gravity stormer	
Krupp 100	
spring and bumping part 5 1272	8f Mill 150 981
mechanism 680	
stick 687	magnetic separators at Mill 158 . 1824 magnets
193	1528 1528
16	1407



ol. II.

2ages 1199-1010, voi. 111.
Capacities of Bartsch rotary percussion table 1497
1691, 1707, 1708, 1709, 1771, 1772, 1828
Bilharz jigs
Capacities of Bartsch rotary percussion table
breakers Blake-Morscher electrical ore separator
blanket concentrating tables at Will 118 1077 blende jigs of Southwest Missouri 602
Boggs and Clark centrifugal pump at Mill 141 1761
boilers
breakers
in Caledonia mill
Browne hydrometric conical sizers
Bryan mills
Boggs and Clark centrifugal pump at Mill 1/01
elevators
elevators. 864 Bucyrus dredge 1654 buhrstone mills 253 Butters' centrifugal pump at mills 1671, 1672, 1674, 1678
Büttgenbach's separator
Büttgenbach's separator
calcining furnace at Friedrichssegen
calcining furnace at Friedrichssegen 1546 Callow conical tanks at Mill 122
Sloughing-off tanks at Mill 122
to various sizes 1860 sloughing-off tanks at Mill 122 1087 claumet and Hecla type Chill mills at Mill 171 1893 classifiers 401 canvas, blanket and carpet tables 701, 702 at mills 1027, 1779 Carr disintegrators 285
tables
at mills. 1688, 1694, 1695, 1696, 1721, 1880, 1890, 1904, 1905
Castelnau belt tables 700 centrifugal pumps 869 at mills 1088, 1694, 1095, 1696, 1721, 1880, 1890, 1004, 1005 1890, 1004, 1005 challenge feeders at Mill 174 1883 Chli mills 269, 270 at Mill 179 1898 chip screens at Mill 173 1879 clarifying reservoirs 400 tanks at Mill 138 1743, 1744 Clarkson-Stanfield centrifugal separators 820 classifiers 403, 405, 432 at mills 1878, 1879, 1880, 1902, 1903 clay washers 1076 Cleyeland-Knowles magnetic separators 1542
at Mill 179
clarifying reservoirs
Clarkson-Stanfield centrifugal separators
at mills
clay washers 10/0 Cleveland-Knowles magnetic separators 1542 cobbing magnets at Mill 164. 1850
cobbing magnets at Mill 164. 1850 Comet breakers 41, 46 compound steam stamp at Mill 181. 1906
256 256
Conkling jigs
conveying belts at various mills
Cummings granulating mills
Conking 183 705
decrepitating furnaces 829
Dellvik-Gröndal magnetic separators
Dings magnetic separator
at Mill 140
Dodge breakers
pulverizers 262 double cone classifiers 427 drag or disc conveyors 1584
drag or disc conveyors
driers

LIZL .	.1 4805 1011 2002, 1011 211
Capac	ities of Edison driers. 882, 1600 magnetic separators 813 elevator at mills. 1661, 1663, 1667, 1685, 1690, 1707, 1727, 1728, 1720, 1749, 1750, 1752, 1753, 1755, 1771, 1772, 1774, 1829, 1842, 1843, 1844, 1845, 1846, 1847, 1853, 1854, 1877, 1880, 1898 Ellenbecker bumping tables 681 Elmore vacuum ofl process 1558 Eureka rubbers 777 Evans classifiers 377 Evans classifiers 377 Farrel Blake breakers, table of 1200 Faust jigs 548 Ferraris ball mill 177 1893 belt tables 698 classifiers 698 classifiers 698 ferraris ball mill 1300 belt tables 698 classifiers 401 patent tables, table of 1490 fixed screens 341 flotation vats at Mill 120 1718 Forsgen's electromagnetic separator 1539 Forster breakers. 28
	magnetic separators elevator at mills1661, 1663, 1667, 1685, 1690,
	1707, 1727, 1728, 1729, 1749, 1750, 1752, 1753, 1755, 1771, 1772, 1774, 1829, 1842, 1843, 1844,
	1845, 1846, 1847, 1853, 1854, 1877, 1880, 1898
	Elmore vacuum oil process
	Eureka rubbers
	slime tables at Mill 177 1893
	Farrel Blake breakers, table of
	Ferraris ball mill
	classifiers
	fixed screens
	flotation vats at Mill 129
	Forster breakers
	Forster breakers 28 Frayer centrifugal pump at Mill 159 1829 Frenier spiral sand pump 871 Frisbee Lucop mills 207 100 June 100 June 101 June 101 June
	Frisbee Lucop mills
	1755, 1880
	Gates and McCully breakers
	Gates and McCully breakers. 45 ball mills, table of 1301 Gates breaker on "choke crushing" 48 breakers 38, 46
	breakers 188 1881 1708 1710 1797 1798 1853
	breaker with short head and concaves, table of 1209
	breakers 38, 46 at mills 1035, 1061, 1706, 1710, 1727, 1728, 1853 breaker with short head and concaves, table of 1209 style "K" breaker, table of 1208 Gebrüder Sulzer centrifugal pumps at Mill 118 1078
	German sweeping tables
	G. G. Gates classifier
	German sweeping tables 703 Geyer slime settlers 400 G. G. Gates classitier 418 Gilpin county bumping tables 681 Golden Gate tables 681 Gould centrifugal pump at Mill 139 1757 regulty slamms 148
	Gould centrifugal pump at Mill 139 1757 gravity stamps 148
	gravity stamps 148 Griffin centrifugal stamp mills 209 mills at Mill 105 1836
	mills at Mill 105
	grinding pans at Mill 105
	Gröndal magnetic separators
	Hallett table
	at Mill 127 1710
	on Montana copper ores
	hand jigs
	10/0, 10/9
	Hathaway gyratory breakers, table of 1217 Heberli magnetic separators
	Heberli magnetic separators 790 mills 257, 259 wet magnetic separators 810
	Heberwasche
	Heberwasche 520 Hendy concentrators 083 Hochstedt apparatus 817 Hodge and Cleaves sand pumps at Mill 182 1916
	13/11
	jigs at Mill 1801902, 1903, 1004, 1905 Hooper air jigs 822
	vanning jigs 505 Huntington mills 280, 281
	Hooper air ligs 1902, 1903, 1904, 1808 1809 1809 1808 1809
	WILL VERIOUS SCREENS
	Husband pneumatic stamps
	International magnetic separator
	Jeffrey swing hammer pulverizers, table of 1322
	affecting number of sieves
	International magnetic separator 1535 James slimer 1402 Jeffrey swing hammer pulverizers, table of 1322 Jigs 507, 598, 597, 599 affecting number of sleves 589 at mills 1085, 1686, 1692, 1693, 1694, 1707, 1708,
	Tohnston vanners 1502
	at Mill 117. 1660 Kennedy gyratory breakers, table of 1214 Vent and the 1304
	Excit fonce mina
	Knowles duplex vacuum pumps at Mill 117. 1673
	King screens 1367 Knowles duplex vacuum pumps at Mill 117. 1673 New Century magnetic separators, table of 1542 triplex pump at Mill 114 1674
۱7	

- 18-2 - 0-0, 000, 21		1 agos 011 1101, 101, 111
Capacities of Krause pneumatic stamps	141	Canacities of Scoby complex at Mill 179 1990
Krom air jigs	824	Capacities of Scoby sampler at Mill 173
Krom air jigs Krupp gyratory breakers, table of laboratory Wilfley tables	1215	Scraping conveyor at Mill 114 1662
laboratory Wilfley tables	1991	settlers
		settling tanks
Langley's dry crushers	1510	shaking feeders at Mill 124
Langley's dry crushers La Point flour gold separators, table of Latta and Martin pumps at Mill 144 launders 875 Linkenbach pointed boxes 412 V.box classifiers 412	1770	Screens 240 24F
launders	878	Sherman re-grinders at Mill 122 1799 1790
Linkenbach pointed boxes	441	Siemens and Halske magnetic separators 799
Unkenbach pointed boxes 412 V-box classifiers log washers 321, Macquisten tubes 321, magnetic separators at Monteponi Przibram Mathey roasting furnaces at Mill 148 May Brothers' jigs at mills 1714, McCully breakers	421	Siemens and Halske magnetic separators. 709 separators 804 simple steam stamps at Mill 182 1909, 1912 slime tables 697 sluices 723 Spitakasten at Mill 173 1878, 1879 stamps 174, 221, 1014 at mills 1602, 1621, 1624, 1632, 1640, 1661, 1668, 1667 in California 1077, 1709, 1915 increasing the 2012 on different size of feed 2012 steam hammer 12
log washers	324	simple steam stamps at Mill 182 1909, 1912
magnetic senerators at Manageria	1565	slime tables
Przibram	810	sluices
Mathey roasting furnaces at Mill 148	1793	stamps 174 001 1014
May Brothers' jigs at mills1714.	1720	at mills, 1620 1621 1624 1632 1640 1661 1669
McCully breakers	44	1677, 1769, 1915
at Mill 139	1749	in California
mmatawa husakawa tahila af	$\frac{1212}{1212}$	increasing the
Meinecke spitalutten	495	on different size of feed
men in cobbing	480	steam stamps 198 190 199 1004
gylatory breakers, table of Meinecke spitzlutten men in cobbing spalling mill bins mills in receive xxy,	11	on ore of Mill 48, table of
mill bins	842	Stedman disintegrators
in receive	1100	Stein, Bilharz, and Luhrig tables 670
in reserve See Individual Mills in Chapter XX.	1109	Stroud mills, tables of
		sturtevant, Dodge type, breakers, table of 1205
Main Centritical number Mill 130	1757	fan at Mill 105
THUMORU & MOOGIE Gry senarators	818	on different size of feed 2012 steam hammer 12 steam stamps 126, 130, 133, 1004 on ore of Mill 48, table of 130, 133, 1004 Stedman disintegrators 286 Stein, Bilharz, and Luhrig tables 670 Stroud mills, tables of 1320, 1321 Sturtevant, Dodge type, breakers, table of 1205 emery mill at Mill 186 1637 mills 288 roll jaw breakers 38 rolary breakers at Mill 186. 1917 Sutton, Steele & Steele dry table 1555 pneumatic separators at Mill 151 1803 Tamarack classifiers 307, 308 Traylor centrifugal pumps 1588 at Mill 14 1602 jigs at Mill 190 1864 Trego roasting furnace 1648 Tremain steam stamp 138 trommels 1563, 1682, 1690, 1691, 1692, 1693, 1742, 1743, 1749, 1750, 1751, 1752, 1771, 1772, 1773, 1774, 1776, 1876, 1877 trough washers 1319
Narod pulverizers	282	roll jaw breakers
SCTEENS	1251	rotary breakers at Mill 186
New Humboldt concentrator	1494	preumetic concretere at Mill 151
New Standard concentrator	1479	Tamarack classifiers 207 200
Nissen stamps at Mill 165	264	Traylor centrifugal pumps 1588
steam stampe	1897	at Mill 114
steeple compound steam stamp at mile 16	997	jigs at Mill 160 1864
New Humboldt concentrator New Standard concentrator Nissen stamps at Mill 165. 1 Nordberg stamp at Mill 179 1 Steam stamps steeple compound steam stamp at mills 1895, 1 Overstrom tables at mills 1711, 1	901	Tremain steem starrage
Overstrom tables at mills	730	trommels
Overstrom tables at mills 1895, 1 Oxland furnace at Mill 137 1711, 1 Page-Happabers dynamics 1711	549	at mills. 1681, 1682, 1690, 1691, 1692, 1693, 1742
Parsons & Fisher jigs		1743, 1749, 1750, 1751, 1752, 1771, 1772, 1773,
tables	aaa	trough washers
Payne magnetic separators Perserverance furnaces at Mill 105. 1	800	trough washers 310 tube mills 1291 at mills 11632, 1770, 1922 Tustin's mill 262 Ullrich magnetic separator 1535 vanners 648, 058, 659, 662, 1110 and slime tables compared 091 at mills 1087, 1778 washing pans 333 wash trommels 330, 332
Perserverance furnaces at Mill 105. 1 Phoenix atmospheric stamps Pierce amalgamator I. Pilling air hoists, table of 1 pulp thickeners at Mill 173 1 pulverizers 232, pumps 232, pumps 232, rectangular buddles revolving knife buddles Riblet aerial tramway at Mill 124 14 Richards' annular classifiers	637	at mills
Pierce amalgamator	141	Tustin's mill
Pilling air hoists, table of	600 917	Ullrich magnetic separator
pulp thickeners at Mill 173	880	vanners
pulverizers232,	326	at mills
rectangular hyddles	872	washing pans
revolving knife buddles	707	washing pans 333 wash trommels 330, 332 Wengler & Lowe's classifier 413 Wenstrom magnetic separator 801, 802 Wetherill magnetic separators 805, 807, 808, 1522
Riblet aerial tramway at Mill 124	829 806	Wengler & Lowe's classifier 413
Richards' annular classifiers	406	Westrom magnetic separator801, 802
Riblet aerial tramway at Mill 124 Richards' annular classifiers 17 Coggin classifiers 302, at Mill 127 1878 1878, 18 1878, 18 1878 1878, 18 1878 1	710	Wetherm magnetic separators 805, 807, 808, 1522,
-Coggin classiners	393	
hydraulic classifier at Mill 150 1878, 18	379	Whelpley & Storer pulverizer
pulsator classifier, table of	200	Wild roller mills, table of
jig, table of	155	willey roasting furnace
vortex classifiers at mills1692, 1693, 1694, 17	74,	slimer
		table
rigid rolls at Mill 181	(27	at mills. 1633, 1661, 1662, 1669, 1687, 1604
Richardson automatic scales at Mill 132. 17 rigid rolls at Mill 181 19 Rittinger Spitskasten 4 tables 6 roasting furnace at Mill 138 17 Robins belt conveyors at mills 1636, 1750, 18 conveying and picking belts at Mill 132 17 rock emery mills 17	140 140	-Rowand magnetic separators at Mill 141. 1763 Whelpley & Storer pulverizer 289 Wild roller mills, table of 1304 Wilfiey roasting furnace 1548 at Mill 140 1759 slimer 1505, 1506 table 074, 675, 1469 at mills 1633, 1061, 1662, 1669, 1687, 1694, 1695, 1715, 1729, 1744, 1745, 1776, 1777, 1795, 1829, 1830, 1880, 1894, 1904, 1908 Woodbury-Benedict jigs at Mill 177 1892, 1893 Woodbury jig compared with that of Collom and Evans jigs 1448
tables	368	Woodbury-Repediat item at 1880, 1894, 1904, 1908
Robins belt conveyors at will 138	47	Woodbury iig compared with that is Cally, 1893
conveying and picking helts at Mill 129	376	Woodbury jig compared with that of Collom and Evans jigs
rock emery mills	55	tables
rolls	26	Worthington pentificani 1669
1751 1771 1773 1774 1707 1703 1709 1709	50,	pump at Mill 175
1977 10)4, '70	on the Rand, by addition of tube mills is
diagram of	28	large increase of
rotary driers at Mill 186	17	
diagram of 127, 18 rotary driers at Mill 186 12 rotary driers at Mill 186 19 round tables at mills 1904, 1905, 19 runs 1908, 1	08	
Samson breakers, table of 12: sand wheels 865, 8 at mills 1668, 1669, 18: formula for 18:	48	See also each machine. Capacity, effect on cost
sand wheels	oo AA	Cape Colony, tin mining in. H. D. Griffiths
at mills	94	Capelton Canada mili at 905
Sautter magnetic consenters	86	Capital Mining and Co
Schmidt spiral screens	ษอ	Caps in amalgamating pan
Schranz jigs	63 03	Captain Harris atmospheric at 1
Schranz jigs	76	John Richards discharge 583 Carat
, _	18	Carat
	10	*



Pages 1199-1610, Vol. III.	IND	EX.	Pages 1611-2052	, Vol. IV.
Carbon added to roast at Mill 137	1544 822	Center discharge for	inkenbach slime table jigs ats of sating pans mill ar Mines Company e Apostles	582
tin dressing in Cornwall Card concentrator	2023 632	mine	nill	1719, 1735
Care of belts journals mercury	1093 1097 785	dust collector separator force in drum magn	ets	883 828 1611 798, 799
Carey mill, bibliography for pulverizing mill Caribou rifle for black sands. F. Powell Carinthia, mill in	1509 2027 1185	Hendy conc Huntington Narod pulve sand wheels	entrator mill rizer	683 278 282
Carkeek classifier James, classifier hydraulic classifier jig beds slope of launders 874	3, 477 595 , 875	separation by use made of in hydro-extractor i machine for sepa	i mills or oil process trating oil from concentr n oil process	827 890 832 ates in
Carlisle stamp mill Carnall wash trommel Carn Dochan mill, dry concentration at mine, dry separation at. Carpenter shop for mill	834 838 820	pumps	, 1694, 1695, 1696, 1711 1850, 1880, 1881, 1890,	, 1712, 1721, 1899, 1904, 1905
Carpenter shop for mill	298 285	sand and we rolls	ter, used for elevating mi	ll pulp 870 74 1237 1588
Carr, M., Carr disintegrator T., Carr disintegrator for flour Carrick, J. T. Carrier for conveyor belt, self-oiling. Carroll, Montana, mill at Carrying conveyors	984 1585	pumps separation separator a dry. T. He	nrofte	1588 839 827 2025
current in Jigs power of water current Cars for concentrates weighing of	477 843 1112 1160	Centripact screens at Mill 109	ield ation on the. L. Kleritz imps	1868 1860 1865
Carter auto-magnetic separator F. L., amalgam in the Transvaal Carterville Foundry & Machine Works, The. Blake breaker. life of wearing parts	789 1201 1223	Cerargyrite, concentra specific gravity of Cerium, atomic weigh	ution of f ot of mill at ra, Mexico	1016 1189 1188
Casapalca, Peru, mill at Case laboratory breaker of the Denver Fire Clay Company Casings for elevators, etc Cassiles Mine, Australia, milling at the. F. B.	1223 1204 1099	Chabazite, specific gra Chabazite, specific gra Chain and sprocket magnetic separat	vity of	1189 1189 1096 811
Stepnens Cassiterite, hindered-settling test on	6,469 1189 698	Chain plate conveyor scraper for remo Chalcocite, hindered-settling velocity of	Nevada picking on val of jig tailings settling test on	489 588 617 466, 469
Cast gears Cast-iron head center for Gates gyratory breakers mortar blocks specific gravity of Castor oil	1220 148 1189 1097	Chalcopyrite, crushin free settling velo- separation from sizing test on	f g by rolls juartz	62 471 720 99
Cataract sand pump Catermole flotation process the minerals separation process Catherine (Australia) mill, wear of shoes and dies in Caucasus Copper Company, Limited	1555 1560	Chalk used in retorts Challenge feed clutch feeder	f	781 657 1578 1883
Caustic potash, use of on amalgamating plates in California	1619 1148	Chalmers and Willian at Mill 12 Huntington Kennedy gy	ns Frue vanners	
Cave Springs, Georgia, manganese ore from Cazin, F., advantages of water over air. Cazin's jig. F. M. F., Cazin's circular jig theory of settling	809 838 641 640 476	power amale rolls at Mill vanners at M Chalmers, estimate of	am squeezer	1519 1868 1687 on the
Cazin's circular jig	640 2, 643 1189 689 211	Chalon, P. F., crushi stamps Chamber mill	Hatch, gold stamp mills	1178 316 227 294
gravel mill stamped grinders grinding screening of surface for slime tables	211	Chamois leather used skin for dressing squeezing a	on amalgamated plates plates nalgam y. Copper handbook	752 759
surface for same tables,	695		y. Copper handbook .	1925

Classifiers, Lake Superior, hog trough, products of in	Clausthal, power at
Mill 46 201	pointed boxes used at
1	
launders for 440 Linkenbach pointed boxes 412, 416 V-box 421	removal of slimes by classifiers at
Linkenbach pointed boxes	rolls at 109
V-box 421	screening at
Lockhart's automatic gem separator 430	sieve scale at
tubular 476	sizes of ore hand picked at 487
Meinecke 430	
spitzlutte. 425 Merrill cylindrical clarifying tank 1406	slope of jig sieves at 548 stamps at
Merrill cylindrical clarifying tank 1406	stroke of jigs at
hadaarlia alamifaan 1907	
hydraulic classifiers	trommels at
large cones	truing rolls at 110
at Mill 106	unwatering sieve at
small cone at Mill 106	Clay and kaolin washing, capacity of Stedman disin-
New Standard	tegrator for
perforated board in	
pointed box, in the mills	crucibles for melting
pointed box, in the minis	crushed in rolls
position of	crushing machine for
principles of action	description of a breaker used for
products, sizing tests on	effect on mercury. 751
position of 1108	elimination of
purposes of 1367 quality of work of 461 Ramsey sludge tank 446	ground by edge runner mills
quality of work of	moved by water
Ramsey sludge tank 446	moved by water 878 preparation of G. Benfey 2020
results of	preparation of G. Benney
Richards' annular vortex	quartz, weight of
	removal of impurities from. F. Lehman 2026
-Coggin or Calumet	setting of 1149
pulsator	rate of
shallow-pocket401	used in retorts
tubular	washing 333, 1075, 1173, 1178, 1183, 1185, 1186
Rittinger pointed boxes	C. F. Binns 2025
Robinson coal washer 478	C. F. Binns 2025 Dümmler 2030
Schöne tubular	D D:
screen for	H. Ries
	J. W. Schamberger 2030
settling tanks	in Ohio. A. M. Fish
Sherman system of settling tanks 1404	in Ohio. A. M. Fish 2026 weight of
sizing tests on	Clayer ores on vanners
slope of sides	Clayton, I. E., on amalgamated plates
spigots for 433	Cleaned-ore plane
spilzlutte 421	Cleaned-ore plane
strainer for 388	Cleaning amalgam 790
suited for testing	amalgamating plates 757
surface-current box	at Mil 100
in the mills	Mill 101
Swain 1420	C-1'f
Swain	Cleaning amalgam 780 30 30 30 30 30 30 30
testing of	jig 894 concentrates 587 screens at Mill 148 1792 sieve 576 machines for concentrates 320 method for rolls 2011 of copper plate before amalgamating 752 plane, definition bf. 1465 on vanners 646 up dredge products 1018
Thisian	concentrates
Thirion	screens at Mill 148 1792
trough or shallow-pocket 389 tubular 421	sieve
tubular	machines for concentrates 320
classifier, spitslutte	method for rolls
for hindered-settling tests	of copper plate before amalgamating 752
investigating free settling	plane, definition of 1465
unwatering boxes	on vanners GAB
used for mercury trap 774	up dredge products
use of hydraulic water	mercury from
U-shaped iron pipe	mercury traps
U-shaped iron pipe	sands from roller mills. H. S. Kenney 2017
in the mills	Clean-up apparatus 1020 barrel 234, 264
versus screens	Darret
vortex	at Muli 111 1656
vortex	at Mill 111 25*, 204 bibliography for 294
Wangles & Lowers	
Wengler & Lowe's	details of in mills
whole-current box	devices 1510
Wunderlich coal washer	of gravity stamps
Yeatman	mercury traps
Classifying by free settling in water, bibliography for	riffles
laws of	stamps in mechanical batea
laws of	Steam stamps
Claudet, A. C. 1182 gold stamp mills at Mesquital, Mexico 1182	pans
gold stamp mills at Mesquital, Mexico 1182	and hamala
	and barrels 202
central ore dressing plant at	bibliography for
central ore dressing plant at 2039 classifiers at 476, 477 concentrating plant 1795	tables of details of in mills
concentrating plant	room
	trolley for a gold mill
details of stamps at	See individual Gold Mills in Chapter XX.
finest size jigged at 606 hand picking at 492	Clearance in steam stamp cylinder
nand picking at	OI gravity stamps
maprovements at	jig plunger
improvements at 1924 jig discharge at 582	Cleats, cast rubber riffle cleats for Rortlatt Simpler
feeder at 549 mechanism at 530	CONCENTRALORS
mechanism at	copper riffle cleats for concentrating tables 1481
SDIROL AL	
jigs at	for Deister concentrators
iigs at	height of riffle closes for Wildow to be
	neight of rime clears for Williey table 1468
mill at 965, 1086, 1102, 1116, 1121, 1174, 1177, 1100	rime for Williey tables 1467
mill at965, 1086, 1102, 1116, 1121, 1174, 1177, 1186 sieve scale at	Overstrom tables 1488 height of riffle cleats for Wilfley table 1408 riffle for Wilfley tables 1407 "tacking on" versus "grooving" 1408 Cleavage, effect of in minerals 3
picking at	Cleavage, effect of in minerals
picking at	Clemens Jones
plunger rous of jigs at	Clerc, G., history of stamps

	Pages 1199-1610, Vol. III.	INDEX.	Pages 1611-2052, Vol. IV.
	Clerc, G., methods of jigging, separation		vashing, discussion of H. L. Siordet
		1798 viii	in a Belgium colliery
	Clifford, H. E. Clinochlore, specific gravity of Clinometer. Clinton fossil ores treated on Wetherill magnetic sep-	1189 1159	W. R. Crane 2051 America. G. W. Harris. 2050 Belgium. E. Discry 2052
	Clitters mines, treatment at the	2041	Colorado, anthracite. R. M. Hosea 2050 bituminous
	Clogging of screens Close sizing for jigging Cloth for dust prevention	373 606 1099	rapide of 2050
	compared with punched plate	170 171	Indiana. G. H. Ashley
× *	details of from the mills	170 788 209	machines, control of. P. Charvet
	double discharge at mercury wells at shoes and dies at	768 183	preliminary investigation of. L. A. Harding 2051 principles of
Ÿ.	Stamps at	1180	results of
	Clutches for gravity stamps	114/ 60	e concentrates on jigs, defined
	Coal. See also Fuel.	2051 li	ine ore, treatment of
	as fuel in Wilfley roasting furnace breaker, a new. W. S. Ayres at Alden, Pennsylvania. M. S. Hochita Bankhead, Alberta. L. Stockett.and B. R.	9063	st size treated by jigs
	Bankhead, Alberta, L. Stockett.and B. R. Warden Stockett, Montana. L. Stockett.	2050 at 2049 cc	amalgam
.7	Stockett, Montana. L. Stockettbriquetting system burned in mills. See Individual Mills in Chap-	2049 cc 2050 sr	ecific gravity of
· .	reasting for magnetism	815 at	Mill 186
100	capacity for, of Stedman disintegrator	820 fo	r asbestos
	classifier combined disintegrator and screen for. M. A. Sattiaux	2018 h	at Mill 186
	consumed in reasting for magnetism	814 m , 882 284	agnets 1531 at Mill 138 1742, 1806, 1807, 1818 Bilharz 1532
	crushing of dressing, changes in anthracite jigs. R. A. Henry	2052	Cranberry
34	jigs. R. A. Henry. dust, air blast for removal of	839 2050 2052	Engineerd 1532
	removed by air blast	837 817 pl 2051 Coche	Manhattan Aslestos Company magnet 1531 (Wethey) at Mill 104 1849, 1850 ant at Mill 158 1821 50, settling tank at 459 60, settling tank at 459
	from handling machinery for C. Piez in Pennsylvania, breaking of anthracite. jigs . 520, 523, 548, 549, 574, 588, 639, 640, 641 magnetic treatment of E. Post method of separating dust from mine to develop electric power	2052 Cochit	I. New Mexico, gold mining at. W. C. Wynkoon, 2036
. 4	magnetic treatment of E. Post	2052 2050	matting for tables 702 on dredges 722, 1007, 1008, 1012 tables at Mill 111 1055 efficiency of 1657
	mining in India chean FL M. Cadell	2050 Codms	efficiency of
	picking in Cainsdorf preparation machinery. R. V. Morris Ramsey sludge tank for required per horse-power hour at Mill 172	2050 A. 446	Locke
	required per horse-power hour at Mill 172 screening	1874 365 2052	hammers used
sel I	by the by-pass system	2050	mill in 1183 milling at 2045 milling practice in the. J. R. Finlay 2037 mining. J. R. Finlay 1922
7, 5e	S. A. Everett. papers on. plant of the Clifton colliery, a new. 3000 tons capacity	2050 2018 Coffee 2051 Coggis	mining. J. R. Finlay 1922 mill 255 i, F. G., Ball and Leavitt stamps 142 vans and Linkenbuch slime tables 728
	3000 tons capacity	2052 E 342 or	a area of discharge of steam stamps 129
4	separation of dust from. A. Wiedl	490	efficiency of steam stamps
(0)	used in roasting for magnetism washeries, anthracite. G. W. Harris2049.	815 st 2050 Cohesi	eam stamps
No.	different Pennsylvania, bituminous. W. G. Wilkins washery at St. Beram. M. Benotte	2050 Conn'	s ball mill
	washing	2050 Coke	for heating
	advances made in. an article on. S. Diescher, Sr. and screening. T. H. Aldridge at Saint Eloy collery.	2049 Cole,	sed in reasting for magnetism
	the Baum colliery	2050 Cole's	breaker
X	Cadeby colliery Reynolds culm bank. A. D. W. Smith bibliography. S. S. Wyer bituminous. G. R. Delamater	2050 2049 Collect	grit
	and the second s	23	,
	· •		
A Star	A STATE ALL		
	And the Market Market and the Market		Control of the Contro

Pages 1-643, Vol. I.	ORE DR	ESSING.	Pages 644-1197, Vol. II.
Collins, A. L., amalgam	789	Combination of	principles of separation891, 1611
		pan	malromation 249
metallurgy of lead and silver	xix	silver mills	41 57-60 2000
cause of hard amalgam H. F., Clarkson sampler metallurgy of lead and silver J. H., definition of slimes Colloids, effect of heat on Collom, Evans, and Woodbury jigs, capacities pared	.1397, 1419	adjustmen	1103
Collom, Evans, and Woodbury jigs, capacities	com-	amount o	to to weat 43 tetails of 41 tons of 44
ijg	. 1440, 1446	dimens	ions of
advantages of		buddles, 1	ercussion tables, vanners, sume
height of tailboardhydraulic water in	551 537	tables	jigs
12f f	604	Clarkson-St	anfield, Mumford & Moodie, Pape- g separator
mechanism on grizzly modifications of size of sieve and plunger		grizzlies, ric	ldles, and trommels 385
size of sieve and plungerslope of sieves in	529 548	hand pickin	ag and picking tables
SDEED OF		Richards-Co	oggin classifier, Büttgenlach's boxes, Bilharz, Rittinger, spitalutte
sampler versus Harz jig	515	Osterspey	sipnon separator used at Mecher-
sampler versus Harz jig Colombia, S. America, milling in. Juan de Posada quartz milling in. F. F. Sharpless Colorado, concentration of zinc ores in.	la C.	Schranz bre	478 aker 60
quartz milling in. F. F. Sharpless	2038	separation	
concentrator, cost of crushing by rolls		slope of jig	sieves
cost of milling in	. 1129, 1133	Commercial limi	sieves 548 rs 594 t of concentration 1118
producing gold in	1965	Comminuting	8
dredging in general milling practice in Gilpin County Iron Works Akens and Evans slimer	1000	Mining and M	mill, Pearce, Arizona, milling at the 2044 illing Co., ball mill 261
Iron Works	1407	Minera del	uanchaca de Bolivia, stamp frames 160 Tiro General
		Comparative siz	ing test of failings and concentrates and Lane Chili mill
breakers at Mill 144	1771	tests of spin	dle and jaw-breakers 53
Challenge-type feedercontinuous grinding pans	1323	wear of met	als for jaw plates of Blake breakers 48
continuous grinding pans Dodge breaker double-cone hydraulic classifier	1381	Work of gra Comparison beta	vity stamps and Huntington mills 1262 ween single-cylinder and compound
grinding pan, continuous Humphrey rolls	1282	steam stamps.	d Dodge type of breakers
impact screen at Mill 151	1351	California	and Colorado systems of stamp
octagonal trommel	1360	canvas an	d rubber vanner belts
on rolls	1609	capacities	of Woodbury, Evans, and Collom
power for rolls	07	concentra	tion and amalgamation 1047 ad concave buddles 706
rolls	1691, 1749	slime	tables
roll springs	74	flat and s	nachines
single cone classifier ofslime tanks	477	Gates and	McCully breakers 45
and classifiersvanner	1419	Harz and	Collom Jigs 515
jig connecting rod in	530	jigs and t	ables 606
mill in	1177		
mill, number and height of drop of stamps	214	weari methods c	ng parts for breakers
practice in different camps	ee 2035	mine and	mill work
Smelting and Mining Company mill Huntington mill in	xxvi, 978	plain copy	bles
Stamps versus California and steam	134	pulverizer punched r	10 10 10 10 10 10 10 10
system of stamp milling	224, 227	riffle table	s
zine Company	1708	rolls and	Sturtevant mills
Color affecting separation	3	Bampang	e and slotted screens
of minerals in artificial light	410	screens	and end-bump tables
vanners in	658 749	side-shake	and end-shake vanners 655
pulsating screen	343	smooth an	double discharge for stamps 209 d corrugated vanner belts 650 eakers 46
separator, Jeffrey Columbite, specific gravity of Columbium, atomic weight of	1189	spindle br	gravity stamps
Combination cone and norizontal ball mill	2017	trommels and ride	
crushing, amalgamating, and cyanide mad M. Dekeyser	chine.	Utah Cop	gravity stamps
		water used	th convex slime tables
L. Bosqui	2045	Compensating w	plate screens
of the Goldfield Consolidated Mines	Brins- 2042		16K1 1669
pany	1828	in Color	mills at Lake Superior 990 ado and Utah 925 and Europe 936
mills	1060, 1101	Monta	and Editore 988
	24	ŧ	

Pages 1199–1610, Vol. III.	INDI	EX.	Pages 1611-208	52, Vol.	IV.
Complex jigging mills in southeastern Missouri	916	Concentrators, Ferraris	table		1490
for blende or pyrite	906	for fine sand and slime	slimes, belt film-tabl	es	644 697
parison between	1254 57	bumping ta	bles		667
breaker edgestone mill	235	intermittent	surface tables		685 700
bibliography forengines	296 1091	riffles	***************************************		$\frac{726}{720}$
steam stamp at Mill 181	1906 1106	general comments	on rectilinear tables		1498
11g	519	Golden Gate			$680 \\ 681$
Compressive strength of stone	300 1404		••••••		$\frac{683}{820}$
classifier	1, 429 465	James slimer			1491
grain sizes for free-settling tests	4000	Johnston			652
grains	1383	Luhrig-Buss table Luhrig slimer	••••••		1492 1496
pocket vortex classifierssingle-spigot vortex classifier	1374	magnetic separator	'S		1521
tank vortex classifier	1380	New Humboldt			1493
work for crushing	$\frac{312}{357}$	New Standard Norbom			$\begin{array}{c} 1478 \\ 652 \end{array}$
Computing tests	1161	Pinder			1479
Comstock, amalgamating pans at lode, Nevada, mills on	, 1184	slimers			
mills, wear of amalgamating pans	249 230	Triumph Tulloch			$\begin{array}{c} 652 \\ 652 \end{array}$
stamp mills Concave buddle	706 692	vanners			1498
slime tables versus convex slime tables	692	table			1465
Concaves and short head, Gates breaker with for spindle breakers	1208 47	Concentric conical tron	mels at mills	1818.	1494 1854
Concentrate drying bins	1570 1669	cylindrical tromme	ls at mills	1655,	1793
Concentrated, list of ores that can be	2049	trommels	•••••••		313 362
Concentrates binscleaned by trunking machine	843 321	at Mill 154 Concheño mill		1815,	1816 1665
cleaning of	320 494	Concrete bins at mills.		756, 1834,	1858
drying of	880	mine, stamping of	ls ore from		220
moisture in	1107 586	mortar blocks C. D. Kaedin	· · · · · · · · · · · · · · · · · · ·		148 2013
percentage of, affecting capacity of jigs	601	settling tanks at M	ill 171 Lions. G. P. Scholl		1870
purity affecting extractionsampling of	845	Condensation of steam			1091
sizes of, in millsstoring and shipping	1116 1112	Condenser for retorts Conductors for electros	tatic separation, list	of good	781
tank for vanners	647 646	and poor			1550
alama of in vannaua	ara	Cone classifier	pan	'444'44	241
Concentration. See also Milling and Ore Dressing, advances in the art of. F. Cirkel	2048	bibliography for		.232, 255,	2017
amount ofby free settling	1118 475	pulleys for Bradfor	d jig	• • • • • • • • • • • • • • • • • • • •	501 533
compared with smelling	1	sampler			846
followed by lixiviation	2049	Cones, pyramids and pr	risms		1855 361
limit of	1118 1521	Conglomerate ore, mills	s for		990 1191
miii	1117	weight of	Ontario. R. Stokes		2046
molybdenite dressing of copper ore. F. H. Probert galena ore. F. H. Mason	1567 1997	Conical trommels	 1783, 1784, 1785, 18	3215555	361
galena ore. F. H. Mason	2046 815	at mills1714,	1783, 1784, 1785, 18	15, 1854,	1898, 1902
prigress in. V. Horel	2049 2049	tube mill, Harding Coning and quartering	e	• • • • • • • • • • • • • • • • • • • •	$\frac{1296}{1577}$
of ratio of. See Individual Mills in Chapter XX. relation of physical properties of minerals to	-0.0	sampling by			844
separation by crushing and screening	1566	Conkling dry magnetic			503
tendencies in	2048	Connecting rods for fig	8		640 530
versus amalgamation	1047	Conrey Placer Mining Consistency of pulp for	Co	and van-	2036
wet. C. Taylor works at Monteponi, Sardinia	1066	ners	And the		1848
Concentrators, air, using a continuous blast of air using force other than air blast	818	vanner feed at Milley table fee	d at Mill 173		1878 1878
amalgam traps for	1516	Consolidated Main Red	of, sand wheel at		1587 677
Bartsch rotary percussion tablebelt percussion table	1497	Virginia mill, cross	mett table ats sills in		153 153
Card	1481	Constant speed for ma Construction and opera	chines		1092
Charleton ore	1484	Aitken			2048
Deisterdepth of bed in644	1488 1510	expenses	4		1123 1887
different turns	2022	of jigs	* • • • • • • • • • • • • • • • • • • •		524
electrostatic separators Ellis	007	rolls		<i>.</i>	1088 63
Embrey	653 ₄		• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • •	684
	26	,			

Construction of stores will. T. T. D	0040	Conveyors Robins belt
Construction of stamp mills. J. J. Deming	2049	
J. Roskelly		
trommels	350	
on the Rand, mill	2049	screw
Consumption of cast-iron per ton rock crushed at	t	Cook, R. A., magnetic plant at Dannemora, Sweden. 1175
Mill 180	1902	Wenstrom separator at Dannemora mine, Sweden 833
coal in American Process Company's driers	1599	Cooley, G. T., dressing zinc ore in Missouri 1180
Argall drier	1600	jig
Edison drier	1800	number of sieves
Edison drier per horse-power in gas system at Mill 172	1974	shafts for
fuel in Willey reacting furness	15/0	tank
fuel in Wilfley roasting furnace	1550	
oil in Elmore vacuum oil process	1000	
pebbles by Abbé tube mills at Mill 101	1026	jigs for blende
Krupp tube mills at Mill 118	1677	Cooling ore from galena roaster
tube mills at Mill 103 steel by Bryan mills at Mill 173	1632	Cooper-Hewitt lamp
steel by Bryan mills at Mill 173	1879	Cooper, J. R., on amalgamated plates
		Copake Iron Works, wash trommel at 330
in shoes and dies at Mill 117	1668	Coppée coal washer
sulphuric acid by flotation process at Mill 130	1722	Copper, action of gravity stamps on
trommel screen steel at Mill 1731876	1877	amalgam
water at mills 1413, 1640, 1648, 1664, 1730	1721	amalgamated plates
water at mins1410, 1040, 1040, 1004, 1700	, 1/1/	
the Rand	1410	amalgamating plates, difficulties in use of 1515
Washington Arizona plant	1411	and silver-plated plates
by Ferraris patent tables, table of	1490	atomic weight of
Hancock jig	1441	boxes for jig products 586
working on Montana copper ores	1442	breaking in Mine 44 54
Johnston vanners	1502	clean-up of in stamp mills
suspended frame vanners	1503	comparison of breaking by hand and by machine 13
Wilfley slimer	1506	concentrated by free settling
Continuity of running, effect on costs	1127	
Continuous grinding pan, Colorado Iron Works	1282	cost of producing
none pane pan, Colorado Hon Works	1202	44
panskieve	727	44
kieve	141	for jig screens
movable sieve power jigs	499	riffle cleats on concentrating tables1481, 1486
movable sieve power jigs	248	screens
surface found tables	1000	handbook, Lake Superior copper mines 1925
tables	686	hindered-settling tests on
fixed, circular, convex slime tables	689	in tailings of Mill 48
revolving, circular, concave slime tables	692	in tailings of Mill 48
versus intermittent action on breakers	55	crushing
Convex and concave rolls	111	mills
huddle		
buddle	1916	
clime tables	1010	native, specific gravity of
slime tables		ore, hand picked
comparison with vanners	691	leaching
versus concave slime tables	092	method for treating low grade. N. S. Keith 2039
Conveying and draining belt at Mill 130	1720	mill for 893, 904, 905, 915, 958, 901, 965, 973, 984,
picking belt at Mill 139	1749	990, 1005, 1022
belts	1585	separated by oil
at mills. 1585, 1631, 1667, 1670, 1681, 1706, 1709, 1771, 1772, 1805, 1806, 1807, 1808, 1810, 1811, 1812, 1813, 1819, 1831, 1859, 1831, 1859, 1852, 1861, 1862, 1863, 1882,	1708.	screening 830
1709, 1771, 1772, 1805, 1806, 1807, 1808	1809	screening
1810, 1811, 1812, 1813, 1819, 1831, 1859,	1860	stamps suited for
1861 1862 1863 1882	1883	treated at Moonta mines, Australia 505
New Kleinfontein Company plant	1505	treated at Moonta mines, Australia 505
on magnetic separators	1000	by Collom jigs 515 in Mills 44, 46, 47, 48 486 percentage of in tailings of Mill 46 131
on magnetic separators Conveyor, Aultman coal.	804	in Mills 44, 46, 47, 48
b-lts language coat.	2031	percentage of in tailings of Mill 46
belts, layer of coarse ore to protect belt at Mill	1000	picking or
158	1826	plate, annealing of 747
cold ore to protect belt	1807	preparation of
Leviathan	1585	screens 174
method of cleaning	2031	plates
of Wetherill magnetic separator, proper speeds		absorption of amalgam by
for	1523	preparation of
portable at Mill 167	1857	stains on
self-oiling carrier for	1585	precipitated by scrap iron
for portable at Mill 167 self-oiling carrier for tripper at Mill 124	1691	pure, specific gravity of
for discharging	1586	pure, specific gravity of
use of with Blaisdell excavator at Mill 117	1670	will tons the tons and the tons tons
notes on a 75-foot	2031	mill
Conveyors	1500	Milg. Co., rock nouses, Michigan 2045
Conveyors	1002	removal of
of Mil 198	1705	results of tubular classifier tests on 613
at Mill 135	1/39	rime clears for Deister concentrators 1488
bibliography for	884	rock, cost of crushing at Atlantic mill 51
bucket Caldwell helicoid conveyor	800	centebing by wells 40
Caldwell nellcold conveyor	1582	stamped at Phoenix Mine
carrying conveyors	1585	settling velocity of
ciassincation of	1582	silver in 766
different types of. W. R. Ingalls	1609	ores tested by Collom jigs in Mill 42
disc, at Mill 124	1695	specific gravity of
classification of different types of. W. R. Ingalls. disc, at Mill 124. drag or disc.	1583	versus silver-plated plates 749
		wire cloth for jig sieves at mills 1707 1700 1080
Edison distributing	861	wire cloth for jig sieves at mills 1707, 1708, 1869 Cordier, E., Vapart disintegrator 299 Core for magnets 794
endless belt	Q.6.1	Core for magnets
for ijg tailings	900	Core of magnets 794
for jig tailings handling concentrates at Mill 173	588	Cores of rolls
hoe	TOOT	Corliss engines 906, 958, 973, 982, 986, 987, 1057, 1091 Cornacchino Mine, Tuscany, mill at 1074
Kraice jayling	1500	
	1582	Cornacchino Mine, Tuscany, mill at
pon or ploto	1582 884	Corning, Frederick (i., Corning belt concentrator 729
pan or plate	1582 884 860	Corning, Frederick (i., Corning belt concentrator 729
pan or plate picking on	1582 884 860	table
Kreiss jerking pan or plate picking on push	1582 884 860	Corning, Frederick G., Corning belt concentrator 729

,		, , , , , , , , , , , , , , , , , , , ,
Cornish frames	704 Cos	t of direct smelting 1
jigs	506	dredge and equipment
pump	994	dredges 1013
rolls	9, 112	dredging
at mills	1808	drying
stamp mill for tin ores	230	dust chamber and fans
stamps tin concentration works, roasting for porosity at	829	electroplating
dressing. E. Walker	2038	erecting a complete decantation slime plant in
mills	1118	South Africa 1940
ore, crushed by Husband stamps	141	large Montana copper-sulphide mill 1939
practiceworks	704	roasting and magnetic separation plant . 1940 20-stamp mill. F. C. Roberts 2049
venning shovel	1152	20-stant 1111. 20-stant 2
vanning shovel	1506	mills 1124, 1618, 1731, 1770, 1875, 1939, 1940
cost of crushing by rolls in	104	filter pressing plant, Mill 108 1647
Elmore vacuum oil process in	1559	fine grinding. W. A. Caldecott 2015
jigging in kaolin washing in	1077	fuel for retory deien at Mill 198
kieves in	727	gold dredging
labyrinths in	448	gold dredging
milling in	1173	grinding at Mill 130
mills in	1185	by arrastra 238
rolls in	111	tube mills
runs in, on tin ore	228	hand jigging
stamps in system of tin dressing. C. M. Myricktin dressing in.	2044	jigs
tin dressing in	1081	galena
E. Skewes	2037	handling material by conveyor belts 1585
E. Walker	2038	ores by Blaisdell system
use of rag frames in	5 547	Heberli mill wear
Organia and and and and and and and and and an	254	jaw and spindle breakers
Corrugated belts for vanners	7, 650	jigging in Missouri 609
Frue vanners at mills	1870	jigs 604
Johnston vanners at Mill 167 1858,	1809	lig screens
versus smooth belts for vanners	650 1088	1941 1887 1941 1887 1941 1887 1941 1887 1941 1887 1941 1887 1941
rolls	2010	for breakers
at Mill 152	1806	Huntington mill
iron for mill buildings	1242	pan amalgamation
table of	107	stamps 206 in mills 1100
stamp screens	226	power, supplies, board, etc. See Individ-
description of Allis-Chaimers type table of sizes, capacities, and power stamp screens Corundum, broken by heating and quenching dressing	9	power, supplies, board, etc. See Individ- ual Mills in Chapter XX.
dressing	2030	lumber
mill of 1078 1070 1176	1184	machines
milling. H. E. T. Haultain	2025	of iron ore
in Canada. D. G. Kerr	2025	McDougall roasting furnaces 1546
ore, mill for	1184	mercury for stamps
specific gravity of washing	1198	mercury for stamps
pun for	335	in Colorado 1129
Cost accounts	1122	Missouri. 1129 Nova Scotia. W. L. Libbey 2049
and extraction	1939	Nova Scotia. W. L. Libbey 2049
bibliography for details of for breaking	50	South Africa
of blanket tables	703	various mills
blowing dust from cosl	817	various mills 1126 on the Rand. J. R. Williams 2049 mining 1120, 1940, 2048 and treatment at Cripple Creek, Colorado 1910
board at mills breaking	1100	mining
ore	1002	effect of attitude of orebody on
in Claten hunnleans	1222	economy and speed on
buckets for conveyor	861	external factors on
buckets for conveyor calcining at Mill 137 changing heads and concaves, Comet breaker.	1549	internal factors on 1942
changing heads and concaves, Comet breaker.	47	size of orebody on
chemicals for pan amalgamation	250 1002	mortar lining
coal	1917	oil for separation
concentrating lead gine ores. A. Hordestix	2049	operating 1940
concentration at Butte. C. W. Goodale copper refining at Mill 173 crushing .00,	2010	all-sliming filter-press system
at Buite. C. W. Goodale	2048 1991	Argall four-tube drier
crushing at will 170	1222	flotation processes
ar milig	1000	Minerals Separation Company, notation
by breakers Huntington mills	49	process
Huntington mills	1318	Pinder concentrators 1481 Trego roasting furnace 1548 with Cleveland-Knowles magnetic separators 1542
jaw breakers, table of	51	with Cleveland-Knowles magnetic separators 1542
volle	104	pan amalgamation
spindle breakers, table of stamps	50	plant for electroplating
stamps	205	power at Mill 105
for interest, taxes, insurance and depre- ciation	205	by gasoline engines
steam stamps	134	producing copper at mills 1894, 1956, 1957
and material	K1	general considerations with regard to 1958,
cyaniding	1028	1959, 1960
cyaniding at Mill 106 decantation slimes plant, Mill 108	1647	for stamps 205 producing copper at mills 1894, 1956, 1957 general considerations with regard to 1958, 1969 in Arizona districts 1958, 1954, 1955 Bisbee or Warren district 1954, 1955
accumulation sumes branch want roo	27	when an it is a second and a second a second and a second a second and
	41	

Pages 1611-2052, Vol. IV.

Pages 1199-1610, Vol. III.

Cost of producing copper in Clifton-Morenci dis-	Cotton cloth for filtering dust 883
trict1953, 1954	duck for tables
	Cottonseed oil
Lake Superior district 1948, 1949, 1950	Coupling of machines
Globe district	Cover for amalgamating pan
Mount Lyell, Tasmania1937, 1930	Cover jigs
Utah district	work of stamps, cleaning up 320
diamonds at Mill 188 1922	Covers for mortars
gold 1974	Cowenhoven Tunnel Co., rock house 485
at Douglas Island, Alaska 1975, 1976, 1977 in Black Hills district, South Dakota 1977, 1978	Coxe automatic slate picker 492
in Black Hills district, South Dakota 1977, 1978	gyrating screen
Cripple Creek district, Colorado 1974, 1975	Coxe, Eckley B., corrugated rolls for coal 110
El Oro district, Mexico1980, 1981	Coxe, Eckley B., corrugated rolls for coal 110 Coxe's finger bar grizzly and gyrating screen. 385 Luhrig coal jig at Drifton, Pa. 640
Grass Valley district, California 1977 Kolar district, India 1981, 1982, 1983 San Juan district, Colorado . 1978, 1979, 1980	Luhrig coal jig at Drifton, Pa
Con Tues district Coloredo 1078 1070 1080	Covheath ore crushed by rolls sixing test 90
Witnesterrand South Africa 1983, 1984.	Cox, William J., manager of Mill 100
Witwatersrand, South Africa 1983, 1984, 1985, 1986	Crab for gravity stamps
iron ore concentrates in eastern United	Cox, William J., manager of Mill 100. 1275 Crab for gravity stumps. 200 "Crack-proof" vanner belt, the 1503
States	Chang (20
lead and silver in Broken Hill district 1994, 1900	Craig coal washer. W. Scott
Cœur d'Alene district1960, 1961, 1962, 1963, 1964	washing machine. W. Scott
Colorado district 1905	magnet
Colorado district	at Mill 156
lead and zinc	magnetite ore, cost of concentrating 1135
in Missouri district1968, 1969, 1970, 1971,	mill for 1180
1972, 1973, 1974	tests on
lead, general considerations regarding 1974	mill
in Flat River district 1971	ore, magnetic separation of
tungsten ore concentrates in Boulder County, Colorado	separated by magnets
zinc in Joplin district	log washer at Mill 95
pumping at Mill 180 1906	Crank arm mechanism for jigs
with Latta & Martin pump 1590	Crawford mill 234
quarrying	bibliography of
refining at Mill 106 1643	Cream separator 827 Creede, Colorado, milling at. 1925
repairs on rolls	Creede, Colorado, milling at
vanners	milling at. A. Lakes
retreatment at Mill 130	Cremer, R., Baum and Sheppard jigs for coal 643
rock emery millstones	Carr disintegrator for coal
roll shells	coal screening
running breakers	Hochstedt apparatus
log washer 324	Cresson, George V., breaker of Blake type 23
screening	Co., rolls
for Bryan mills	wash trommel
jigs	Cripple Creek, Colorado, concentration at 2044
shoes and dies	cost of mining and treatment at
slime table	producing gold in
smelting versus chlorination	mill at
stamp cams	miling practice at
milling 2048	rock house
screens 173	Crocker's patent stamps
stem	Crocoite, specific gravity of
tappets	Crookes, Sir Wm., diamonds
steam power	the washing pan 2020 Cross compound steam stamps 1250
treatment at mills	mill, Colorado, gold and silver in amalgam in 762
treatment at mills	hydraulic classifier in
tube mill lining in New Zealand 2016	mercury trap at
vanner 691	wells in 709
belts	plates 741
for stamps 206	mine, Blake breaker at
wearing parts for stamps 206	sills for gravity stamps
of Blake breakers	Crossley pebble mill
Dodge breakers	Croton iron mines, cost at
Forster breaker	mill at
spindle breakers	ore concentrated by magnets
on Bryan mills	Crown dry concentrating system, description of 2026
Costs. See also each machine.	ore sizer 2020
at Mill 97	ore sizer. 2019 gold dry concentrating plant, Tintic, Utah 2044 mill, Georgia. H. V. Maxwell 2038
effect of altitude on 1941 climate on 1941	mill, Georgia. H. V. Maxwell
homogéneity of ore on 1049	romi, mm at 901
losses on	Reef Gold Mining Company, was of will of live
marketing the products on	Reef Gold Mining Company, use of milk of lime for slime settling at
population on 1941	mill, details of stamps 221
temperature on	
transportation on	Crucible for melting
general principles governing 1040	Crucible for melting 784 Crusher in a stamp mill, description of a fine 2014
high-grade versus low-grade mines 1948 on the Rand and in California 2048	Maric
on the Rand and in California 2048	MCLananan and Stone single-roll 1941
Cosumnes River, Cantornia, mili at 1023	sectional custioned
n	Q

20800 2200 2000, 1021 2221		
Crusher, Sturtevant	32	Current water wheels 1090
Crushers for testing		wheel dredges
Crushing. See Breaking.		Curtis, A. H., ball mills
Crushing and jigging department at Mill 146	8	Berdan's pan
and jigging department at Mill 146	1783	Blake, Gates, Comet, Dodge, Marsden breakers 59
screening, separation by	1566	Bryan mill 295
of molybdenite by	1558	Crawford mill
article on. L. H. Sturtevant	2009	crushing machines
Take Superior graded T. P. Channing	2000	Cyclone pulverizer 299 Cyclops mill 294
the Simmer and Jack mine	2010	Harvey's stamp, Hope's compound battery 227
bibliography for laws of	315	Howland pulverizer
choice of breaker for	54	Hunt'ngton mill vs. stamps
choke	98	Husband pneumatic stamps 143
by breakers	48	Krom's rolls 111
comparisons between wet and dry. F. Merrick	2018	Lamberton mill
concentrates	49	Leviathan pulverizer 299 Morel and Hall's mill 295
at Mill 162		Niagara crusher
by breakers	49	on breakers
gravity stamps	205	pneumatic pulverizer 299 Schranz mill 296
Huntington mills	1318	Schranz mill
jaw breakers, table	50	stamp mills, Krom rolls, Huntington mills 1182
rolls	104	Curve of cams
spindle breakers, table of	50 134	Curves of film sizing tests
steam stamps	65	jig work 632 settling velocities 467, 473 sizing tests 1139, 1144
department at mills	1771	sizing tests
dry. P. Argall	2010	stamp velocities
cylinders department at mills	1224	Cushman and Hubbard Prevost, decomposition of
extent desired	303	feldenare 1418
nnal	02	A. S., decomposition of the feldspars 1400
for cyanide, comparison between wet and dry free	98	effect of water on rock powders
graded by rolls	103	mills
graded by rolls in sampling	849	hins for 842
laws of	1325	plates in 748
machines, advance in	2018	sampler of Mill 102 1629
compareddiscussion of fine. R. Allen	$\frac{313}{2014}$	Cut gears 1096 Cutten, W. H., gold dredging in New Zealand 1179, 1184 Cutter, G. A., tests on strength of granite 302 H. C., testing plant at the University of Minnesota 1179
for cement	2014	Cutter G. A tests on strength of granite 302
kinds of	Я	H. C., testing plant at the University of Minnesota 1179
sizing tests of	315	Cutting down in sampling 849
means of computing efficiency. Pearce & Cal-		Cutting down in sampling
sizing tests of means of computing efficiency. Pearce & Caldecott mechanics of. C. De Kalb	2017	127, 128, 133
mechanics of. C. De Kalb	1340	Cyanide, amount used on plates
mernous or		
mill, description of a wet	2017	for cleaning mercury
middlings	1119	machinery
middlings. plant at Kalgoorlie, dry. H. J. Brooke	2035	of silver used for electroplating
mills	1882	of silver used for electroplating
ideas on a modern mie. I. Argan	2010	Robinson riffle in
power for. E. A. Hersam	1340	the Windsor in the West Rand
preliminary	1224	practice in S. Dakota. J. Gross
principle of roll crushingquality of, by rolls	50	process, rolls for
relative merits of wet and dry crushing. P. Danckwardt		slimes plant, Mill 106
P. Danckwardt	2018	slimes plant, Mill 106 1642 -treatment at Mill 117 1671
ribbons	101	tests
rolls	62	used on amalgamating plates751, 760 1619
rules for power used	309 103	C. Butters, E. Hamilton 2040
single stagetests of Gates and McCully breakers		Goldfield Nevada, M. R. Lamb
tabulated results of. J. B. Porter	2017	Goldfield, Nevada. M. R. Lamb
theory of. E. A. Hersam	2018	bibliography for 1173
· with stamps, coarse	2015	in New Zealand. J. Park 2024
work required for	3U4 1100	or gold and silver ores. Julian and Smart 1323
Cryottellization affecting separation	800 1109	Cyanita specific gravity of 1190
Crystallization affecting separation effect on mill scheme	1120	Cycle of gravity stamps
of stamp stems	188	Cyclone beater at Mill 186
of stamp stems	1190	the Homestake. C. W. Merrill 1419 bibliography for 1173 in New Zealand. J. Park 2024 of gold and silver ores. Julian and Smart 1323 with and without concentration 2047 Cyanite, specific gravity of 1189 Cycle of gravity stamps 216 Cyclone beater at Mill 186 1917, 1918 disintegrator and pulverizer 1319 dust collector at mills 1637, 1803, 1863 pulverizer 236, 288, 297, 817 bibliography for 298
measures, equivalents of	1187	dust collector at mills
Culm banks, methods of washing. B. T. Berthelot	2050	pulverizer
classifiers at Mill 134	1866	table of details of
Cummer drier	880	Cyclops mill
Cummer drier Cummings mill, bibliography for	292	bibliography for 294
ore granulating mill	200	Cylinder, Alsing
mill	232	crushing
Cumulative direct plot logarithmic plot	114U 1140	steam
plot of sizing tests	1144	Alsing Company, J. R. 1597
Cunnack's pulverizer	232	Cylindrical driers 880, 1596 Alsing Company, J. R., 1597 American Process Company 1597
bibliography for	293	Argall
bibliography for	1189	retorts
Currents in box classifiers	434	roasting furnaces at Mill 148
settling tanks	451 454	trommels 348 wash trommel 335
velocity of in settling tanks		
	29	9

Pages 1611-2052, Vol. IV.

Pages 1199-1610, Vol. III.

D	Dayton, Nevada, amalgamating pan	241
Daggett, E., on lixiviation	mill at Dead plate on trommels sea water, weight of	1184
Russell leaching process	Dead plate on trommels	300 1188
Dahlonega district light stamps	Deadwood, Terra mill, amalgam in	
mortars 148, 150 mortars 152	order of drop	215
Daily amalgam, gold and silver in		$\frac{2038}{1562}$
Dalhousie University, the ore dressing apparatus at	at Broken Hill De Beers Co., diamond dressing	831
the. F. H. Sexton	Consolidated mines	1080
hydraulic classifier	Consolidated mines Ltd.	1923
Daly-judge mill	Mining Company	$\frac{1922}{2045}$
Park City, Utah. 1923, 2038 P. A. Gow, A. M. Hobart, G. S. Kruger, F. H.	Deck cover lindeum for	1467
Parsons 2035		1504
	table	1467 1479
Daly-West mill. W. I. Spencer 2035		1846
Daly-West mill. W. I. Spencer 2035 Park City, Utah 1923, 2038, 2042 Mining Company 1726 slime plant, Park City, Utah 2042 Mining Company 2042	Decomposition of feldspars, A. S. Cushman and Pre-	
slime plant, Park City, Utah	vost Hubbard DeCourteney, H. W.	1418 225
		225
Dams for classifiers 406 Dana, E. S. 2, 3		1611
	and screening	839
minerals 11/0	at Mill 137	1741 829
system of mineralogy	of minerals	5
table of hardness 2 Dana's tube mill 2017	separation by use made of, in mills	1565
Daniela C III on cettling knolin	use made of, in mills	890 416
Dannemora, Sweden, magnetic concentration at	Deep double trough classifiers pocket hydraulic classifiers	409
separation of iron ore 801 mill at 1175	free settling classifiers	1371
Darlington, I., on breakers	hindered-settling classifier. Deetken, G. F., Atwood amalgamator, Eureka rubber	1387
TOILS	concentration in California stamp mills	789 1181
trommels	kieve	729
Dash pot for steam stamps	stamp battery Definition of free settling and hindered settling	229
of Nordberg steam stamp 1247	Definition of free settling and hindered settling	464 484
Data from the mills concerning settling tanks	of hindered settling Definitions for jigs	494
Datolite, specific gravity of	Deflection of wire rope	1005
Davey, Paxman and Company	Deflectors for spitzkasten	440 458
Davidsen, formula for calculating amount of pebbles	in settling tanks	742
for charging tube mill	with plates De Gournay and Suisse, Mathet, Hochstrate appara-	
speed of revolution of tube mills	fils	837 2022
tube mill	Deister concentrator	2023
Davies, D. C., Blake breaker	concentrators	1400
free-settling velocities 470	at mills	1900 2011
gravity stamps		
son spring stamp	amalgamation inside the mortardefinition of slimes	1398
hydraulic mining	De Kalb classifier discussion of conditions under which crushing	2020
Marsden breaker 56	is effected	1320
metalliferous minerals and mining xix movable sieve and Harz jigs	graphic records of screening tests	1340
E. H., amalgamation 787	mechanics of ore crushing on settling tank	1340
Blake-Marsden, Dodge, Gates breakers 56 breakers 56		
breakers	sizing test on sample grinder	25
concentrator	stamp mill practice	401
Clarkson-Stanfield process 837 Crickboom wash trommel 334	standardization of screens for testingtests on corundum	118
free-settling velocities, hydraulic classifier,	De Kalb's perforated-board classifier	140
notated boxes		
gravity stamps	Mill Delameter coal-testing device	199
grizzlies and trommels 384 Grüson ball mill 293	mill	169
Huntington mili 296	separator	04
jig bed 574 Krom's rolls 109	Delesse on magnetic attraction Dellyik-Gröndal magnetic separator	79 80
Lion mill 294	Del Mar. A., advantages of stamps	201
machinery for metalliferous mines xix	Del Mar, A., advantages of stamps discussion of plate amalgamation	202
material of bottom bed	dredging, cost of. stamp mill experiences milling in California	203
Monarch magnetic separator 832	milling in California	204
movable sieve Harz Bilharz jigs	milling in California Deloro, Ontario, milling at, an auriferous mispickel at. P. Kirkegaard Delprat, G. D., Broken Hill milling practice	000
on limit of sizes tigged	at. P. Kirkegaard	203
roll speeds	concentration at Broken Hill	156
filter press at Mill 102	concentration at Broken Hill. flotation process	, 156
Davis, F. M., Iron Works Co., Ferraris ball mill 1323	at Mill 129	, 171 100
patent cams	testing for ore dressing at Broken Hill process of flotation. D. Clark	192
M.C. on Tremain stemp. 139	process of flotation. D. Clark	156
rolls	Demaret L. Bartle pulverizer	. 29
rolls	breakers Cornish stamps	. 28
,,	an .	

Pages 1199–1610, Vol. III.	'INDE	X.	Pages 1611-2052, Vol. I
Demaret, L., Husband pneumatic stamp	143	Details of screens	168. 1
mechanical versus hand crushing	61	for stamps, ta	
Nicholas pulverizerstamps and other pulverizers	292	spindle breaker	s in the mills
tin ores in Cornwall	316 1185	stamp bosses	
Tregoning pulverizer	297	shaft table o	f 1
Demond, C. D	viii	stem	f
on electrolytic dissociation of slimes	1414	tappets	
Denny, G. A., and H. S. Rand metallurgical prac-		staves from mil	is, table of
tice	1923	steam stamps.	
Rand mill equipmentdesign and working of gold mill equipment	2041	Sturtevant roll	jaw breaker
equipment of stamp mills	2012	trommels	
hydraulic stamp	1257	whole current h	oox classifiers 444, 4
mill of the Van Ryn gold mines estate	2041 1	Detroit Copper Mir	ing Company of Arizona 18
on hand picking	2021	milling pra	ctice of the 20
sectional guide blocks	1269	sizing test	of Bryan mill product at 13
H. S., discussion of grading analysis	2048]	Development, effect	on mining cost 11
sizing tests on slimes and sands	2019		n steam stamps
Density of liquids affecting concentration	3 J	used on convex	slime tables
effect on free settling	465	Devoisinie, kaonii	138
		Dewaterer, shovel	
Denton, F. W., crushing	57	Dewatering device a	at Mill 141 17
plant at Minnesota Iron mine	57	screens	
purp for sime tables Denton, F. W., crushing. plant at Minnesota Iron mine rolls versus steam stamps at Mill 179 Denver, cost of mill at Engineering Works Company, Blake breaker avaity stamps	1900	at mills	
Engineering Works Common Plake had	1126	Fitzgerald	
gravity stamps	1203 1979	Kogers' dewa	tering screen
grinding machinery	1323	wheele	r at Mill 172 18
revolving grizzly	1353	at mills	1591, 1725, 1772, 1773, 1878, 18
revolving grizzly	1388	Fleming	
1107	1459	Dewey, C. E., Blak	e breaker versus Dodge
-Shepard spitzkasten	1401	on breakers	
and Richards' pulsating classifier	1419	sizing tests o	f jig products 6
rigid rolls	1230 .	Diagram of Sizing	tests of products of Tustin mill
scoon feed for tube mills	1287	Dial cocks	
scoop feed for tube mills	1296	for classifiers	
at Mill 143	1770	gravity sta	mps 1
Fire Clay Company, Case laboratory breaker 1204	, 1223	on ites	
Depreciation expenses	1123	Diamagnetic substa	nces 7
Depth of bank in trommels	380	Diameter of classific	er spigots 4
bed on concentrators	1510	iron pipe	4
marz jigs at minis1700, 1701, 1077, 1070,	1929	chafte in iige	
Hodge jigs at Mill 180 1902, 1903, 1904,		slime tables	5
Derrick, W. H., tin ore in the Malay Peninsula	1182	trommels	
Derr, Louis	viii	effect of	
Derry, W., Husband stamp	143	wire for scree	ens
Description of Blake breaker	13 7 2045	Diameters and velo	cities of quartz grains2003, 200 2005, 20
Desert mill, Tonapah, Nevada. A. R. Parsons Power and Mill Company	1666	areas of circl	es
life of shoes and dies at	1277	of stamp shoes a	and dies
Designation of holes in stamp screens	172	Diametral ratio bet	ween quartz and galena hindered
Design of Blake breakers	1201	settling	
cams	196	Diamond dressing i	n S. Africa. A. F. Williams 20
classifiers	1434	neids of South	Airica, washing pans used in
electro-magnets	1006	pans	of 11
machines	2049	washing	
mills	LIZD	at Mill 188	
mining machinery. S. H. Pearce	2048	in Africa. I	R. Stokes
A. C. McCallum	2048	W. H. N	of 11
rolls	78	Brazil H	. W. Furniss
settling tanks sulphide mill, 150 ton. A. Harvey two small mills. S. I. Hallett	9041	South Air	.ca
suipfilde mill, 100 ton. A. Flarvey	2041	tuba mille for	
Deslore, I. M., Blake breakers	57	Diamondiferous ear	th, washing pan for
Desloge, J. M., Blake breakers Desloge mill for lead in Missouri	1175	Diamonds recovered	th, washing pan for
mill	. 1185	separated by w	reathering d
disposal of concentrates in	57	Diaspore, specific g	ravity of
trunking machine in	587	Diepenlinchen, jigg	ing four minerals at
De Soto mine ore, Krom air jig on	824	Lunrig tables a	ıt
Dessauer, H. A. von, temperature of water for amalgamation	789	Die rings and roller	shells in Huntington mills
Details of Blake type of breakers from the mills	. 23	for Huntingt	on mill
cams, table of	192	Diec	•
clean-up of gravity stamps	202	and shoes for	grinding pans, wear of 15
Comet breaker	41	at Mill 117	
cost of crushing by breakers	. 49 . 104	tor amalgamat	ing pans
crushing by rolls	. 10 4 . 135	gravity stam	ps, nie or
steam stamps	180	weight, lit	e. etc
dies	30	life of	
dressing and cleaning plates	. 757	table of details	of
incide plates	. 178	Diescher coal jig	
	540	connecting r	od for
jig screens	7.77	T): #	iin Wadaa iin
jig screens. McCully gyratory breaker rings from mills, table of	. 44 . 122	Differential-motion	jig, Hodge jig

14505 1 010, 101. 11	14500 011
Differential motion, Woodbury jig 1447	Dissemination of mineral affecting crushing limit 304
variable-crank mechanism for jigs	Distances between rolls for various angles, in author's
Difficulties in concentration	
screening	Distilled water, effect of in settling 474
Dillon concentrator	Disti-Susky screw grate screen
Iron Works, Perfection ore feeder	Distributing conveyor 861 at Mill 143 1769
Dilution of fine slimes	devices
Dilution of fine slimes. 1121 Dimensions of Abbé tube mills at Mill 101	or sizing launder
Comet breaker	tanks
iig sieves 591	gold recovered in mill 749
Linkenbach pointed boxes	pulp in settling tanks
Richards' pulsator jig, table of	Distributors
stamp dies 180	bibliography for
mortars	Blaisdell
tappets	Butters & Mein at Mill 106
tube mills at Mill 103 1632	for amalgamated plates
Wetherill magnetic separators, table of 1522 Dimmick classifier	buddles
J. O., on classification	feed on Roberts' slime tables
sizing before amalgamation	slime table feed and water
& Son, distributing launder	stamp mills 772 vanners 646
Ding Electromagnetic Separator Company, the Ding	machine 857
separator	mill
description of the	revolving distributor or divider
table of weights, dimensions, and power for 1541	Dives-Pelican Mine, Samson breaker at 1203
roasting furnace	Robert, advantages of hand picking
Dingey mill	Dividend gold saver. 2030 Division of concentrating 318
bibliography for	mills for different ores
Diorite, strength of 301 Dipper dredge 1007, 1011	Dodd buddle. G. Attwood
sample	disc water wheel
Direction of rotation for tube mills	table 675
Direct pumps	tables at Mill 96
Dirt	W. G viii
Disadvantages of gravity stamps as compared with rolls and grinders	on amalgamating pan
Krom jig	at Mill 183
springs on jigs	compared with Blake
at mills	Humboldt type 1206 improvements on in Mill 26 35
motion for accelerated jigs 536	movements on, made by Gates Iron Works 34
Discharge, bell, for jig concentrates	Parke and Lacy Company 34 perspective of 29
concentrates 500	section of
in Krupp Harz jig	sizes of
_ Woodbury jig 1448	Sturtevant-Dodge type breaker
Leavitt steam stamp 993	used in stamp mills 1014
steam stamps	wear of
tube mills	jaw breaker 28
into the hutch in jigs	mill, bibliography for
elevators	pulverizers
jig concentrates by rakes 502 ore bins 842	sizing box
products on Hooper air jig 821	Dolcoath mill 1000
settling tanks 458 stamps, area of 209	Dolcoath mill
neight of	Thomas
roll for vanner concentrates	III IIII
with unwatering sieves	
Bryant	Dolomite, with disseminated galena, crushed in Mill 25
sorting tube results 467 Disintegrating and screening for graphite one 1974	25. 47, 98 ore, weight of 1190 specific grayity of 1990
	ore, weight of 1190 specific gravity of 1189 Domeykite, specific gravity of 1189 Donahue, P. J., oiling device for amalgamating pan 247 Donald, J. T., Cylcone fibreizer 298 Dörnberg and Aurora mill 1177 classifiers at 1277
followed by screening	Donahue, P. J., oiling device for amalgamating pan 247
Disintegrators	Donald, J. T., Cylcone fibreizer
and pulverizers	classifiers at
bibliography for 299 Bourdais 899	sieve scale at
Brink and Hübner	and Aurora works, sizes of ore hand picked at 487
Carr	mill, jigs at
Stedman	Dorr classifier at Mill 103
Dispersion of magnetic lines 701	Hills, South Dakota
Displacement pumps 1500	Dorotheer mill 641
Disposal of concentrates 586 tailings 1113	Double-cone classifiers
3:	2



Pages 1199-1610, Vol. III.	IND	EX.	Pages 1611-2052, Vol. IV.
Double-cone classifiers at Mill 117	1669 1689 1381 1381 1381 1381 1370 3583 1266 201 167 1361 167 1361 167 1361 167 1361 167 1361 167 1361 167 17 181 183 183 183 183 183 183 183	Dredging gold, how to saving tables us ground, testing of in Alaska. O. F. gold. C. A. Borneo, gold Brazil. F. C. British Column California	makeit pay. A. W. Robinson. 2035 sed in. C. W. Purington. 2041 f. R. M. Downie 2043 falla. 2045 Tupper 2041 2045 2046 2046 2046 2046 2046 2046 2046 2046
W. F., amalgamation. on temperature of amalgamation Draper's dry concentrator in Australia Dredge at Ruby, Montana bucket in New Zealand. current motor for phosphate limit for Stewart River district, Alaska. A. W. Robinson. New Zealand gold. J. P. Smith. yield of a California Dredges and equipment, cost of at Ruby, Montana, electrical Bucyrus comparison of American and European. F. C. Perkins. old and modern style construction and operation of. D. K. Blair detailed comparison of. R. L. Montague different types of. B. Cunningham electrical equipment of gold. C. W. Whitney. history of. J. P. Hutchins hydraulic power for. improvements in gold. G. E. Walsh revolving versus shaking screen in riffles for Risdon Dredging. P. G. Morgan. amalgamated plates and riffles in gold. J. M. Sweeney article on gold. R. H. Postlewaite	789 767 767 76229 898 898 898 2037 897 2044 897 2037 2045 6654 2042 2044 2044 2044 2044 2044 2044 20	modern gold. H. on the Feather Ri Klondike. J. I Saskatchewan. Snake River, Ic operation, returns plants pneumatic tube in power plants for prospecting and o river. C. C. Lon sluice extension v sluices and riffles tin. tables for with a Hammond Dressing of belts of plates plates at Mill 114 tin ore American Process and drying of ore. Argail cylindrical at mills. capacity of drying classification of cylindrical driers drying floors. Edison tower dries Grill four-company	G. Clark 2046 ver, California 2043 P. Hutchins 2048 I. Cowie 2034 Internation 2048 I. Cowie 2034 Internation 2046 Internation
at Boise, 10tho. 2 Golden, Colorado, K. Thomas 2 Nome, Alaska. J. P. Hutchins 2 gold, G. P. Grimsley. 2 Oroville, California 2087, 2 N. B. Knox. 2 Ruby, Montana, gold. J. P. Hutchins. 2 by the Oroville Dredging Co., California 2 water power. J. M. Gowan 2 cost data on. Alex. Del Mar 2 cost of 1 gold 2 discussion on. L. J. Hahl 2 for gold. 1007, 1181, 1 tables for	048 039 036 044 040 040 039 044 046 046 046 046	ore. C. O. Bartle revolving, at Mill cylindrical drier shaft, at Mill 151 Drifting tool for stamp Drifton, Luhrig jig at rolls at Drill points in mills Driver in amalgamatin Driving mechanism for clutches gearing gravity stamp rolls tightener trommels table of Drop between jig sieve	pany driers. 1597 tt 2021 188 1748 at Mill 135 1735

Pages 1-643, Vol. I.		DRE
Drop hammers limits of speed and height of, due to morta maintaining height of in gravity stamps of gravity stamps, order of on amalgamated plates order of. C. S. Richardson		$^{12}_{218}$
maintaining height of in gravity stamps	····· .	200
of gravity stamps, order of	1	737
order of. C. S. Richardson	1	737 1278
order of. C. S. Richardson for stamps Drops in amalgamated plates number of in gravity stamps of stamps, number and height of Tremain stamp, number of Drumlummon mine ore Drum magnetic separators. Dry blanket method of concentration blowing in prospecting for gold ores		733
number of in gravity stamps		214
of stamps, number and height of	• • • • •	138
Drumlummon mine ore	. 1027, 1	1040
Drum magnetic separators		825
blowing in prospecting for gold ores	2	2029
concentration	:::::: 2	815 2027 2047
Roseberry Round Mt., Nevada. G. A. Packard	}	2047 2038
bibliography for		837 2027
bibliography forin Australia. B. Dunstan		2027 2030
Australia, comparison of on the Cammett table crusher, Langley's improved crushing and cyaniding at the Luipardsvlei F. White, G. H. Furnee by Edison process stamps in Colorado		2022
crusher, Langley's improved	mina	274
F. White, G. H. Furnee	inine.	2047
by Edison process		$\frac{2010}{226}$
		1244
rolls for	• • • • •	1224
magnetic separator, Conkling		809
-ore sizer, Keedy		1555 1075
panning and blowing		825
placer machine	838	, 839 1139
separation	890,	891
separator used in Germany		2029 1039
rolls for house for men. magnetic separator, Conkling -ore sizer, Keedy pan, for clay panning and blowing. placer machine screening versus wet separation separator used in Germany silver mill milling stamping		$\frac{1176}{221}$
at Ontario mill		210
stamping stamping at Ontario mill table, Sutton, Steele & Steele vanner		1554 838
Drying bin at mills	, 1705,	1570
floors	880,	1596
in bilne		899
iron ore		1054 1077
kaolinnecessary for air concentration		826
of cree W. P. Trocalle		1077 1610
of clay of ores. W. R. Ingalls slimes at Mill 129 use of hot fines for drying coarse ore at Mill Dubuat, M., Hydraulique et Pyrodynamique		1717
use of hot fines for drying coarse ore at Mill Dubnat. M. Hydraulique et Pyrodynamique.	108	1826 xix
launders		885
Duck for canvas tables	†òo	, 701
at mills	, 1755,	1779
W. L., amalgams		787
Dufferin mill		1099 1181
bunuat, M., Hydraunque et Pyrodynamique launders. on transporting power of water Duck for canvas tables at mills	plates	787
gold amalgamationhand jig		1182
on amalgamated plates		741
Dummler, K., crushing and washing clays		1173
testing jigs. Dummler, K., crushing and washing clays Handbuch Dump at Mine La Motte, Missouri, treating t	ha old	xix 2045
for tailings		1113
for tailings of the Bellevue Colliery, method of we	orking.	2041
Dunham's spring stamp	141	143
Duniap Manufacturing Company, perfect clay Dunnellou, Florida, mill at	screen	1357 899
of the Bellevue Collety, method of w. G. W. Harris Dunham's spring stamp Dunlap Manufacturing Company, perfect day Dunnellon, Flori'a, mill at Phosphate Co., mill Duplex breaker Of Blake type	xxv	, 899
of Blake type		60 21
Callow screens at Mill 123		1689
Dupont, O, and Ch. Quéhant, dressing lea	d and	1673
of Blake type Callow screens at Mill 123. vacuum-pumps at Mill 117 Dupont, O. and Ch. Quéhant, dressing lea zinc in Belgium Durango, sectional from stamp frame for. Duet blaum from coal		1185 161
Dust blown from coal		817
		3





Pages 1199–1610, Vol. III.	INDEX.	Pages 1611-2052, Vol. IV.
Edison, T. A. on power for crushing	310 Eissler, M	., pointed boxes, spitzlutte, cone classifier . 476
millstrajectory in screeningtower screen at Mill 152	. 1093 silver . 369 stamp	amalgamation 1039 of rames 153 nill, Zacatecas, Mexico 1408 mill, cost of milling at 1127
Edman, J. A., arrastra	290 El Callao	mill, cost of milling at
Edman, J. A., arrastra Edwards, G. E., Woodbury jigging system. J., & Co., on centrifugal pumps. 80 J. H., on Griffin mill	19, 870 Electric C	cobbing magnet at Mill 164.
R. M	. viii curre	nt. See also Power.
Effectiveness of blow of gravity stamps Effect of acid water on screens	218 on 173 lights	electroplating copper plates
air currents on mechanical sampling	1576 for 1544 powe	hand picking
centrifugal force in trommelsdissolved substances in settling fine slimes	. 373 XX	(,
explosives	ala n	mills
slope of trommel on capacityspeed on capacity of a trommel	. 377 Electricity	versus steam as a motive power 1927
strength and specific gravity of rocks on power used		nductivity
temperature on amalgamationat Mill 106	373 Electrolyt 766 Electroma 1640 Electroma	gnet, hand 812 gnetic and electrostatic separators, general ons of. W. M. Johnson 2025 ator, Ball-Norton 1568 g 1568
weathering on flotation process results at Mil	discussi	ons of. W. M. Johnson
on capacity of trommels of varying the diameter Efficiency of classifier jig at Mill 120	379 Di	lg
cocon matting tables at Mill 111 gravity stamps	1657 For 219 Electroma	ksson's 1529 sgren's 1538 gnets, design of 790
Hancock jig, quality of work	. 1441 Electropia	ting copper plates
labor, effect on costspumpsrolls.	. 868 discussi . 109 separ	on of. W. M. Johnson 2025
rope transmissionsand wheel	. 1095 art . 1587 at	ation
steam stamps	31, 133 of	Mill 151 1804 copper ore, discussion of. W. G. Swart 2026 zarious zinc blendes 1550 nciples of 1199, 1549
tube mill	. 1292 pri . 1090 separ	nciples of
Egleston, T., Allouez and Atlantic mines	. 1174 - 131	ike-Morscher electrical ore separator 1550
amalgamating pans	. 787 dis . 289 Hu	cription of a generator for
hall mills	. 298 list . 142 Su	s of good and poor conducting minerals 1550
Ball stamp Blake breaker edge runners	57, 58 Electrum, 295 Elevating	tton-Steele
estimate by, of wear of iron in pans	. 249 whee	ls 804
gravity stamps	4, 225 Elevators For	boot as unwatering box
Huntington mill	. 492 at m . 296 10	Ns. 1661, 1663, 1667, 1681, 1685, 1689, 1690, 91, 1693, 1700, 1702, 1703, 1707, 1710, 1711, 1715,
hydraulicking jigs at Tombstone stamp mill Krom rolls	. 1173 17 . 639 17	25, 1727, 1728, 1729, 1737, 1738, 1742, 1743, 49, 1750, 1752, 1753, 1755, 1756, 1759, 1760,
Lowe's mill	09, 110 17 . 294 18	62, 1763, 1760, 1771, 1772, 1774, 1792, 1793, 1804, 18, 1819, 1829, 1837, 1839, 1840, 1842, 1843, 1844,
non-amalgamation	. xix 18 . 1174 18	46, 1846, 1847, 1853, 1854, 1855, 1857, 1858, 1866, 67, 1869, 1870, 1877, 1880, 1883, 1888, 1889, 1890,
metallurgy non-amalgamation on breakers mortars diversional generation 1	64, 165 biblio	
BILVER BUILDINGHUM COMPANY COM	. 1000 DUCK	et
stamp frames wear of amalgamating pans stamping and washing at the Allouez mine	. 249 detai	fugal sand pump 1588 Is regarding running of. E. S. Wiard 2032 accement pumps 1589 redges 1012
Tustin mill	. 294 for d . 293 tai	reages 1012
Eich, L., on impurities in amalgam Eissler, M., amalgamating pans	. 251 in m . 290 John . 1173 Land	lings 1113 ills, use of 1086 A. Traylor centrifugal pumps 1588 1580 1588
silver. amalgamation Blake breaker	. 787 or ra	taster rotary pumps
Dodge and Krom breakersbreakers	. 56 sand	pumps. 1587 seels 1586
Cyclops mill definition of slimes	. 294 whee	el agitator used for
Gates and Krom rolls	. 109 Elkton m	line, ore washing at
breakergold stamp millinggravity stamp clutches	. 1173 table	pal washer and Hardy dust extractor. E.
stamps	. 223 Greave . 639 Elliptical	gear for jigs
Grüson ball mill	. 293 m	echanism for bumping tables
Harz and Collom jigs Huntington mill Krom jig	. 297 vanr	er
Krom jig	. xix oil c	A. S., flotation process
mortar linings,	: 166 35	advantages of the
	99	

Elmore, oil process in Cornwall. M. Baldauf	2047	Engis, air classifier at	81
Ore Concentrating Companyplant, London, England	$\frac{1993}{2035}$	classifier 475, English standard gauge steel for shoes and dies	47
process at Dolcoath. E. Walker		steel for shoes and dies	18
the Tywarnhaile copper mine, Cornwall,	2039	system of jigging	140
England	2038	Enterprise mill, Plattesville, Wisconsin E. P. Allis Company . 72, 76, 111, 181, 187, 189, 197, 228, 243,	194
C. M. Rolker E. Walker	2025	197, 228, 243, batea made by	24
failure of	2029	dies made by	68 24
for Slocan ores	2025	adma was nou mada las	27
Rossland, failure of	2020	inside plates muller and shoes made by	$\frac{17}{24}$
in diamond washing Rossland, failure of saves 93 percent, of values statement on the. F. H. Claudet	2029	power for 5-foot pans estimated by	24
statement on the. F. H. Claudet	2025	shoe and die channels in amalgamating pans	0.4
testing fortests on, at Glasdir mine, Wales	832	weights of spider and driving cone made by.	$\frac{24}{24}$
results of	2049	Epidote, hindered-settling test on	62
vacuum flotation process, description of the. A.S. Elmore	, 2027	settling velocity of	40: 118:
E. Walker	2027	Equipment of gold mills, G. A. Denny	01
oil process	1559	Equivalents of weights and measures	112
Mill 141	1765	Erecting mills, costs of	93
consumption of oildescription of the. F. H. Prentiss	2027	Eriksson's electromagnetic separator	1529 831
in Sweden El Oro cast-iron ribbed liners for tube mills at Mill	1560	Errors of small tests	168
El Oro cast-iron ribbed liners for tube mills at Mill	1677		18
district, Mexico, cost of producing gold in	1011	Espiritu Santo mill at Cana, Darien. E. R. Woakes 2	83(201
1980.	. 1981	plates in	788
lining for tube mills	1676	Essential qualities of classifiers Essentials of a good breaker.	389
tube mill lining	2016	Esser concentrator 2	02:
smelter, sampling at	1803 884	Estimates on cost of hand picking Eureka Hill mill	487
El Potrerito mill	1665	W. McDermott 2	038
Elspass mill	$\frac{763}{1323}$	stamps	228
Elutriation	1611	rubber	249 770
for emeryuse made of, in mills	1079	Outil, mill at	041
Embrey vanner	653	Europe, hand picking in	$\frac{486}{175}$
testing	1171	milling in 1 mills in 987, 10 Eustis, Canada, hammers used	088
ore, mill for	1079	mill at	10 የዐ4
separated by magnets	790	Mining Company	RRR
washing wheel for truing roll shells	1243	W. E. C. and H. M. Howe, magnetic process for	904
Emmons, S. F., gold stamp mills in Maryland and G. F. Becker, amalgamating pans	$\frac{1175}{291}$		
amaigamation	789	at mills	470 24 K
arrastraedge runners	290 295	Evans classifier	
Empire mill. xxvii, Plattesville, Wisconsin.	1020	G. H., hydraulicking	448 006
Plattesville, Wisconsin	2038	hydraulic miningxix, 1	173
stamp mili Zinc Company	1759	ideas on jigging 90	395
Ems	907	G. 11., hydraulicking	$5\overline{24}$
Linkenbach V-box classifier at	421	at mills	845 529
mill at		water used by compared with that used by	· · · · · · ·
sieve scale at	590 367	round tables at Mill 182	142 346
Enargite, specific gravity of End-bump group of tables.	1189	short stroke jig at Great Falls	32ĭ
tables	$1497 \\ 1464$		893 389
comparison with side-bump Ellenbecker table	682		396
Gilpin County concentrator	681 680	W. L. slope of launder in mill of Atlantic Conner	333
Golden Gate concentrator	681	Mining Company	378
Endless belt	681 1094	mechanical discharge for its tollings	341
conveyors	859	Evrard's coal jig	588 342
chain conveyor	1500	Examination for minarals	343
End-shake vanners	1500	Excavating expenses 11 Excavator, the Blaisdell 10 Excavator breakers 11	122
Embrey concentrator	653 1153	Excavator, the Blaisdell	3 <u>Ö</u> Ğ
Triumph concentrator	652	Excelsior breaker 16 Excelsior breaker 10 Exhaust fans 10	00 99(
versus side-shake yibration in	655 658	steam for heating 10 Expandled metal riffles703, 722, 1007, 1008, 10 Expanding cone wash trommel	98
_ Woodbury	655	Expanding cone wash trommel	112
Energy of gravity stamps	219 133	Expense accounts	22
steam stamps Engelmann, H., air <i>versus</i> water jigging, Utsch side		study	111
plunger jig	640	Expense accounts 11 Experimental plant at Mill 182 19 study 11 Experiments on film sizing 7 with launders. Blue's 1	/07
Chapter XX.		with launders, Blue's. 15 Overstrom's 50	94
in mills		Overstrom's	'nô
		36	



Pages 1199-1610, Vol. III.	IN1	DEX.	Pages 1611-2052,	Vol.	ıv.
Extent of crushing desired Extraction at Meyer & Charlton mill, South Africa			er inch		2012
average, percentage made in various districts table of in mills. 1618, 1622, 1626, 1639, 1648, 1649, 1659, 1600, 1675, 1678, 1690, 1705, 1718, 1724, 1726, 1724, 1726, 1721, 1726, 1724, 1726, 1721, 1745, 1767, 1711, 1782, 1791, 1815, 1816, 1817, 1820, 1826, 1830, 1834, 1849, 1856, 1805, 1870, 1871, 1887, 1891, 1897, 1899, 1900, 1906, 1907 of metals and minerals by Elmore process percentage of . See Individual Mills in Chapte percentage of . See Endividual Mills in Chapte percentage of . See See See See See See See See See S	5, 1612 1657, 3, 1721, 1780, 5, 1827, 1881, 1908, 0, 1922 1559 er XX. 1115 1930 2014 1665	and slime tal proper consis Wilfley tables, I free and choke for maximum size for natural, on Wilfle opening in mortar openings for tube sized, for Wilfley versus classified size of feed to Bal in gravity statement by De Ferraris mag sole for classifiers	oles compared tency of proper consistency of ed for rolls compared Wetherill magnetic sepa y table. s mills table feed for Wilfley table L-Norton magnetic separa mps savay process actic separator	rator	658 1, 692 1404 1229 1525 1471 1687 1478 1528 207 1562 1525 434
Faber du Faure furnaces at Mill 117	. 1674	to rolls	slimer		1505 63 674
E., washing of graphite for lead pencils Face of rolls	. 1176 . 83 . 1323		indard concentrator		
Nissen stamps. False bottoms for stamps	180	bibliography for	• • • • • • • • • • • • • • • • • • • •		1700 884
for stamps Falun, Sweden, mill at 1136 stamps at 137 Fan for air blast	6, 1177 . 225	type			1578 1580 1600
shaped apron for distributing Fans at Mill 186		clavev ore	••••••••		71 199
Farbaky, Stefan, comparison between Wetherill sep-	. 883 -	movable sleve ji	gs		278 500
		small steam star	mps		71 137 1287
-Blake breaker at mills .1221, 1690, 1749, 1769 life of wearing parts at Mill 139	1889 1868 1221				2016
Fargo guide for gravity stamps 15 Farrel-Bacon breaker at Mill 175 1888 -Blake breaker at mills 1221, 1690, 1749, 1769 life of wearing parts at Mill 139 duplex breaker, table of sizes of Foundry and Machine Company Blake breaker	11.41	improved swing or in the mills Musterschutz	e. P. J. Johnson Pepler.		2032 2032 856 884
jaw movementsbreakers cost of breaking ore	. 59	Perfection ore	Pepler	i578,	2032 1609
information on Blake breakers	1223 87	push feeder at Mil shaking, at Mill 12	1 113 24		1581
Fastening plates to table Father de Smet gold stamp mill mill breaker in	1174	arrangements of st	ity of jigsamps		128
Eureka rubber infalse bottoms in mortar	777 180	gravity stamps			207
grizzlies in	385	magnetic separator		• • • •	548 802
plates in	787	trommels	·····	• • • •	689 857
stamp screensstamps in	$\frac{169}{224}$	tube mills Feldspars, decomposition	on of. A. S. Cushman	and	848 1288
Faults and features of rolls Faust. FL. on jig capacity	183 1220 602	for beds on coal jig	(S	1	574 574
Faust, H., on jig capacity jig, slope of sieves on width of sieve	548 591	Fenner, C. M., on gold Ferguson, H. T., Dinge	and silver in amalgam .		1398 763 293
width of sieve Fawcett, W., testing of black sands Fawns, S., milling at Mt. Bischof, Tasmania Feather River, California, dredging on	2048 2037 1184	rolls in Cornwell	c stamps	• • • •	143
Federal Lead Company Mining and Smelting Company	1690 1685	Ferrand, P., amalgamat	ing pans at Ouro Preto.	Bra-	478 1182
Mining and Smelting Company Morning mill: shaking screen at Mill 124 Feed arrungements on slime tables. box for iigs	ROO	amalgamation at O California versus Br	uro Preto, Brazil razilian stamps at Ouro I	reto.	291 173 227
box for jigs Wilfley table	1468 1473	gold mill at Ouro I L'Or a Minas Gen	Preto, Brazil	1	1182 xix
cone for trommels	0. 701	Ferraris adjustable ecce	ntric for jigs		$\begin{array}{c} 727 \\ 532 \end{array}$
Freid dry-process separator Gilpin County bumping table	1554	at Mill 137		1	1300
gravity stamps Huff electrostatic separators	207 1553	W. R. Ingalls	oower, weights, etc	1	300
kieves	726	classifier		478, 1	808 8081
rifile tables rolls slime tables stamps	720	capacity of jigs .	Monteponis at Monteponi	1	597 1185
	37	aressing zinc ore	s at intontepont	1	1180

Ferraris, E., Ferraris adjustable eccentric 643	Fine sand and slime concentrators, riffles 720
belt tables	concentrators, Wilfley table 1466
classifier	slimes, effect of
shaking screen	Sinness of bullion. 749, 763, 781 crushing desired 30 gold and silver in amalgam 76
Harz jigs at Monteponi 643	gold and silver in amalgam 762
magnetic separation at Monteponi 2046	retort residue 783
mechanical preparation of ore in Sardinia 1568	Fines for miners
riddle	in water 1547
separator at Monteponi 836 velocity of particles falling in water 477 hand screen 1360 intermediate jig 539, 540, 584	Finest size jigged
velocity of particles falling in water 477	to which middlings are re-crushed in the mills 1116 Finger bars for gravity stamps
intermediate jig 539 540 584	Finger bars for gravity stamps
jig	geared rolls
magnetic separator	Finish angles in film sizing tests
at mills	Finishing machines
drum type	Finland, magnetic separation in
method of removing tailings	mining in Cœur d'Alene, Idaho
drum type 1528 method of removing tailings 587 shaking screen 342, 386, 1347 at Mill 137 1347	on costs
stay box for jig discharges	assay of gold ore
tables	tube boilers
stay box for jig discharges 585 tables 1154, 1490 at mills 1659, 1740, 1741, 1782, 1785, 1786, 1914 tables of sizes, capacities, speeds, power, weights and water consumption 1490 versus jigs. M. Lenicque 2021 waving screen. C. W. Wright 2019 at Mill 137 1739, 1740, 1741 wet ball mill at Mill 137 1740, 1741 Verreira mill defails of stamps 221	water for
tables of sizes, capacities, speeds, power,	Fischer, formula for speed of revolution of tube
versus iigs. M. Lenicque 2021	mills
waving screen. C. W. Wright	Herman, operations of tube and ball mills 1340
at Mill 1371739, 1740, 1741	Fisher's steam stamp
wet ball mill at Mill 137 1740	Fitzgerald shaking screen-launders at Mill 142 1767
Ferreira mill, details of stamps	Fixed circular convex slime tables
weight of ore at	Roberts table
weight of ore at	sieve hand jigs 519
shoes and dies	jigs
Ferrous sulphate used in dressing plates 757 Fiber asbestos	Hodge 1447
Fiberizer at Mill 186 1917	Hodge. 1440 Krupp Harz jig 1440 New Century 1444 Richards' pulsator jig 1458
um gauge 1159	New Century 1444
on a circular slime table, thickness of 695	Richards' pulsator jig 1453
sizers 1464 sizing, results of tests 719	Woodbury jig 1447 Flange, Brownell 647
tables	for amalgamating pan
Acme table	Flanged rolls
bibliography for	at Mill 130 1720
building tables	Flash point of oils 1098 Flat grains, action of 892
continuous surface tables	on sume tables
depth of bed	in middlings
intermittent surface tables	River district, cost of producing lead in 1971
principle of	mill
revolving circular convex slime tables 686	Missouri, mill at
surface tables 685 use made of, in mills 889	Missouri, mill at 917, 920 1085 1085 1085 1086
thickness of on amalgamated plates	at mills 1500 170s
on slime tables	at mills 1590, 1725 J. D., Fleming dewatering wheel 1590 Flint pebbles for grinding. 297 Flints for tube mills 1288 Floors for draining concentrates 1112 Concentrates 290 Concentrates 29
films on canvas tables, thickness of	Flint pebbles for grinding
ilter	Floors for designing concentrates 1110
at Mill 171 1870	drying
boxes for jig concentrates	drying
in cyanide plants	mus 1088
iltering mercury	receiving ore
slimes 1160	steam stamps 128
ilters in settling tanks	weathering
hindered settling and suction	diamond ground 1080
inal conclusions on crushing 02 hindered settling and suction 631 separators 480	slope of
mancial standing	Florida, phosphate mills in
indley, O. P	Florida, phosphate mills in
ico	of clay
ico	at Broken Hills 2038
objections to 1053	acid
concentration test	F. H. Jackson 2045
crushing by breakers	data on. C. Blämeke
gravity stamps used for	De Bayay
mills	Delprat
grains investigation on rate of settling	at Mill 129
importance of. F. C. Brown	economic side of the. W. G. Swert
importance of. F. C. Brown	Elmore
limit of screening	at Broken Hills 2038 acid. 2035 F. H. Jackson 2045 Mill 130 1719, 1721 data on. C. Blömeke 2030 De Bavay 1555, 1562, 1568 Delprat 1555, 1561, 1568 at Mill 129 1718 description of different 2026 economic side of the. W. G. Swart 2029 Elmore 1555, 2029 Elmore 1556, 2029 E. Walker 1569 yacuum-oll process 1556
classification of	vacuum-oii process
kieyes	vacuum-oil process 1556 history of the. C. Gopner 2028 list of minerals floated by 1555
38	1000
	ý.

Pages 1199–1610, Vol. III.	IN	DEX	Pages 1611–2052, Vol. IV.
Flotation process, Macquisten	. 155 5	Foster,	C. Le N. Tordan's centrifued owinder 205
Macquisten's Coates tubes	. 1561		berg machines
Minerals Separation Company	. 1560]	mit of Sizes negect ROS ROR
or Catermole	1, 1568	ľ	pointed boxes, cone classifier, Lockhart's classifier, siphon separator 476
principle ofsalt cake. Pittman	. 1199	5	621
theory of the	, 1555	į	ext-book, ore and stone mining
G. Hoagland used at Broken Hill, acid	. 2027		valuari disintegrator
van Meter testing apparatus	. 1992	r oster-	Coolidge automatic sampler
vats at mills	h-	Founda	on concentrating tin ore 288 tion for arrastra 238
ton	2020	{	ravity stamps 145
Flow in launders	. 751 . 876	r	nills 1088
of sand and water in launders 1592, 1593, 159 water in launders	4, 1595 • 884	1	Willey table 1465
Flues in hoilers	. 1091	r ounga	me for amalgamating pan
Fluorine atomic weight of	. 1105	at	Grass Valley, mortar 2012 Huntington mills 1313
Flume for water Fluorine, atomic weight of Fluorite, specific gravity of Fluorspar, decrepitation of	. 1189	r	nills
separated by Hooper air jig	. 829 . 822	S	Nordberg steam stamp
Fluxes for meltingF. M. Davis Iron Works Company72,	784		mills, concrete
Folsom dredge of 140,000 cubic yards capacity	. 2044	t	team stamps
Fonseca on impurities in amalgam	$\frac{251}{1187}$	in s	stamp mill, masonry 2012
A. D., battery screen	. 1270		
North Star mill	. 2045 1925	r oundr	y for mill 1088 ineral separation on jigs 590
Foote, A. E., glass classifier	. 1146	towie,	J. C., Buchanan and Wenstrom separators at
Foot-pounds, equivalents of Force required on rolls	. 1188	ma	Superior
Forces, table of value of, acting at different angles in	1	τ	erior
rolls	1086	Fracture	al selection for sampling
Forged-steel roll shells at Mill 1411760, 1763 Forms of frames for gravity stamps	l, 1762 . 156	ette	ct of, in dressing ores
launders	. 876	Frame,	Boss cantilever frame for gravity stamps 1272
riffles Formula for centrifugal force	. 721 . 827	ior	slime table
in trommels	. 374	W i	fley table tilting frame
free settling47 magnetic lines of force	. 793	' Cor	nish
path of particle in trommel	. 794 . 375	for I	amalgamated plates
settling tanks	. 455	g	ravity stamps
Formulæ, Blue's formulæ for flow of sand and wate in launders	. 1594	ji S	gs507, 522 creens176
Forsgren electromagnetic separator 1538, 1815 Forster breaker	, 2038	ti	in ores 1083
of law type	. 25	V	anners
plan of table of wear, in Mill 67 Fort Scott Foundry & Machine Co., rolls	. 28 . 28	nev	Dimmick patent slime table
Fort Scott Foundry & Machine Co., rolls	76	r	olls
Machine Works, rolls	5, 762	Framing	1507 cof mills
breakage of stamp stems	188	France	mills in
wear of shoes and dies in	183	Francou	rt, Italy, mill at
weight of stamps in		Franklir	jig
Foster, C. Le N.	1173		wetherin magnetic separators and operating
Ball & Leavitt stampsbelt tables, Cornish frames, buddles, percus	-	J., :	attendance required at
sion tables, kieves	727	si	naking plates and blankets at the Idaho mine, labama
breakers Carr disintegrator Chase Concling Edison Hoffman Kessler	56	Mir	ning Co
Chase, Conkling, Edison, Hoffman, Kessler	298	Nev	v Jersey, magnetic separation at 835
Lovett-Finney, Ball-Norton, Buchanan Friedrichsegen, King's, Wenstrom mag		Franklir	ite magnetic senaration of \$05 \$07 \$08
neuc separators	832	spe	rated by magnets
concentration of miscellaneous materials Cornish rolls, Krom rolls	1069	Fraser a	nd Chaimers
Cyclone pulverizer	298	a	gitators made by
double-cone classifiers	. 295	C	lassifier
Gates breaker gravity stamps	56	d	eep pocket classifier
Grüson ball mill	. 293	q	iai cocks for gravity stamps 199
hammers and breakers	. 11		ies made by
hand breaking and picking, picking tables . Harz jig, Heberwäsche	. 492	g	auges 1194
Huntington mill	. 297	E	eared rolls
Husband and Patterson stamps	. 143	I	Tuntington mill
		39	• # °

Fraser and Chalmes on samalgamators	700	77.1.100
capacity of rolls		
classifying vanner feed 658 clutches 1008, 1008 1008		angle in trommels
power for 148	classifying vanner feed 658	clutches
power for 148	design of cams 196	for gravity stamps
Stamps	mortar bolts	the H. W. Caldwell and Son Company friction
Setum stamps	stamps 204	in jirs A02
punched screens 170 roll journals 58 58 58 58 58 58 58 5	steam stamps	
shoos shanks 187		roll journals
Stamp bosses		rolls, how reduced
Cleivrance		
stems		
trackness of screech plate warring parts of breakers		gravity stamps
trackness of screech plate warring parts of breakers		process of concentration. O. Witt 2030
vanners color co		ore dressing 2028
wearing parts of breakers	vanner adjustments	Friedeneralla iira at
power for rolls 97 settlers 779 roll trommels 737 roll Mill 130 1737, 1738 at Mill 136 1737 at Mill 137 at Mill 136 1737 at Mill 137 at Mill 137 at Mill 137 at Mill 137 at Mill 138 1737 at Mill 138 1738 at Mi		movable sieve jig at
settlers	power for rolls 97	Pennsylvania, mill at
rolls at Mill 136 1737 1738 amalgaming tables 1514 1516 1516 1516 1516 1516 1516 1516 1516 1517 1518 1516 1518	settlers 779	Zinc Co., millxxv, 903
at Mill 175 1890 1890 1891 1890 1891 1890 1891 1890 1891 1890 1891 18	trommels 357	
Mill 175 1390 1300 1311 1311 1320 1321 132	at Mill 136 1737 1739	amaigam press
roll speeds	Mill 175 1890	box-traps 1516
sample grinder 257 sand wheel 158 sandy wheel 1587 stamp frames 158 standard rolls 2010 cam 114 116 118 119 120 121 127 steam stamp 114 110 118 119 120 121 127 steam stamp 114 1123, 120, 127, 123, 131, 121 two-stamp mill 223, 120, 127, 123, 131, 122 rever can rifugal water-lined pump at Mill 159 129 Freaver centrifugal water-lined pump at Mill 159 129 Frea and choke feed for rolls, comparison of 1299 cushing milling test 1290 cushing from 150 120 120 120 120 120 120 120 120 120 12	roll speeds 87	ball mill
settlers spindle breaker wearing parts 47 spindle breaker wearing parts 47 stamp frames 153 stamp frames 153 stamp frames 153 stamp frames 153 the stamp frames 153 the stamp 114, 116, 118, 119, 120, 121, 122 steam stamp 114, 116, 118, 119, 120, 121, 122 steam stamp 114, 116, 118, 119, 120, 121, 122 weights of spider and driving cone made by 247 Frayer centrifugal water-lined pump at Mill 159 1820 Frecheville, R. J., Cornish tin dressing 1183 Free and choke feed for rolls, comparison of 1229 crushing est 229 crushing affected by natural properties of min- erds 229 crushing affected by natural properties of min- erds 229 crushing affected by natural properties of min- erds 229 crushing affected by natural properties of min- erds 229 crushing affected by natural properties of min- erds 229 crushing affected by natural properties of min- erds 229 crushing affected by natural properties of min- erds 229 crushing affected by natural properties of min- erds 229 crushing affected by natural properties of min- erds 229 crushing affected by natural properties of min- erds 229 crushing affected by natural properties of min- erds 229 crushing affected by natural properties of min- erds 229 crushing affected by natural properties of min- erds 229 concentration by 447 desperoach classifiers 4131 formula 461, 121 formula 461,	sample grinder	breaker jaws 23
spindle breaker wearing parts	sand wheel	
Stamp Frames 153	spindle breaker wearing parts 47	
standard rolls 2010 cam stamp 114, 116, 118, 119, 120, 121, 122 steam stamp 1114, 116, 118, 119, 120, 121, 122 steam stamp 1114, 116, 118, 119, 120, 121, 122 steam stamp 1114, 116, 118, 119, 120, 121, 122 Fresheath of spider and driving cone made by 247 Frayer centrifugal water-lined pump at Mill 150 1829 Free and choke feed for rolls, comparison of 1229 crushing rolls, 122, 122, 118, 118, 118, 118, 118, 118	stamp frames	high speed rolls
steam stamp 114, 116, 118, 119, 120, 121, 123 two-stamp mill 123, 126, 127, 123, 131, 133 two-stamp mill 123, 126, 127, 123, 131, 133 weights of spider and driving come made by 247 Frayer centrifugal water-lined pump at Mill 169 1229 Frecheville, R. J., Cornish in dressing 1183 Free and choke feed for rolls, comparison of 1229 milling test 1229 milling test 1100 settling affected by natural properties of minerals affected by natural properties of mineral settling defined 404, 1221 formula 247, 473 general principles 404 investigated by tubular classifier 409 ratio free to hindred settling 409, 471, 1420 of quartz and galena 409, 471, 1420 of quartz and galena 409, 471, 1420 of quartz and galena 409, 471, 1420 of mineral particles 409 velocities 475 sorting by 485 velocities 5100 of mineral particles 409 velocities 6100 of mineral particles 409 velocities 6100 of mineral particles 436, 1600 point of mercury 7700 Freiberg Bilharz jig at 508 classifier at 1087, 1099, 1102, 113 screens at 31087, 1099, 1102, 113 screens at 329 stamming jigs at 576 Stein, Bilharz and Lubrig tables at 576 Stein, Bilharz and Lubrig tables at 576 Freight, coof 67 (111), 1812, 1830, 1885, 1886 Freight, coof 79 (111), 1812, 1830, 1885, 1886 Freibility of minerals, affected by calcining 99 separation by 480 under a blow 1011	standard rolls	mill for five mineral separation 591
two-stamp mill	cam	picking tables 1435
Trayer centrifugal water-lined pump at Mill 159 1529	steam stamp114, 110, 118, 119, 120, 121, 122,	spitzlutten
weights of spider and driving cone made by. 247 Freyare centrifugal water-lined pump at Mill 159 1820 Fres and choke feed for colls, comparison of 1229 crushing 98, 313 milling test 1106 settling affected by natural properties of minerals, and hindered settling defined 464 and hindered settling defined 464 classifiers, tublus 481 defined 464, 1421 formula 471, 473 general principles 464, 1421 formula 477, 473 general principles 478, 147, 1473 general principles 478, 147, 1	two-stamp mill	Friedrichsgegen calcining furnace at 1548
Frescheville, R. J., Cornish th dressing. 1183 1183 Free and choke feed for rolls, comparison of 1299 milling test 106 settling affected by natural properties of minerals 464 dassification by 474 475 deep-pocket classifiers 464 471 475 deep-pocket classifiers 476 471 475 deep-pocket classifiers 476 471 475 deep-pocket classifiers 476 476 deep-pocket classifie		classifiers at
Pree and choke feed for rolls, comparison of 1229 mills crushing 9.8, 318 milling test 106 settling affected by natural properties of minerals 464	Frayer centrifugal water-lined pump at Mill 159 1829	distributing tanks at
crushing self-ling affected by natural properties of minerals. settling for magnetism at	Frecheville, R. J., Cornish tin dressing	Heberli magnetic separator
miling test settling affected by natural properties of minerals settling affected by natural properties of minerals and hindered settling defined. 464 classification by 474 classification by 474 classification by 475 deep-pocket classifiers 484 defined 464, 1421 defined 464, 1421 defined 464, 1421 general principles 474 sinvestigated by tubular classifier 499 ratio free to hindered settling 499 ratio free to hindered settl	crushing 02 212	magnetic separator at
settling affected by natural properties of minerals — 464 and hindered settling defined — 464 classification by — 474 classification by — 474 classification by — 475 deep-pocket classifiers — 1376 deep-pocket classifiers — 1376 deep-pocket classifiers — 464 formula — 471, 473 general principles — 464 investigated by tubular classifier — 499 ratio free to hindered settling — 1430 of quartz and galena — 469, 471, 1420 of quartz and galena — 469, 471, 1420 sorting by — 1430 vise made of, in mills — 858 vide investigation — 458 use made of, in mills — 858 vide made of in mills — 858 oblong movable sive power ig used at — 503 oblong movable sive power ig used at — 503 oblong movable sive power ig used at — 503 sieve scale at — 1087, 1099, 1102, 1135 bibliography for — 207 Saxony, mill at — 1087, 1099, 1102, 1135 sieve scale at — 367 Seive scale at — 367 Seive scale at — 368, 174, 1177, 1179, 1183 screens at — 368, 184, 1849, 1929, 1939 classifier at — 168, 184, 1929, 1939 classifier at — 168, 184, 1929, 1939 classifier at	milling test	
Sieve scale at 364	settling affected by natural properties of min-	roasting for magnetism at
classification by	erals	sieve scale at
classifiers, tubular	and hindered settling defined	Frisbee Lucop mill
Concentration by	classifiers, tubular	Erisco mill Html Paddock lige at 822
Chep-pocket classifiers		Mining Company
Paddock jig at Paddock jig at Say Paddock jig at Paddock jig at Say Paddock jig at Say Paddock jig at Paddock jig at Paddock jig at Pado	deep-pocket classifiers	Utah, mill at
general principles investigated by tubular classifier 469 ratio free to hindered settling 1430 ratios 409, 471, 1426 of quartz and galena 409, 471, 1426 table of 1428 sorting by 489 tube investigation 465 use made of, in mills 889 velocities 476 of mineral particles 1421 Freeizing of stone, effect on strength 301 point of mercury 730 Classifier at 503 classifier at 1087, 1099, 1102, 1135 hand picking at 1087, 1099, 1102, 1135 screens at 364, 365 sieve scale at 364, 365 reight, cost of feed for 1553, 1554, 1769, 1779, at mills . 1630, 1708, 1755, 1756, 1761, 1769, 1779, 1779, at mills . 1630, 1708, 1755, 1756, 1761, 1769, 1779, 1779, 1730, 1730, 1730, 1730, 1731, 1731, 1712, 1752, 1844, 1865, 1863, 1870,	defined	Paddock jig at 839
investigated by tubular classifier 469 ratio free to indicared settling 1430 ratios — 409, 471, 1420 rotuped from the first of the total free to indicared settling 1420 rotuped from the investigation 469 tube investigation 469 release and of in mills 889 velocities 476 of mineral particles 476 of mineral particles 476 of mineral particles 476 rotuped from the first point of mercury 730 retaining 152 retaining 1431 for testing 1431 for testing 1431 for testing 1431 hand picking at 4087 rotuped for testing 1431 hand picking at 4087 rotuped for testing 1431 screens at 4087 rotuped from the first point of mercury 730 rotuped from the first point of mercury 730 rotuped for testing 1431 hand picking at 4087 rotuped for testing 1431 rotuped fo	general principles 484	Fritsch rolls
ratio free to hindered settling	investigated by tubular classifier 469	mill, bibliography for 201
ratios	ratio free to hindered settling 1430	Fröding separator
table of 1426 sorting by	ratios	in Sweden, data on
sorting by tube investigation	table of	Froitzheim's spring stamp
tube investigation 455 use made of, in mills. 889 velocities 476 of mineral particles 476 of mineral particles 1421 versus hindered settling 1421 point of mercury 730 point of mercury 730 oblong movable sieve power jig used at 503 classifier at 48, 49, 413 hand picking at 503, 203 mill at 1087, 1099, 1102, 1135 Sacreens at 304, 365 sieve scale at 304, 365 reight, cost of 1554, 1564 Freight, cost of 1553, 1554, 2027 Freight, cost of 1553, 1554, 2027 sand pumps 1266 Freight, cost of 1553, 1564, 1769, 1769, 3109 sand pumps 1811, 1812, 1830, 1885, 1886 Friability of minerals, affected by calcining 9 separation by 830 under a blow 1611	sorting by	Frue vanners. See also Vanners
Separation by	tube investigation 465	
Freezing of stone, effect on strength	use made or, in muls	at mills. 1625, 1627, 1662, 1689, 1694, 1695, 1703,
Freezing of stone, effect on strength		1704, 1711, 1712, 1755, 1844, 1865, 1868, 1870,
Freezing of stone, effect on strength 301 description of 645 point of mercury 730 freiberg, Bilharz jig at 503 for testing 1158 Septemberg, Bilharz jig at 503 dolong movable sieve power jig used at 503 modification of 661 classifier at 486, 492 mill at 1087, 1099, 1102, 1135 modification of 668 mill at 1087, 1099, 1102, 1135 water used in 059 saxony, mill at 958, 1174, 1177, 1179, 1183 screens at 367 sieve scale at 367 skimming jigs at 576 Stein, Bilharz and Luhrig tables at 670 burned in driers 880 required by roasting furnace at Mill 138 1747 required by roasting furnace at Mill 188 1947 Freight, cost of 1553, 1554, 2027 Frenier, J. H., & Son, spiral sand pump 870 sand pumps 1587 at mills. 1630, 1708, 1755, 1756, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1769, 1761, 1	versus hindered settling	capacity of 1880, 1881, 1884, 1929, 1930
Point of mercury	Freezing of stone, effect on strength 301	description of
Colong movable sive power lig used at	point of mercury	for testing
Classifier at	oblong moveble giave power iig used et 509	m Cornwall. R. A. Thomas
Saxony, mill at 958, 1174, 1177, 1176, 1183 Saxony, mill at 958, 1174, 1177, 1176, 1183 Screens at 304, 365 Sieve scale at 367 Skimming jigs at 576 Stein, Bilharz and Luhrig tables at 670 Water used on bumping tables at 670 Fredd Engineering Company, gravity dry-process separatro 1553, 1564, 2027 Freight, cost of 1553, 1564, 2027 Freight, cost of 1156 Frenier, J. H., & Son, spiral sand pump 870 Sand pumps 1811, 1812, 1830, 1885, 1886 Friability of minerals, affected by calcining 9 Separation by 830 under a blow 1611 Seesalso Wood and Coal. See also Wood and Coal. See	classifier at	testing 1171
Saxony, mill at 958, 1174, 1177, 1176, 1183 Saxony, mill at 958, 1174, 1177, 1176, 1183 Screens at 304, 365 Sieve scale at 367 Skimming jigs at 576 Stein, Bilharz and Luhrig tables at 670 Water used on bumping tables at 670 Fredd Engineering Company, gravity dry-process separatro 1553, 1564, 2027 Freight, cost of 1553, 1564, 2027 Freight, cost of 1156 Frenier, J. H., & Son, spiral sand pump 870 Sand pumps 1811, 1812, 1830, 1885, 1886 Friability of minerals, affected by calcining 9 Separation by 830 under a blow 1611 Seesalso Wood and Coal. See also Wood and Coal. See	hand picking at	vibrations of
Saxony, mill at 958, 1174, 1177, 1176, 1183 Saxony, mill at 958, 1174, 1177, 1176, 1183 Screens at 304, 365 Sieve scale at 367 Skimming jigs at 576 Stein, Bilharz and Luhrig tables at 670 Water used on bumping tables at 670 Fredd Engineering Company, gravity dry-process separatro 1553, 1564, 2027 Freight, cost of 1553, 1564, 2027 Freight, cost of 1156 Frenier, J. H., & Son, spiral sand pump 870 Sand pumps 1811, 1812, 1830, 1885, 1886 Friability of minerals, affected by calcining 9 Separation by 830 under a blow 1611 Seesalso Wood and Coal. See also Wood and Coal. See	mill at	water used in
Screen sale at 304, 305 Sieve scale at 367 Stein, Bilharz and Luhrig tables at 576 Stein, Bilharz and Luhrig tables at 670 Freid Engineering Company, gravity dry-process separation by company, gravity dry-process s	Sevent miles 059 1174 1177 1170 1199	without previous classification, use of 2023
sieve scale at	screens at	hurned in driers 900
water used on bumping tables at	sieve scale at	consumption by Wilfley roasting furnace 1548
water used on bumping tables at	skimming jigs at	required by roasting furnace at Mill 138 1747
1811 1812 1812 1814 1812 1815 1815 1815 1815 1811 1812 1815 1815 1811 1812 1815 1811 1815 1811 1815	Water used on humping tables at	
1811 1812 1812 1814 1812 1815 1815 1815 1815 1811 1812 1815 1815 1811 1812 1815 1811 1815 1811 1815	Freid Engineering Company, gravity dry-process sep-	Full teeter velocities of quartz and colons table of 1420
Freight, cost of 1126 The history of the Homestake mills 2041 French Rand Mining Company mill T. Dupont 2039 Frenier, J. H., & Son, spiral sand pump 870 870 870 sand pumps 1588 4170 870 870 870 at mills 1630, 1708, 1755, 1756, 1761, 1769, 1779, 1811, 1812, 1830, 1885, 1886 1811, 1812, 1830, 1885, 1886 1811 1812, 1830, 1885, 1886 Friability of minerals, affected by calcining 9 9 1811 1812, 1830, 1885, 1886 separation by 830 1611 1811 1811 1811 1811 1811 1811 separation by 830 1611 18	arator	1431
Freight, cost of 1126 The history of the Homestake mills 2041 French Rand Mining Company mill T. Dupont 2039 Frenier, J. H., & Son, spiral sand pump 870 870 870 sand pumps 1588 4170 870 870 870 at mills 1630, 1708, 1755, 1756, 1761, 1769, 1779, 1811, 1812, 1830, 1885, 1886 1811, 1812, 1830, 1885, 1886 1811 1812, 1830, 1885, 1886 Friability of minerals, affected by calcining 9 9 1811 1812, 1830, 1885, 1886 separation by 830 1611 1811 1811 1811 1811 1811 1811 separation by 830 1611 18	size of feed for	Fulton, C. H., cyaniding in the Black Hills 2033
Frenier, J. H., & Son, spiral sand pump 870 sand pumps	French Rand Mining Company will T Dynam 2020	the history of the Homestake mills 2041
Framulty of micrais, anected by calcining 9 Furmar, H. van F., amalgam 788 separation by 830 amalgamated plates 735 under a blow 1611 amalgamating pan 291	Frenier, I. H., & Son, spiral sand numb	Tron Works breaker of Blake type
Framulty of micrais, anected by calcining 9 Furmar, H. van F., amalgam 788 separation by 830 amalgamated plates 735 under a blow 1611 amalgamating pan 291	sand pumps	distributor at Mill 126
Framulty of micrais, anected by calcining 9 Furmar, H. van F., amalgam 788 separation by 830 amalgamated plates 735 under a blow 1611 amalgamating pan 291	at mills 1630, 1708, 1755, 1756, 1761, 1769, 1779,	mechanical batea
separation by 830 amalgamated plates 735 under a blow 1611 amalgamating pan 291	Friability of minerals affected by coldining	rolls
under a blow	separation by 9	amalgamated plates 788
	under a blow	amalgamating pan
	40	



Pages 1199-1610, Vol. III.	IND	EX.	Pages 1611-2052, Vol. IV.
Furman, H. van F., amalgamation and concentration for gold and silver and S. R. Krom, pneumatic concentration arrastra Blake, Dodge, Comet, Schranz breakers breakers Bryan mill capacity of jigs clean-up pan Crawford mill cyaniding	1173 838 290 58 58 295 597 291 295	Galland coal bree Gallium, atomic Gallon	e ores at Broken Hill, separation of 1611 ne, crushed by rolls 66 aker 2006 weight of 1188 of 187 of 188 stellars 187 used on amalgamated plates 752 classifiers 1144 relevators 862
Cyclops mill edge runners gold amalgamation gravity stamps Griffin roller mill Huntington mill jigs material for jig screens Morning mill, Mullan, Idaho, and Hecla mill,	294 295 1179 225 297 297 642 545	Gangue minerals Chapter XX. Gantry clam shell 167. Garde, A. G., Ne Gardiner breaker Garfield Chili mil at Mill 167	in mills. See Individual Mills in in mills. See Individual Mills in in s for loading concentrates at Mill is for loading concentrates at Mill is for loading concentrates at Mill is 50 cm in 1858.
Paddock jig at Frisco, Utah practical assaying Roger's rolls sample grinder spitakasten, Frazer & Chalmers deep pocket classifier, cone classifier, made by Colorado Iron Works, Carkeek classifier testing of gold ores	292 477 2048	Screen and Smelting Con Garland wire-rope Garnet rock, weal separated by specific gravi treated on H. Garn, M	ysis of product 1307 apany, Silver Lake mill 1771 e disc conveyor at Mill 124 1605 thering of 831 magnets 790 ty of 1189 coper air jig 505, 824 effect of varving speed on percent
Furnace for drying heating for decrepitation melting roasting at mills for magnetism Furnaces, roasting Future of ore dressing G	829 784 1862 815 1545	or undersize in Gas engines power plant a Gasoline engines Gassaway, A. D., the Magalia dri Gate and dam dis for jigs height	crusning 2017 tt Mill 172 1091 plates, riffles, and sluice plates at ft mine 789 charges, center discharges 582 of dam 579
Gaetzschmann, M. F., amalgamating pans. amalgamators arrastra Aufbereitung Ball and Wilson stamps ball mills Bogardus mill Carr disintegrator classifiers cone mill	203 202 298 476 202	on jigs ratio o side dis tail dis Sates	te
gravity stamps grist mill or buhrstone mill hammers, breakers, roasting for friability for breaking hand picking Hughes pneumatic stamp	315 295 639 1173 223 291 56 11 492 143	at mills1 compared v description details of on "choke with short l at Mill canvas plant of the Ko	635, 1661, 1700, 1710, 1713, 1716, 1727, 1708, 1817, 1818, 1821, 1828, 1853, 1857, vith McCully 45 38, crushing 48 and concaves 1208 165 1017, 1184, concept Mining and Milling Com-
Nicholas pulverizer pneumatic concentration riddles and trommels roll speeds schleudermühle sledging, spalling, and cobbing hammers slime tables, bumping tables, buddles trough washers and wash trommels various obsolete breakers Whelpley & Storer pulverizer Gagnon ore sizing test on jid stillings	202 837 384 87 209 56 727 334 209 607	cast-iron head classifier economic rolls feeder for rolls ore bins G. G. G	nili
Galena and quartz, jig tests on used for film sizing tests blende ore, Missouri, sizing tests on treated at Diepenlinchen crushed by rolls. cost of hand picking of. extraction plant at Mill 130 free-settling velocity.	1189 620 707 303 670 62 488 1720	patent vann gunlock mang breakers hydraulic class Iron Works, h Blake bre breaker iaw mo	anner 653 er belt 650 ganese-steel mantles for gyratory sifier 477 eveled rolls 71 aker 23 vements 34 tf jigs 597 we tests of jaw and spindle
hindered-settling tests on 612, in dolomite, crushed in Mill 25 47 in Missouri, treatment of O. M. Bilharz 2 Iron Works, Blake breaker at Mill 148. Kansas, mill at 901, 902, 1 ore, weight of pulsion jig test on roasting furnace separation from quartz settling velocity of 480, specific gravity of	1792 1179 1190 624 1548 720 409	estimate of Lowry Nation on design of friction in wearing power for ji rolls	of cost of crushing 51 onal breaker 45 cams 196 rolls 97 aurts of breakers 48 gs 63 87 38 73 87
-x granty or ittititititititititititititi	41	aprings	74

Gates Iron Works, Tremain steam stamp 136	Gilpin County shoes and dies 18
vanner	stamp mill
in mercury traps	practice
wells 768	stamps
on Tremain stamp	in
P. W viii	Girard water turbine 97
rolle 100 111	Girders for Nordberg steam stamp 124
at mills	Giroux Consolidated Mines Company 186
rule for power used in crushing	mill, Elv. Nevada. W. R. Ingalls 203
tube mill	Gladolinium, atomic weight of
vanner	Glasdir mine. Wales, mill at
Gauges	oil process at
for brass and iron wire	oil process at
screens 171 172	iig
water films	jig
wire and plate	table for film sizing tests 70
Gavet argentiferous galena at Villefort France 1178	testing
Castelnau belt table	Glendale, jigs at
Geared rolls	Montana, mill at
at Mill 183	Glenn, Wm., sampling
Gearing 1096	Glenn, Wm., sampling 88 Glidden, J. T., Woodbury jig 202
for gravity stamps	Globe battery stem guide
Gears for amalgamating pans	guides for stamps 15
trommels	iron stamp guide
sand wheels	iron stamp guide
Gebrüder Sulzer centrifugal pump at Mill 118 1678	Clustering for respire tons
Geddes & Bertrand mill, sizing test on crushed ore 100	Crackling A Laboratic ball will 20
	Glycerine for respirators 110 Gmehling, A., Lohnert's ball mill. 29 Lord & Banfield, Wood machines. 83
Geldenhuis Deep mine saying by hand picking 487	Gmelinite, specific gravity of
mill, details of stamps 221	
	Gneiss, weight of
of the Milwaukee Mining Company xxvi	Edison's concentrating plant
separator, Lockhart's automatic	
General considerations about breakers and breaking. 47	rolls
of jigs	1565, 161
regarding costs of producing lead 1974	Gold, action of gravity stamps on 314
construction of rolls	amalgam
expenses	used in preparing copper plates
ideas on milling	amalgamated plates used in milling 178
milling ideas, bibliography for	and silver in amalgam, proportions of 762
practice in the Witwatersrand, South Africa. 1643	proportions of, caught on plates 763
principles	retained by amalgamated plates 750
governing costs	retained by amalgamated plates
of ore dressing	assay for in Mill 55
pulsion	Mill 68
suction	atomic weight of
remarks upon jaw breakers	Bluff Mining Company, plant of 1654
table of roll data from the mills	Bluff Mining Company, plant of 1654 Coins Mines Co. 1133
Genesee-Vanderbilt mill xxv, 893	combination mills
Gentle Annie millxxviii 1035	combination mills
Geometrical ratio for sieve scale 987	condition of
Georgetown, Colorado, Krom jigs at	COSE OF DECISION 1974
Georgetown, Colorado, Krom jigs at 838 George V. Cresson Company 23, 72 Georgia stamp mill, an old time. W. S. Yates 2036 gold milling in. H. V. Croll 2043 Georgia stamp mills and time with the colorage of	dredges, metal riffles used on
Georgia stamp mill, an old time. W. S. Yates 2036	dredging1179
gold milling in. H. V. Croll	in general 1009
Germanium, atomic weight of	plant 1007
German mas. C. blomeke 2034	tables for
mills	fineness in bullion
arrangement of	hydraulicking and dredging 1006
cost of milling	in amalgam 767
labor in	sluices, distribution of 2044
overflow battery	Snake River, Idaho, recovery of fine. R. N.
stamps 230	
sweeping table 703	2046 Strained mercury 781 tailings, a trap to save coarse. P J. Johnson 2024 King amalgamator 777 738 mill, Gladstone, Colorado. G. P. Scholl 2042 left in retorted mercury 788 loss of 786 by use of cyanide. B. C. Wilson 2024 milling. W. R. Ingalls 2040 Dools on 2040 tailing 2040 tailing
tests on strength of stone	tailings, a trap to save coarse. P J. Johnson . 2024
Gernet, A. von, definition of slimes	King amalgamator
Gersdorflite, specific gravity of	mill, Gladstone, Colorado. G. P. Scholl 2042
Geyer, R., concentrating lead and sliver at Silberau. 1177	left in retorted mercury 788
roll	loss of 786
sime setting apparatus	by use of cyanide. B. C. Wilson 2024
settler 460 G. G. Gates' hydraulic classifier 418	milling. W. R. Ingalls 2040
G. G. Gates' hydraulic classifier	books on
Giant rock breaker 22	cost of
rolls, Edison's 105 Gibbonsville, Idaho, mill at 1028, 1181	details on modern. G. P. Scholl 2035
etemps of	in Bendigo. H. C. Bogdell
stamps at	Mexico, cheap. H. L. Collins 2033
Gibs for stamp tappets	1908. A. James 2048
Gilchrist, L. Carr disintegrator	notes on modern
Gilchrist, J., Carr disintegrator 298 Peter S., test of American Process Company's drier 1599	small steam stamps used for
Guion, A., Cyclone pulverizer	mill test
on preakers	mill with gravity stamp and canvas table 1038
on breakers 61 Gilpin County bumping table	piates and no vanners 1017
With screens attached 342	plates and no vanners
	and of grazily deed in
migs in	
	using plates, vanners, and canvas or blanket
mining in	tables
milling in	using plates, valuers, and canvas or blanket tables
mills, acid water	tables 1029 with gravity stamps 1013
miling in	using places, vaniers, and canvas or blanket tables

Pages 1199-1610, Vol. III.	INL	DEX.	Pages 1611-2052, Vol. IV.
Gold obtained on canvas tables ores crushed by arrastra Bryan mill rolls stams stamps Gunnison, products of stamping improvements in the mechanical treatment of W. J. Adams mills for . 1013, 1014, 1017, 1018, 1029, 103 process of separating by clean-up pan proportion of gold and silver on successiv plates in daily and hard amalgam screening test on, at Mammoth testing percentages recovered in different parts of th mill Prince mill Animas Forks, Colorado. G. P. Scholl and R. L. Herrick Silverton, Colorado. H. J. Barm mine and mill, Colorado. G. P. Scholl and R. L. Herrick quartz mills, distribution of machines in ratio of, to silver in plate amalgam recovered by mercury traps from ashes waste 482, 70 on cocoa matting cradle plates rilles in Mill 56 retained by copper plates plates saved on Wilfiey tables in western Chihuahua saving fine, on Snake River, Idaho. W. H Washburn separation from quartz by amalgamated coppe plate specific gravity of native pure stamping advantage of using mercury in stamp mills 1100 Clean-up barrel in suggestions for saving flour. R. P. Hall treated on outside amalgamated plates value of recovered by sweating Golden concentrating plant, plain transverse troughs or rilles in mill Gate table Star mill, mercury trap in mortar order of drop screens in stamp clean-up Goldfield Consolidated Mines Company. Combi- nation mill of Goldrinnen Goddate, C. W. Anaconda classifier Chill mill cleaning base amalgam concentration at Butte crushing by rolls steam stamps milling Huntington mill versus rolls ig tailings at Butte ore dressing of jig huches specific friffin roller mill	. 701 . 238 . 272 . 135 . 139 . 135 . 139 . 135 . 139 . 135 . 2046 . 763 . 284 . 1167 . 784 . 1167 . 1784 . 1167 . 1784 . 1167 . 1784 . 1167 . 1784 . 1189 .	Göthite, specific Gottesgabe mill jigs at. stroke of Gould centrifug Mill I Goupiliter, Ha blast ma Carr disi Cours di Crushing gravity si grizzlies in ammers for bre hand pici jaw breal movable rolls schemes siphon s draulic spalling a Vapart di Gouverneur rots chemes siphon s draulic spalling a Vapart di Gouverneur rots Govard, G. Mon on roasti manger di Govard di Gover mill, and chuck ble cost for v plates in screens ir screens ir screens ir sizzing and stamp carading analysi Gradet crushing by rolls sizzing and Grading analysi Gradeter, A. E., Grain, equivaler Grains, measure Gram, equivaler Granherry, J. I N. Y Granhy Consolid hand jig Granhy Consolid weight of Graphical representation of Inderessizing the crushing continuous for tubricati stamp car milling at Calum paddle in m separated by specific gray treated on used in reto washing at Calum paddle in m separated by specific gray treated on Land Grass Valley, and California mill at Eureka riffless at Calum paddle in m separated by specific gray treated on I used in reto washing at Calum paddle in m separated by specific gray treated on Land Grass Valley, and California mill at Eureka riffless at Calum paddle in m separated by specific gray plates at, riffles at Calum paddle in milling in A mercury it mining in A mercury it mining in A mercury it mining in A milling in A mi	Pages 1611—2052, Vol. IV. gravity of 1189 1177 1189 1177 15
	4:	3	

Page	s 1-	643,	Vol	. I.	ORI	DR	ESSING.	Pages 644-119	7, Vol. II.
Gravel	scre	ens				339	Gravity stamps, mo	outh or feed openings in	166
sta	ump	mill fo	or cen	nent		2012	mud sills		152
W2 Zeoven	isnin F	g	edge		• • • • • • • • • • • •	1006	newton mor	rta r	
-ravit	y mu	ller. S	tanwo	od		1285	North Star	p mill	1263
-S0	reen	at M	ill 138	3		1746	mortar .	mill	161. 162
sp	ecino	, errec	t of			3	number and	neight of drop	210
Sta	imps	etman:	te of	• • • • • • • • • • • • • • • • • • • •	144,	1246	used		231
	adya	ntages	s of fo	or fine crushing		$\frac{206}{314}$	Oldnam moi	rtar	162
	anal	ysis of	Mori	or fine crushing son's curves of	the velocity of	215	order of dro	typep for	914 1974
	area	of dis	cnarg	e		209	overflow bati	tery	214
	belt :	tiontei	ner			198	Pachuca		1272
	blan	bete a	nd mi	bber sheets for i	norton blooks	$\frac{223}{148}$	parts of		181
	blow	. effici	encv	of	nortar blocks	219	placing scree	en in	170
	Boss	cam .	key to	r		1273		• • • • • • • • • • • • • • • • • • • •	
	ca	ntileve	er fran	ne for		1272	power	d purpose of action weights of parts.	204. 1274
	nea	ad for	~~~		• • • • • • • • • • • •	1271	principle and	d purpose of	113, 1262
	or	head	Rer		• • • • • • • • • • • • • • • • • • • •	185	principles of	action	144
	we	dge-gr	rip taj	ppet for		1272	proportions i	elt transmission	189; 1272
	buck	staves				154	pulp, weight	of	1191
	Calif	ornia	versus	Colorado pract	ice	215	patting on n	lew snoes	200
	cam came	snait.	••••	***************************************	• • • • • • • • • • • • •	190			
						191 1272	right and lef	t hand cams	195
	Cand	la can	ıs for			1273	running of	lotted hole screens	169
	chucl	k bloc	ks			177	screen area .	· · · · · · · · · · · · · · · · · · ·	209
	clean	-up .	••••	• • • • • • • • • • • • • • • • • • • •		201	irames	· · · · · · · · · · · · · · · · · · ·	176
	clutch	hes .	• • • • •	· · · · · · · · · · · · · · · · · · ·	195	, 196 198	openings		167
	collar	s and	beari	ngs		190	designation	n of	167
	comp	aranv	e wor	k of stamps an	1 Huntington		material ar	nd cost	172 173
	mı	ls	::.: ÷	· · · · · · · · · · · · · · · · · · ·			sectional guid	des for	1268
	omn duno:	ensati	na we	funtington mill ights for	1045	278	mortar		183 164
	cost	of crus	shing	ignis ioi	1040,	205	setting up	olash board	200
	Crock	ter's p	atent			229	shoe	Mash Doard	177 181
							and dies, s	ize, life, cost, etc.	182 183 184
•	letaii	S		· · · · · · · · · · · · · · · · · · ·	223, 224,	225	rasteneo ro) head	198
ć						170	single and do	OUDIE discharge mortare	167
c	usaa	vantag	es ot			222	size of reed .		207
·	LIVI	и шес	manis	m		107	sizing tests	oles	210 210
е	cono	mic ra	ange c	t		1276	sockets in bo	sses	187
-	fficie	ncy of	Fiallon	in ore pared with stead		207	South Africar	n practice	221
13	aise	botton	ns			134 180	Splash boards	s in	177
1	eeder	S				199	stamp stem	sh	218
1.	ınger	bar, e	cam s	ticks, and crab.		199	staves for she	oe shanks	187 186
f.	oote	scree	n for			1270	stay battery	************************	214
f	rame	auon S	• • • • •		• • • • • • • • • •	145	stem		187
g	auge	s for s	creen	s		$\frac{152}{172}$	table of weigh	hts of parts	190
g	earın	g				198	triple dischar	ge two-stamp mills	188
g	ibs a	nd ke	ys for	tappets		188	types of fram	es	209 156
9	nide	hlock	ity		••••••	152	used in Califo	ornia	231
	tim	ners				1267 1 55	velocity cards		216
g	uides	,	• • • • •	• • • • • • • • • • • • • • • •		155	versus rolls at	nd grinders	222
Į.	Iarve	y's pa	tent .			227	Walker's pate	ps	134
h h	cavy eigh:	stamp	ps at .	Mill 107		1645	water pipes		102
						212 200	required		221
E	loper	s pate	nt			200	wear of snoes	and dies	182
17	rowra	ind's i	patent			225	drop, capac	low of	218
i.	Luntii	ngton	paten	t		227	power, et	C	210
ir	on si	amn i	rican frame	practice	• • • • • • • • • • • • • • • • • • • •		of mortars .		164
Ŕ	rupr	cam	shaft	for		$\frac{158}{272}$	wire screens.		170
li.	fe of	shoes	and o	fordies	184, 185, 1	277	Gray copper and bar	angement of	1108
						216	I. W. New Zea	rite separated by decrepitate land gold dredges	tion . 829
10	eatio	ron	nain c	haft	• • • • • • • • • •	178			
Ĺ	uckli	ng's r	nortar	er Engineering	• • • • • • • • • •	197 227	Grease, ellect on me	rcury	751
m	ade	by the	Denv	er Engineering	Works Com-	441	Greased plate		1611
						278	surface action	, in mills	890
m	ainta	uning	heigh	t of drop in		200	for diamonds		000
117	ercu	rv rea	Urec	ing parts of		277	tables at will 18	58	. 1921
m	erno	1 OI 16	eaing			208 207			
						207 200	Greasiness of minana	ls	1097
m	ortar	plock	75			145	Greasy flotation		1101 1011
							use made of, 1	in mills	. 800
	uime	nsion	Q			167 165	Great Douiner Persey	Verance mina	1005
	reea	openi	nσ			166	piant, R. A	Allen	1005
	Jinin	grs				100	Fingall mine, star	mill atmp milling at the. G. E. B	974
m	oi iai	a		•••••	160, 161, 1	263	Salt Lake water,	, weight of	1188
						44	·		

Pages 1199–1610, Vol. III.	INI	DEX.	Pages 1611–2052, Vol. IV.
Greece, ancient milling in. L. De Launay	2033	Gröndal ball mill	for iron ores. G. Gröndel 2016
Greene Cananea, Mexico, concentration at. R. B. Brinsmade	20/19	versus fied	erii miii
Consolidated Copper Company, copper hand-		magnetic sepa	magnetic separators
mill, Cananea, Mexico. D. E. Wood-	1925	process for ire	1828, 1829 1837 1837 1837 1847 1857
pringe	2038	in Norway.	H. V. Hansell 2039
Greensburg, Pennsylvania, coal washing at	2039	separation	of iron ores by
Green's movable sieve jig	$\begin{array}{c} 639 \\ 1190 \end{array}$	riffle, of Card	concentrators, shape of
FILL	643	Groppel concentra Gross, John, cyan	concentrators, shape of 1483 tor. C. Blömeke 2023 ide practice in S. Dakota 1419
Greenwell's conveying grate and picking table Greenwood, California	385	Golden con	centrating plant, Colorado 1183
Gregory Bobtail mill, acid water	173	Grouping of mach	redging in the United States
T., Ferraris hydraulic classifier Grey, jig at Karwin	$\begin{array}{c} 479 \\ 642 \end{array}$		
Grey, jig at Karwin Griffin centrifugal stamp mill 234 mills	, 268 2016	table of det	y for
capacity of power required for	1636	Guanaxuaro, arras	1
in Australia life of wearing parts in Mill 105 motion of the roller. H. A. Siordet	$\frac{2013}{1636}$	(bill mill of	255, 270 269, 295 ation. 1123
motion of the roller. H. A. Siordet	2017	Guaruting work of	machines 1111
versus buhrstone mills	297	milling	oratory amalgamator, versus actual
stamps	284 236	Guide blocks for g	ravity stamps
pulverizer. bibliography for roller mill	299	rollers for belt	conveyors 860
bibliography for	297	Guides for gravity	avity stamps
Griffith's rock breaker Grill four-compartment direct heat drier	59 1596	sections types of	1
Grinders, Braun sample grinder	1182	stamp stems	3, iron 2012
		materials of	15K 150
classification of	1410	Guiding the belt of	ul, life, lubrication
IIIIG	2015	Gun-metal screens Gunnison ore crust	n Frue vanners. 645 on batterics at Mill 185 1915 hed in Tremain stamp 139
details of	2016	Guston, Colorado,	mili at 803
Nevada sample	1284	Gute Hoffnung mil	der and Manufacturing Company,
purpose of	$1279 \\ 1284$	Spadone concent	ber and Manufacturing Company, rator belt
Sturtevant sample	1284 222	Gypsum, crushing	of
versus gravity slamps Grinding action of centrifugal pumps	870	specific gravity	Of 1180
amalgam	2014	Gyrating amalgam	Iontana. J. P. Rowe
fine. A. W. Warwick in amalgamating pans at Mill 105	1340 247	breakers, McC motion on med	ully
at Mill 105	1638	or spingle brea	Rers 1206
machinery 1323, machines compared with pressure pans	313	for coal	2019
at Mill 130	1790	Gyratory breakers	
Colorado Iron Works continuous pan	$1283 \\ 1282$	Austin	1910
sizing tests of pulp from	1282	Gates' cast-l	way
		style "K"	anguiese steel mannes for 1220
versus tube mills. R. Clark Grip for stamps.	200	Hadfield bre	skers at Mill 130
Grist mill	201	Krupp	1213
Grizzlies	384	McCully	9. Life of wearing parts 1212 ustment of 1218
at Mill 170	4000	range of adj	ustment of
mills . 1660, 1661, 1737, 1759, 1792, 1805, 1 1828, 1831, 1853, 1860, 1888, 1892, 1909, Denver Engineering Works Company's revolv-	1913	mill, Hathaway	ed product
IUE +	1858		2020
for dredges	1012		H
life of	340	Habermann, J., Bri	nk and Hübner disintegrator 298 shells at Przibram 111
picking on purpose of shaking, at Mill 124	491 340	Dingey mill.	202 203
Vibrating	1690 345	double rolls	at Przibram 111
Grizzly bars, forms of	227	une nus and	at Przibram 1185 Salzburg tables 641
Groke's ball mill Gromier, G	1178	graded crush gravity stamt	ing
hand picking spathic iron ore at Allevard, France	492	Heberli mill.	292 achment 292
on roasting for friability roasting iron ore at Allevard, France spathic iron ore at Allevard, France	58	iron <i>versus</i> w	700den stamps
spathic iron ore at Allevard, France	1178	Neuerberg tr	532 ommel

TY 1 Y 1	
Habermann, J., ore dressing at Raibl 1177	Hammond cylinder feeder for gravity stamps 199
pistons	dredge at Nome Beach
power for jigs	Mfg. Co., two-stamp mill
proposed concentration mill at Przibram 1177	roller feeder
crushing plant at Przibram	Hancock, H. R., inventor of Hancock jigs 1440
rolls and grinders 110	jigs
at Przibram	at mills1710, 1711, 1846, 1847, 1869, 1870, 1871
Schwarzmann's rolls, Neuerberg's rolls,	Mine La Motte
for crushing coal	for dredges
for graded crushing 110	punchings as bed for 1459
in a lead mill	versus Evans jigs at Mill 162
shells in two sections	
versus stamps	Evans jigs
Salzburg table	Michigan, mill at
Schranz mill	Hanctin's mill 285
separator at Przibram	bibliography for
stamps at Przibram 229	Hand breaker for testing
Stefan mill at Przibram 1177	breaking
trommels and jigs at the Anna mill, Przibram 1177	advantages of
screens 385	and picking
zinc ores at Raibl 1185	electromagnet
Habets, A., Baum jig for coal	feeding
Hadfield, R. A., manganese steel for jaw and cheek	for gravity stomps 100
plates 57	for gravity stamps
on breakers	jig mills
ordinary versus manganese steel for jaw plates 60	Jigs
Blake breaker at Mill 134 1733	192
hreaker 9000	1150
breaker	operation of
	skinning of 497
rolle at Mill 134	speed, labor, and capacity 499
Heile gold mine Chili mill at	pan 1152
North Carolina mill at	with flange
rolls at Mill 134	picking. See also Picking.
	picking
purifying mercury at 785 Mining Company 1621 Halk breaker 2009	advantages of
Mining Company	after breaking by nammers
maik Dreaker	an equation for
Hall breaker	assisted by layers on belt conveyor at Mill 145. 1781
R. G., sizing test of roll product	trommels and belt conveyor at Mill 145 1781
stamp mill in Danionega district	at Clausthal
Hallett, S. I viii	Cripple Creek Colo 9091
Hallett's hand jig	Mill 176!
on extent of crushing desired	belt, rope and plate conveyors for 489
fine crushing 1004	bibliography for
form of launders 873	breaking for
power used for crushing	combined with screening on grizzlies 340
roll speeds 88	comparison of picking tables
screens in concentrating	COST OT
screen versus hydraulic sizing	definition of
testing jigs	general considerations on
table	10 mus
three mineral separation in Mill 49	use made of
Hallett's hand testing jig 1180	mine
rialidie's corrugated stamp screens	rock house
maise, E., amaigamated plates	South Africa 402 2021
copper plates versus silver plates for amalga-	South Africa
mation	light for
tests on loss of gold with plain copper plates 749,	limits of
750	mathematical discussion of
Hamboic classifier 2020	mathematical discussion of
Hammer and spring mechanism for jigs 536	nugget copper in Mine 44
drop for cleaning mass copper	
for breaking	on steam stamps. 129 picking chutes. 489
cobbing	revolving circular tables
at Mill 186	shaking tables
kieves 726	shaking tables
scaling plates	
sledging 10	
and spalling 480	tables for
spalling, and cobbing	tests
spalling	sampler for slime table
and cobbing	dipper or bucket semale
steam for cleaning copper rock	dipper or bucket sample
used in hand picking	grab sample
Hammerswäsche mill 1177 jigs at 597, 641	moisture samples
jigs at	pipe sampler
stroke of jigs in	
Hammond, J. H.	sledges
amalgamated plates 725 757	kinds 10 sorting tests at Mill 162 1842
cost of gold milling	weekens for plant and 1842
plating copper plates	
Stroke of jigs in	
gravity stamps	Handles for hammers 11 Handling concentrates at Mill 178 1881
mercury used in stamping 226, 226	Hanna M & M Common and 173
milling in the Transyaal 2022	
plates and trans	Honcell N. W. 2043
riffles	rado 2048 Hansell, N. V., study of water jigs 1463
	Hanson, P., on Tremain stamp 139 Hard amalgam 750 causes of 761, 767 on plates 760
tables for supporting plates 735 breaker, descriptions of the new 2051	causes of
breaker, descriptions of the new	on plates
	780

Pages 1199-1610, Vol. III.

Haussner, A., curves for lifting cams Haverstraw sandstone, compressive strength of Hayden, Ralph, free-settling velocities Head center, Gates cast-iron, for gyratory breakers for gravity stamps spindle breakers turbine water wheels motion of Card concentrator New Standard concentrator	
Havaretraur candatone commenced the first	
	228
Harrier Delah for a compressive strength of	300
ranyden, Raiph, free-settling velocities	1421
mead center, Gates cast-iron, for gyratory breakers.	1220
for gravity stamps	185
spindle breakers	16 47
turbine water wheels	1000
motion of Card concentrator	1400
New Standard concentrator Overstrom table Willley slimer	1400
New Standard concentrator	
Overstrom table	1485
Willey slimer	1504
table	1466
plunger jig	510
plunger jig. Heard, John, Jr. concentrating antimony on Paddock jig. Krom jig. and Paddock jigs Paddock air jig. Sturtevant mil. Heat and quenching for breaking rock effect of on amalgamation	518 288
concentrating entire and an De Jalana, the	200
Variable and mony on Pandock Jig	838
Krom hig	825
and Paddock jigs	838
Paddock air iig	823
Sturtevant mill	208
Heat and quenching for breaking rock	~~~
effect of on ampleamenting fork	700
enect of our antalgamation	, 700
setting	474
slimy water	1414
settling slimy water strength of stone	302
to change porosity	Ā
to change porosity used for settling line slimes	1147
in straining amalgam	7771
in straining amalgam Heating for decrepitation	781
file title	829
friability	56
in magnets	795
the mill	1008
to change magnetism	1000
form mornatic axides of iven	010
There adults a	919
ricavy solutions	1174
testing by	1993
Heberle, E., Heberli mill	292
limit of screening	369
ore dressing at Falun Sweden	1177
discharge for jieg	7801
etampe at Palus Caralas	001
Trabagle O assessment Sweden	220
rieberie O, magnetic separation at Friedrichssegen.	834
Eleberit and Grondal mills compared	2013
magnetic separator	799
mills	257
hibliography for	, 200
compared with Solvens wills	000
none positived for	292
power required for	200
tests on work required by	305
versus rolls	258
system of trommels	984
such managed to the second to	
wet magnetic separator	810
Fleberwasche 421 479 520	810
Heberwasche	810 610
Heberwasche 421, 478, 520 used at Mechernich	810 610 477
Heberwasche 421, 478, 520 used at Mechernich Hecla mill 1179,	810 610 477 1892
Heberwasche 421, 478, 520 used at Mechernich Hecla mill 1179, jigs in	810 610 477 1892 642
friability in magnets. the mill to change magnetism. form magnetic oxides of iron Heavy solutions testing by	810 610 477 1892 642 1688
Heberwasche 421, 478, 520 used at Mechernich Hecla mill 1179, jigs in Mining Company Heclon breaker	810 610 477 1892 642 1688 2009
Heberwasche 421, 478, 520 used at Mechernich Heela mill 1179, jigs in Mining Company Heelon breaker Heetor mill	810 610 477 1892 642 1688 2009
Heberwasche 421, 478, 520 used at Mechernich Hecla mill 1179, jigs in 1179, Heclon breaker Hector mill 120mpany Heclon breaker Mining Company mill 220mpany 220mpany	810 610 477 1892 642 1688 2009 1184
Heberwasche 421, 478, 520 used at Mechernich Hecla mill 1179, jigs in Mining Company Hector mill xxvii, Mining Company mill xxvii, Hedburg, E., hand ligs and Cooley if it is continued.	810 610 477 1892 642 1688 2009 1184 1014
Heberwasche 421, 478, 520 used at Mechernich Hecla mill 1179, jigs in 1179, Heclon breaker Hector mill xxvii, Hodburg, E., hand jigs and Cooley jigs in southwest	810 610 477 1892 642 1688 2009 1184 1014
Heberwasche 421, 478, 520 used at Mechernich Hecla mill 1179, jigs in Mining Company Hector mill xxvii, Mining Company mill xxvii, Hedburg, B., hand jigs and Cooley jigs in southwest Missouri	810 610 477 1892 642 1688 2009 1184 1014
Hector mill xxvii, Hector mill xxvii, Mining Company mill xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri ijg	2009 1184 1014 643 2022
Hector mill xxvii, Hector mill xxvii, Mining Company mill xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri ijg	2009 1184 1014 643 2022
Hector mill xxvii, Hector mill xxvii, Mining Company mill xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri ijg	2009 1184 1014 643 2022
Hector mill xxvii, Hector mill xxvii, Mining Company mill xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri ijg	2009 1184 1014 643 2022
Hector mill xxvii, Hector mill xxvii, Mining Company mill xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri ijg	2009 1184 1014 643 2022
Hector mill xxvii, Hector mill xxvii, Mining Company mill xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri ijg	2009 1184 1014 643 2022
Hector mill xxvii, Hector mill xxvii, Mining Company mill xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri ijg	2009 1184 1014 643 2022
Hecton breaker Hector mill Mining Company mill Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills . 1621, 1624, 1632, 1640, 1098.	2009 1184 1014 643 2022 2630 177 212 129
Hecton breaker Hector mill Mining Company mill Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills . 1621, 1624, 1632, 1640, 1098.	2009 1184 1014 643 2022 2630 177 212 129
Hecton breaker Hector mill Mining Company mill Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills . 1621, 1624, 1632, 1640, 1098.	2009 1184 1014 643 2022 2630 177 212 129
Hecton breaker Hector mill Mining Company mill Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills . 1621, 1624, 1632, 1640, 1098.	2009 1184 1014 643 2022 2630 177 212 129
Hecton breaker Hector mill Mining Company mill Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills . 1621, 1624, 1632, 1640, 1098.	2009 1184 1014 643 2022 2630 177 212 129
Hecton breaker Hector mill Mining Company mill Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills . 1621, 1624, 1632, 1640, 1098.	2009 1184 1014 643 2022 2630 177 212 129
Hecton breaker Hector mill Mining Company mill Hedburg, B., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills. 1621, 1624, 1632, 1640, 1 in California drop of stamps in mills. 1618, 1620, 1621, 1624, 1626, 1 gate and dam in jigs riffile cleats for Williev table.	2009 1184 1014 643 2022 2630 177 212 129
Hecton breaker Hector mill Mining Company mill Mining Company mill Medburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps of steam stamps stamps at mills. 1621, 1624, 1632, 1640, 1 1608, in California drop of stamps in mills . 1618, 1620, 1621, 1624, 1626, 1 1640, 1658, 1661, 1668, 1677, 1769, gate and dam in jigs riffle cleats for Williey table.	2009 1184 1014 648 2022 2030 -177 -212 -129 661 1677 1619 215 632 1916 1916 1468
Hecton breaker Hecton mill Mining Company mill. Mining Company mill. Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills. 1621, 1624, 1632, 1640, 1 in California drop of stamps in mills. 1618, 1620, 1621, 1624, 1626, 1 1040, 1058, 1061, 1068, 1077, 1709, gate and dam in jigs riffle cleats for Williey table. Pinder concentrator	2009 1184 1014 648 2022 2680 177 2129 1601 1677 1619 215 1315 1468 1468
Hecton breaker Hecton mill Mining Company mill Mining Company mill Mining Company mill Mining Company mill Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps of steam stamps stamps at mills. 1621, 1624, 1632, 1640, 1 in California drop of stamps in mills . 1618, 1620, 1621, 1624, 1626, 1 1640, 1658, 1661, 1668, 1677, 1769, gate and dam in jigs riffle cleats for Williey table. Pinder concentrator tailboard affecting jig capacity	2009 1184 1014 648 2022 2637 -129 661, 1677 1619 215 632, 1916 578 1468 1481
Hecton breaker Hecton mill Mining Company mill Mining Company mill Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps of steam stamps stamps at mills1621, 1624, 1632, 1640, 1 in California drop of stamps jin 1640, 1658, 1620, 1621, 1624, 1626, 1 1640, 1658, 1661, 1608, 1677, 1769, gate and dam in jigs riffic cleats for Williey table. Pinder concentrator tailboard affecting jig capacity on jigs Finite in the state of the stat	2009 1184 1014 648 2022 2630 177 1212 1001 1677 1615 578 1468 1468 1468 1468 150
Hecton breaker Hecton mill Mining Company mill Mining Company mill Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps of steam stamps stamps at mills1621, 1624, 1632, 1640, 1 in California drop of stamps jin 1640, 1658, 1620, 1621, 1624, 1626, 1 1640, 1658, 1661, 1608, 1677, 1769, gate and dam in jigs riffic cleats for Williey table. Pinder concentrator tailboard affecting jig capacity on jigs Finite in the state of the stat	2009 1184 1014 648 2022 2377 -129 661, 1619 1619 1618 1481 601 504
Hecton breaker Hecton mill Mining Company mill Mining Company mill Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps of steam stamps stamps at mills1621, 1624, 1632, 1640, 1 in California drop of stamps jin 1640, 1658, 1620, 1621, 1624, 1626, 1 1640, 1658, 1661, 1608, 1677, 1769, gate and dam in jigs riffic cleats for Williey table. Pinder concentrator tailboard affecting jig capacity on jigs Finite in the state of the stat	2009 1184 1014 648 2022 2377 -129 661, 1619 1619 1618 1481 601 504
Hecton breaker Hecton mill Mining Company mill Mining Company mill Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps of steam stamps stamps at mills1621, 1624, 1632, 1640, 1 in California drop of stamps jin 1640, 1658, 1620, 1621, 1624, 1626, 1 1640, 1658, 1661, 1608, 1677, 1769, gate and dam in jigs riffic cleats for Williey table. Pinder concentrator tailboard affecting jig capacity on jigs Finite in the state of the stat	2009 1184 1014 643 2022 2037 212 -120 1677 1619 215 1468 1468 1468 1468 1468 1468 1468 1468
Hecton breaker Hecton mill Mining Company mill. Missouri Jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills. 1621, 1624, 1632, 1640, 1 1098, in California drop of stamps in mills. 1618, 1620, 1621, 1624, 1026, 1 1640, 1658, 1601, 1608, 1677, 1769, 1684, 1685, 1687, 1688, 1687, 1688,	2009 1184 648 2023 2177 212 120 1661 1677 1619 2032 1916 578 1481 601 5034 1178 2034
Hecton breaker Hecton mill Mining Company mill. Missouri Jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills. 1621, 1624, 1632, 1640, 1 1098, in California drop of stamps in mills. 1618, 1620, 1621, 1624, 1026, 1 1640, 1658, 1601, 1608, 1677, 1769, 1684, 1685, 1687, 1688, 1687, 1688,	2009 1184 648 2023 2177 212 120 1661 1677 1619 2032 1916 578 1481 601 5034 1178 2034
Hecton breaker Hecton mill Mining Company mill. xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills. 1621, 1624, 1632, 1640, 1 1608. in California drop of stamps in mills. 1618, 1620, 1621, 1624, 1626, 1 1640, 1658, 1661, 1608, 1677, 1769, gate and dam in jigs riffle cleats for Williey table. Pinder concentrator tailboard affecting jig capacity on jigs Heinstein's ball mill Helena & Frisco mill Gem, Idaho, tree of the. W. M. Edwards Mining Company mill zinc concentrator, the new	2009 1184 648 2023 2177 212 1661 1677 1619 2032 1916 578 1481 601 5034 1178 2034
Hecton breaker Hecton mill Mining Company mill. xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills. 1621, 1624, 1632, 1640, 1 1608. in California drop of stamps in mills. 1618, 1620, 1621, 1624, 1626, 1 1640, 1658, 1661, 1608, 1677, 1769, gate and dam in jigs riffle cleats for Williey table. Pinder concentrator tailboard affecting jig capacity on jigs Heinstein's ball mill Helena & Frisco mill Gem, Idaho, tree of the. W. M. Edwards Mining Company mill zinc concentrator, the new	2000 1184 1014 2022 2030 1177 1212 1061 11619 215 1081 1081 1081 1081 1081 1081 1081 10
Hecton breaker Hecton mill Mining Company mill. Xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills. 1621, 1624, 1632, 1640, 1 1698, in California drop of stamps in mills. 1618, 1620, 1621, 1624, 1026, 1 1640, 1658, 1661, 1668, 1677, 1769, gate and dam in jigs riffle cleats for Willey table. Pinder concentrator tailboard affecting jig capacity on jigs Heinstein's ball mill Helena & Frisco mill Gem, Idaho, tree of the. W. M. Edwards Mining Company mill zinc concentrator, the new Helical current in classifiers	2000 11184 1014 2022 2030 1177 1212 1007 1019 1019 1019 1019 1019 1019 1019
Hecton breaker Hecton mill Mining Company mill. Xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills. 1621, 1624, 1632, 1640, 1 1698, in California drop of stamps in mills. 1618, 1620, 1621, 1624, 1026, 1 1640, 1658, 1661, 1668, 1677, 1769, gate and dam in jigs riffle cleats for Willey table. Pinder concentrator tailboard affecting jig capacity on jigs Heinstein's ball mill Helena & Frisco mill Gem, Idaho, tree of the. W. M. Edwards Mining Company mill zinc concentrator, the new Helical current in classifiers	2000 1184 1014 2022 2030 2127 2122 2122 2127 1107 1107 1107 110
Hecton breaker Hecton mill Mining Company mill. Xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills. 1621, 1624, 1632, 1640, 1 1698, in California drop of stamps in mills. 1618, 1620, 1621, 1624, 1026, 1 1640, 1658, 1661, 1608, 1677, 1769, gate and dam in jigs riffle cleats for Willey table. Pinder concentrator tailboard affecting jig capacity on jigs Heinstein's ball mill Helena & Frisco mill Gem, Idaho, tree of the. W. M. Edwards Mining Company mill zinc concentrator, the new Helical current in classifiers Helicoid conveyor Helicial current in classifiers Helicoid conveyor	2000 11184 1014 2022 2030 2177 1019 1061; 1019 1019 1019 1019 1019 1019 1019 10
Hecton breaker Hecton mill Mining Company mill. xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps in California drop of stamps in California drop of stamps in California drop of stamps in mills . 1618, 1620, 1621, 1624, 1626, 1698, 1601, 1608, 1607, 1709, 1608, 1601, 1608, 1607, 1709, 1608, 1601, 1608, 1607, 1709, 1601, 1608, 1607, 1709, 1601, 16	2009 11014 643 2022 2630 1217 1217 1619 1619 1632 1618 1618 1618 1618 1618 1618 1618 161
Hecton breaker Hecton mill Mining Company mill. xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps in California drop of stamps in California drop of stamps in California drop of stamps in mills . 1618, 1620, 1621, 1624, 1626, 1698, 1601, 1608, 1607, 1709, 1608, 1601, 1608, 1607, 1709, 1608, 1601, 1608, 1607, 1709, 1601, 1608, 1607, 1709, 1601, 16	2009 11014 643 2022 2630 1217 1217 1619 1619 1632 1618 1618 1618 1618 1618 1618 1618 161
Hecton breaker Hecton mill Mining Company mill. Xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills. 1621, 1624, 1632, 1640, 1 1698, in California drop of stamps in mills. 1618, 1620, 1621, 1624, 1026, 1 1640, 1658, 1661, 1668, 1677, 1769, gate and dam in jigs riffle cleats for Willey table. Pinder concentrator tailboard affecting jig capacity on jigs Heinstein's hall mill Helena & Frisco mill Cem, Idaho, tree of the. W. M. Edwards Mining Company mill Xxvi, Zinc concentrator, the new Helical current in classifiers Helicold conveyor Helical current in classifiers Helicid conveyor Heliupon Earth mill Helmacker, R. hand picking of quicksilver at Idria, Austria.	2009 11014 643 2022 2630 1217 1217 1619 1619 1632 1618 1618 1618 1618 1618 1618 1618 161
Hecton breaker Hecton mill Mining Company mill. Xxvii, Hedburg, E., hand jigs and Cooley jigs in southwest Missouri jig magnetic separator. R. T. Clegg Height of chuck blocks discharge in stamps of steam stamps stamps at mills. 1621, 1624, 1632, 1640, 1 1698, in California drop of stamps in mills. 1618, 1620, 1621, 1624, 1026, 1 1640, 1658, 1661, 1608, 1677, 1769, gate and dam in jigs riffle cleats for Willey table. Pinder concentrator tailboard affecting jig capacity on jigs Heinstein's ball mill Helena & Frisco mill Gem, Idaho, tree of the. W. M. Edwards Mining Company mill zinc concentrator, the new Helical current in classifiers Helicoid conveyor Helicial current in classifiers Helicoid conveyor	2000 11184 1014 2022 2030 2177 1019 1061; 1019 1019 1019 1019 1019 1019 1019 10

INDEX.

Hematite, See also Iron.	High-speed rolls, advantage of
concentration of	Humboldt 12
crushed by Minnesota Iron Company 51	Krupp 123
concentration of	Krupp 12 versus Bryan mills 13 Hill, R. T., Mexican placers 20
mill for	Hill, R. T., Mexican placers
weight of	Hille, F., Bilharz spitstutte
preparation for paint	gravity stamps 25
preparation for paint 839 separated by magnets 790	gravity stamps
specific gravity of	gamator
specific gravity of	gamator
Vermillion, action of Monarch breaker on 21	material for jigs
Hemp ropes	Himmelfahrt-Fund mine, classifier at
Hendrick Manufacturing Company's screen at Mill	mill 936, 958, 1087, 1099, 1102, 1116, 1127, 113
157	\$\frac{1177}{36}\$ \$\frac{118}{36}\$ \$\frac{1177}{36}\$ \$\frac{118}{36}\$
Hendrie & Bolthoff, double-cone classifier 427	Himmelfürst-Fund mill
	mine, air concentrator at
portable stamp mill	dry concentrator at
Hendryx cyanide method at Nelson, British Colum-	Hindered settling 146
bia	and suction, final conclusions on 63
Hendy and Meyer, rolls	classifiers, deep-pocket
Challenge feeder used in Huntington mill 278 feeder	shallow-pocket
feeder 853 concentrator 683	defined
feeder	general principles
for gravity stamps	in kieves
rolls	pan concentrator
gold hand pan 1184	on jigs 49
Machine Works, Blake breaker	ratio, theoretical value of 142
mechanical batea	on jigs
on design of cams	ratios
two-stamp mill	testils of tubular classifier tests on 61.
Henninger's limonite washer	tests
Henry, A., breakers	use made of, in mills
capacity of jigs 597	versus free settling 143
dressing lead and zinc in Belgium and the	washer 52
Rhenish provinces	Hinged hammer pulverizer, Jeffrey
gravity stamps	Williams 132
hand breaking and jaw breakers in Belgium 57	stone breaker
Harz eccentric jigs at Przibram 641 jigging in Belgium 641	History of hydraulic classifiers
jigging in Belgium	Hoagland, M., Sons Co., rolls
ifiers, Dor classifier, and siphon separator	breaker 5 rolls at Mill 157 182 Hobson, J. B., and E. A. Wiltsee, arrastra at Smarts-
used at Mechernich 477	Hobson, J. B., and E. A. Wiltsee, arrastra at Smarts.
magnetic separation at Przibram	ville and Mooney Flat 29
ore dressing at Przibram 1176	gravity stamps
Rittinger spitzlutte at Przibram 477	Hochstedt air blast apparatus
table	Hochstrate air blast apparatus
stroke of jigs 594	dust apparatus
wash trommel	tubular classifier for coal
menry raust jigs, slope of sleves in 548	Hodge, C. J., Collom jig
width of sieves in 591	disc motion for jigs
Faust millxxv, 901	igs
Nourse Gold Mining Co., sand wheel	and Cleaves sand pumps at Mill 1821910, 191
	Classifier
nensourg, great screening tower at 2018 Hercules mill, Burke, Idaho. S. Turner 2045 rock breaker of Blake type 22 Heriog, R. and J. C. Trautwine, Jr., formula for the	jigs
rock breaker of Blake type	1910, 1911
Hering, R. and J. C. Trautwine, Jr., formula for the	differential motion for
	Hodges, A. D., amalgamating pans
naunciers	Comstock lode 291
Herrang, Sweden, Gröndal magnetic separators at . 1537	hand sampling
Herreshoff roasters at Mill 168	Jr., impurities in amalgam
Hersam, E. A., power required for crushing 1334	Hoe conveyors
power-in crushing 1340 size of opening in screens 2019	at Mill 141
size of opening in screens 2019	for skimming ligs
sources of lost power in crushing 1325 theory of crushing 2018	Hoffman 900
Hessite specific gravity of	magnetic senarator 920 925
Hessite, specific gravity of	mili 1706
	O 291
Hexagonal trommels 362	cone mill
at-Mill 183 1913	cost of milling
at-Mill 183 1913 HiBernia magnetic concentrating plant 835	magnetic concentration at the Croton iron
- min	mines
	Sturtevant mill 288
magnetic separation at 803 New Jersey, mill at 1058 Hick revolving grizzly bars 385	at Croton iron mines
	Anaconda Conner Company
tin ores in Cornwall 1180 Hidden Treasure mill xxviii, 1035	Anaconda Copper Company 1922 Blake and Gates breakers in the Black Hills 57
didden Treasure mill	Travity stamps in the Black Hills 994
actor water	grizzlies in the Black Hills 905
- moriar	hand sampling and various samplers 884 Homestake and Caledonia mortars 228 Lewis and Bartlett bag process 885
plates in 788 High-power magnetic separators 805	Homestake and Caledonia mortars 228
speed machines	Lewis and Bartlett bag process 885
48	metallurgy of lead xix


Pages 1199-1610, Vol. III.	INDEX.	Pages 1611-205	2. Vol. IV
Hofman, H. O., mortars mortar linings plates and traps in the Black Hills roasting a blende-marcasite concentrate magnetism Hog trough classifier Holsts for gravity stamps Pilling's pneumatic Holes, arrangements of in screens in screens relation of (thickness of plates at wires to diameters of, as found in the mills size of, in sieves Holibaugh, J. R., hand jigs in Missouri zinc ore in Missouri Holloway, G. T., disadvantage of the mesh desig tion Holman Brothers' Ltd. Acme table Holmes & Blanchard, buhrstone mill Holtoff, H. C. Homberg, Hochstedt apparatus at Home Run mill, Prescott Arizona, Nissen stamps Homestake mill, cam shatis cyaniding at. F. L. Bosqui dies used in dimensions of tappets in fineness of amalgam guides in history of the. C. H. Fulton life of cam shafts in shoes and dies. mortar mouth mortars plates in rate of crushing in screen frame scr	. 164, 165 787 166 787 166 787 2025 168	Pages 1611–205 power, rule for breakers steam stamps Sturtevant roll jaw breaker ore feeder - beating - do for sweating plates ter for sweating plates shing of clays on County, Michigan, mill in g for elevators, etc. olis - concentrating silver ores at H. M. und W. E. C. Eustis, magnetic pro- nickel J. and M. B. Jamieson, Collom jigs at concentrating silver ores at Hill, New South Wales stamps at Broken Hill, New Wales steam stamps at Broken Hil South Wales - steam stamps at Broken Hil South Wales di mill No. 1 - lo. 2 bibliography for ent stamp battery verizer No. 1, bibliography for ces try stamp mill aca Mining Co., size of stamp feed. 1, Prevost, decomposition of the felds; reverizer No. 1, bibliography for est stamp battery serizer with the felds and Cushman, A. S., decomposition of spars. Bartsch and Linkenlanch tables ing slimes at Tranowitz Geyler's jig ettling cylinder arles H., electrostatic separation rrostatic separator principle of action of sizes treated by. Daviot, electromagnet matic stamp pld mill. A. Lakes rida, mill at th coal breaking machine. M. J. Juli ming rolls inneering Works Company ball mill Bartsch rotary percussion table belt percussion table Blake breakers Dodge-type breakers high-speed rolls Humboldt crushing rolls magnetic separators picking table sand wheels lables at Mill 150 speed rolls A. K., roll crushing eeede, Colorado rolls stamp mills in. J. Bauer pred classifier arrastra l's revolving knife buddle stamp mills in. J. Bauer pred classifier arrastra - dra revolving knife buddle	53
Horn rotary slime concentrator, the Hornsilver Mining Co. mill Horn speedxxvii	. 201 mill . 1499 riffles . 1181 Hungary, i. 1015 U-she	stamp mills in. J. Bauer.	770 787 725, 770 2034
Horse-power. See Power also under each machine. equivalents of of Blake breakers	. 1188 bro 21, 24 Bri	arrastra li's revolving knife buddle akers	290 334 56
Forster breaker Forster breaker Gates and McCully breakers breaker McCully breaker rolls	. 28 Ca: 45 cos 38, 46 Cu	ldle jig nstone mill rr disintegrator t of crushing by rolls nnack's pulverizer to runners	208
AUMS	. 64 En	ge runners	olls 109

Hunt, R., general milling ideas			
tiunt, A., general mining ideas	1173	Hutchinson, W. S., standardization of screens Huxley, E. C., breakers	201
gravity stamps	223	Huxley, E. C., breakers	5
grist mill or buhrstone mill	291		5
Harz, Argalls, Collom, circular slime jigs Husband and Sholl pneumatic stamps, Patter-	639	Hyams, G. M. Hydraulic classifier. See Classifiers.	vi
Husband and Sholl pneumatic stamps, Patter-	•	Hydraulic classifier. See Classifiers.	
son spring stamp	143	Classifici	38
Jordan's pulverizer	299	Bilharz	47
Jordan's pulverizer Marsden breakers	56	Dalton	39
Michell and Tregoning pulverizer	294	deep double trough	41
Nicholas pulverizer	292	pocket	40
Nicholas pulverizer		double cone	42
ifier	476	extent of classification	143
Wilson's small stamp	1/19	Farmeric	40
Huntington amalgamating pan centrifugal roller mill. mills	291	Ferraris	
antaifusel selles will	791	C. C. Catar	41
centifitigat roller milli	235	G. G. Gates'hopper-shaped shallow-pocket	41
mins110, 228, 270, 1182,	1911	nopper-snaped snanow-pocket	40
as regrinding machines	-1333	measures of a four-spigot, with sorting columns	
at Butte, Montana mills: 1625, 1668, 1684, 1686, 1687, 1689, 1701, 1711, 1738, 1753, 1839, 1845, 1867,	2014	of a 3-inch pipe	40
mills1625, 1668, 1684, 1686, 1687, 1689,	1694,	purpose and essential qualities of	389
1701, 1711, 1738, 1753, 1839, 1845, 1867,	1869,	Richards' shallow-pocket	40
1870, 1871,	1897	sizes of feed to	389
bibliography for	296	trough or shallow-pocket	389
Boss, M. P	1281	Yeatman	39
roller mill	1313	Yeatman	1897
capacities of	281	giants55,	200
with various screens	1314	for phosphate	
centrifugal force in	278	Monitor	898
comparative work of stamps and Huntington		Monitor	333 204
		gord mining. G. II. Evillis	
mills	1910	jigs, compared with air jigs	824
cost of crushing by281,	, 1910	mean depth in launders	876
costs, life of, wearing parts in the. C. E.	0044	methods, discussion of. R. H. Grider	202€
Parsons	2014	mining. See under Placer.	
die rings and roller shells	280	at British Guiana. F. W. Luick	2033
dimensions and weights	280	at British Guiana. F. W. Luick by elevator. C. W. Wright	2044
feeding	1314	cost of. W. H. Radford	2033
foundations for	1313	in British Columbia	2033
Fraser and Chalmers figures on	280	California	2037
Harron, Rickard & McCone	1281	W. H. Radford	2035
improved	1311	Colorado W E Thomas	nnne
improved	2014	K. Thomas	2016
El Oro, cost of running	2014	riffler for 701	7770
general	1313	morter discharge at Mill 100	1010
general	1323	mortal discharge at will 1021909,	1817
life of screens	1317	pheumane, and spring stamps	1240
wearing parts	1217	K. Thomas riffles for mortar discharge at Mill 182 pneumatic, and spring stamps separators at Kalgoorlie mill	2034
new improved	1017	Sizings	1257
new improved	1919	the Denny	1257
number used	231	tables	1187
Power & Mining Machine Co		water for jigs	537
purpose, power and capacity	280	quantity	598
quality of work done by	1317	table of	597
screens for	1314	in classifiers	387
screen sizing test of feed and product of Hun-	1314	in classifiers	387 1006
screen sizing test of feed and product of Hun- tington mill	1314	In classiners. Hydraulicking 897.	$\frac{387}{1006}$
screen sizing test of feed and product of Hun- tington mill	1314	Hydraulicking 897, bibliography for	$387 \\ 1006 \\ 1173$
screen sizing test of feed and product of Hun- tington mill	1314	In classifiers. Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar	387 1006 1173 2045
screen sizing test of feed and product of Hun- tington mill	1314	Hydraulicking 897, bibliography for	387 1006 1173 2045 2044
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317	Hydraulicking 897, bibliography for	387 1006 1173 2045 2044
screen sizing test of feed and product of Hun- tington mill Sherman	1314 1316 1313 1317	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman	387 1006 1173 2045 2044
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer.	387 1006 1173 2045 2044 1006 2044
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests	387 1006 1173 2045 2044 1006 2044
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests	387 1006 1173 2045 2044 1006 2044
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of.	387 1006 1173 2045 2044 1006 2044 1147 752 1188
screen sizing test of feed and product of Huntington mill Sherman 1281, sizing test of pulp from 1281, sizing test of pulp from table of sizes, power, speeds, and weights of improved used in California Mill 21 near Tremnitz, Hungary valuable paper on. C. E. Parsons versus Bryan mills stamps	1314 1316 1313 1317 1312 231 413 282 2016 273	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of.	387 1006 1173 2045 2044 1006 2044 1147 752 1188
screen sizing test of feed and product of Huntington mill Sherman 1281, sizing test of pulp from 1281, sizing test of pulp from table of sizes, power, speeds, and weights of improved used in California Mill 21 near Tremnitz, Hungary valuable paper on. C. E. Parsons versus Bryan mills stamps	1314 1316 1313 1317 1312 231 413 282 2016 273 228 227	Hydraulicking	387 1006 1173 2045 2044 1006 2044 1147 752 1188
screen sizing test of feed and product of Huntington mill Sherman 1281, sizing test of pulp from 1281, sizing test of pulp from table of sizes, power, speeds, and weights of improved used in California Mill 21 near Tremnitz, Hungary valuable paper on. C. E. Parsons versus Bryan mills stamps	1314 1316 1313 1317 1312 231 413 282 2016 273 228 227	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of amalgamator Hyposulphite leaching	387 1006 1173 2045 2044 1006 2044 1147 752 1188
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 273 228 227 229	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of.	387 1006 1173 2045 2044 1006 2044 1147 752 1188
screen sizing test of feed and product of Huntington mill Sherman 1281, sizing test of pulp from 1281, sizing test of pulp from table of sizes, power, speeds, and weights of improved used in California Mill 21 near Tremnitz, Hungary valuable paper on. C. E. Parsons versus Bryan mills stamps oscillating stamp patent stamp mill theory of flotation processes.	1314 1316 1313 1317 1312 231 413 282 2016 273 228 227	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of amalgamator Hyposulphite leaching	387 1006 1173 2045 2044 1006 2044 1147 752 1188 787 1167
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 273 228 227 229 1556	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates Hydrogen, atomic weight of amalgamator Hyposulphite leaching I Ice, specific gravity of	387 1006 1173 2045 2044 1006 2044 1147 752 1188 787 1167
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 273 228 227 229 1556	Hydraulicking	387 1006 1173 2045 2044 1006 2044 1147 752 1188 787 1167
screen sizing test of feed and product of Huntington mill Sherman 1281, sizing test of pulp from 1281, sizing test of pulp from 14ble of sizes, power, speeds, and weights of improved 12 mear Tremnitz, Hungary 12 mear Tremnitz, Hungary 13 waluable paper on C. E. Parsons 14 versus Bryan mills 15 stamp 16 oscillating stamp 16 patent stamp mill 16 theory of flotation processes. Hundy Gurdy water wheels 1023	1314 1316 1313 1317 1312 231 413 282 2016 273 228 227 229 1556 1566 1089	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates Hydrogen, atomic weight of amalgamator Hyposulphite leaching I Ice, specific gravity of Ichon, separation process. Idaho, cost of mining and milling in	387 1006 1173 2045 2044 1006 2044 1147 752 1188 1187 1167
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 273 228 227 229 1556 1566 1089 1173	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates Hydrogen, atomic weight of amalgamator Hyposulphite leaching I Ice, specific gravity of Ichon, separation process Idaho, cost of mining and milling in	387 1006 1173 2045 2044 11006 2044 1147 752 1188 787 1167
screen sizing test of feed and product of Huntington mill Sherman 1281, sizing test of pulp from 1281, sizing test of pulp from 1281, sizing test of pulp from 14ble of sizes, power, speeds, and weights of improved 15 mean Tremnitz, Hungary 16 mear Tremnitz, Hungary 17 valuable paper on C. E. Parsons 18 mean Tremnits Hungary 18 mear Tremnits Hungary 18 mean Tremnits Hungary 18 mean 18 me	1314 1316 1313 1317 1312 231 413 282 2016 273 229 1556 1566 1089 1173 xx	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of amalgamator. Hyposulphite leaching I Ice, specific gravity of Ichon, separation process Idaho, cost of mining and milling in milling in dredging in	387 1006 1173 2045 2044 11006 2044 1147 752 1188 787 1167
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 273 228 227 229 1556 1566 1089 1173 xx 1619	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of amalgamator Hyposulphite leaching I Ice, specific gravity of Ichon, separation process Idaho, cost of mining and milling in milling in dredging in milling in	387 1006 1173 2045 2044 11006 2044 1147 752 1188 787 1167 1189 839 1130 1134 1009
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 227 229 1556 1566 1089 1173 xx 1619 143	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of amalgamator. Hyposulphite leaching I Lce, specific gravity of Ichon, separation process Idaho, cost of mining and milling in milling in dredging in mill in mile, Alabama mill at	387 1006 1173 2045 2044 11066 2044 1147 752 1188 787 1167 1189 1130 1130 1178 1174
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 227 229 1556 1566 1089 1173 xx 1619 143	Hydraulicking 897. bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of amalgamator Hyposulphite leaching I Ice, specific gravity of Ichon, separation process Idaho, cost of mining and milling in milling in mill in mine, Alabama, mill at amalgamation at	387 1006 1173 2045 2044 11006 2044 1147 71188 787 1167 1189 839 1130 1178 1174 1009
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 273 229 1556 1566 1568 1173 xx 1619 143 1082 586	Hydraulicking 897. bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of amalgamator Hyposulphite leaching I Ice, specific gravity of Ichon, separation process Idaho, cost of mining and milling in milling in mill in mine, Alabama, mill at amalgamation at	387 1006 1173 2045 2044 11006 2044 1147 71188 787 1167 1189 839 1130 1178 1174 1009
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 273 228 227 1556 1566 1089 1173 xx 1619 143 1082 586	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of amalgamator Hyposulphite leaching I Ice, specific gravity of Ichon, separation process Idaho, cost of mining and milling in milling in dredging in mile, Alabama, mill at amalgamation at Springs, Colorado, Cammett table at mills at	387 1006 1173 2045 2044 11006 2044 1147 71188 787 1167 1189 839 1130 1178 1174 1009
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 273 228 227 1556 1089 1173 1082 586 583 495	Hydraulicking	387 1006 1173 2045 2044 11006 2044 1147 71188 787 1167 1189 839 1130 1178 1174 1009
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 273 228 227 1556 1089 1173 1082 586 583 495	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of amalgamator Hyposulphite leaching I Ice, specific gravity of Ichon, separation process Idaho, cost of mining and milling in milling in dredging in mill in mine, Alabama, mill at amalgamation at Springs, Colorado, Cammett table at mills at pan concentrator shaking screens of	387 1006 1173 2045 2044 1106 2044 1147 752 1188 787 1167 1189 1178 1130 1174 683 677 1047
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 273 228 227 1556 1089 1173 1082 586 583 495	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of amalgamator Hyposulphite leaching I Ice, specific gravity of Ichon, separation process Idaho, cost of mining and milling in milling in dredging in mill in mine, Alabama, mill at amalgamation at Springs, Colorado, Cammett table at mills at pan concentrator shaking screens of	387 1006 1173 2045 2044 1106 2044 1147 752 1188 787 1167 1189 1178 1130 1174 683 677 1047
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 273 228 227 1556 1089 1173 1082 586 583 495	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of amalgamator Hyposulphite leaching I Ice, specific gravity of Ichon, separation process Idaho, cost of mining and milling in milling in dredging in mill in mine, Alabama, mill at amalgamation at Springs, Colorado, Cammett table at mills at pan concentrator shaking screens of	387 1006 1173 2045 2044 1106 2044 1147 752 1188 787 1167 1189 1178 1130 1174 683 677 1047
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 2311 413 2282 2018 227 229 1556 1566 1089 1173 xx 1619 143 1082 586 523 495 523 495 523 2039 2038	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of amalgamator Hyposulphite leaching I Ice, specific gravity of Ichon, separation process. Idaho, cost of mining and milling in milling in dredging in mill in mine, Alabama, mill at amalgamation at Springs, Colorado, Cammett table at mills at pan concentrator shaking screens at Idlers for belts Iddevild Gold Mining Co., mill Iddria, Austria, hand picking at	387 1006 1173 2045 2044 11006 2044 1147 752 1188 1188 1188 1189 1178 1189 1178 1179 1179
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 2311 413 2282 2018 227 229 1556 1566 1089 1173 xx 1619 143 1082 586 523 495 523 495 523 2039 2038	Hydraulicking	387 1006 1173 2045 2044 11006 2044 1147 752 1188 1188 1188 1189 1178 1189 1178 1179 1179
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 2311 413 2282 2018 227 229 1556 1566 1089 1173 xx 1619 143 1082 586 523 495 523 495 523 2039 2038	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of amalgamator Hyposulphite leaching I Ice, specific gravity of Ichon, separation process. Idabo, cost of mining and milling in milling in dredging in mill in mine, Alabama, mill at amalgamation at Springs, Colorado, Cammett table at mills at pan concentrator shaking screens at Idlers for belts Idlewild Gold Mining Co., mill Idria, Austria, hand picking at mill for quicksilver ore picking of wester at	387 1006 1173 2045 2045 2044 11064 1147 752 1189 839 1134 1178 1178 1178 1178 1178 1178 1178 117
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 2311 413 2282 2018 227 229 1556 1566 1089 1173 xx 1619 143 1082 586 523 495 523 495 523 2039 2038	Hydraulicking	387 11006 11733 2045 2044 1147 752 1188 787 1167 1189 1130 1178 1178 1178 1178 1178 1178 1178 117
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 2311 413 2282 2018 227 229 1556 1566 1089 1173 xx 1619 143 1082 586 523 495 523 495 523 2039 2038	Hydraulicking	387 11006 11733 2045 2044 1147 752 1188 787 1167 1189 1130 1178 1178 1178 1178 1178 1178 1178 117
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 2311 413 2282 2018 227 229 1556 1566 1089 1173 xx 1619 143 1082 586 523 495 523 495 523 2039 2038	Hydraulicking	387 11006 11173 2045 2044 11006 2044 1147 752 1188 787 1167 1189 839 1130 1178 677 1047 683 342 1094 1174 1094 1174 1094 1174 1094 1174 1094 1174 1094 1174 1094 1189 1194 1194 1194 1194 1194 1194 11
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 2311 413 2282 2018 227 229 1556 1566 1089 1173 xx 1619 143 1082 586 523 495 523 495 523 2039 2038	Hydraulicking	387 1006 1173 2045 1006 2044 1147 752 1188 839 1130 1134 1177 1177 1177 1047 1177 1047 1047 104
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 227 229 1556 1566 1089 1173 1619 143 2038 2037 2292 2038 2038 2038 2038 2038 2038 2038 203	Hydraulicking 897, bibliography for in Oregon. A. P. Dittmar of low-grade gravels. P. Bouery plants under artificial pressure. J. A. Yeatman See also Placer. Hydrochloric acid in settling tests used on plates. Hydrogen, atomic weight of amalgamator Hyposulphite leaching I Ice, specific gravity of Ichon, separation process. Idabo, cost of mining and milling in milling in dredging in mill in mine, Alabama, mill at amalgamation at Springs, Colorado, Cammett table at mills at pan concentrator shaking screens at Idlers for belts. Idlewild Gold Mining Co., mill Idria, Austria, hand picking at mill for quicksilver ore picking of waste at quicksilver dressing at I. Know mill I. M. Standard laboratory singe seed.	387 11006 1173 2045 2044 1147 1188 1188 1167 1189 1130 1134 1178 1179 683 342 1094 1188 1174 1188 1174 1189 1189 1189 1189 1189 1189 1189 118
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 227 229 1556 1566 1089 1173 1619 143 2038 2037 2292 2038 2038 2038 2038 2038 2038 2038 203	Hydraulicking	387 1006 1173 2045 1006 2044 1147 752 1188 1187 1167 1189 1130 1130 1178 1178 1178 1178 1178 1178 1178 1189 1178 1189 1178 1189 1183 1194 1183 1194 1183 1183 1183 1183 1183 1183 1183 118
screen sizing test of feed and product of Huntington mill Sherman	1314 1316 1313 1317 1312 231 413 282 2016 227 229 1556 1566 1089 1173 1619 143 2038 2037 2292 2038 2038 2038 2038 2038 2038 2038 203	Hydraulicking	387 1006 1173 2045 1006 2044 1147 752 1188 1187 1167 1189 1130 1130 1178 1178 1178 1178 1178 1178 1178 1189 1178 1189 1178 1189 1183 1194 1183 1194 1183 1183 1183 1183 1183 1183 1183 118

Pages 1199-1610, Vol. III.	INJ	DEX.	Pages 1611-2052, Vol. I	v.
Imperfections of deep-pocket classifiers	2209	Oity ii	ic weight of	,,,,,
Improved Huntington mill table of sizes, power, speeds, and weights	1311	concen	trates, disadvantage of	173)53
Impulse water wheels	1089	for jig mill	buildings	60 45 88
Inch, equivalents of	1187 18, 1121	frames	s for jigs	81 22
action of Indian metallic red paint mine Indicator bell on steam stamps	. 230	Gate,	Virginia, iron ore from 8	51 09
Indicator bell on steam stamps	132, 133 657	jig life o	of	55 10 04
diagrams of Nordberg single-cyclinder stean stamp125 steeple-compound stamp	m 0, 1251	tank lining :	for ore bins	22 42
for iig	632	magne manufe	pan amalgamation. 2: tic oxides of	49 13
Individual mortar mortars at Mill 165 Merrill's mortar	. 1264	Mount hydr	raulic nozzle at	20 00 34
M. P. Boss mortar Nissen mortar Rusid Fooromy	1263	mill pla	tain, Bradford jig at 56 -aulic nozzle at 895, 897, 11 at 885, 897, 11	85 73
Rapid Economy	1927	saini sizin	g tests of trommel products at	45 83
Ingalls, W. R., conveyors Ferraris ball mill. 132 Giroux mill, Ely, Nevada. gold dredging in the United States	3, 2014 . 2039	conc	centrated by magnets	98 18
		bi L	entrated by magnets 77 entration of 20 billiography for 11 ake Superior L. H. Hardenburgh 20 Nordensten 20	73 36
Macquisten process mill of the Steptoe Valley S. & M. Co., Ely Nevada milling the ore of Bingham, Utah	, 2039	cost	Nordensten 20/ of milling 112 oducing concentrates in eastern United	10
Off urying	. 1010	in Q	States	37
power required for screw conveyors Inman, A. L., multiple jaw breaker plant on breakers	. 57	wa jig fo	or 204	18
Inscribing circles for camsgravity stamps	. 196 . 216		or 51 netized by heat .799, 80 s for	36
Inside amalgamated plates amalgamation	. 178 . 223	separ treate	rated by magnets	00 34
amalgamation Inspection of jig bed Instalment plan of mills Institution of mining and metallurgy on sieve scales	. 1171	in by	log washer	30
Instructions for mounting Blake breaker Interest and depreciation on breakers	. 18			
Intermediary jig Intermediate bins	. 571 . 843	Louati	netic separation of. H. Wedding 203 ed for magnetism	4
Intermittent automatic discharge for jigs bumping tables moyable sieve power jigs	. 082	washi	magnetic oxides 81 ling of Mesabi 204 bility of 79 110 10	3
movable sieve power jigs or tank system of working amalgamating pan surface tables	. 700	pipe sizes	110	6
blanket tables carpet tables	. 703	riffles .	ngs for jig bed	2
cocoa matting Cornish "frames" German sweeping tables	703	sieve fra	bles on dredges	
Emery & Corundum Co mill 1079	. 1188	Cas	it	9
magnetic separator. separators at mills	. 1533 7, 1748	stamp f strip for	r fastening amalgamated plates	8 5
Interstitial currents, tests on	826	Wear an	r amalgamated plates	9
factor on jigs	575 10, 631	Irregularity .	of feeding 1110 oved hydraulic sizer 2020 um Co., mill 118	5
feed, slope, and water for film sizing tables pulsion and suction in mill jigs	707 632	Ivanhoe mill	um Co., mill	3 1
settling of fine grains	478 1469		1	
classified feed	1477	Jacket shaft	for gravity stamps	ä
natural feed	1471	Jackling con	or amalgamating pan	8 0 7
sized feed	1473 1156	van	mer at	3
potassium and mercury	. 1188	J. W., r	and R. L. Grider 2042 olls 111 72, 72, 72	2
Iridium, atomic weight of	1188	roll spee	eds	7
Iridosmine, specific gravity of	1189 288	discus	ssions of the tube mill	5 4
Iron-aluminum, alloy for jig beds	575 5, 751	automat	mill installation	4 2



Jigs, Cazin's	Tigs. McLanahan's
center discharge in	Jigs, McLanahan's
circular	britch and tallings
classes of 551	material of porton) hed
classiner	Marchais for tanks
180 180	method of running 551
coarse concentrates of	movable sieve hand 548
	CSUIIR
compressed air 519	New Century 1444 drop motion 537
connecting rods for	number of compartments to the second
construction of	strokes 502 operation of 500
	Usterspev
COST OF	Parsons & Fisher 517 pipe discharge in 583
cover. 537 dead box on 510	Flumb circular
depin of longitudinal partition	plunger. 528 attachment to connecting rods. 529
details of	plungers for
Diescher coal 552 difference in specific gravity of minerals for 009 different types of 2021 differential-motion, variable-crank mechanism of 1457	on
differential-motion, variable-crank mechanism	power used by 602 principle and advantages of 2022 purpose, and definitions 494
of	purpose, and definitions 2022
disc motion in	
with unwatering sieves	pulsion
disposal of concentrates in	LVDC
With one shaft	purpose and adjustments 552 range of sizes fed to 606
eccentric for	relation of sieve to fullbook
	tailings in 576
1403 slimy water	ACPAILS OIL ***********************************
	Rexroll
Dynard's	
feed aprons for	Polymon 643
Ferraris intermediate	
	Schranz
fixed sieve	Shift and differs for
three mineral separation	side discharge in
589	DAUDRET
P FRDCOU 810 049	sieve wires and prices
gate and dam discharges 577	sieves 641 size of grains of bottom bed 575
	sieve hole 573 sizing before jigging 1403
	SKIIIIIIII Or
practice in the mills	slime 518
10 10 10 10 10 10 10 10	Sieves
	snow return 533
Mean plunger form	DDHSDURY
Delgiii of date and dam	Starff that ben crank mechanism for 511
hinged connecting red for	
	black in discharges 584
Huet & Cevler's	steam driven 519 Strob's 642 study of water. N. V. Hansell 1463
hutch spigot	study of water. N. V. Hansell 1463 G. G. Bring 1463
hutch spigot 507 hydraulic water quantity in 537, 598 indicator cards of 632 intermittent automatic discharge	Stutz
intermittent automatic discharge 584 movable sieve 506	tailboards for
iron	tests on suction in
datas for bedding	
kinds of for	under-piston type
Krom's penumatic 824 Krupp Harz 1446	Utsch
ILLUOF TOP	Utsch 519, 640, 641 versus Ferraris tables. M. Lenicque. 2021 magnets 836
Lamarche and Schwarz 641 Lemière's 641	12Digs 836
lentere's	NSVANDIE OF TELES
limits of sizes treuted by	Wendt 537, 598
length of stroke 590 1/10 of 1	whole bed of, products of
Luhrig	Winners
{\ 53 <u>\</u>	magnets 836 106 107 1150
	METALLUNGY & WILLIAM
(10)	Maria
0.6	MATALA MATALANA
	TETALLUNG
	A CONTRACTOR OF THE PROPERTY O



Pages 1199-1610, Vol. III.	IND	EX.	Pages 1611–2052, Vol. IV.
Kinkead ball mill bibliography for	. 234	Krom rolling toggle b	reaker
bibliography for	4, 2014 . 2038 . 296		:
number used Kirby, E. B., jigs.	. 231 . 643	T. A. Blake,	urman, pneumatic concentration 838 improvements by Krom 59
systems of ore dressing weight of broken ore weights of ores	. 1190		73
Kirschner, L., breaking	56 56		
gold mills in Europe gravity stamps Grundriss der Erzaufbereitung	1173 223	Krom's pneuma	utic jig 839
Káván-Rittinger and Luhrig tables. Laszlo's amalgamator	729	tires	87, 88 65
magnetic separationmovable sieve hand jig, Harz and Bilharz jigs	832 639	aramina and ton	8 310
Pape-Henneberg concentrator picking tables pointed boxes, spitalutte	492	versus rolls .	######################################
Schranz millslime tables	$\frac{296}{727}$	ball mill at Mill 128 .	table
three types of rolls	109 831 2020	cam shaft	
principle ofjig, description of the	$2020 \\ 2021$	high-speed rolls .	1215
L. A., dressing asbestos moving grizzly bars Klein's solution	386	magnetic separato	r
Kley breaker Knee-frames for gravity stamps	55 7. 158	picking tables	tion, magnetic plant of
Knife for scraping plates	762	roll shell turning of sectional guides for	1202 levice 1243 r gravity stamps 1270
Knobs, rolls with	788 290	tables at Mill 128 tube mills at Mill	118 1677
California stamps	225 1177	discharge of. Krupp's wearing parts	for jaw breakers
Knop turbine Knott dredge Knowles' duplex vacuum pumps at Mill 117	973 1011 1673	Kubale, Sheppard coal Kunhardt, W. B. and	1270 1270 1280 12715 1281 1281 1281 1281 1281 1291 1281 1291 1291 1391
New Century magnetic separator		iron ores jigging tests	643
weights, etc., of	1, 922 1674		d mill separate 56 56 per disintegrator 298
Knox amalgamating pan	776 291	buddles, same to	ables, percussion tables, and
capacity of jigs	597 1177	capacity of jigs	
jigs at Gottesgabe and Hammerwäsche mills at Westphalia	641	Dingey mill drop between jis	z sieves
stamps in Comstock mills stroke of jigs H., ore dressing at Tarnowitz, Silesia.	230 594 1186	general milling .	
Empire Zinc Company	907 xxv	hand breaking a	nd picking
Köhler on jigs Kolar District, India, cost of producing gold in 1981,	643 1982, 1983	jig bed	harge
Kolshorn & Streckers grinder bibliography for Kominor mill	232 292	plunger cleara jigging unsized r	nce
Konus breaker Kootenay Ore Company, B. C., the custom mill of	2017 2010	length of jig siev	7CB 592 604
Koppel shoes and dies at Mill 97	2045 1620	Nicholas pulveri ore dressing in F	ces 592
Kosmann, Freideberg mill Propte mill Kossmann, B., Nicholas pulverizer	297 297 292	pneumatic stamp removal of jig ta	os
Krause mortar discharge for steam stamps997, 1003, at Mill 179	1256 1897	speedsrunning jigs	
pneumatic stamp Kreiss jerking conveyor Kretschmer, Franz, graphite dressing in Moravia Krogh contributed from a challe 1626 1627 1623	141 884 1183	Schranz mill settling tests	572 572 276, 296 1146
Kroga centragai pump at mins 1020, 1021, 1038, .	1929, 1930	siphon separator.	pointed boxes, spitalutte 476
Krom air jig belted rolls breaker.	824 82 56	slime tables slope of jig sieve slime tables	s 696 8 548
movement of jaws	34 31	stay boxes for ite	r discharges KK1 KOK
cushioned rolls	2010 824 824	thickness of jig t	ped 575 Idles 384
results on Seminole ore	821	wear or jig scree	ns

1 agos 1 1040, VOI. 1.	OKE D	KESSING.	Pages 644-1197, Vol. II.
Kutscher, E., jigs at Clausthal	643	Lake Superior rock hor	
ore dressing at Clausinal.	1100	slime tables at .	uses
Kutter formula for flow of water	885	Take Warm mill, power	er used at
L		Lakes, Arthur, America	na. A. G. Charleton 2035 in pebbles for tube mills 2015
Labor cost of	1130	arrastra	ting plant
IOT Drenkers	F 4	Standard mill. It	ling plant 2048
efficiency effect on costs	50	Lamar, J. R. de	1183
for arrastras	1127 239	Lamarche and Schwarz	coal jug 641
canvas tables	701	II. M., mining in 1	Sritish Columbia
cleaning plates Conkling jig	758, 760	M. R., cyaniding a	t Goldfield, Nevada 1922
dredge	898	Lamberton mill	coal jug 284 s sampler 1573, 1609 sritish Columbia 2035 t Goldlield, Nevada 1922 mill, Goldlield, Nevada 234 295 s 296 breaker, Wolf's jaw breaker 56
Hooper air iig	499	bibliography for	234 205
jigs mills	824	Brown's spindle	Samuel and Military Strates Services 56
mills	1101	Carr disintegrator	treaker, wolf's Jaw breaker 56
		classifiers for coal	
stampe	459	coarse and fine ii	gs for coal 574
stamps	206	cone mill	gs for coar
washing pans in the mills required at crushing plant of Mill 174 mills . 1619, 1621, 1622, 1628, 1638, 1 1664, 1676, 1678, 1695, 1688, 1698, 1 1712, 1730, 1739, 1745, 1757, 1759, 1 1708, 1786, 1791, 1793, 1801, 1816, 1 1827, 1830, 1835, 1841, 1848, 1852, 1 1881, 1887, 1890, 1 by sampling department at Mill 174 wage scales at mills . 1619, 1621, 1622, 16 1633, 1657, 1664, 1670, 1678, 1680, 1685, 1 1690, 1698, 1705, 1712, 1730, 1746, 1757, 17 1794, 1804, 1816, 1820, 1830, 1841, 1848, 1 Laboratory breaker, Case.	1931	grizzlies, riddles,	and trommels
mills 1619, 1621, 1622, 1628, 1633 1	1883	revolving and beli	and trommels
1664, 1676, 1678, 1685, 1688, 1698, 1	705, 1709,	Lancaster breaker	coal 109
1768, 1786, 1791, 1793, 1801, 1816, 1	761, 1764,	Company, James II	Lancaster rotary pumps 1500
1827, 1830, 1835, 1841, 1848, 1852, 1	856, 1871,	Land pebble phosphate	gold amalgamator 1520
by sampling department at Mill 174	918, 1920	Co. mill	tables 384 tables 492 coal 109 ., Lancaster rotary pumps 1589 gold amalgamator 1520 895 superstands 1779 z jigs 642 le, Pa. 642 c classifier 477 Friedensville, Pennsylvania 1178
wage scales at mills . 1619, 1621, 1622, 16	26, 1629.	Landis, H. K., blende m	ills in Missouri 1179
1690, 1698, 1705, 1712, 1730, 1748, 1757, 17	687, 1688,	jigs at Friedensvill	le. Pa
1794, 1804, 1816, 1820, 1830, 1841, 1848, 1	702, 1704, 852, 1850	Yeatman hydrauli	c classifier 477
Laboratory breaker Case 1805, 1	881, 1919	Landolt and Bornstein	Friedensville, Pennsylvania 1178
Laboratory breaker, Case	285 1323	tables	xx 1188
slime table. H. S. Munroe	2023	milling practice	with the 2014
Labradorite, specific gravity of	1137	J. A. S	tewart
sime table. H. S. Munroe tools for testing Labradorite, specific gravity of Labyrinths La Cananea, concentration at. M. Schwerin mining camp. D. E. Woodbridge Lacing for belts	447, 476	at Ropita Minin	1188 2014 with the 2014 2016 (ewart 2015 308 308 2016 201
mining camp. D. E. Woodbridge	2037	Langerfeld, A., new coal	picker
Lacing for belts	1093	Langguth, E., history of	magnetic separation 2031
Lady Barkly mill maint to	1008	Langley's crusher, bibliog	raphy for
La France Copper Company Lagging for belis Lagrange colliery, air blast at Lake City. Colorado, mill at	1836	dry crusher	296
Lagrange colliery, air blast at	1093	Lannisdorf, centrifugal m	achine at
Lake City, Colorado, mill at	837	Lanthanum, atomic weigh	arating Company, the C. A.,
Superior conton dis-	1178	suspended riffles	arating Company, the C. A.,
Collom jigs at concentration methods. R. R. Robert copper mills . 114, 475, 1085, 1093, 109	515	gold separators, t	able of sizes, capacities, and
concentration methods. R. R. Robert	2040	Lord	1510
11 1000, 1000, 1000, 1000	8, 1108, 109, 1113		
morter blocks in	586	Laschinger's formula for	1119
T. A. Rickard	148	Last Chance mill	
T. A. Rickard mines, copper handbook rock, settling slimes from	1925	Lateral thrust, right and t	eft hand cams
size of grizzly used for	458	Latrobe steel die rings and	roller shells, life of in mills 1728
rock, settling slimes from size of grizzly used for cost of die, etc., at milling at	121	wearing parts of H	1749, 1771, 1773
milling at	30, 1131 48 1040	Mill 139	untington mills, life of at Company, displacement
houses 1	1950	pump Pump	Company, displacement
hammers used. hog-trough classifier hydraulic classifier, products of in Mill 46 Mill 45 iron ores works spindle breaker wearing parts jigs	300 470	o+ Mill 14	7 1000 X010
nydraulic classifier, products of in Mill 46	391	Laumontite, specific grant	Przibram1590, 1779
iron ores	391	Launders	у от 1189
works spindle breaker wearing parts	47	at Mill 152	
life of Collom sign at	017	Discoulation of the contract o	121111111111111111111111111111111111111
magnetic concentration at	833	distributing or sizing	d' + 117
magnetic concentration at method of feeding jigs at milling practice. A. S. Atkinson mills. T. A. Rickard mills at. 1089, 1102, 1174, 1175, 1184, 118	549	design and flow of sar	nds. F. K. Blue
mills at 1080 1109	1997	for amalgamental	C. Blue
at1009, 1102, 1174, 1175, 1184, 118	3, 1186,	canvas tables	743
automatic discharge in	1001	shunting	th
disposal of concentration	1103	DVCTSIIIIc maan dand	21()
size of grains in ore dressing, improvements in region, drop hammers used in steam hammers used in	693	in the mills	
region, drop hammers used in	2037	mean volcaleta ac	****** 1095
steam hammers used in	12	on Linkenbach slime t	er in
	56	Oversiroin's experimen	nts with 1592



Pages 1199-1610, Vol. III.	IND	EX.	Pages 1611-2052, Vol. IV.
Launders, pipe launders at Guanajuato plate glass launder linings at Mill 173. quantities of water in rectangular skimming as applied to clarifying tanks. speed of water current necessary to carry sand theory of flow in wetted perimeter Laurenburg, Prussia, hand picking at jigging at mill at sieve scale at picking at picking at running jigs at Schranz mill at Laurium, Greece, magnetic separation at Lautenthal, classifier at hand picking at jigging at mill at picking at range of sizes at sieve scale in mill Lawrence, H. L., dressing zinc blende and magnetite at new Pierrefitte mines, France Machine Co., centrifugal pumps Laws of classifying bibliography for conditions under which crushing is effected fineness of the desired product nature of material crushed power required for crushing relative efficiency of regrinding machines. sources of lost power free-settling particles, method of investigation of, in surface current box classifiers results of investigation of, in surface cur- rent box classifier rent box classifier is giging bibliography for copper ores for wolframite in tin ores silver ores with hyposulphite Lead amalgam separated by hot straining and silver ore, crushed by Blake breaker and Chili mill atomic weight of bullets for jig bed City, South Dakota, mill at cost of producing. ores, mill for specific gravity of respective for silver ores, mills of specific gravity of spe	1595 1595 878 8778 1409 878 876 409 1407 1307 1407 1307 1409	Le France Cop Leggett, Thom Africa panar yeatheri Lehigh Mounta Zine & Irc Lehman, F., w Leighton, Geor lina Length and slop of amalgam jig sieves stroke of Evan feede Frue great Han Harr 17 18 Hode jigs a t John mort Over plung shaki gri lau simpl Sutto 155 Triur vann Wilfle Leyath gri Leyath g	per Company, copper handbook 1925 as H., diamond washing in South 1178
Lead amalgam separated by hot straining and silver ore, crushed by Blake breaker and Chili mill atomic weight of bullets for jig bed City, South Dakota, mill at cost of producing ores, mill for 893, 900, 908, 909, 910, 911, 913, 916, 926, 928, 935, 958, 961, 965, 1004, 1005, size of grizzly used for treated at Mills 24, 25 by revolving knife buddle.	730 781 271 1188 1081 1025 1968 915, 1015 1066 340 69 329 251	units of	1187 1188 12048
sliver ores, mills for	1189 2041 1120 1570 1179 2035 814 1070 793 1093 1093 1093 1142 122 142 1892 993	corundum heating an Libbey, W. L., a cst of mil sodium an Liberty Bell Gole mill, Tellu Libra scales Lidner, P. G	at Corundum Hill, North Carolina 1176 d quenching
rules for sampling	1089 57		1710, 1853 buckets on elevators803, 804

ife of blanket tables	Life of at M
buckets in sand wheels at Mill 117 1668, 1669	
cam shaft. 190 cam shaft. 190 canvas, blanket, and carpet tables 700, 702 cantrifugal pumps 870 chilled-iron jaw plates at Mill 161 1837 crushing machinery, long 2009	
tables	
dewatering wheels at Mill 173 1878 dies at Mill 103 1632	
dies at Mill 103 1032 distributors at Mill 126 1707 duck for canvas tables at Mill 103 1033 elevator belts at mills 1032, 1633, 1661, 1667, 1707	
buckets at mills1632, 1633, 1661, 1667, 1725 parts at Mill 182	
1910 1910 1917 1918 1917 1918 1917 1918 1917 1918	
Hancock jig sieves at Mill 127 1710	
screens at mills	Lifting Lift of
Jaw plates for Blake breakers at Mill 100 1624 1igs	Light fo
sieves at mills1687, 1707, 1708, 1909, 1910,	Lightin mil Lightne
1620	Lignite
Midwele steel roll shells at mills 1797 1999 1997	Lime.
open-hearth crucible-steel screens at Mills 1707, 1806, punched plate trommel screens at mills 1707, 1876, 1876, 1877, 1902	cru for
retorts	S
Robins beit conveyors at mills. 1661, 1824, 1825, 1876	
conveying and picking belts at Mill 132 1727 roll shells	use
sand wheels	
860 870	Limesto
for gravity stamps	Limesto
guides	weight Limit of
1277 1278 1277 1278 1277 1278	cı h
stem	80
	Limits o
vanner belts	to n
wearing parts of Alis-Chalmers rolls at Mill	Limonite
179	cono
breakers	resu
Buchanan jaw breakers at Mill 157 1818 Butler's centrifugal pumps at Mill 117 . 1671.	spec wasl weig
Blake breakers 27 at mills 1621, 1724, 1749, 1858 breakers 1221 Bryan mills at Mill 173 1879 Buchanan jaw breakers at Mill 157 1818 Buther's centrifugal pumps at Mill 117, 1671 Byron-Jackson pump at mills 1622, 1674 Eyron-Jackson pump at mills 1632, 1633, 1711	Lincoln Linder,
1712, 1856, 1899, 1904, 1905	phide
Cyclone beater at Mill 186 1917, 1918	Lindgren
Dodge breakers 31 drag or disc conveyors 1583	Calico, pl Liners, E
elevators at mills . 1707, 1710, 1711, 1727, 1728, 1729, 1749, 1750, 1752, 1753, 1755, 1756, 1756, 1757, 1757, 1756, 1757, 175	Lines of
Dodge breakers	Lining, of
Forster breaker	an ca
Griffin mills at Mill 105	ce gr
grinding pans at Mill 105	jig

703	Life of wearing parts of Hodge and Cleaves sand jigs at Mill 182	
379 361	at Mill 182 1910, 19	1
369	Huntington mills	1
760 190	at mills1669, 1687, 1689, 1711, 176	õ
703	117 1673 167	7
702 370	117	3
37	Monadnock Chili mills at Mill 144	1
109 178	Nordberg steeple-compound steam stamps at Mill 180	r
32	rolls at mills1244, 1685, 1080, 1707, 171)
07	1749, 1750, 1751, 1752, 1771, 1773, 177	4
33 37,	188 188	į
25	Sherman Huntington mills at Mill 132 172); ?!
25 10	spindle breakers	ľ
77	Traylor centrifugal pumps at Mill 114 166	
$\frac{08}{12}$	trommels at Mill 166 1853, 1854, 185	Ė
40	Wetherill magnetic separators	(
10 80	Wilfley tables at Mill 126	į
11	Lifting magnets, Eastwood improved	į
24 04	Lift of elevators	1
46	Light for hand picking	į
0,	mills	1
11 20	bibliography for	į
	Lignite as fuel for roasting furnace	C
11 7	Lime. See also Quicklime.	
7. 77	crust on plates	0
8 8	for acid water 110	ģ
6,)2 32	settling	5
32 5	slimes	6
5,67 168 168 187 187 126 189 189 189 189	Lime See also Quicklime 154	1
27 16	in Arizona copper mills	6
4	investigating classifier currents	ļ
36	settling tests	₹ 7
ĩ	to remedy acidity in stemp mill	į
18	Limestone, Missouri, jaw plates used in crushing	į
í	strength of	į
2	weight of	i
Ö	crushing	į
8	hand picking tests	i
2	screen sizing	į
ĺ,	settling 455 sizes treated by jigs 604 Limits of drop in stamps 604	ĺ
1, 2 2 0 2	Limits of drop in stamps	
Ō	to number and height of drop of stamps 219	
2	sieve scale 365 sieve scale 365 to number and height of drop of stamps 218 Limitations of the hydraulic classifiers 1368 Limonite. See also Iron. concentrated by Bradford Mg	į
8	Limonite. See also Iron. concentrated by Bradford jig. 502 concentration of 1054 magnetic separation of 800 results of classifying in Mill 5 405 separated by magnets 700 sepecific gravity of 1189 washer xxv, 895, 896 Lincoln mill, dies used in 120 Linder, S. E. and FI. Pictou, action of arsenic sulphide solution on electrodes 1178 powers of metallic salts on arsenious sul-	
8 7	concentration of	Ł
8 7 3 1 9	results of classifying in Mill 5	
g G	separated by magnets	i
8	washer	
1	weight of	
ŝ	Linder, S. E. and H. Pictou, action of avenie and	
5	phide solution on electrodes	
	powers of metallic salts on arsenious sul-	
8 8 1	phide	
í	placer mining	
3	Liners, El Oro tube mill	
,	cost of	
3	Lines of force, magnetic 791 Lining, discussion of iron tube mill 2016 for Abbé tube mills at Mill 101 amalgamating pan 264	
3	for Abbé tube mills at Mill 101	
)	cars	
}	, and participal	
3	gravity stamp mortars	
58	munders 872	
vu		



Pages 1199–1610, Vol. III.	IND.	EX.	Pages 1611-2052, Vol. IV.
Lining for ore bins. steam stamps tube mills. A. E. Drucker at Bodie, Calif. W. W. Bradley Mill 103 Link belt conveyors Company elevator at Mill 125 elevators. Linkenbach, C	8420 16320 10320 1	Lock, A Locke, Lockha Loevy, Logarit Log wa Lohner Longda Longfel Longftel Longric	A. G., amalgamating pans
tator table decks Wilfley table Linton's level Lintorf, Prussia, disintegration and screening at jigs at filmit of sizes jigged at mill at stroke of jigs at Vapart disintegrator at Lion mill bibliography for Lip apron for stamps plates	1479 1467 672 1159 830 , 642 , 605 1179 594 289 234 294 178 739	Loss in	maigamated plates 757 75
Liquation in bullion Lisburne mines, Wales List of minerals floated by flotation processes List of good and poor conducting minerals for electrostatic separation Liter, equivalents of Lithium, atomic weight of Little Giant quartz mill Lixiviation 1616, bibliography for Loam, M., Husband stamp Location of amalgamated plates machines in mills main shaft for stamps. mills xxv,	1550 1187 1188 1310 1676 1175 143 737 1109	Losses i	gold 786 nercury See Individual Gold mills in Chapter XX. nercury 786 at Mill 114 1603 in amalgamating pans 250 ill in separation 811 n concentration 822 ry concentration 825 inses 1119 nagnetic concentration 1054 nilling 1945 olate amalgamation 749 limes 1119 lames 1119 tamping pyrite ores 1047 allings 1171, 1172

Losses of iron and mercury in pan amalgamation 249	M
on amalgamated plates	Mace mill
vanners	
Louis, H. 142, 167, 200, 839 amalgamated plates	
amalgamation	distributors
amalgams 731	shop for mill
arrastra	shop for mill 1098 Machinery at Paris Exposition, exhibition of 2009 Machinery at Paris Exposition, exhibition of 2009
Chinese stamping machine 224	recentified is a contion, exhibition of 9010
connecting table with mortar	crushing and grinding. Philip Appell
crushing machines	James Douglas Tames Douglas and grinding.
economy of stamp blow	Machines, arrangement of
efficiency of stamps	Machines, arrangement of 2017 design of 1107 design work of 1096
gravity stamps	guarding work of 1096 guarding work of 1111 in series and in parallel 1111
grizzlies	Macquisten, A. P. S., flotation process 1555, 1563
Huntington mill	guarding work of 1111 in series and in parallel 1110 Macquisten, A. P. S., flotation process 1555, 1563 flotation process. W. R. Ingalls 1509, 2027 at Golconda, Nevada 1555, 1565, 1611 Mill 149
Krom rolls	Mill 149
mercury wells	Contes tubes 1563 water flotation process. F. C. Nicholas 2046 Matter I. A repressing a contest of the contest
pointed boxes	
power for stamps	MEGISON DUIL
size of stamp feed	of the Utica Company xxvii Madrid, New Mexico, electric power 1002 Magrid, deff. deff.
spring and pneumatic stamps	wangana drift min, plates in
mortars 164	Magic crushes 770
stems	Magnesium, atomic weight of 1188 Magnesium, atomic weight of 1188 Magnesium, atomic weight of 1188
stamping, amalgamating, and concentrating for gold	Magnesium atomic weight of
for gold	Magnet for testing 1156 Magnetic combination mills 1000
use of surdauric acid on mates 759	Magnetic combination mills
	concentration 1053 concentration 790
weight of stamps 219 Lovet-Finney magnetic separators 832, 833, 835 Lowe F. A smalleymetries over the Receiville.	at Broken Hill
	at Broken Hill
ico	cost of
stamp mill at Silver Islet mill. Lake Supe-	principles of magnetic separators 1521 roasting before 1544
rior	roasting before 1544 the Hibernia mill, New Jersey 2040 fold
bibliography for	attractability of substances in
Lowry breaker	min at 17/00 Mile
Lubrication 1007	ore, Port Henry, products of crushing
and care of journals	
cams 194	at Broken Hill, Australia
cam shafts	D. Clark 1668 1735 1741 1793 1868 1741 1793 1869 1741 1793 1869 1741 1793 1869 1741 1793 1869 1741 1769 1741 1769 1741 1769 176
wire rope 1005 Lucknow, New South Wales, mill at 1181	Mineville, N. V. 1663, 1785, 1741, 1793, 1810
	Port Henry, N. Y. F. Cirkel 2034
Lucop & Cook mill 294 Ludlow, E., report used by Choctaw Coal and Railway Company.	Krupp mining administration 2038
	London mill, Australia
	bibliography for
Lubric and Constant and Constan	H. Smits 2030
Duss Concentrating India 1400	H. Smits 2026 history of Witter 2031 F. T. Spyder 2031
118	in Cornwall. E. Skewes
scraper for removing tailings 588 picking table. C. Blömcke 2021	F. T. Snyder. 2031 F. T. Snyder. 1568 in Cornwall. E. Skewes 1037 Finland. G. Gröndel 2047 Hungary, dry and wet. C. Blömeke. 2040 Sweden. 2040
shiner 1496	Sweden2040
capacity of at Diepenlinchen Prussia 870	Sweden. 2040 Sweden. 2047 K. G. Brunnberg 2040 of hematite and magnetite. Dr. Weiskopf. 2047 iron ores in Sweden. G. W. Peterson. 2047 tin oxide and wolfrage.
	iron ores in Sweden. G. W. Peterson 2047
vanners at wills 1734 vanners at mills 1717 Luhrmann, F. W., Pfeiffer's mill 205 Luipaards Viei Estate, ore reduction plant of 1645 Lumber for mills, cost of 1125 Lumber L. M. minerals in volk section 1125	tin oxide and wolfram. 2027 and copper ores in Cornwall. 2040
Luipaards Vlei Estate, ore reduction plant of 1645	and copper ores in Cornwall 2040 and wolfram. E. Treloar and G. John-
	son
SCDAFALIOR OF MINERALS by solutions 1179	son 2028 zinc fron sulphides. G. H. Elmore 2042 ores in Wisconsin. H. A. Wheeler 2042
Lurmann, separation processes 836 Luster affecting separation 889	references to
Luting referts	roasting zinc ores for
Luting retorts	
Luttermann, rolls at Clausthal	with Wetherill's
Lyon mill amalgamating par	separators at London mill, Queensland, Australia 2042
ncat used in amaigamaing in 940	Laughton 2029 with Wetherill's 804 separators at London mill, Queensland, Australia 2042 mills1741, 1763, 1765, 1808, 1810, 1815, 1862, Monteponi. E. Ferraris 1863, 1891, 1916
Mountain, Conkling jig at	Monteponi. E. Ferraris 2028
mm at	Balch
methods at the 2046	or Monarch
60	



Pages 1199–1610, Vol. III.	INL	DEX.	Pages 1611-2052, Vol.	IV.
Magnetic separators, Blake. Bromilow. Buchanan C. Blömeke Chase Chase Chase Chase Chase At Mill 148 Cobbing magnets Comparison of. Cleveland-Knowles magnetic separator at Mill 148 Cobbing magnets Comparison of. Conkling Construction of Cranberry magnet Dellvik Gröndal. description of different types of. C. Bugge Dr. Weiskopf H. C. McNeill M. Lenicque O. Simmerback S. W. Osgood Dings Edison Edison's electromagnetic separator F. Schiff. Ferraris Ferraris Ferraris Ferraris Ferraris Ferraris Forsgren's electromagnetic separator full description of different types of Gröndal Nos. 2, 3, 4, and 5 Heberil Wet Hoffman Wet Hoffman S3 Hughes Daviot Humboldt in a lead zinc plant Cornwall International Kessler Knowles' New Century Leighton Lovett-Finney Fayne principles of Rowand secondary or induction magnet type principles of Rowand secondary or induction magnet type Siemens & Halske suited for testing theory and conditions of. E. Langguth Trustedt Ullrich Ullrich Used at Przibram Monteponi using drums Vial Waring at Mill 148 Wenström wet S04 Wetherill Wet Magnetism Calcining for chauge of by heat effect of carbon in roasting for on free settling roasting for chauge of by heat effect of on H. O.	836 836 836 836 836 836 837 836 837 837 837 838 838 838 838 838	Magnetite, separation settling velocity of specific gravity of Magnetomotive force. Magnets. See also El Bilharz cobbing metality of Bilharz cobbing metaling of Magnets See also El Bilharz cobbing metaling of Magnetomotive force. Magnets. See also El Bilharz cobbing metaling of Manhattan Asbest of Wetherill separrelative attraction when applicable. Mahanoy City, shaking Maiern, Austria, hand magnetic separa mill at	of in Finland f	8469 11892 11532 115322 11532 11532 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 11532 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 115322 11532 115322 115
carbon in roasting for on free settling roasting for	4 1544 465 1544 2027 2027 2027 2027 791 890 503 1923	Marshall Basin, Colorad vanners at Creek Martin Iron Works brea Martin's buddle Maryland, mills in Mining Company n Marysville, Montana, Bi mill at Massachusetts Institute chies at tests on distributi effect of tem Materials for amalgama	o, Browne hydrometric sizer at (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	410 658 015 009 090 175 019 181 156 764 767
hindered-settling test on	1059 901	gravity stamp gui	eyor flights 11 ide blocks 11 at Mill 183 14	267

Pages 1-643, Vol. I.	ORE .	DRESSING.	Pages 644-1197, Vol. II.
Materials for Huntington mill parts	2	McCormick, E.,	Calumet and Hecla mill scheme 1184
jig tanksscreens	b	22 S. G., gold of McCully breaker	ores at Ouro Preto mine, Brazil 1182
mortar linings	1	66 compared	with Gates
riffle cleats	14	67 gyratory bro	r
roll shells	1720, 19	13 life of v	wearing parts at Mill 139 1222
round table decks at Mill 162	18	to mangar	iese steer sen-ngmening manne for . 1215.
and cost		54 McDermott, W. 73 amalgama	
in trommels	3.	50 and P. V	W. Duffield, amalgamated shaking
shaftsstamp batteries	12	oi piates.	
bosses	1	86 Baltic mil	ll, Michigan 2041
guidesparts	155, 1		of Calumet classifier
at Mill 143	17	69 Eureka H	Iill mill 2029
tappetssurface of Rittinger table	18	88 hand con 88 standardi:	centration test
of slime tables	688, 69	5 tin dressii	ng in Bolivia 2040
tube mill linings	12		Browne hydrometric sizer 410
		11 4	scharge
breakers. centrifugal pumps at Mill 103	48, 123	20 mining re	port xx
Cyclone beaters at Mill 186	.1917, 19	18 size of sta	175 imp feed
Dodge breakers		ot stamps at	Gibbonsville, Idaho
at Mill 183	1854, 18	55 weights of	f ore
fans at Mill 186	.1917.19	is McDougail type	roasting furnace 1546
Hodge and Cleaves sand pumps at	Mill	mine	., concentration at the Tilly Foster
182 Huntington mills at Mill 161 McCully breakers at Mill 139	. 1910, 19	Conkling	separator at the Tilly Foster mine 833
McCuliv breakers at Mill 139	174	1111y Post McFarlane & Co	ter magnetic plant
Nordberg steeple-compound steam st at Mill 180	amps	Manufactur	ing Company, parallel rolls 1244
rolls	124	12 mortar bolts 13 parallel rolls	150 s, description of
rolls	1843, 184	*, rous	
screens at Mill 158	185		12 1766, 1767 es 153
spindle breakers	46. 4	7 McKenno Bross	Company, laboratory ore grinder 1285
steam stamps trommels at Mill 165 Waddell Chili mills at Mill 174	188	1 laboratory o 1 McLanahan and	re grinder
Waddell Chili mills at Mill 174	188	6 phate washing	1244 324
of belts for gravity stamps bottom bed on jigs	$$ $\frac{19}{57}$	3 single-roll c	rusher at Alleghany Ore and Iron
bucket elevators	. , . , 86	company	· · · · · · · · · · · · · · · · · · ·
dies	18	30 des	International Phosphate Company 1241 peription of 1241
jig screens	54 14	tab	ole of sizes, power and weights 1241
screens	169, 17	O McLeod concent	
shoes and dies	32, 183, 18 19	table, tests a	rator
screens	17	3 Sweden	magnetic separators and plants in
stemtappets	18 18	Means of getting	a whole current in settling tanks
Mathet, De Gournay and Suisse, Hochstrate	appa-	Measurement of	mineral particles
ratus Mathey roasting furnaces at Mill 148	88	ore grains	470
Mathez, A., on drop of stamps Mathines Creek, Huntington mill at	22	0 Measures of a	enings
Maurice. P. E., iigs	28	sorting co	lumn of 3-inch pipe
Maurice, P. E., jigs. motion of solid particles in a liquid	47	7 Measuring	
centrifugal coal washer, results from Maximum profit in concentration	200	Mechanical bates	1 683
size of feed to rolls ore treated by Wetherill magnetic separat	Ĝ	3 efficiency of	ces
Maxwell's law of magnetic field	or . 152	ore, handling	Blaisdell system 1600
Maxwell's law of magnetic field May Brothers' jigs at mills	1717, 172	0 Brunton	
W. J., close sizing before jigging	117	z oscillatir	ng 1575 omatic tailings sampler 1573
Mayflower drift mill, mercury wells in	78	9 Snyder	
riffles at	740, 75	Vezin	·····
pan concentrator atshaking screen in	68	3 Brunton s	ampler 847
unwatering box in	45	2 cleaning n	nill between tests 1577 mpler 847
Maynard, G. W. and W. B. Kunhardt, dressing	g of	comparison	n of machines
iron oresjigging tests	64	5 difficulties	attending 1575
May's jig	64	3 moisture s	amples
Accept & Company, New Standard classifier.	1373 141	principles	of 1574
McCallum, A. C., design of mining machinery .	204	8 size of san	nples
rolls, crushers and mortarsstrength of machines	109	8 winnowing 6 shovel for re	g effect of air currents
McClave, J. M., an electrostatic separator the Wilfley roaster	202	8 squeezer for	amalgam 781
	100	stirring	

Pages 1199-1610, Vol. III.	IND	EX.	Pages 1611-2052, Vol. IV.
Mechanical trippers for discharging conveyor belts		Merrall mill	•
unwatering	. 533	VV	for
crank arm	. 678	cyaniding at tailings of	the Homestake mine 1419 f Montana Mining Company.
bumping tables Cammett table	. 680 . 677	effect of tem	perature on amalgamation 1520
vanners	55. 657	treatment at	the Homestake ore
sliding block Mechernich, classifier at	533 477	cones at will 1	at Mill 104
Heberwäsche at	78, 520	at Mill 1	ifying tanks 1406 106 1642 mes 1399
magnetic separator	. 1535	filter press at m	nics
mill atprocess in the Harz	. 1176	at Mill 1	106 1640 ishing cones, and water cylinders 1367
separator, results from thesieve scale at	. 2031 . 367	small cone class	sifiers 1371 106 1641
stroke of jigs at Megraw, H. A., slimes Meier, E. D., Osterspey jig	594 1419	Merrill's mill	1910
1. W., automatic feeders at Przibram	. 884	IVLESNES IN SCREENS, V	ashing plant for
Dingey mill Helerli mill	293 292	Mesquital, Mexico, Metal riffles, expand	mills at
Luhrig tableore dressing at Przibram	1180	plant, Argall fo	our-tube drier at 1600
revolving picking table and picking belt Rittinger and Salzburg tables and buddles at	t	treatment, prob	lems involved in
Przibram, Stein belt concentrator Schranz mill wash trommel	296	Metals, specific grav	vities of
Meihe's pulverizer bibliography of		Methods of crushing	of
Meinecke classifier	7. 478	feeding gravit	cleaning plates
work ofpointed box at Clausthal	5 477	preliminary c	rushing
stamps at Clausthal	225	jigs studying mills	551 s 1613
Melting bullion	2044	testing	
Men. See also Labor. Mercadel, magnetic separation at	835	Metric system of we	eights and measures 1187
Merced amalgamated plates at	1514	Mexican crushing ar H. Probert	nd milling plant a primitive F
action of	753	cost or broaders	milling in. H. T. Collins 2038 ng gold in 1980, 1981
antidote for atomic weight of hibliography for	1188	mill in milling at El O	ro. E. Burt
bibliography for	787 785 767	ore dressing at	Santa Fe. H. T. Collins 2046
fed to gravity stamps	208	Meyer & Charlton,	gold extraction at
for stampsgold in, after retorting	206	mill details	ng Company Ltd., mill of 1646 of stamps 221 and Company 77
after straining	781	Miargyrite, specific a	gravity of
in amalgamating pan riffle boxes riffles	$\frac{724}{770}$	grinding of scra milling of. F.	P
loss of. See Individual Gold Mills in Chapter loss of.	XX. 786	Micas for washing k Michell & Tregonin	P. 2017 Cirkel 2025 acolin 1077 ug pulverizer 283
lost in pan amalgamationore, separated by oil	240 831	Michigamme iron m	ine
mill for	730	magnetic se	eparation at 802 1175 1185
retained in retort residue sickening and flouring sink for clean-up	751	Michigan, cost of m mill, a recently	illing in
specific gravity of	266 1189	milling copper o	1008 1008
sprinkler for	. 1516		
box traps cleaning up	773	microscope	g grains
Grass Valley traplined with plate	774	micrometer for	measuring grains
plain transverse troughs or riffles	772 737	for the stud	dy of slimes
transverse with gates	72-773 2024	defined disposition of .	
used on dredges	1012	on machines	oncentrates and failings 1164
wells versus plates	771	product size of recrushi	
Meronitz, Bohemia, weathering garnet rock at . 83 Merrall, individual mortar	1264	treatment of Midland coal breake	er, West Virginia, F. W. Parsons 2051
Mill Company, Merrall's stamp mill	. 1278 6;	ividivate Co., steel t	or shoes and dies 185

Midvale steel ring dies at mills, life of1728, 1775
Midvale steel ring dies at mills, life of
trunnion tires at Mill 144, life of
Mile, equivalents of
Miles, William A., wash trommer Milk of lime, use of at Crown Reef Gold Mining
Company's mill
210, 319, 339, 486, 498, 499, 522, 892, 893, 1100,
324, 64, 66, 87, 498, 499, 892, 902, 1091, 1100, 1101,
1116, 1119, 1129 4 321 362 486 491 502 895 1116
5322, 339, 347, 350-352, 358, 405, 480, 486, 491,
6341, 870, 895, 897
7
9. 524, 528, 533, 548, 550, 552, 571, 574, 575, 587, 590,
1024, 26, 64, 66, 72, 76, 90, 91, 101, 347, 350, 352,
358, 359, 361, 366, 524, 528, 537, 540, 545, 547, 550, 552, 571, 575, 587, 590, 592, 593, 596, 599,
601, 603-606, 609, 863, 900-902, 908, 917, 1091,
11362, 366, 706, 707, 900, 902, 1116
1224, 64, 66, 76, 90, 319, 339, 347, 350, 352, 486, 488, 491, 506, 524, 528, 540, 550-552, 577, 604, 865,
900, 903, 1091, 1100, 1103, 1105, 1111, 1116
488, 491, 498, 499, 515, 523, 524, 528, 529, 540,
547, 548, 551, 552, 572, 574, 576, 589, 592–594, 605, 875, 900, 904, 1091, 1099, 1100, 1114, 1116, 1119
14. 10, 339, 480, 485, 488, 491, 524, 530, 536, 540, 548, 550, 552, 572, 574, 592, 593, 596, 605, 900, 905
1091, 1116, 1119
358, 359, 366, 399, 442-444, 485, 522-524, 528,
530, 533, 537, 538, 540, 550, 552, 572, 586, 590, 592, 593, 604, 605, 684, 689, 696, 863, 874, 875,
900, 906, 907, 1091, 1100, 1116, 1129, 1163
350, 352, 354, 358, 366, 524, 528, 534, 540, 545,
546, 549, 550, 552, 570-572, 579, 592, 593, 604, 605, 863, 893, 906, 908, 1091, 1105, 1111, 1116
1712, 24, 26, 64, 66, 69, 72, 76, 90, 91, 97, 101, 347, 350, 352, 354, 358, 366, 400, 480, 486, 524, 528
534, 540, 547, 550, 552, 584, 590, 592, 593, 596,
1824, 26, 64, 66, 76, 90, 101, 347, 350, 352, 358, 366,
369, 373, 410, 444, 522-525, 528, 530, 533, 537, 538, 540, 550, 552, 590, 592, 593, 604, 648, 863.
906, 909, 911, 1090, 1091, 1100, 1112, 1114, 1116,
19. 24, 64, 66, 76, 347, 350, 352, 358, 427, 444, 456,
486, 489, 491, 524, 552, 590, 648, 906, 910, 1114, 1116, 1121
2024, 26, 64, 66, 69, 70, 72, 76, 83, 90, 91, 95, 101, 347, 350, 352, 354, 355, 357, 358, 361, 366, 421,
524, 528, 537, 540, 541, 550, 551, 554, 572, 574-
872, 873, 875, 906, 913, 1091, 1100, 1103-1105,
2124, 26, 64, 66, 72, 76, 87, 90, 97, 101, 280, 281,
347, 350, 352, 358, 359, 361, 366, 369, 413, 451, 525, 528, 537, 538, 541, 546, 547, 550, 554, 573
577, 592, 593, 596, 601, 603, 605, 684, 691, 696,
1116, 1122
2230, 31 34, 64, 66, 69, 72, 76, 87, 90, 91, 95, 97, 101, 320, 338, 339, 347, 350-352, 356, 358, 359,
361, 366, 381, 383, 399, 442, 456, 462, 523-525, 528, 533, 534, 537, 538, 541, 550, 554, 572, 573
579, 584, 587, 592, 593, 599, 604, 605, 684, 688,
697, 863, 875, 906, 915, 1089, 1100, 1105, 1112, 1116, 1122 2230, 31 34, 64, 66, 69, 72, 76, 87, 90, 91, 95, 97, 101, 320, 338, 339, 347, 350-352, 366, 358, 359, 361, 366, 381, 383, 399, 442, 456, 462, 523-525, 528, 533, 534, 537, 538, 541, 550, 554, 672, 573, 579, 584, 587, 592, 593, 694, 605, 684, 688, 693, 697, 856, 857, 870, 872, 874, 875, 916, 917, 1100, 1102, 1103, 1105, 1112, 1116, 1122, 1129, 1100, 1162, 1163, 1165, 1112, 1176, 1141, 1141, 1141, 12324, 64, 66, 71, 76, 87, 90, 91, 347, 349, 350, 352, 352, 352, 352, 352, 352, 353, 364, 36, 355, 502, 541, 554, 577, 562
2324 .64 .66, 71, 76, 87, 90, 91, 347, 349, 350, 352, 358, 359, 366, 442, 525, 528, 541, 554, 571, 592, 605, 684, 882, 916, 917, 920, 1116, 1122, 42, 26, 50, 51, 64, 66, 69, 72, 76, 90, 91, 101, 347, 359, 352, 355, 358, 359, 361, 366, 414, 444, 446, 456, 517, 525, 528, 529, 535, 537, 538, 541, 546, 547, 549, 550, 554, 577, 579, 584, 589, 592, 593, 604, 605, 648, 663, 664, 684, 692, 863, 870, 916, 917, 921, 1091, 1092, 1100, 1101, 1105, 1106, 1112,
358, 359, 366, 442, 525, 528, 541, 554, 571, 592,
2424, 26, 50, 51, 64, 66, 69, 72, 76, 90, 91, 101, 347,
300, 302, 300, 308, 309, 301, 300, 414, 444, 446, 456, 517, 525, 528, 529, 535, 537, 538, 541, 546,
547, 549, 550, 554, 577, 579, 584, 589, 592, 593, 604, 605, 648, 663, 664, 684, 692, 863, 870, 916
917, 921, 1091, 1092, 1100, 1101, 1105, 1106, 1112,
1112, 1110, 1122, 1129

Lagor			,_0,								_
Mill 40	10.	24. 20	3. 48.	64. 6	37-69	. 72.	76, 8	7, 90	, 91,	101.	
	313,	339,	347,	351,	353,	356,	361,	366,	373,	395,	
	403,	4U4,	416, 546	444, 547	446, 550	450, 582	482, 579	483, 587	480, 592	520, 593	
	604	605,	607,	638,	647,	648,	656,	663,	863,	872,	
	875	879,	973,	978,	1086	108	9, 10	91, 10	099, :	1100,	
41	24.	26. 4	8. 64.	87.	347.	351.	353.	358.	366.	396.	
	424	444,	451,	456,	482,	526,	543,	546,	550,	562,	
	572	, 592,	593,	605,	647,	648,	650, 5 11	601,	663,	973,	
42	64.	67, 72	2, 76,	91. 9	7. 10)1, 11	8, 12	0-12	3, 126	-128	
	134	, 258,	339,	340,	345,	347,	351,	353,	366,	396,	
	403 526	, 404, 528	520	400, 543	408, 551	481, 564.	572	587.	592	605	
	638	684	696	697	, 86	3, 87	5, 98	4, 1	085,	1098,	
40	0.4	ח מים	. 70	1102,	1105	, 111	[2, 1]	[16, 1]	1121, 126	$\frac{1130}{100}$	
43	133	07, 08 . 134.	339.	347.	351.	353.	358.	366.	396.	403.	
	404	444,	451,	456,	517,	526,	543,	546,	547,	551,	
	680	, 572, 692	587, 695-	692,	593, 843	596, 861	863.	872.	875	084,	
	987	109	1, 11	00, 1	112,	1113	, 111	5, 1	116,	1121	
44	18,	24, 2	7, 54,	118,	120-	-123,	126-	129,	131,	133-	
	481.	485.	486.	489.	491.	515.	522.	526,	529.	537.	
	543	564,	571,	577,	580,	582,	583,	586-	589,	592-	
	594,	843	857	805,	865	888	870	.879	874-	.876	
	990	995,	100	0, 10	091,	1002	109	5, 11	.03, 1	1105,	
45	101	1108,	1109,	1112	, 111	3, 11	16, 1	120, 1	149,	1191	
40	515.	526.	529.	537.	586,	587.	589,	592,	684,	696.	
	805,	870,	90, 9	93, 10	91, 1	103, 1	105,	1110,	1116,	1130	
46	12,	24, 21 337-	7, 118 339	390 390	⊢123 301	, 120 396~	-128, 398	403	133- 449	-135, 458	
	480	-482,	485,	486,	489,	491,	515,	526,	537,	543,	
	544,	547,	566,	571,	577,	583,	586,	587,	592-	594,	
	990.	994	າວຍ, ບາ 1088.	90, 09 1091	110	3, 727 3. 110	15. 1	10.	116.	1131	
47	12,	24, 27	, 118	121	-123	126	-128,	133-	135,	280,	
	332,	337- 480	339,	397, 515	403, 522	449, 526	450, 520	480, 537	482, 544	485,	
	571,	572,	586,	587,	589,	592-	594,	605,	684,	697,	
	707,	726,	727,	843,	857,	870,	872,	875,	990,	998,	
48.	. 10.	12. 2	υνι, 4. 27.	118.	120	-123.	126-	-131.	133-	1131	
	320,	337-	339,	397,	398,	400,	404,	449,	456,	480-	
	482, 538	485, 544	480,	489, 550	491, 568	515, 571	522, 572	520, 577	529, 586-	537, 588	
	502-	594,	596,	599,	601,	605,	684,	689,	695-	-697,	
	843,	870,	872,	875,	990,	997,	₂ 100	0, 10	91, 1	103,	
49					27	70, 67	6, 10	04. 1	116.	1172	
50.					.100	4, 100	15, 10	73, 1	116,	1126	
51. 52	• • • • •		• • • •	1000	oor :	100 8.100	70, 10 09. 10	107, I 111, 1	009, 013	1116	
53.	. 30, 8	31, 16	7, 170	, 199	, 202	205,	207,	208,	212,	210,	
	648,	655,	659,	663,	1014	, 108	9, 10	01, 1	100, 1	103,	
54.	.27.	6. 17	0. 199	. 205	. 207	208.	212.	219.	339.	482.	
	0.4	(148, (63,	1014,	1015	, 11	10, 1	116,	1131	
00.	180	182.	186. -	187.	189-	104	196	170, 199.	201.	202.	
	205,	207-	209,	211,	212,	219,	222,	304,	482,	485,	
	491,	648,	665,	701,	768,	1014	, 101 0 11	6, 10 01 1	30, 1	.091.	
56.	. 145.	156,	158,	164,	165-	167,	170,	174.	177,	178,	
	180,	182,	186,	187,	189-	192,	196-	199,	201,	202,	
	744.	745.	748.7	214, 56. 7	68. 7	70. 7	200, 83. 78	724. 85. 10	137, 17, 1	089.	
	,		, .	1003	, 110	3, 110	5, 11	16, 1	119,	1131	
57.	170-	27, 14 .182	5, 157 186	3, 150 187	180-	, 166, 102	, 167, 108⊶	. 169, 100	174, 201	202	
	204,	205,	207-	209,	212,	214,	219,	222,	252,	265,	
	339,	340,	647,	648,	650,	(155,	659,	661,	663,	664,	
	768.	772.	774.	783.	1018	. 108	9. 101	2. 1	100. 1	105.	
F.C.	1 2 10	150	150	100	107	170	111	16, 1	131,	1191	
58.	. 145, 198	150,	188,	100, 192	107, 195	170,	172, 201	178, 202	180, 205	182, 207-	
	209,	212,	214,	219,	222,	239,	252.	450.	648,	650.	
	655,	661,	663.	737	744,	745,	748,	756,	772,	774,	
59.	. 24.	27, 14	5, 15	3, 158	166	, 167	169	174.	177-	-180.	
	182,	186,	187,	189-	192,	190-	109,	201,	202,	205-	
	209, 655	212, 659	663	219, 664	222, 737	339, 744	340, 745	482, 748	047, 758	759	
	765,	772,	785,	1018	, ĭo20), 108	8, 10	89, i	100,	(103,	
Mill 40 41 42 43 44 45 46 47 48 49 501 52 53 54 55 56 57 59	·					110	14, 11	09, 1	116,	1132	^
											6

Pages 1611-2052, Vol. IV. Mill 60..38, 46, 145, 156, 167, 169, 180, 182, 189, 1 201, 205, 207, 208, 212, 214, 219, 222, 648, 6 601, 737, 740, 742, 744, 748, 1018, 1021, 10 61. 38, 46, 145, 156, 158, 164–167, 169, 174, 175, 179, 189, 182, 185–187, 189–192, 196–199, 202, 205, 207–209, 212–214, 219, 222, 266, 340, 648, 659, 661, 663, 664, 737, 740, 746, 756, 765, 768, 783, 785, 848, 858, 861, 1018, 1021, 1030, 1089, 1090, 1100, 1103, 1116, 664, 748, 148, 148, 158, 158, 158, 168, 167, 169 1018, 1021, 1030, 1089, 1090, 1100, 1100, 1106, 1116, 1116, 12, 185-187, 180-192, 107-199, 201, 202, 207-200, 212, 214, 219, 212, 265, 330, 340, 659, 661, 703, 733, 737, 741, 742, 748, 750, 757, 765, 768, 772, 783, 1018, 1022, 1089, 103, 1022, 207, 208, 212, 214, 219, 648, 737, 756, 772, 1023, 1089, 1024, 107, 107, 177, 178, 182, 190, 191, 199, 201, 207, 208, 212, 214, 219, 648, 737, 756, 772, 1023, 1089, 1023, 1089, 1024, 65. 24, 156, 158, 166, 169, 174, 177, 178, 180–182 187, 189–191, 196–199, 201, 202, 207–209, 214, 219, 222, 238, 266, 338, 339, 482, 491, 648, 659, 661, 733, 735, 737, 738, 740, 741, 744, 746–748, 750, 754, 756, 772, 773, 783, 1024, 1039, 1089, 1092, 1103, 1104, 1116, 66..46, 47, 156, 166, 167, 169, 177, 180–182, 186, 180–192, 197–200, 202, 205, 207, 212, 214, 222, 252, 682, 735, 738, 741, 744, 745, 747, 756, 760, 768, 773, 775, 781, 785, 1018, 1088, 1091, 1098, 1100, 1102, 1105, 1116, 1 67. .28, 145, 152, 153, 156, 158, 166, 167, 169, 175, 177-182, 184-187, 189-192, 194-199, 202, 204, 205, 207-210, 212, 214, 219, 222, 733, 735, 738, 740-742, 744, 746, 747, 752, 759, 765, 768, 771, 773-775, 783, 785, 872, 1026, 1030, 1091, 1100, 1103, 1105, 1106, 1026, 1030, 1091, 1100, 1101, 1201, 69...158, 173, 175, 184, 212, 214, 648, 735, 745, 783, 785, 1018, 1028-1030, 1080, 1091, 1105, 1116, 1 71. 145, 156, 167, 170, 174, 177, 178, 182, 187, 189, 196–199, 201, 205, 207–209, 212, 214, 219, 205, 418, 048, 060–602, 605–607, 738, 740, 745, 748, 772, 773, 780, 1029–1031, 1037, 10390, 10390, 1039, 1039, 1039, 1039, 1039, 1039, 1039, 1039, 1039, 1039, 10 205, 418, 048, 606-602, 606-607, 738, 740, 743-745, 745, 772, 773, 780, 1020-1031, 1037, 1089, 1092, 1116, 187, 189, 101, 102, 106-109, 201, 202, 206-209, 212, 214, 219, 222, 205, 320, 339, 448, 456, 648, 661, 676, 683, 738, 741, 743, 744, 747, 766, 772, 773, 777, 783, 856, 1030, 1032, 1037, 1088, 1089, 1032, 1037, 1088, 1089, 1082, 123, 124, 129, 222, 288, 265, 388, 339, 468, 462, 485, 491, 647, 648, 659, 633, 339, 456, 462, 485, 491, 647, 648, 659, 733, 736, 758, 760, 772, 773, 777, 781, 783, 1024, 1030, 1031, 1032, 1037, 1038, 1038, 1039, 1039, 1039, 1031, 1101, 1132, 1108, 1314, 1030, 1034, 1038, 1038, 1039, 1031, 1031, 1031, 1031, 1131, 1132, 1108, 1031, 1031, 1031, 1031, 1031, 1131, 1132, 1108, 1031, 1031, 1031, 1031, 1031, 1131, 1132, 1108, 1311, 132, 1108, 1321, 1031, 1031, 1031, 1031, 1031, 1031, 1031, 1131, 1132, 1108, 1312, 1414, 1419, 222, 238, 265, 338, 339, 482, 485, 491, 647, 648, 650, 652, 659, 601, 733, 738-741, 743, 744, 746-748, 750, 754, 756, 783, 1024, 1030, 1034, 1038, 1038, 1038, 1039, 1100, 1101, 1101, 1102, 1101, 1103, 1117, 1132, 1108, 131, 1103, 1117, 1132, 1108, 1107, 1101, 1102, 1101, 1102, 1101, 1103, 1117, 132, 1108, 1391, 1202, 144, 219, 222, 339, 648, 659, 663, 664, 700, 701, 703, 738, 744, 756, 772, 870, 1030, 1034, 1089, 1092, 11003, 1101, 1117, 1009, 1103, 1105, 1117, 1009, 1103, 1105, 1117, 1009, 1103, 1105, 1117, 1009, 1103, 1105, 1117, 1031, 1105, 1117, 1031, 1105, 1117, 1031, 1105, 1117, 1031, 1105, 1117, 1031, 1105, 1117, 1031, 1105, 1117, 1031, 1105, 1117, 1031, 1105, 1117, 1031, 1105, 1117, 1031, 1105, 1117, 1031, 1105, 1117, 1031, 1105, 1117, 1031, 1105, 1117, 1031, 1105, 1117, 1031, 1

the state of the s	
Mill 76145, 156, 158, 166, 167, 169, 177, 179, 180, 182, 186, 187, 189, 190–192, 196, 198, 199, 201, 202, 205, 207–209, 212, 214, 219, 265, 648, 664, 703, 738, 740, 743, 750, 765, 772, 879, 1080, 1035, 1089, 1105, 1117, 177–182, 185–187, 189–192, 195–199, 201, 202, 204–209, 211, 212, 214, 219, 220, 222, 342, 482, 680–682, 703, 739, 741, 747, 753, 756, 757, 761–763, 765, 766, 768, 774, 842, 1030, 1035, 1046, 1047, 1089, 1091, 1100, 1105, 1117, 1133, 144, 446, 648, 653, 653, 658, 660, 661, 665–667, 700, 702, 703, 857, 874, 1017, 1029–1031, 1035, 1037, 1038, 1089, 1090, 1100, 1101, 1117, 1117, 1117, 1117, 1117, 1128, 1037, 1038, 1089, 1090, 1100, 1101, 1117, 1117, 1128, 1035, 1037, 1038, 1089, 1090, 1100, 1101, 1117, 1126,	Mill 100
186, 187, 189, 190-192, 196, 198, 199, 201, 202	101 1489 1623 1626 1024
205 207-200 212 214 210 265 646 664 702	1699 1690 1094
790 740 749 750 745 770 070 1000 1000	102 1029, 1029, 1034
100, 140, 140, 100, 100, 112, 519, 1030, 1030,	103 1291, 1292, 1017, 1031, 1934
1089, 1105, 1117	104 1634, 1934
7710, 145, 148, 156, 158, 164, 166, 167, 169, 174.	105
177-182, 185-187, 189-192, 195-199, 201, 202	106 1371 1406 1416 1516 1634 1639 1034
204-200 211 212 214 210 220 222 242 422	1694 1645, 1994
200 200 211, 212, 214, 215, 220, 222, 342, 402,	107 1094, 1093, 1934
080-082, 703, 739, 741, 747, 758, 756, 757, 761-	108 1931, 1934
763, 765, 766, 768, 774, 842, 1030, 1035, 1046.	109
1047, 1089, 1091, 1100, 1105, 1117, 1133	110 1634 1651 1034
78 418 444 448 649 659 655 650 660 661 665	1659 1654 1994
20, 411, 411, 410, 010, 000, 000, 000, 00	111 1032, 1034, 1934
007, 700, 702, 703, 857, 874, 1017, 1029–1031,	112 1052, 1057, 1934
1035, 1037, 1038, 1089, 1090, 1100, 1101, 1117,	113
1126	114 1541 1652 1660 1034
79456, 648, 655, 658, 700, 701, 703, 723, 875, 1030, 1032, 1033, 1037, 1038, 1100, 1117, 80456, 700-703, 875, 1029, 1030, 1033, 1038, 1039, 1030,	115 1652 1665 1024
101. 100, 010, 000, 100, 101, 100, 120, 010, 1000,	110 1005, 1934
1032, 1033, 1037, 1038, 1100, 1117	116 1065, 1934
80456, 700-703, 875, 1029, 1030, 1033, 1038, 1039,	117
1100, 1101, 1117	118
81238 1030 1038 1039 1089 1100 1117	110
29 94 97 145 156 150 164 166 167 170 174 170	100 1904
0224, 27, 140, 100, 104, 100, 107, 170, 174, 178,	120
180, 182, 185-187, 189-192, 196-199, 201, 202,	121
205-209, 212, 214, 219, 222, 244, 248-250, 252.	122
339, 456, 458, 480, 486, 491, 648, 659, 661, 663,	123 1361 1680 1689 1024
664 723 733 735 730 748 755 756 760 761	124 1261 1690 1600 1025
769 765 766 769 777 790 705 969 1007 1000	124 1000, 1000, 1000, 1000, 1000
100, 100, 100, 117, 180, 180, 808, 1027, 1028,	120 1350, 1361, 1680, 1700, 1932, 1935
81238, 1030, 1038, 1039, 1089, 1100, 1101, 1117, 8224, 27, 145, 156, 158, 164, 166, 167, 170, 174, 178, 180, 182, 185-187, 189-192, 196-199, 201, 202, 205-209, 212, 214, 219, 222, 244, 248-250, 252, 339, 456, 458, 480, 486, 491, 648, 659, 661, 663, 664, 723, 733, 735, 739, 748, 755, 756, 760, 761, 763, 765, 766, 766, 777, 780, 785, 863, 1027, 1028, 1039, 1040, 1091, 1100, 1101, 1103, 1104, 1111, 1114, 1117, 1134, 1137, 1134, 117, 178, 183, 185-187.	126
1114. 1117. 1134	127
83. 46, 47, 145, 156, 167, 170, 174, 178, 183, 185-187, 189-192, 196, 197, 199, 201, 202, 205-208, 212, 214, 219, 244, 246, 248, 249, 252, 456, 458, 460, 482, 648, 663, 777, 778, 780, 783, 1039-1041, 1091, 1095, 1100, 1101, 1103-1106, 1110,	128 1713 1020, 1025
189-192 196 197 199 201 202 205-200 215	190 1881 1710 1715 -005
914 910 944 946 949 940 950 450 450 460	120 1935
214, 219, 244, 240, 248, 249, 202, 400, 408, 400,	130
482, 648, 663, 777, 778, 780, 783, 1039-1041,	131
1091, 1095, 1100, 1101, 1103-1106, 1110.	132 1361, 1404, 1406, 1713, 1726, 1932, 1935
1117	122 1712 1721 1025 1040
84 24 27 42 46 145 156 158 166 167 170 174	100
177 170 100 101 107 107 107 107 107	134
8424, 27, 42, 46, 145, 156, 158, 166, 167, 170, 174, 177, 178, 180, 181, 183, 185–187, 189–192, 196–199, 201, 202, 205–209, 212, 214, 219, 222, 244, 219, 242, 242, 242, 242, 242, 242, 242, 24	135
199, 201, 202, 205-209, 212, 214, 219, 222, 244,	136
246, 248, 249, 252, 339, 347, 351, 353, 354, 356,	137 1300 1347 1438 1458 1548 1713 1730 1028
199, 201, 202, 205-209, 212, 214, 219, 222, 244, 246, 248, 249, 252, 339, 347, 351, 353, 354, 356, 359, 366, 456, 458, 460, 448, 663, 739, 742, 743, 756, 768, 772, 777, 780, 783, 785, 860, 861, 875, 1039, 1040, 1045, 1085, 1089, 1091, 1095, 1100, 1101, 1103-1106, 1109, 1110, 1117, 1134, 1100, 1101, 1103-1106, 1109, 1110, 1117, 1134, 1100, 120, 208, 219, 220, 351, 353, 411, 442, 451, 526, 528, 568, 586, 592, 682, 739, 742, 773, 1029, 1046, 1047, 1089, 1117, 280, 281, 342, 347, 351, 353, 354, 366, 410, 419, 526, 528, 544, 545, 550, 568, 572, 587, 588, 592, 593, 604, 605, 648, 682, 684, 696-698, 703, 735, 737, 739, 748, 756, 774, 785, 848, 857, 863, 872, 879, 883, 1046-1048, 1091, 1100, 1105, 1117, 200, 200, 200, 200, 200, 200, 200, 20	190 1000, 1011, 1100, 1100, 1110, 1100, 1900
740 756 760 770 777 700 709 705 000 100	188 1985
746, 706, 708, 772, 777, 780, 783, 780, 880, 861,	139
875, 1039, 1040, 1045, 1085, 1089, 1091, 1095,	140
1100, 1101, 1103-1106, 1109, 1110, 1117, 1134	141 1345 1361 1525 1591 1748 1759 1035
8524. 65. 67. 76 167 169 178 179 199 202 205	149 1766 1005
207 208 210 220 251 252 411 442 451 506	142 1700, 1935
207, 200, 213, 220, 331, 333, 411, 442, 431, 320,	143 1768, 1935
526, 566, 586, 592, 682, 739, 742, 773, 1029, 1046,	144 1361, 1365, 1590, 1592, 1768, 1771, 1932, 1935
1047, 1089, 1117	145
86 24. 27. 65. 67. 72. 76. 87. 90. 101. 168. 169. 174	148
280 281 342 347 351 353 354 366 410 410	147
508 500 544 545 550 560 570 507 500 700	147 1763, 1760, 1930
220, 323, 344, 343, 330, 308, 372, 387, 388, 592,	148
593, 504, 505, 548, 682, 684, 696-698, 703, 735,	149
737, 739, 748, 756, 774, 785, 848, 857, 863, 872	150 1794 1795 1096
879. 883. 1046-1048. 1091. 1100. 1105. 1117.	151 1704 1909 1026
1122	100 1001 1001 1001 1001 1000
97 94 97 40 65 67 79 76 97 00 101 145 150 150	132
8724, 27, 49, 69, 67, 72, 76, 87, 90, 101, 149, 156, 158,	153
100, 107, 170, 178, 180, 183, 185–187, 189, 191,	154
192, 196, 199, 202, 205, 207–209, 212, 219, 347,	155
351, 353, 358, 359, 413, 427, 450, 451, 526, 528,	156 1361 1520 1521 1016 1017 1026
537 544 568 586 592 593 648 730 742 769	167
8724, 27, 49, 65, 67, 72, 76, 87, 90, 101, 145, 156, 158, 166, 167, 170, 178, 180, 183, 185–187, 189, 191, 192, 196, 199, 202, 205, 207–209, 212, 219, 347, 351, 353, 358, 359, 413, 427, 450, 451, 526, 528, 537, 544, 568, 586, 592, 593, 648, 739, 742, 768, 848, 856, 863, 872, 1046, 1050, 1089, 1092, 1112,	150 1001 1507 1507 1018, 1930
0±0, 000, 000, 012, 10±0, 1000, 1009, 1092, 1112,	100
1117	199 1361, 1828, 1936
8824, 27, 65, 67, 76, 87, 90, 101, 145, 156, 158, 166.	160
167, 169, 178, 180, 183, 189, 191, 192, 197–199	161 1361 1836 1939 1038
201, 205, 207, 208, 212, 214, 219, 347, 351, 353	162 1328 1320 1361 1301 1440 1403 1615 1926
358 359 414 450 451 526 528 527 544 550	1000, 1001, 1001, 1710, 1700, 1010, 1000,
568 592 503 605 648 600 720 740 770 070	169 1041, 1932, 1930
1020, 1040, 1050, 1050, 1050, 144, 113, 872,	100
8824, 27, 65, 67, 76, 87, 90, 101, 145, 156, 158, 166, 167, 169, 178, 180, 183, 189, 191, 192, 197–199, 201, 205, 207, 208, 212, 214, 219, 347, 351, 353, 358, 359, 414, 450, 451, 526–528, 537, 544, 550, 568, 592, 593, 605, 648, 682, 739, 742, 773, 872, 1030, 1046, 1052, 1089, 1105, 1112, 1117, 8921, 24, 27, 45, 40, 65, 07, 77, 87, 90, 91, 101, 347, 351, 353, 362, 366, 790, 798, 863, 880, 883, 1053, 1055, 1112, 1117, 11	104 1346, 1361, 1532, 1607, 1836, 1849, 1936
8921, 24, 27, 45, 46, 65, 67, 77, 87, 90, 91, 101, 347.	165
351, 353, 362, 366, 790, 798, 863, 880, 883, 1053	166 1361 1836 1939 1936
1055, 1117	167 1305 1509 1509 1505 1936 1099 1099
90. 23 24 27 30 31 65 67 77 87 00 101 202 247	160 1000, 1002, 1000, 1000, 1000, 1000, 1000
90. 23, 24, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 347, 351, 353, 803, 861, 863, 1053, 1055, 1091, 1100,	100 1830, 1800, 1937
001, 000, 000, 001, 000, 1000, 1000, 1091, 1100,	109
1117	170
9165, 101, 106, 107, 310, 340, 790, 810, 813, 816, 843, 856, 858, 861, 863, 864, 881, 882, 883, 1053, 1054, 1056, 1091–1094, 1096, 1098, 1100, 1108,	171 1361 1836 1868 1921 1027
843, 856, 858, 861, 863, 864, 881, 882, 883, 1052	172 1317 1361 1826 1871 1021 1020 1027
1054 1056 1091-1094 1096 1098 1100 1100	172 1400 1419 1505 1505 1000 1075 1007 1007
1110 1114 1117 440	1101400, 1410, 1000, 1090, 1850, 1870, 1927, 1928,
00 04 07 05 07 77 00 101 201 202 202 1135	1929, 1930, 1931, 1937, 1940
9224, 27, 65, 67, 77, 90, 101, 304, 338, 339, 341,	174 1361, 1478, 1585, 1836, 1882, 1932, 1937
347, 351, 353, 366, 451, 486, 489, 491, 522, 527	175 1889 1027
528, 544, 550, 570, 592, 593, 605, 790, 805, 807,	176 1981 1904 1997
814 843 860 862-864 880 882 882 001 1000	177 1056 1440 1507 1001 1001 1007
1054, 1056, 1091–1094, 1096, 1098, 1100, 1108, 1112, 1114, 1117, 1135, 1112, 1114, 1117, 1135, 1112, 1114, 1117, 1135, 1114, 1117, 1135, 1347, 351, 353, 366, 451, 486, 489, 491, 522, 527, 528, 544, 550, 570, 592, 593, 605, 790, 805, 807, 814, 843, 860, 862–864, 880, 882, 883, 891, 1060, 1063, 1088, 1091, 1094, 1112, 1118, 1117, 1135, 1136, 1137, 1136, 1137, 1136, 1137, 1136, 1137, 1136, 1137, 1137, 1138, 1137, 1138, 1137, 1138, 1137, 1138,	Mill 100
1005, 1055, 1091, 1094, 1112, 1113, 1117, 1135	1/8
93 24, 27, 65, 67, 69, 87, 90, 347, 351, 353, 354, 366.	179
790, 800, 814, 895, 1060, 1065, 1117	180 1256 1801 1001 1027
9496, 103, 104, 309, 346, 848, 856, 861, 880, 889	181 1250 1254 1256 1261 1201 1202 1227
883 1070 1001 1004 1008 1100	100
OE 000, 1070, 1091, 1094, 1090, 1190	1021254, 1256, 1891, 1908, 1931, 1937
1616, 1934	183
95	$\begin{array}{cccccccccccccccccccccccccccccccccccc$
97	185 1015, 1097
98 1620 1621 1022 1024	186
00 1000 1000	107 1916, 1937
55	187 1919, 1937

•				
	1001	1097	Mills serving iron and server restore 1646 40	00
Mill	188	1000	Mills saving iron and copper values	
	arrastra	1000	manganese values	14
	at Monteponi, Sardinia	1066	lead and zinc values	80
	buildings, construction of	1088	zinc and copper	94
	Clausthal	965	iron values	83
	tenta for the engineer importance of E T		only asbestos	18
	constants for the engineer, importance of. F. T.	9049	1010, 10	101
	Snyder	2048	copper values	ăŢ
	construction. See under Construction. saving of mill height at Mill 158		diamonds	21
	saving of mill height at Mill 158	1826	iron values	15
	data on spindle breakers	46	lead values	റദ
	distributors	857	mercury values	ñã
	distributors		1010 10 10 10 10	10
	for asbestos	1018	pyrite	13
	clay and kaolin	1075	silver values	79
	Elmore oil process	1072	silver and lead values	80
	graphite	1074	lead, and zinc values	13
	mercury ores	1074	tin and tungsten values	îř
	mercury ores	1001	1010, 19	120
	tin ores	1091	zinc and manganese values 1616, 18	
	heating of	1098	sectional	.08
	Himmelfahrt	958	sieve scales in American, table of	61
	Tues Mauntain	207	silver 10	
	Joseph Wharton Laurenburg	1050		
	Joseph Wnarton	1000	combination	
	Laurenburg	90T		00
	Mons phosphate	000	using hand jigs 8	392
	Monteponi	1066	stamp 10	13
	numbers, key to	xxv	with plates and vanners 10	18
	-1	1007		17
	plant	1070	10 values - 10 - 10 - 10 - 10 - 10 - 10 - 10 - 1	
	practice in California, gold. E. B. Preston	12/8		14
	processes and management	888	steam stamp in Montana 9	184
	sampling at Mill 182	1912		04
	screens	1365	hydraulicking or dredging 10	006
	SCREENS	1005		
	sites	1000	magneusm	53
	Sulphur Mines & Railroad Co	905	with jigs, vanners and tables 11	03
	testing	1168	log washers 8	395
	sieve for1996,	1997	Millstones, discussion of	33
	tests	1184	Milwaukee Mining Co., mill	40
	tests	1012	Trimedia and if a manifes of	00
	treatment, schemes of	1019	Mimetite, specific gravity of	89
	Vieille Montagne Co	911		25
	with stamps and canvas tables	1038	Tecolotes y Anexas mill. G. A. Burr 20	137
	Witherbee Sherman	1059	Mine 1 4	182
	anonly	381	12	
	workcompared with small tests	1160	24	
	compared with small tests	1100		
Mill	er pump	927		182
	Robert, Hick revolving grizzlyerite, specific gravity of	385	26	182
Will	erite specific gravity of	1189	30	82
34:11	igram, equivalents of	1187		82
3 (11)	ingrami, equivalents of	1107		82
TATILI	imeter, equivalents ofing. See under Ore Dressing and Concentration	1101		
Mill	ing. See under Ore Dressing and Concentration	۱.		181
	accounts at Gundling No. 5. Joplin Missouri. D. Brit-	1122		182
	at Gundling No. 5. Toplin Missouri, D. Brit-		42	181
•	toin	2046		12
	tain	1702		43
	COSIS OF AL HILLS	1100		
	expenses R. D. O. Johnson	1123		12
	experiences. R. D. O. Johnson	2048	54	181
	improvements in 1904 in	2047	57	182
	in Western Chihuahua	1664		182
	losses	1045		182
	IOSSES	1070		
	of chromite	10/9		182
	plants for small mines. F. L. Bartlett	2036		181
	practice in the Witwatersrand, South Africa	1643	87	182
Mill	s, arrangement of1086,	1107	09*	181
	bibliography for	1179	and Smelter Supply Company, cone classifiers at	
	California versus Colorado	1020	Mill 141	761
	Camorina versus Colorado	1000	Mantiner in	7,7
	canvas plants	1029	blasting in	
	care of	1114	fines, treatment of	[11
	choice of	1161	La Motte mill xxvi, 9	121
	complex jigging, at Lake Superior	990	La Motte mill xxvi, 0 picking in	181
	in Colorado and Utah	925	water used 11	105
	Idaho and Europe	937	water used	
	Montana	973	mation	520
	Montana	010	AMERICAL CONTRACTOR AND	
	southeastern Missouri	916	aggregate	163
	construction of	1088	examination1	ιυZ
	costs of erecting	1124	oils 10	97
	divisions of for different ores	1111	Minerals, adhesion of	4
	for corundum and emery	1078	aggregation of	3
	and combination	1048	aggregation ofchanged by heat	å
	gold combination	1040	changed by neat	3
	key to numbers	XXV	color and juster of	3
	location, capacity, etc	XXV	decrepitation of	5
	of	1085	effect of greatiness of	4
	magnetic combination	1060	magnetism of	4
	method of studying	1612	momentum of	4
	method of studying	1700	nottling power	4
	Mining and Reduction Company	1182	settling power	
	name, location, minerals and capacity	VXX	specific gravity of	3
	order of	1616		555
		889	Floration Company, floration processes 16	560
	outlines of	200	hardness of	2
	outlines of	220	Hat of good and moon conductors for alcotro-	-
	principles in	889		
	principles in	232	hat of good and poor conductors for electro-	EFO
	principles in	232 1888	static separation	550
	principles in	232 1888		550 790
	principles in pulverizing. saving copper and sulphur values. 1616, gold and copper values. 1616	232 1888 1831	static separation	
	principles in pulverizing saving copper and sulphur values gold and copper values silver and copper values 1616 1618	232 1888 1831 1836	separated in mills. See Individual Mills in	
	principles in pulverizing. saving copper and sulphur values. 1616, gold and copper values. 1616 silver and copper values. 1616 lead and copper values. 1616	232 1888 1831 1836 1786	magnetism of	790
	principles in pulverizing saving copper and sulphur values gold and copper values silver and copper values 1616 1618	232 , 1888 , 1831 , 1836 , 1786 , 1748	separated in mills. See Individual Mills in	790

INDEX.

Pages 1199–1610, Vol. III.

Pages 1611-2052, Vol. IV.

Pages 1-643, Vol. I.	ORE DRESSING.	Pages 644-1197, Vol. II.
Minerals Separation process at Mill 130	1560, 1719, 1721, Monitor and Aj	jax fraction
Minerals Separation process at Mill 130. specific gravities of structure and fracture of tenacity and brittleness which become magnetic on roasting Miners' inch measure for water ton. Mines de Pierrefitte Mineville, New York, mill at Minimum difference in specific gravity for Mining, cost of costs, statement of wire cloth screens, sizes of Minnesota iron mine, Blake breaker at cost of crushing at crushing at Iron Co., cost of breaking ore Silver Company, Ltd. Minnie & A. Y. mill Minor processes of separation Miscellaneous apparatus machines using agitation plates processes of separation Miscouri, capacity of jigs in concentration in southwest. R. B. B cost of mill in milling in producing lead and zinc in. drop between jig sieves hand jigging in jigs lunger clearance in jigs in ligs plunger clearance in jigs in -Kansas district, milling in the. O. I. concentration in the. H. A. Titt lead and zinc mills, methods of jiggin mills in. 200, 1120, 1179, 1180, 1181, milling in O. M. Bilharz southwest. O. Ruhl. number of sieves on jigs in Robinson jig in typical milling practice in Joplin. son R. L. Herrick Zinc and Lead Company mill jigs in mills, general scheme of. R. H. ores, improvements in milling. W. Mixed Sizes, tests on ligging Mixer. Blaisdell mechanical mixer for oil separation Mixing box at Mill 162 pans at Mill 188 vats at Mill 188 vats at Mill 180 Modifications of Collom jig Evans jig Frue vanner Moisture in concentrates drained ore removed in driers samples Molasses spigot for jigs Molybdenite, concentration of. dressing separated by oil specific gravity of	1560, 1719, 1721, 1723	iax fraction 1732 jaint 333 , phosphate dressing at 1170 hosphate
removed in driers samples Molasses spigot for jigs Molybdenite, concentration of T Obly		ine, height of discharge of stamps 213
specific gravity of	1189 mill	rence N., electrostatic separation 1550 achinery & Supply Company, the Wild
Molybdenum	1569 F. B., corr 1188 Tustin n	ugated vanner belt
of minerals use made of, in mills. used in dry separation	4 gravity s	tamps
Monarch breaker, cost of crushing by	1775, 1850 blocks for parely	perg steam stamps
of Blake type table of sizes of magnetic separator Monazite dressing in the Carolinas	20 of concre	itc
Monazite dressing in the Carolinas sands, concentration of. F. Katzer . sand washing in the Carolinas	2030 Morison covers	open front 2011 167 t Mill 181 1906
C. R. Bohmseparated by magnets	2027 Mortar discharg	g amalgam 780

Pages 1199–1610, Vol. III.	INDI	$m{x}$	Pages 1611-20	052, Vol. IV.
Mortar hand, for testing housing for steam stamps jig discharge for steam stamps jigs at Mill 177 linings at Mill 117 Mortars at Mill 117 Boss individual mortars standard battery mortar Dahlonega for gravity stamps gravity stamp Homestake type introducing water into Merrall's individual mortar Nordberg steam stamp Rapid Economy individual	9, 120 1250 1892 1668 1668 1265 1267 152 0, 161 1263 1267 2011 1264 1003 1266	process for corunding Stanwood gravity Multiple jaw breaker Munding & Moodie de Mundie	y amalgam gam im y separator th of stone at t Bonne Terre the English and (gging n slime tables	204 780 1078 11285 28 818 900 168 301 viii 57 Continental 403
Schorr stay-overflow, the single and double discharge standard ten-stamp battery steam stamps table of dimensions of weights of Traylor double-discharge sectional mortars Mosler, C., Ball stamp.	1267 119 165 164 1266 1267	figures on practic lic classifiers formula for pulsi gravity stamps . jigging copper at laboratory slime Lake Superior h	Superior ee with Lake Superior ion velocity in jigg t Lake Superior table og-trough classifier	ior hydrau
Collom jig copper dressing at Lake Supperior Phoenix pneumatic stamp stamps in Quincy mill Mosser, W. F. & Co., rolls Motion of a solid through a liquid. H. S. Allen Poynting and Thomson Motors, increased use of induction motors in milling Motte's breaker	230 76 1433 1433 1927 58	new laboratory of Parson's jigs at Lake Superi Rittinger table separation by jig sizing tests of jig of tailings it illings it illin	Superior lassifier Bonne Terre, Collor or products Mill 25	lom jigs at 640 728 640 607 608
Mouchet, C., Harz jigs in the Vaucron mill. pointed boxes at the Vaucron mill. rolls at Vaucron mill stroke of jigs Vaucron, Var, France, mill for galena blende Mould for melting Mount Bischoff, costs and results at mill. D. Clark stamps at Tasmania, tin mill at tin dressing at. S. Fawns	2046 2034 225	Munroe's lalvoratory sli Muntz metal amalgama for amalgamatio plates, preparatic Murphys, California, T Muscovite, specific grav Musterschutz feeder	n plates n plates n plates ustin mill at vity of	
tin dressing at. S. Fawns mill. Hope mine, ore, magnetic separation of Lyell Tasmania, costs of producing copper in . 1957 Shasta, California, mill at Mounting a Blake breaker of jig sieves	1083 810 , 1958 1047	Mysore, India, cost of p Nacosari, Mexico, the p Layton	N new concentrator s	nt. H.B.
Moustier centripetal breaker Mouth of spindle and jaw breaker feed openings of gravity stamps Movable sieve power jigs, Bilharz oblong. Bradford eccentric Conkling Hancock vanning Hooper vanning	2010 54 166 503 500 503 504 505	Layton Nagel, M. L., free-settl Nagle's formula for bel Naphtha, specific gravi- Narod pulverizer bibliography for National Concentration Woodbury system Drill and Man breaker	Company, descrip	235, 282 297
intermittent Robinson Schranz sieve continuous power jigs hand jigs method of working table of practice in the mills jigs Hancock jig testing jig	500 504 503 499 495 497 498	Native amalgam copper ores, mills i Copper ores, mills i Natural feed on Wilfley Navaho mill Nederland mill, wear o. Needle wire gauge Needles for screens, siz Negaunee, Michigan, n Neill, J. W., on roastin Neodymium, atomic we Neodymium, atomic we	for table f amalgamating pa	781 990 1471 1092 108 249
tables for amalgamated plates Movements, head motion for Card concentrator New Standard concentrator Overstrom table Wilfley slimer tables of breaker jaws Moving power of water	733 1483 1478 1485 1504 1166 23, 34	Neon, atomic weight of Nernst lamp in Mill 17 Net yield	s of products of hankony	1871, 1931 1123 and picking 492 xx ony1174
Moxham, E. C., concentration plant of the Bertha Zinc Company, Virginia	1439 1105 152 1126 1170 1137	Neuerberg's mill, biblio rolls Neuerberg system of tr trommel wet mill Neuhof mill Nevada City, stamps at Consolidated Copp Engineering Work Goldfield Reductio	graphy for	293 110 364 385 233 1186 230 1866 1284
Haihaway Little Giant quartz mill, Oregon Mullo quartz mill or Merrill's mill	"1310 60	mills in		1284

Newaygo Portland Cement Company, Newaygo sep-	Nip, angle of for gyratory breakers	89
arator	for gyratory breakers	1218
screen, data on the	rolls	1226
separator	rolls Nissen, Peter, tests at Boston Consolidated mill	2013
table of capacities with various sizes of screens 1351 New Blanton cam	individual stamp mortar stamps at Boston Consolidated	1263
New Blanton cam	Home Pur Mill Descrit Address	1278
Bulfontein Diamond Co	Home Run Mill, Prescott, Arizona	1264
central mill of the Aktien Company 1786	connects of	1852
ore dressing plant, Clausthal	capacity of	2011
Century Blake breaker 1203, 1222	description of	2010
Century Blake breaker	Niter for melting	784
disintegrating screen	Niter for melting	752
drop motion jig537, 2022	Nitrogen, atomic weight of Nitze, H. B. C., and H. A. J. Wilkens, gravity stamps	1188
jig	Nitze, H. B. C., and H. A. J. Wilkens, gravity stamps	224
magnetic separator, Knowles	magnetic separation	835
Chum Consolidated mill, amalgamated plates in 745	magnetic separation	787
Comet mill, details of stamps	Wetherill magnetic separators	833
Newcum, W. A. 228 Elkhorn mill 1134 Newell & Newell, plates in Penn and Iron City mills,	Norbom vanner North Brookfield, Nova Scotia, ore from	652
Newell & Newell plates in Penn and Tron City mills	North Brookfield, INOVA Scotia, ore from	1147
Colorado	Nordberg Corliss engines	987
Colorado	manuscruming Company, tests on Northberg	1001
orado 229	steam stamps	1201
S. V., on drop of stamps 220	pump t Mill 182 rolls at Mill 182 single-cylinder steam stamp at Mill 179 indicator diagrams of	1011
Newfoundland chromite concentrated by free settling 475	single-cylinder steam stamp at Mill 179	1807
crushed by rolls, sizing test	indicator diagrams of	1251
sized in Richards' classifier	test at Mill 181	1250
New Himmelfahrt mill 958	steam stamp	2011
Newhouse mine and mill	test at Mill 181 steam stamp	
Mines and Smelter Company 1923	pound foundations, anvil blocks, mortar beds, sills,	1254
New Humboldt concentrator 1493 improved Huntington mill 1313 Jersey & Pennsylvania Concentrating Co., mill 1058	foundations, anvil blocks, mortar beds, sills,	
Tersey & Pennsylvenia Concentration Co. will 1050	and girderspiston, piston rod, dash pot, flange, revolv-	1247
bluestone rock, treated in Frisbee Lucop mill 267	piston, piston rod, dash pot, llange, revolv-	
costs of milling in	ing pulley, stamp stem, stamp shoe of	1247
costs of milling in	single cylinder	1249
mill in	tandem compound at Oscaela and Toma	1249
mill in	rack	1954
Nicinionicia Company, conveying beit of plant of Than	steeple-compound steam stamp at mills 1894,	1895
mill, S. Africa, E. G. Wary 2039	analys some assess seems at mind 100 x,	1901
mill, S. Africa, E. G. Wary. 2039 Mexico, mill in 1180 stamps in 226	North American Lead Company, Missouri, mill of the.	
stamps in	R. B. Brinsmade Brookfield, Nova Scotia, plates at	2042
plate error 747	Brookfield, Nova Scotia, plates at	765
plate error	Butte Mining Company Carolina, amalgamator	1836
mill 1004	Carolina, amalgamator	788
mill	mills inseparation of corundum in	1180
hydraulicking in	Norther purp	1000
Standard classifier	North Star mill	11027
concentrator 1478	Northey pump North Star mill California, A. D. Foote dies used in Grass Valley, California, milling practice at the. G. E. Alexander mortar plates in	2045
W. G. Weatherby	dies used in	180
Newton gold millxxviii, 1029	Grass Valley, California, milling practice at	-00
jigging mill xxviii mill .227, 1047	the. G. E. Alexander	2043
mill	mortar	165
mortar	pintes in	101
rate of crushing in	stamps	224
shoes and dies	ioundation	145
slope of screens	Mines Company A. D. Feets	188
slope of screens	central mill of	1020
	foundation. wear of shoes and dies Mines Company. A. D. Foote. central mill of mill	1017
York mill, acid water	mortar	162
York mill, acid water 173 Zealand, dredging in 1009, 1179, 1181 dredges in 1184 gold yield for April, 1899 2049 plates in 788 stamps in 202 900 907	mouth on Sultan mill Silverton Mining Company	167
dredges in 1184	on Sultan mill	1050
gold yield for April, 1899 2049	Silverton Mining Company	xxix
plates in	stamp mill	149
stamps in	stamp mill Nova Scotia, cost of milling in gold milling in ore, tests on mill in new mining plant at Salmon River. B. Mc- Donald	1133
N. Henninger's limonite washer	gold milling in	1174
Niagara crusher and pulverizer	mill in	1117
bibliography for	new mining plant at Salmon Piver B Ma	1104
Falls, power at	Donald Donald	9034
nulverizer sizing test on 918	stamp milling. E. P. Brown	2034
Niccolite, specific gravity of 1189 Nicholas pulverizer 233 bibliography for 099	Donald stamp milling. E. P. Brown mill practice.	2043
Nicholas pulverizer	Nozzles for water wheels	1000
Dibliography for	Number of compartments on jigs	507
r. C., the Edmore Hotation process 2030	drops of stamps	215
Nichola Chamical Co. mill	Tremain stampjaw compared with spindle breakers	138
Nicholas pulverzer	jaw compared with spindle breakers	51
Nicholson Frank blende in the Toplin district 1109	mills, key to	XXV
concentrating blende in Missouri 1199	strokes on line	, pas
Nichter spiral slate picker	See also Speed.	, o92
Nickel amalgam 730 atomic weight of 1188 in steel roll-shells at Mill 128 1714 magnetic separation of 833 ore, dressing of 1185	noc amo opeca.	
atomic weight of	0	
in steel roll-shells at Mill 128 1714		
magnetic separation of 833	Oakum for caulking Oberegger coal jig. V. Waltl	735
ore, gressing of	Oberegger coal jig. V. Waltl	2022



Pages 1199-1610, Vol. III.	INDE	X. Pages	s 1611–2052,	Vol. 1	īV.
Oberegger jig for coal washing Occasional expenses Ocean water, specific gravity of Ochre washing Octagonal revolving screens tronmels Octayonill W. A. Root	2021 1123 3 3 1353 362 2046 2048 2048 111 2028 1088 59 2025 1993 2029 2027 1072 2029 2027 1072 2029 1072 2029 1072 2029 7 1874 880 49 1094 1094 1094 1558	Opening for ventilation in wire screens, sizes of measurement of screen. percentage of, in jig scree. Operating costs with all slime filter-pres American Process Co Argall 4-tube drier Blaisdell system flotation processes. minerals separation p Oxland roasting furna Operation of Blake breaker canvas tables circular slime tables. Gates breaker hand jigs settlers slime tables vanners Wilfley roasting furna for Ophir Con. Mines Co., Color Oppermann, M., Harz jig a Utsch jig zinc dressing at Ammebe Orange peel dredge Order of drop of gravity stam at Mill 100 stamps at Mill 117	ns	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1099 1196 1362 546 1648 1648 1694 1694 1694 1694 1694 1694 1694 1694
Old Bed magnetic concentrating mill Buchanan breaker, table of movements of Clitters mine Dominion Copper Mining and Smelting Company copper handbook Globe, Arizona, concentration at. H. J. Baron English gauge 1195, screen gauge	1059 23 1915 1882 1925 2043 1999 173	mills Ordinary direct plot Ore bins breakers, Gates type concentrator, the Charlet deposits of U. S. and Ca dressing compared with s divisions principles, summary of granulating mill, Cummi handling, Blaisdell systen kind of, in gravity stamp sorting in S. African g	on nada. J. F. Ken melting	mp	1010 1142 842 1222 427 1924 1 5 1611
Oldham mill	765 765 220 60 7, 178 180 681 165 789 165 181 187 169 187 228 183 162 1184	Yeatman testing washing at Elkton mine weight of, before and alt Oregon, dredging in multer quartz mill Organization of labor in mill Oriental mill, amalgamated p life of guides mercury wells in Orion, Co., stamp mill Oro Fina mill, heavy stamps Plata mine, sizing tests of Oroville, California, dredging concrete mortar block at Orova-Brownhill mines. Av	er breaking lates in f ore from at		2021 1136 883 1190 1310 1310 145 155 771 120 220 1012
Old Hundred mill, Howardsville, Colorado Jordan & Galena Mining Co., mill	769 771 2045 2046 1189 1815 311 1144 2034 1181 12040 210 1134 290	Orpiment, specific gravity of Orthoclase, specific gravity of Oscola Consolidated Mining copper handbook mill. Burgan classifier at . Lake Superior, Michig Nordberg tandem, con slime tables in . Osmium, atomic weight of Osterspey, classifier invented discharge for jigs . jig siphon separator . Otago, dredge at . New Zealand, mills at plates at . Ottawa Gold Mining Co. plates used by	Co. .xxvii, 131, 995 gan. L. Fraser apound stamps at by	1181, 5, 1182, t	1189 1189 11906 11906 1371 2039 1254 697 1188 421 5842 478 703 1180 703 1157 741
Open-hearth high-carbon punched plate at Mill 180 life of Opening, discussion of the designations of size of E. A. Hersam	1802	Otto Abeling jig mechanism Ounce, equivalents of Ouray, Colorado, mill at Ouro Preto, Brazil, amalgam mill at	ating pan at		291



Own Posts Provide million of	
Ouro Preto, Brazil, milling at	Paper for lining cars
Outlines of mills	used in retorts 78 Parabolic formula, Rittinger's 78 for free settling 472, 47 Parallel arrangement of machines 111 rolls
Outside amalgamated plates	for free settling
fastening the plates to the tables 775	Parallel arrangement of machines
position of in the mills	rolls
principle of action	McFarlane 1234 Parallelism of rolls 7
total areas in mills	
Ovens district, amalgamated plates in745, 748	Paramagnetic substances
mercury wells in	sen, the Zollverein collieries, at St. Louis and
plates in	
Victoria, mills in	Lucien, Karlik grizzly bars, trommels 38 Park City, speed of jigs at 50
Overflow battery for gravity stamps	
Overhead crab	rarke and Lacy Company
Overlapping error on amalgamated plates748, 757	Diake breaker law movements o.
Overshot water wheel	Dodge breaker
	sizing box 410 Giant rock breaker 22
sampler 2032	Parker, R. A., false shoe 221
sampler 2032 table 679, 1479, 1485 at mills1487, 1711, 1712, 1730, 1880, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 18980, 1898, 1898, 1898, 1898, 1898, 1898, 1898, 1898, 1898, 1898, 1898, 1898, 18980, 1898, 18980, 1898, 1898, 1898, 1898, 1898, 1898	
1899, 1901	Parkin, C., pneumatic stamps in Cornwall 145 Parkyn, T., tin dressing at St. Dennis, Cornwall 1188 Parlow, P. G., on weight of stamps 222 Parnall-Krause stamp mill morter
test at Mill 162	Parlow P. C. on weight of stomms, Cornwall 1184
Owen, F., gold stamp mills in the Remedios district 1182 tin placers in Perak, Malay Peninsula 1182	Parnall-Krause stamp mill mortar 2011
tin placers in Perak, Malay Peninsula 1182	Parrot mill, Wilfley table at
Owyhee mill, banking in stamp mortar	Silver and Copper Mining Company 1836
details of stamps	Damana 9- 132-1
silver mill, amalgamation at	activantages of
Oxidizing roast for magnetism 1995 Oxland furnace at Mill 137 1548, 1741	construction of
Oxygen, atomic weight of	construction of 524 disadvantages of 514 Cyril, Huntington mills in southern Rhodesia 1326
effect of in copper plates	Cyril, Huntington mills in southern Rhodesia 1323
Ozocerite, specific gravity of	Huntington mills
	Wearing parts of Huntington mills 1915
P	rarsons distributor
*	Jig 640
Pachuca cams at Mill 101 1626	size of sieve and plunger
gramm haftery 1979	table
at Ionopan Mining, Milling, and Develop-	Partial turbine 977 Partitions across jig sieves 574
Packard, G. A., dry concentration at Round Mt.,	Partitions across jig sieves
Nevada 2038	Pasley, C. S., tin dressing in Bolivia
Packing for jig screens	Passau, Bavaria, Germany, mill at 107-Path of grains in trommel 376, 377
Paddock air jig	settling particle 453
assay of products of	Patterson Elephant stamp
Pails for concentrates	Patton amalgamating pan
for moisture samples	Paul, A. B., California and Colorado systems 228
Paint for mills	milling
table tops. 1483 Palladium, atomic weight of 1188	ball mill
	Paving blocks, strength of
Pallausch, A., graphite dressing in Bohemia 1177	Paxman mill 282, 297 Payne, C. Q. viii
Pan amalgamation	magnetic separatorviii
for silver, cost of	magnetic separator 798 mine, British Columbia, New Century magnetic separator at 1542
mills	separator at
notes on	Peace River Phosphate Company
settling tanks for	millxxv, 897 Peak Hill mine, amalgamated plates in
bottom of amalgamating pans	refort residue at
conveyors 860	Pearce, Arizona, ball mill at
sampler 846	S. H
Pandora mill 1016 1016 1016 2016 2016 2016 2016 2016	and Caldecott, W. A
Panning at clean-up	data on sampling
gold ore, dry	design of mining machinery
Pans, amalgamating and clean-up	discussion of H. A. White's results
continuous grinding	sampler for tailings
continuous grinding	sampler for tailings 884 tube mill grinding in S. Africa 2014
Cican-up 250	I carr (Australia) filli, wear of shoes and dies in
diamond washing	amalgamated plates in
hand panning	
washing 333 corundum and emery 333 grinding, Colorado Iron Works Company 1323	Pebble, Florida, mill at
corundum and emery	Pebbles, for tube mills, American. A. Lakes 2015
Australian practice	amount charged, formula for 1288
sizing tests of pulp from 1283	at mili 148
Australian practice 1283 sizing tests of pulp from 1284 wear of shoes and dies 1284	consumption of
Hendy	Petriline for Potter Scale 1027 Pebble, Florida, mill at 897 Pebbles, for tube mills, American. A. Lakes 2015 amount charged, formula for 1288 at mill 143 1770 C. C. Schnatterbeck 2016 consumption of 1291 for tube mills 1288 Peck's centrifueal elevator 2021 Peck's centrifue
versus tube mills	Peck's centrifugal elevator 2081
water for	separator828. 839
	Montana, concentrating mill C W Winter 2002
water for	Peck's centrifugal elevator 2031 separator 828, 839 Montana, concentrating mill. G. W. Winter 2036 Pein, A. von, rolls with tension rods 112



	TOT 1111 TYPE TO 1 1 MOVED
Pelton water wheels 931, 935, 939, 945, 947, 951,	Phillips, W. B. and A. Thies, stamp mill at Haile gold
1015, 1019, 1020, 1021, 1022, 1023, 1029, 1032, 1034, 1089,	mine, North Carolina 11
1090	concentration in Alabama 8
at Mill 96 1619	of Cranberry ore in North Carolina 11
for dredges	cost of milling 11
Penalties on Joplin zinc ores	magnetic concentration in Alabama 8
products at Mill 148 1793	of Cranberry ore in North Carolina 8
Penn and Iron City mills, plates in	roasting and magnetic separation of iron 11
mill, stamps in	for magneticm
	for magnetism
	Wetherill separator in Alabama
Pennsylvania, driving mechanism for trommels 357	Phlogopite, specific gravity of
mill, Grass Valley, Calif	Phœnix atmospheric stamp
Steel Company, Lebanon, plant of 1828	mill 1
Pepler ore feeder. D. J. Pepler	false bottoms in mortar 1
Pepler's operative device for the Challenge feeder.	inside plates 1
D. J. Pepler 2031	mortar î
Perak, Malay Peninsula, tin washing at 1182	rate of crushing in 1
Percentage of extraction in mills	mine, stamp at
moisture in ore	Phonolite and andesitic breccia crushed in Florence,
opening in jig screens 546	Colorado 1
screens	Phosphate dressing
Percy, C. M., picking belt of steel plates 492	in Belgium
reduction in rolls, diagrams of	Phosphates in Tennessee, milling of, R. D. O.
shaking riddles	Johnson 20
Percussion tables, bibliography for	mill for
Bartsch rotary	of the Pyrenees
	tune ted bus bridgerslip megale
belt	treated by hydraulic nozzle
Perfection laboratory breaker	in log washer
ore feeder 1578	washing 11
Perforated board for riffles 724	Phosphor bronze cloth screens 1
in classifiers	plate screens 1
plate and wire cloth screens, for medium and	Phosphorus, atomic weight of
fine work 340	Physical properties of minerals
plates in settling tanks	adhesion
Peridotite weathering of	change of magnetism by heat
	porosity by heat
Peripheral discharge tube mills of the Davidsen type 1297	color and luster
overflow, depth of discharge versus velocity of	decrepitation
discharge	greasiness
for slime tanks, use of lead strip for maintain-	hardness
ing level	magnetism
wood strip for maintaining level 1407	mineral aggregation
Periphery speed of rolls	specific gravity
Perm mine, mill	structure and fracture
works, double discharge on jigs at 584	tenacity and brittleness
Permeability for magnetic lines	
	Picker for slate
	Picking. See also Hand Picking.
Pernolet	belts
A., Carr disintegrator	at mills 1438, 1617, 1737, 1749, 1806, 1815, 184
A., Carr disintegrator	at mills1438, 1617, 1737, 1749, 1806, 1815, 184 1871, 1875, 1882, 18
A., Carr disintegrator 298 Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101	at mills1438, 1617, 1737, 1749, 1806, 1815, 184 1871, 1875, 1882, 18 detailed information on. E. H. Messiter 20
A., Carr disintegrator	at mills1438, 1617, 1737, 1749, 1806, 1815, 184 1871, 1875, 1882, 18 detailed information on. E. H. Messiter 20
A., Carr disintegrator	at mills1438, 1617, 1737, 1749, 1800, 1815, 184 1871, 1875, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137
A., Carr disintegrator 298 Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, velocity of particles falling in water and air 477	at mills 1438, 1617, 1737, 1749, 1806, 1815, 188 1871, 1875, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14
A., Carr disintegrator 298 Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637	at mills 1438, 1617, 1737, 1749, 1806, 1815, 188, 1871, 1875, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137
A., Carr disintegrator 298 Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637	at mills 1438, 1617, 1737, 1749, 1806, 1815, 184 letailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4
A., Carr disintegrator 298 Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V. pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance turnaces at Mill 105 1637 Pestarena, Italy, mill at 1637 Peter McFarlane Sons Iron Works Company, Horn	at mills 1438, 1617, 1737, 1749, 1806, 1815, 188 1871, 1875, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137
A., Carr disintegrator 298 Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499	at mills
A., Carr disintegrator 298 Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 152 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 111	at mills 1438, 1617, 1737, 1749, 1806, 1815, 188 1871, 1875, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4
A., Carr disintegrator 298 Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 152 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 111	at mills
A., Carr disintegrator 298 Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V, pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 spalling 11 E. D., Blake breaker at Sudbury, Canada 57	at mills 1438, 1617, 1737, 1749, 1806, 1815, 188 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4
A., Carr disintegrator 298 Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50	at mills
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 56, 57, 59 copper smelling xx	at mills 1438, 1617, 1737, 1749, 1806, 1815, 188 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 on conveyors 4
A., Carr disintegrator 298 Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V. pneumatic concentration 641, 837 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 56, 57, 59 copper smelling 51 copper smelling 51 xx xcost of breaking 51	at mills 1438, 1617, 1737, 1749, 1806, 1815, 188 1871, 1875, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 on conveyors 4 shaking table 4
A., Carr disintegrator 298 Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 56, 57, 50 copper smelting xx cost of breaking 51 dust chambers 885	at mills 1438, 1617, 1737, 1740, 1806, 1815, 188 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 on conveyors 4 summary of in the mills 4 summary of in the mills 4 summary of in the mills 4 servers 4 serv
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs . 641 ribbon theory of roll capacity . 101 V. pneumatic concentration . 641, 837 velocity of particles falling in water and air . 477 Perseverance furnaces at Mill 105 . 1637 Pestarena, Italy, mill at	at mills 1438, 1617, 1737, 1749, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 on conveyors 4 shaking table 4 summary of, in the mills 4 summary of, in the mills 485, 486, 488, 492, 14
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs . 641 ribbon theory of roll capacity . 101 V. pneumatic concentration . 641, 837 velocity of particles falling in water and air . 477 Perseverance furnaces at Mill 105 . 1637 Pestarena, Italy, mill at	at mills 1438, 1617, 1737, 1749, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 houses 4 in the mine 4 of rich ore for economy 4 of rich ore for economy 4 on conveyors 4 summary of, in the mills 4 tables 485, 486, 488, 492, 14 annular Allis-Chalmers turns
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs . 641 ribbon theory of roll capacity . 101 V. pneumatic concentration . 641, 837 velocity of particles falling in water and air . 477 Perseverance furnaces at Mill 105 . 1637 Pestarena, Italy, mill at	at mills 1438, 1617, 1737, 1749, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 houses 4 in the mine 4 of rich ore for economy 4 of rich ore for economy 4 on conveyors 4 summary of, in the mills 4 tables 485, 486, 488, 492, 14 annular Allis-Chalmers turns
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs . 641 ribbon theory of roll capacity . 101 V. pneumatic concentration . 641, 837 velocity of particles falling in water and air . 477 Perseverance furnaces at Mill 105 . 1637 Pestarena, Italy, mill at	at mills 1438, 1617, 1737, 1740, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 hund 4 hund 4 houses 4 of rich ore for economy 4 on conveyors 4 summary of, in the mills 4 summary of, in the mills 4 tables 485, 486, 488, 492, 14 annular Allis-Chalmers types 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 19
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V. pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting xx cost of breaking 51 dust chambers 885 hand versus machine breaking 59 rolls 109 Peterson, G. W., magnetic separation in Sweden 1569 Feiffer, J., Pfeiffer's mill 294 Feiffer's horizontal ball mill 234	at mills 1438, 1617, 1737, 1740, 1806, 1815, 188 1871, 1875, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 summary of, in the mills 485, 486, 488, 402, 14 annular Allis-Chalmers types 14 at mills 1783, 1780, 1787, 1792, 1795, 1805, 19 circular revolving 4
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V. pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting xx cost of breaking 51 dust chambers 885 hand versus machine breaking 59 rolls 109 Peterson, G. W., magnetic separation in Sweden 1569 Feiffer, J., Pfeiffer's mill 294 Feiffer's horizontal ball mill 234	at mills 1438, 1617, 1737, 1749, 1806, 1815, 1882, 18 detailed information on. E. H71, 1875, 1882, 18 of wire at Mill 137
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V. pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting xx cost of breaking 51 dust chambers 885 hand versus machine breaking 59 rolls 109 Peterson, G. W., magnetic separation in Sweden 1569 Feiffer, J., Pfeiffer's mill 294 Feiffer's horizontal ball mill 234	at mills 1438, 1617, 1737, 1749, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 summary of, in the mills 485, 486, 488, 402, 14 annular Allis-Chalmers types 14 at mills 1783, 1786, 1787, 1792, 1795, 1805, 19 circular revolving 4 compared 4 Humboldt 14
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 59 copper smelting xx cost of breaking 55, 57, 59 copper smelting xx cost of breaking 51 dust chambers 885 hand versus machine breaking 59 rolls 109 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer, J., Pfeiffer's mill 295 Pfeiffer's horizontal ball mill 234 mill, bibliography for 295 Pfordte, O. F., concentration at Casapalca, Peru 1180	at mills 1438, 1617, 1737, 1749, 1806, 1815, 1882, 18 1871, 1875, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 cost of hand picking 14 hand 14 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 shaking table 4 summary of, in the mills 4 tables 485, 480, 488, 492, 14 annular Allis-Chalmers types 14 annular Allis 1783, 1787, 1792, 1795, 1805, 19 circular revolving 4 compared 4 Humboldt 14
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 447 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 111 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting 51 dust chambers 885 hand versus machine breaking 50 Peterson, G. W., magnetic separation in Sweden 1509 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer, J., Pfeiffer's mill 295 Pfeiffer's horizontal ball mill 295 Pfordte, O. F., concentration at Casapalca, Peru 1180 eedge runners 295	at mills 1438, 1617, 1737, 1749, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 on conveyors 4 summary of, in the mills 4 anutar Allis-Chalmers types 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 19 circular revolving 4 compared 4 Humboldt 14 intermittent motion of 4 Krupp type 14
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 447 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 111 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting 51 dust chambers 885 hand versus machine breaking 50 Peterson, G. W., magnetic separation in Sweden 1509 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer, J., Pfeiffer's mill 295 Pfeiffer's horizontal ball mill 295 Pfordte, O. F., concentration at Casapalca, Peru 1180 eedge runners 1180	at mills 1438, 1617, 1737, 1740, 1806, 1815, 1882, 18 letailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 summary of, in the mills 485, 486, 488, 402, 14 annular Allis-Chalmers types 14 at mills 1783, 1780, 1787, 1792, 1795, 1805, 19 circular revolving 4 Humboldt 14 intermittent motion of 4 Krupp type 14 speed and capacity of 17
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting xx cost of breaking 51 dust chambers 885 hand versus machine breaking 59 rolls 109 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer's horizontal ball mill 295 Freiffer's horizontal ball mill 295 Pfordte, O. F., concentration at Casapalca, Peru 1180 edge runners 728 Pheby. F. S., battery frames 158 228	at mills 1438, 1617, 1737, 1749, 1806, 1815, 1882, 18 detailed information on. E. H.1. 1875, 1882, 18 of wire at Mill 137
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting xx cost of breaking 51 dust chambers 885 hand versus machine breaking 59 rolls 109 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer's horizontal ball mill 295 Freiffer's horizontal ball mill 295 Pfordte, O. F., concentration at Casapalca, Peru 1180 edge runners 728 Pheby. F. S., battery frames 158 228	at mills 1438, 1617, 1737, 1740, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 summary of, in the mills 485, 486, 488, 402, 14 annular Allis-Chalmers types 14 at mills 1783, 1780, 1787, 1792, 1795, 1805, 19 circular revolving 4 Humboldt 14 intermittent motion of 4 Krupp type 4 speed and capacity of 4 stationary 4 stationary 4 speed and capacity of 4 stationary 4 stationary 4 speed and capacity of 4 speed and capacity of 4 stationary 4 stationary 4 speed and capacity of 4 speed and capacity of 4 stationary 4 stationary 4 speed and capacity of 4 speed speed and capacity of 4 speed and capacity of 4 speed and capacity of 4 speed speed and capacity of 4 speed and capacity of 4 speed and capacity of 4 speed and capacity of 4 speed speed and capacity of 4 speed and capacity of 4 speed and capacity of 4 speed speed and capacity of 4 s
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting xx cost of breaking 51 dust chambers 885 hand versus machine breaking 59 rolls 79 Peterson, G. W., magnetic separation in Sweden 1509 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer's horizontal ball mill 294 mill, bibliography for 150 Pfordte, O. F., concentration at Casapalca, Peru 1180 edge runners 295 Pheby, F. S., battery frames 158, 223 Pheby F. S., battery frames 158, 223 Phelps breaker 68	at mills 1438, 1617, 1737, 1749, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 summary of, in the mills 4 annular Allis-Chalmers types at mills 1783, 1786, 1787, 1792, 1796, 1805, 19 circular revolving 4 compared 4 Humboldt 14 intermittent motion of 4 Krupp type 14 speed and capacity of 4 pickling comper plates 748, 7
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1037 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 56, 57, 50 copper smelting xx cost of breaking 56, 57, 50 copper smelting xx cost of breaking 51 dust chambers 885 hand versus machine breaking 109 Peterson, G. W., magnetic separation in Sweden 1569 Pfeiffer, J., Pfeiffer's mill 295 Pfeiffer's horizontal ball mill 234 mill, bibliography for 295 Pfordte, O. F., concentration at Casapalca, Peru 1180 edge runners 728 Pheby, F. S., battery frames 158, 228 Phelps breaker 518, 228 Philadelphia & Reading Coal Co., shaking screens 342 Graphite Co. mill 317	at mills 1438, 1617, 1737, 1749, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 summary of, in the mills 4 annular Allis-Chalmers types at mills 1783, 1786, 1787, 1792, 1796, 1805, 19 circular revolving 4 compared 4 Humboldt 14 intermittent motion of 4 Krupp type 4 speed and capacity of 4 pickling comper plates 748, 7
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1037 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 56, 57, 50 copper smelting xx cost of breaking 56, 57, 50 copper smelting xx cost of breaking 51 dust chambers 885 hand versus machine breaking 109 Peterson, G. W., magnetic separation in Sweden 1569 Pfeiffer, J., Pfeiffer's mill 295 Pfeiffer's horizontal ball mill 234 mill, bibliography for 295 Pfordte, O. F., concentration at Casapalca, Peru 1180 edge runners 728 Pheby, F. S., battery frames 158, 228 Phelps breaker 518, 228 Philadelphia & Reading Coal Co., shaking screens 342 Graphite Co. mill 317	at mills 1438, 1617, 1737, 1749, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 summary of, in the mills 4 annular Allis-Chalmers types at mills 1783, 1786, 1787, 1792, 1796, 1805, 19 circular revolving 4 compared 4 Humboldt 14 intermittent motion of 4 Krupp type 4 speed and capacity of 4 pickling comper plates 748, 7
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V. pneumatic concentration 4477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 111 Spalling 112 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting 51 copper smelting 51 dust chambers 885 hand versus machine breaking 59 rolls 109 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer, J., Pfeiffer's mill 295 Pfeiffer's horizontal ball mill 294 mill, bibliography for 295 Ffordte, O. F., concentration at Casapalca, Peru 1180 edge runners 295 Frue vanners 295 Frue vanners 158, 228 Phelps breaker 518, 228 Phelps breaker 518, 241 Graphite Co., mill 5035 dry gold concentrator E. B. Allen 5025	at mills 1438, 1617, 1737, 1749, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 on conveyors 4 summary of, in the mills 4 summary of, in the mills 4 annular Allis-Chalmers typics 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 19 circular revolving 4 thumboldt 4 intermittent motion of 4 Krupp type 4 speed and capacity of 4 of 4 stationary 4 Pick points, removal of 4 Pick points, removal of 6 Pictou, H. and S. E. Linder, action of arsenic sul- phide solution on electrodes 1
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V. pneumatic concentration 4477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 111 Spalling 112 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting 51 copper smelting 51 dust chambers 885 hand versus machine breaking 59 rolls 109 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer, J., Pfeiffer's mill 295 Pfeiffer's horizontal ball mill 294 mill, bibliography for 295 Ffordte, O. F., concentration at Casapalca, Peru 1180 edge runners 295 Frue vanners 295 Frue vanners 158, 228 Phelps breaker 518, 228 Phelps breaker 518, 241 Graphite Co., mill 5035 dry gold concentrator E. B. Allen 5025	at mills 1438, 1617, 1737, 1740, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 4 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 summary of, in the mills 4 annular Allis-Chalmers types 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 1805, 1805, 1805, 1805, 1805, 1805, 1805, 18
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V. pneumatic concentration 4477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 111 Spalling 112 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting 51 copper smelting 51 dust chambers 885 hand versus machine breaking 59 rolls 109 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer, J., Pfeiffer's mill 295 Pfeiffer's horizontal ball mill 294 mill, bibliography for 295 Ffordte, O. F., concentration at Casapalca, Peru 1180 edge runners 295 Frue vanners 295 Frue vanners 158, 228 Phelps breaker 518, 228 Phelps breaker 518, 241 Graphite Co., mill 5035 dry gold concentrator E. B. Allen 5025	at mills 1438, 1617, 1737, 1740, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 4 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 summary of, in the mills 4 annular Allis-Chalmers types 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 1805, 1805, 1805, 1805, 1805, 1805, 1805, 18
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V. pneumatic concentration 4477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 111 Spalling 112 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting 51 copper smelting 51 dust chambers 885 hand versus machine breaking 59 rolls 109 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer, J., Pfeiffer's mill 295 Pfeiffer's horizontal ball mill 294 mill, bibliography for 295 Ffordte, O. F., concentration at Casapalca, Peru 1180 edge runners 295 Frue vanners 295 Frue vanners 158, 228 Phelps breaker 518, 228 Phelps breaker 518, 241 Graphite Co., mill 5035 dry gold concentrator E. B. Allen 5025	at mills 1438, 1617, 1737, 1740, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 4 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 summary of, in the mills 4 annular Allis-Chalmers types 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 1805, 1805, 1805, 1805, 1805, 1805, 1805, 18
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V. pneumatic concentration 641, 837 resolventy of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 111 Spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting 250 copper smelting 50, 57, 50 copper smelting 51 dust chambers 885 hand versus machine breaking 59 rolls 109 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer, J., Pfeiffer's mill 295 Pfeiffer's horizontal ball mill 294 mill, bibliography for 295 Pfordte, O. F., concentration at Casapalca, Peru 1180 edge runners 295 Frue vanners 158, 228 Phelps breaker 296 Phelys, F. S., battery frames 158, 228 Phelps breaker 201 Phillips 1035 dry gold concentrator. F. B. Allen 2025 J. A., amalgamation 787 for silver 1174 amalgamating pans 200	at mills 1438, 1617, 1737, 1740, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 4 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 summary of, in the mills 4 annular Allis-Chalmers types 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 10 At mills 1783, 1786, 1787, 1792, 1795, 1805, 1805, 1805, 1805, 1805, 1805, 1805, 1805, 18
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 59 copper smelting xx cost of breaking 50, 57, 59 copper smelting 50, 57, 59 copper smelting 50, 57, 59 rolls 70 rolls 70 Peterson, G. W., magnetic separation in Sweden 1509 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer, J., Pfeiffer's mill 295 Ffeiffer's horizontal ball mill 2934 mill, bibliography for 295 Frodte, O. F., concentration at Casapalca, Peru 1180 edge runners 70 Frue vanners 158, 223 Pheby, F. S., battery frames 158, 223 Phelps breaker 78 Philladelphia & Reading Coal Co., shaking screens 342 Graphite Co., mill 77 hillips 67 for silver 78 for silver 78 for silver 78 for silver 1174 amalgamating pans 290 arrastra 290	at mills 1438, 1617, 1737, 1749, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 summary of, in the mills 4 summary of, in the mills 4 annular Allis-Chalmers types 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 19 circular revolving 4 circular revolving 4 circular revolving 4 circular revolving 4 speed and capacity of 4 fumboldt 14 intermittent motion of 4 Krupp type 14 speed and capacity of 4 Picking copper plates 748, 7 Pick points, removal of 1517, 1520, 20 powers of metallic salts on arsenious sulphide solution on electrodes 1517, 1520, 20 at mills 1517, 15
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V. pneumatic concentration 641, 837 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1189 Peters, hammers for breaking 11 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting xx cost of breaking 51 dust chambers 856 hand versus machine breaking 59 rolls 109 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer's horizontal ball mill 294 mill, bibliography for 295 Pfordte, O. F., concentration at Casapalca, Peru 1180 edge runners 728 Pheby, F. S., battery frames 158 Philadelphia & Reading Coal Co., shaking screens 342 Graphite Co., mill 1075 Phillips 1075 for silver 1174 amalgamation pans 290 gravity stamps 223 gravity stamps 223	at mills 1438, 1617, 1737, 1749, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 houses 4 in the mine 4 block system 4 of rich ore for economy 4 on conveyors 4 on conveyors 4 summary of, in the mills 4 summary of, in the mills 4 annular Allis-Chalmers types 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 19 circular revolving 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 19 circular revolving 4 stepp type 14 speed and capacity of 14 intermittent motion of 4 Krupp type 14 speed and capacity of 14 phide solution on electrodes 748, 7 Pick points, removal of 1517, 1520, 20 at mills 1517, 1520, 20 at mills 1517, 1520, 20 Mill 114, saying effected 16
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 447 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 56, 57, 50 copper smelting xx cost of breaking 51 dust chambers 885 hand versus machine breaking 109 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer, J., Pfeiffer's mill 295 Pfeiffer's horizontal ball mill 295 Pfordte, O. F., concentration at Casapalca, Peru 1180 edge runners 295 Pheby, F. S., battery frames 158, 228 Phelps breaker 58 Philadelphia & Reading Coal Co., shaking screens 427 Phillips 1035 dry gold concentrator. F. B. Allen 2025 J. A., amalgamation 787 for silver 1174 amalgamating pans 290 gravity stamps 223 Krom's rolls 100	at mills 1438, 1617, 1737, 1740, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 4 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 on conveyors 4 summary of, in the mills 4 annular Allis-Chalmers types 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 thumboldt 4 intermittent motion of 4 Krupp type 4 speed and capacity of 4 pickling copper plates 748, 7 Pickling copper plates 748, 7 Picklong copper plates 748, 7 Picko points, removal of 4 Pictou, H. and S. E. Linder, action of arsenic sulphide solution on electrodes powers of metallic salts on arsenious sulphide solution on electrodes 1517, 1520, 20 Mill 114, saving effected 1517, 1520, 20 Mill 114, saving effected 16 W. H. gold milling in Nova Scotia
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 447 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 56, 57, 50 copper smelting xx cost of breaking 51 dust chambers 885 hand versus machine breaking 109 Peterson, G. W., magnetic separation in Sweden 1509 Pfeiffer, J., Pfeiffer's mill 295 Pfeiffer's horizontal ball mill 295 Pfordte, O. F., concentration at Casapalca, Peru 1180 edge runners 295 Pheby, F. S., battery frames 158, 228 Phelps breaker 58 Philadelphia & Reading Coal Co., shaking screens 427 Phillips 1035 dry gold concentrator. F. B. Allen 2025 J. A., amalgamation 787 for silver 1174 amalgamating pans 290 gravity stamps 223 Krom's rolls 100	at mills 1438, 1617, 1737, 1746, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 summary of, in the mills 4 summary of, in the mills 4 tables 485, 486, 488, 492, 14 annular Allis-Chalmers types 4 at mills 1783, 1786, 1787, 1792, 1796, 1805, 10 circular revolving 4 timermittent motion of 4 Krupp type 4 pseed and capacity of 4 plickling copper plates 748, 7 Pick points, removal of. 9 Pictou, H. and S. E. Linder, action of arsenic sulphide solution on electrodes 1 powers of metallic salts on arsenious sulphide solution on electrodes 1 powers of metallic salts on arsenious sulphide solution on electrodes 1 Pierce amalgamators 1517, 1520, 20 at mills 1517, 1520, 20 at mills 1517, 1600, 16 Will 114, saving effected 16 Will 114, saving effected 16 Will 114, saving effected 16 Pierceite mines, France, mill at 11
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V. pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 111 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 56, 57, 50 copper smelting 51 dust chambers 885 hand versus machine breaking 50 rolls 109 Peterson, G. W., magnetic separation in Sweden 1569 Pfeiffer, J., Pfeiffer's mill 295 Pfeiffer's horizontal ball mill 234 mill, bibliography for 295 Pfordte, O. F., concentration at Casapalca, Peru 1180 edge runners 728 Pheby, F. S., battery frames 158, 228 Phelps breaker 578 Phillips 1075 Phillips 1075 dry gold concentrator. F. B. Allen 2055 Frue vanners 787 for silver 1174 amalgamating pans 290 gravity stamps 290 gravity stamps 290 gravity stamps 290 metallurgy 283 on height of discharge. 213	at mills 1438, 1617, 1737, 1749, 1806, 1815, 182, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 houses 4 in the mine 4 block system 4 of rich ore for economy 4 of rich ore for economy 4 of rich ore for economy 4 summary of, in the mills 4 summary of, in the mills 4 annular Allis-Chalmers types 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 19 circular revolving 4 summary of 4 compared 4 Humboldt 14 intermittent motion of 4 Krupp type 14 speed and capacity of 14 plick points, removal of 4 Pick points, removal of 5 Pick points, removal of 5 Pictou, H. and S. E. Linder, action of arsenic sulphide solution on electrodes 748, 7 Picker 1517, 1520, 20 at mills 1517, 1520, 20 at mills 1517, 1520, 20 Mill 114, saving effected 1517, 1520, 20 Mill 114, saving effected 1517, 1520, 20 Mill 114, saving effected 1517, 1520, 20 at mills 1517, 1520, 20 Atter magnet at 7 Sautter magnet at 7
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting xx cost of breaking 50, 57, 50 copper smelting 50, 57, 50 copper smelting 50, 57, 50 rolls 50 rolls 70 Peterson, G. W., magnetic separation in Sweden 1509 Peterson, G. W., magnetic	at mills 1438, 1617, 1737, 1746, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 houses 4 of rich ore for economy 4 of rich ore for economy 4 on conveyors 4 summary of, in the mills 485, 480, 488, 492, 14 annular Allis-Chalmers types 4 annular Allis-Chalmers types 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 tintermittent motion of 4 Krupp type 14 speed and capacity of 4 picking copper plates 748, 7 Pick points, removal of 4 Pick points, removal of 9 Pictou, H. and S. E. Linder, action of arsenics sulphide solution on electrodes 1517, 1520, 20 at mills 1517, 1520, 20 Mill 114, saving effected 1517, 1600, 16 W. I., gold milling in Nova Scotia 11 Picte mines, France, mill at 5 Sauter magnet at 15 Pick Hill mines 15 Picke Hill mines 15 Pick Hill mines 15 Picke Hill mines 15 Pick
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V. pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 111 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 56, 57, 50 copper smelting 51 dust chambers 885 hand versus machine breaking 50 rolls 109 Peterson, G. W., magnetic separation in Sweden 1569 Pfeiffer, J., Pfeiffer's mill 295 Pfeiffer's horizontal ball mill 234 mill, bibliography for 295 Pfordte, O. F., concentration at Casapalca, Peru 1180 edge runners 728 Pheby, F. S., battery frames 158, 228 Phelps breaker 578 Phillips 1075 Phillips 1075 dry gold concentrator. F. B. Allen 2055 Frue vanners 787 for silver 1174 amalgamating pans 290 gravity stamps 290 gravity stamps 290 gravity stamps 290 metallurgy 283 on height of discharge. 213	at mills 1438, 1617, 1737, 1746, 1806, 1815, 1882, 18 detailed information on. E. H. Messiter 20 of wire at Mill 137 17 Robins conveying 14 speed and capacity of 14 chutes 4 cost of hand picking 14 hand 4 houses 4 in the mine 4 houses 4 of rich ore for economy 4 of rich ore for economy 4 on conveyors 4 summary of, in the mills 485, 480, 488, 492, 14 annular Allis-Chalmers types 4 annular Allis-Chalmers types 4 at mills 1783, 1786, 1787, 1792, 1795, 1805, 10 circular revolving 4 tintermittent motion of 4 Krupp type 14 speed and capacity of 4 picking copper plates 748, 7 Pick points, removal of 4 Pick points, removal of 9 Pictou, H. and S. E. Linder, action of arsenics sulphide solution on electrodes 1517, 1520, 20 at mills 1517, 1520, 20 Mill 114, saving effected 1517, 1600, 16 W. I., gold milling in Nova Scotia 11 Picte mines, France, mill at 5 Sauter magnet at 15 Pick Hill mines 15 Picke Hill mines 15 Pick Hill mines 15 Picke Hill mines 15 Pick
A., Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs 641 ribbon theory of roll capacity 101 V., pneumatic concentration 641, 837 velocity of particles falling in water and air 477 Perseverance furnaces at Mill 105 1637 Pestarena, Italy, mill at 1182 Peter McFarlane Sons Iron Works Company, Horn rotary slime concentrator 1499 Peters, hammers for breaking 11 spalling 11 E. D., Blake breaker at Sudbury, Canada 57 breakers 50, 57, 50 copper smelting xx cost of breaking 50, 57, 50 copper smelting 50, 57, 50 copper smelting 50, 57, 50 rolls 50 rolls 70 Peterson, G. W., magnetic separation in Sweden 1509 Peterson, G. W., magnetic	at mills

Pilling Air Engine Company, pneumatic hoists 1608, 1610	Plate screens, stationary
table of sizes, capacities, speeds, weights, etc. of	
etc. of	table of details of
Pillow blocks for rolls	
Pinder concentrator 1479 2022 2023	
Pine board for amalgamation 750	mercury by amaigamating plates 1514
for riffles	acid water on
for riffles	amangamation
Pinita enerific gravity of	apron 740
Pinite, specific gravity of 1189 Pipe and plug jig spigot 527 conveyor 861	apron 7420 arrangement of 787, 742 bibliography for 787
Tipe and plug hig spigot	bibliography for
conveyor 801	bucking to remove nard amateum 780
covering 1091	cleaning
discharge for jigs 583 at Mill 137 1458	coated with amalgam
at Mill 137 1458	quicksilver 747
distributors	connection to mortar 798
launders at Guanajuato 1595	copper and silver-plated
sampler 845	versus silver-plated
sizes of	details of dressing and cleaning
steam for amalgamating pans	dimensions, area, and thickness
Pipes for gravity stamps	
launders	
water	
Pirchl. L. Meinecke classifier and spitzlutte 478	drops between 758
Piston in jig discharge	drops between
of Nordberg steam stamp 1247	offect of warm water
Pitch angle in trommels	for a malman water 750
for smoking moulds	TOP RIBERTATION. DIRIT COPPOR TIPPEUR PILVAN.
Pitkäranta, Finland, magnetic separation at 004 000	plated. E. Haise
Pitkäranta, Finland, magnetic separation at	. Itom battery, author advocates separating. P.
Pittshurg and Montana Conner Company	Morgan 2024
Pittsburg and Montana Copper Company 1836	graphite coating on
coal jig	grease on
washer, drawings of	gyrating
Pittsburg Foundry and Machine Co., rolls	how tastened to table
Monarch breaker at	inside amalgamated
Silver Peak Gold Mining Company 1634	lip
Placer County, California, sizing tests of stamp pulp 211	loss of gold on
deposits, testing of R. Nye 2036	maintaining of right consistency 758
helds of northwest America. T. Tonge 2040	materials for amalgamated 747, 1514
Placer County, California, sizing tests of stamp pulp 211 deposits, testing of. R. Nye 2036 fields of northwest America. T. Tonge 2040 gold. A McDougall. 2043	method of electroplating
burlap processs for saving. D. Macquire 2041	miscellaneous
recovered by dry panning	Muntz metal, conted with mercury 750
ground, working of. J. W. Pinder 2036	new scheme at Mill 66
burlap processs for saving. D. Macquire 2041 recovered by dry panning 816, 825 ground, working of. J. W. Pinder 2036 machines, dry 838, 839 Tierra Seca 838	of pure silver coated with amalgam 750
Tierra Seca	on mortar lip
material in sluices, mathematical discussion of the	splash board
action of L. St. Rainier	vanners and bumping tables
mines, cost of operation of. C. W. Purington 2047	outside amalgamated 731
	position of
ancient stream orayel to W Lindows 2041	preparation of new 752 principle of action 731
history of. J. M. Maclaren 2039 in Alaska. C. W. Purington 2042, 2045, 2047 costs of. C. W. Purington 2044 British Calumbia	principle of action 731
in Alaska. C. W. Purington 2042, 2045, 2047	proportions of gold and silver caught on 763
costs of. C. W. Purington 2041	removal of amalgam from
British Columbia	spots and stains
British Columbia 2040 California G. L. Holmes 2046 Columbia, S. America. F. F. Sharpless 2037 Guiana. H. Tweddle 2036 Siberia.	rubber for
Columbia, S. America. F. F. Sharpless 2037	shaking 740
Guiana. H. Tweddle 2036	sickening and flouring of mercury on 751
Siberia 2046	slope of 744
the Philippines. G. D. Rice 2036	sluice
on the Yukon. J. M. Bell 2047	sodium amalgam on 752
Siberia 2046	sodium amalgam on
plants 1006	stains on
plants 1000 of La Cienaga, Sonora, Mexico. R. T. Hill 2038 Alaska. L. M. Prindle 2047 the Seward Peninsula. F. H. Moffit 2047	stains on
Alaska. L. M. Prindle 2047	sweating with hot water 759
the Seward Peninsula, F. H. Moffit 2047	
	tables for 799
washing 702, 723 Placerville, California, mili at 1017, 1022, 1035 Placing of screens 170, 373 the mortar in stamp mills 148	
Placerville, California, mill at	use of galvanic couple and electric current on
Placing of screens	versus mercury wells
the mortar in stamp mills 148	
Plain copper plates coated with amalgam 747	
quicksilver 747	
comparison of with silver plated	
Diates 748 1772 1772 1772 1773 1774 1775	for gravity stamps
transverse troughs or riffles 772	
Plaminek, A., air blast for coal	Plating copper plates with silver
Hochstrate apparatus at the Rheinpreussen	Platiniridium, specific gravity of
	Platinum amalgam
Planet mill hibliography for 994 994	atomic weight of
	deposits of the Urals, C. W. Purington
Plaque for vanning	in dredging, the saving of
Plaque for vanning	Plating copper plates with silver 754 Plating copper plates with silver 754 Platiniridium, specific gravity of 1189 Platinum amalgam 730 atomic weight of 1188 deposits of the Urals. C. W. Purington 2033 in dredging, the saving of 2040 scrap, recovery of 1148
amalgamation 1611 use made of, in mills 890	2040 Scrap, recovery of
use made of, in mills	pure
annealing of, before amalgamating 747	
conveyors 860	
picking on	Floching, Prance, mill of
gauges	* 40 mb, ft. Mt., Icsuits from the bigke-Morgoner cen.
gaass launder mnings	REALOF 0000
screens, cost of	Plots of sizing tests
for gravity stamps	Plotting sizing tests

Discount for the	
Plug spigot for jigs	Power and Mining Machinery Co., improved Hunt-
Plunger clearance on jigs	ington mill
Plunger clearance on jigs	rolls 1244
	at will 100 1856
versus centrifugal pumps	size of crushed products from breakers . 1218 surface measurements in stone crushing by Von
Flungers and sieves, sizes of in mills 529	ISEVIE
attachment of to the connecting rods	applied to belt conveyors
Plush for tables	1030
tables on dredges	cost of for breakers
Pneumatic and spring stamps	crushing
products of 818	data in regard to
concentration	effect of strength and specific gravity on 313
bibliography for 837	for Alsing cylinder
concentrator, Hooper820	arrastra 000 000
hydraulic, and spring stamps	Dan min
pulverizer	Ball-Norton magnet 798 bucket conveyor 861
bibliography for 299 separation at Mill 151 1804	buhrstone mill
separators	breakers
Freid gravity dry-process separator 1553 Sutton, Steele & Steele dry table 1479, 1554	Bryan mill 272 273
Sutton, Steele & Steele dry table 1479, 1554	Cammett table 677
stamps 130, 224, 1257 bibliography for 143 Hughes 143	centrifugal pumps 869 clean-up pans 252
Hughes' 143	cone mill
Krause's 141 Pocket in launders 873	Cylcone pulverizer 289
Poech, F. J., Siemens and Friedrichssegen separators. 833	Delvik-Gröndal magnetic separator 804 Dodge pulverizer 262
Pointed boxes	Edison magnetic separators
at Friedrichssegen	electroplating copper plates 755
Rittinger type 411	Ferraris magnetic separator 799 Fraser and Chalmers rolls 97
tube classifier 421	Frisbee Lucop mill
Pole pieces for magnets	gravity stamps
Polybasite, specific gravity of	roller mili 283
Pomeroy dredge	Hancock jig 505
Ponds for water	hand electromagnet
Poor ore treated separately 1111	magnetic separator
Porcelain lining for Alsing cylinder	Hooper air jig 822
Porosity changed by heating	igs
Porphyry, strength of301, 302	jigs
roasting for 828, 890 Porphyry, strength of 301, 302 weight of 1190 Portable belt conveyor at Mill 135 1735	Langley's dry crusher 274
conveyors at Mill 167	magnetic separator used at Monteponi 810 mechanical batea 683
stamp mill 226	mills
Portage Lake foundry	movable sieve jig at Przibram
Porter-Allen engine	Narod pulverizer 282
electrolytic dissociation of slimes 1414	Pape-Elenneberg dry separator 820
J. A., gold stamp mill at the Smuggler Union	picking table
mine, Telluride, Colorado	Saizburg table
S. R., Baliol mill, Sutters Creek, California 1184	sample grinder 257
Port Henry iron ore concentrated by magnets 802 magnetite crushed by Sturtevant mill 288	Sautter magnetic separator 798 Schmidt spiral screen 863
sizing test on	Schranz mill
ore, magnetic separation of	settlers
Portland mill, Colorado City, Colorado	shaking screen
Port Oram, New Jersey, mill at	steam stamps, table of
Position of amalgamated plates	Stedman disintegrator 286 Sturtevant mill 288
Postlethwaite, R. H., dredging	tronmels 957
Posts for gravity stamps 153	Tustin's mill 262
Potash for cleaning mercury 786 Potassium, atomic weight of 1188 amalgam 780 Potassium, atomic weight of 188 amalgam 780	vanners
Potassium, atomic weight of	wash trommel
rot distributor 858	Wenström magnetic separator 802 Wetherill magnetic separator 805, 807, 808
retorts 791	Whelpley & Storer pulverizer 289
Potter flotation process 1555, 1561 D. Clark 1568	house for mill 1087
testing for 1993 Pound, equivalents of 1187	in crushing. E. A. Hersam
Found, equivalents of	continuous movable sieve
of water	Hooper vanning
1187	intermittent movable sieve
Powell, F., gold dredges on Snake River, Idaho 1181 the black sand problem 1511	Schranz 503
TUWER. See Morse-mower	measures of
amaigam squeezer	Cummings granulating mill
and efficiency of stamps	gravity stamps

ower of Husband stamp	Power required by Horn rotary slime concentrator 1	1500
rock emery mills	Humphrey rolls, table of	1235
rolls	Huntington mills at mills 1669, 1686, 1687, 1	
1723, 1730, 1757, 1768, 1794, 1802, 1827, 1830, 1835	improved Huntington mills, table of	1753
rolls 108 plant at mills 1639, 1675, 1680, 1698, 1709, 1712, 1723, 1730, 1757, 1768, 1794, 1802, 1827, 1830, 1835, 1856, 1859, 1863, 1871, 1874, 1887, 1895, 1899, 1906, 1912, 1913, 1914 required by agitators at Mill 103	improved Huntington mills, table of individual machines at Mill 139	1757
1912, 1913, 1914	Mill 154	1816
required by agitators at Mill 103 1634	International magnetic separators	1535
Allis-Chalmers suspended frame vanners . 1503 toothed and corrugated rolls, table of . 1243	at Mill 138 1746, 1747, 1	1748
Alsing tube mills table 1206	James table	1491
Alsing tube mills, table 1296 American Process Company driers 1599 Austin gyratory breakers, table of 1210 automatic tripper at Mill 174 1883 ball mills at mills 1830, 1914 Ball-Notton belt-ture magnetic accessory	swing hammer pulverious table of	1700
Austin gyratory breakers, table of 1210	iigs at mills	1030
automatic tripper at Mill 174 1883	Kennedy gyratory breakers, table of 1	214
ball mills at mills 1830, 1914		304
Dan-rotton, bett-type magnetic separator		
at Mill 158 1825	table of	542
type "M" magnetic separators	Kropp bell mills at Mill 198	930
drum-type magnetic separator at Mill 158 1822 type "M" magnetic separators 1825 type "M" magnetic separators 1825 Bartlett Simplex concentrators 1487 Bartsch rotary percussion table 1497 belt conveyors at mills 1634, 1667, 1690, 1691, 1707, 1709, 1768, 1769, 1771, 1772, 1853, 1882,	Knoph pumps at mills	215
Bartsch rotary percussion table 1497	Linkenbach table at Mill 146 1	786
pelt conveyors at mills1634, 1667, 1690, 1691,	magnetic separators at Mill 152 1	814
1707, 1709, 1708, 1709, 1771, 1772, 1853, 1882,	May Brothers' jigs at mills 1714, 1 McCully gyratory breakers, table of	723
1883 percussion table	McCully gyratory breakers, table of 1	212
Blake breakers at mills . 1618, 1634, 1742, 1749	McLanahan and Stone single-roll crushers,	749
1821, 1882, 1883	table of	241
	Mill 97	621
Bleichert gerigi framway at Will 130 1792	McLanahan and Stone single-roll crushers, table of	629.
breakers at Mill 144	105	639
Butters centrifugal agitating pump at Mill	111	656
	117	676
Card tables	118	870
at mills	120 1	685
centriugai pumps at milis1634, 1688, 1694, 1695,	123	690·
Chalmers & Williams vanners at Mill 1221687,	126 1	709
1699	128	715
cleaner jigs at Mill 148	132	720
cleaner jigs at Mill 148	138	74ß
cobbing magnet at Mill 164 . 1849 Cole shovel wheel at Mill 124 . 1693 conveying and picking belt at Mill 139 . 1749 conveying and picking belt at Mill 139 . 1749	141 1759, 1760, 17	762
conveying and picking belt at Mill 120 1740	$142 \dots 17$	768
crushing	145 1782, 17	783
crushing 1334 plant at Mill 174 1883 Davis rolls at Mill 144 1771, 1773, 1774 Denver Engineering Works Company's	147	700
Davis rolls at Mill 1441771, 1773, 1774		
Denver Engineering Works Company's	151	$2 \Omega A$
Blake breakers, table of	103	215
at Mill 140	104	216⊾
disc conveyor	155	317
at Mill 140	108 10	200
elevators at mills 1690, 1691, 1693, 1707, 1715, 1727, 1728, 1729, 1743, 1769, 1771, 1772, 1774, 1830, 1853, 1854, 1883, 1928, 1929, 1930	109	ะนก
1727, 1728, 1729, 1743, 1769, 1771, 1772, 1774,	161	40·
Elmore vacuum oil process 1528, 1929, 1930	162 1847, 19	30
Elmore vacuum oil process 1558 Evans jigs at Mill 162 1930	100 ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	152
Farrel-Blake breakers at Mill 124 1690 table of 1200 Ferraris ball mills, table of 1300	166	100
table of	1/1	71
remains ball mills, table of	1/4	107
magnetic separators 1525, 1527 table at Mill 146 1786 tables of 1490		
tables of		
Forsgren magnetic separator	170	97
	180 19 183 19 184 19 186 19 Monadnock Chili mills at Mill 144 19 Morris centrifugal pumps at Mill 130	na.
Frenier spiral sand pump at Mill 126 1708 Frue vanners at mills 1694, 1695, 1929, 1930	183	14
Frue vanners at mills 1694, 1695, 1929, 1930 Galena roaster 1548 Garland disc conveyors at Mill 124 1695 Gates ball mills, table of 1301 breakers at mills 1635, 1706, 1713, 1727, 1768, 1830 style "K" breakers table of 1208	184	14
Garland disc conveyors at Mill 124 1605	Manada ad Chair an 19	18
Gates ball mills, table of	Morris contributed runner at Mill 144 17	75
breakers at mills1635, 1706, 1713, 1727.	Morris centrifugal pumps at Mill 139 17. New Standard concentrator 147.	
1768, 1830		
style "K" breakers table of	Mill 180 19	01
118 1678	Mill 180	3 0
gravity stamps 1274 Griffin mills at Mill 105 1636 Griffin ells at Mill 105 1636 Griffin ells at Mill 105 1636		
Grill 4-compartment driers 1596	revolving driers at Mill 181	90 10
grinding pans at mills	raff wheels at Mill 128	02 06
Grillin milis at Mill 105 1636 Grill 4-compartment driers 1596 grinding pans at mills 1638, 1723 Gröndal magnetic separators 1537 at mill 159 1828, 1830 Hadfield breakers at Mill 130 1719 gyratory breakers at Mill 130 1723 Hancock jigs 1441	Robins conveying and picking belt at Mill 181.	06
Hadfield breakers at Mill 120	Robins belt conveyors at mills 1636, 1637. 175	0,
gyratory breakers at Mill 130	Robins 0000000 1830, 183	76
Hancock jigs	100	
Hancock jigs 1441 at Mill 162 1930	rolls at mills. 1690, 1691, 1693, 1707, 1711, 171	41
Harz jigs at mills 1296	1727, 1742, 1743, 1749, 1750, 1751, 1752, 1896	ď,
Hardinge tube mills	177. rolls at mills. 1690, 1691, 1693, 1707, 1711, 171 1727, 1742, 1743, 1749, 1750, 1751, 1752, 1830 1877, 1883, 1928, 1929, 193 sampling department at mills	šĠ
Hathaway gyratory breakers table of	sampling department at mills 1667. 188	34
	Samson breakers, table of) 3

		,	1 ages 1011-2002, VOI.	1 V .
	Power required by sand wheels at Mill 1171668, 1669,	, 1894	Preparation of pulp previous to amalgamation	1514
	scraper conveyor at Mill 126 screw conveyors	1709		
	at Mill 105	1007	tailings Preserving timber for mortar blocks.	1114
	shaking feeders at Mill 124 grizzly at Mill 124 launders at Mill 124	1691	Press for graphite	1075
			Presses for amalgam, Chalmers and Williams power	
	Sherman regrinders at Mill 1321728	1729	V	1519
	Sherman regrinders at Mill 132 1728, simple steam stamp at Mill 182	1909	Pressure box in classifiers	1518 419
	stamps at mills1618, 1624, 1634, 1668,	1679,	exerted by rolls	311
	Stroud mills, table of	$\frac{1769}{1321}$	machines compared with grinding	313
	Stroud mills, table of	1234		1188 108
	Dodge type breakers, table of emery mill at Mill 186	1205	springs on rolls	73
	rotary breakers at Will 186	1017	Presion, E. B., amalgam	788
	testing plant at Mill 141. trommels at mills . 1690, 1691, 1692, 1693, 1707, 1714, 1742, 1743, 1749, 1750, 1751, 1771, 1772, 1773, 1774, 1897, 1997, 1997,	1766	or rolls springs on rolls Preston, E. B., amalgam amalgamated plates	200
	trommels at mills. 1690, 1691, 1692, 1693,	1706,	Blake and Gates breakers	58
			breakers	ua
	tube mills at mills	1289	Bryan mill California gold stamp mills gold mill practice	$\begin{array}{c} 295 \\ 1179 \end{array}$
	at mills	1770	gold mill practice J gold mill practice J clean-up barrel pan Gates hydraulic classifier gravity stame	278
			clean-up barrel	294
	vanner at mills	1930	Gates hydraulic classifier	477
	various groups or machines at mills1706,	1780,	gravity stamps Griffin roller mill	228
	Vezin samplers at mills1835,	1836	Huntington mill	297
	Wetherill magnetic separators	1525	mercury trans	$\frac{297}{774}$
	Rowand magnetic separators at Mill 141	1763	order of drop of gravity stamps	274
	Wharton magnetic cobber at Mill 157 Wild roller mills, table of		snaking plates	741
	Wilfley slimers	1506	vanners	225 663
	Wilfley slimers	1729	stone breaker 2 Prichard, W. A., definitions of slime 1398, 1 Primosigh, E., separator at Pitkäranta, Finland	2009
	1694 1695 1708 1715 1720 1744 1	1688,	Prichard, W. A., definitions of slime	419
	1777, 1929, 1	1930.	Principles and purposes of gravity stamps 1	836 [262
		1490	rolls	62
		1669 1745	governing costs	
	at Mili 175	1890	of action of breakers compared	268
	rule for	1092	Wilfley table group	465
	sources of losses in crushing	1325	amalgamated plates	731
	summary for Mill 124 tests at Mill 173	1927	crushing machines	300
	transmission	1174	deep-pocket classifiers	549
	by ropetransmitted by belts	1094	notation processes	555
	used by breakers	53		144 610
	rolls	97	jigs	494
	steam stamps for breaking	310 50	magnetic separators	521
	friction of piston on water	603	mechanical sampling 1 operation of Willey slimer 1	5/4 504
	on jig walls	602	order of drop of stamps	215
	inertia of starting lifting sand	603 602	ore dressing, general	199
	mechanical friction	603	summary of	139
	oscillatory action	603	pulsion, general	460
	work of drawing the returning water down in crushing	602 309	pulverizers roll crushing1	231
_	jigging	602	sampling843, 8	224 240
į	ractical limits of settling in settling tanks	455	screen sizing	366
Ŀ	Practice, roasting practice in Wisconsin	1122	bibliography for	384
Ī	Pratt ore sizer	345	separation, combined	246
	A. H. Wethey 1	1360	suction	461
	-Wether screen	2018	vanner separation	865
Ī	recipitating agents for slimes	416	supplementary	870 5
Į.	-Wethey screen 2 Precipitating agents for slimes 1 Precipitating of gold solutions at Mill 117 1 Prehnite, specific gravity of 1 Prehnite, specific gravity of 1	673	used in mills	389
Ė	reliminary breakers, classification of	1800	Prinz and Rau dust collector at Mill 141	165
		9	Prister, A., slime settling	361 178
	bibliography for	55	Prize mill, acid water	173
	blasting in the minebreaking by hammers	9	Probert, F. P., comparison between Bryan mills and rolls for crushing jig tailings	
	calcining for friability with or without quench-		Sizing tests on Bryan mills	323 323
	ing by water	9	F. H., concentration of copper ore 1410 10	ליחו
	methods of	318 9	in Arizona	141
	washers	341	primitive Mexican mill	38
		334	r rocess, testing for	สา
P	remier diamond mine 1	OTL	r rocesses, notation, principles of	199 190
	mill, plates in	788	Product of Blake and Dodge breakers compared	36
p		481	breakers, size of crushed	218
T.	screen gauge	195 194		45
_	F. H., the Elmore flotation process	569	nand 11gs	505 198
P	reparation of new amalgamated plates	752		186
		77		

Pages 1611-2052, Vol. IV.

Pages 1199-1610, Vol. III.

Pages 1-643, Vol. I. ORE DRESSING. Pages 644-1197, Vol. I Product of jigs
Willey roasting furnace, fines sink in water 1547 Centripact screen 15
tailings pules 1112 In the filling fill the filling f
maximum
of ore dressing 1119 direct form 15 Progressive pulverizer 236 Richards' 15 Progressive pulverizer 299 use with jigs and tables 14
piphography for
Properties of mercury
Propte mill
Proportions between parts of stamps
stamps 190 on air Jigs 8 Proprietary mine 1715 hand Jigs 9 Prousitie, specific gravity of. 1189 jigs 9 Providence mill, Webb City, Missouri. D. T. Board- adjustment of 5
Providence mill, Webb City, Missouri. D.T.Boardana
plates in
stamps in 230 jigs 518, 520, 538, 6 wear of shoes and dies in 183 definition of 518, 520, 538, 6
Descrip Dishard and H. W. B. Kayser to dressing at for hindayed sattling tests
Bischoff, Tasmania
Prussian mine, air separation at 820 bibliography for 2 Praibram, Bohemia, mill at 1180 Cunnack's 57 center discharge at 582 bibliography for 2 braker at 57 center discharge at 478 477 478
classifiers at
feeders at 884 Dodge improved 2 hand picking at 492 Griffin 2
Heberli mill at
screens at 540 Heylandar Screens at Screens at State Meilne's 2
magnetic centrator at NZ 34 1 1 1 Th
mili at
movable sieve light at
WORK necessary for Crushing one kild of timer.
for jigs at
picking at
roasting for magnetism at
Salzburg table at
stamps at
Stroke of jigs at
trommels at
Pulley for gravity stamps 197 sand and water.
steam stamps
Pulp bed on vanners 661 Lancaster rotary 16 consistency for Wilfley tables and vanners 1848 sand 15 courser in amalgamating plans 245 versus sand wheels in Witwatersrand 16
current in amalgamating pans 245 versus and wheels in Witwaterstand 1702, 18 density for slime tables 695 Punched plate jig screens at mills 1792, 18 for vanner feed 660 screens 5
in amalgamating pans
amount of tank room required per ton of material treated. Mill 173 Purification of mercury 1413
at mills
Berenger and Stingls slime tank
classification of 1401 jigs 494, Colorado Iron Works, slime tanks 1407 affecting number of sieves 1 De Kalb's perforated-board classifier 1402 preliminary washers 1
De Kalb's perforated-board classifier 1402 preliminary washers 16 Merrill cylindrical clarifying tanks 1406 pulverizers 11 large cones 1406 rolls
Richards-Shepard spitzkasten 1401 stamps 113, 15 Sherman tanks 1404 power and capacity of Huntington mill
78

Pages 1199-1610, Vol. III.	INI	DEX.	Pages 1611-2052, Vol. IV	7.
Purtscher, E. Push conveyors	31, 1636 855 201 762 361 1189	Oninca	ver ore, dressed at Idria, Austria 48 5 the dressing of 107 granite, result of crushing 3 6, stamps in 2 1 ubbell, Michigan 2 1 upbell, Michigan 2 1 upper handbook 1181, 190 1 opper handbook 192 1 R	74
concentration in New York crushed in Mill 13	2038	Raborg,	W A separating quality for	26
crushed in Mill 13 dressing in Massachusetts. J. J. Rutledge plant of the Verein Chemischer Fabriken for jig beds in New York, concentration of. R. Brinsmade mill for 904, 905, 958, 958 milling in New York ore, mill for 900, 909, 910, 9 test on weight of	2038 1914 574 2037 061, 965 2047 013, 915	Radium Radius Raff wh a	, atomic weight of 1188 of slime tables 63 eels 864, 1806 t Mill 128 171	98795
weight ofrendered magnetic by heat	1105	Rag frai Ragian	Willey table 146: mes 1083, 150: Township, Ontario, mill at 107: iill at 1177, 118: i at 114: hurg tables of 114:	7 8
roasted for magnetism	1544	rolls	ill at	5
porosity specific gravity of with quartz and porphyry crushing in Mill 20. Pyrolusite, specific gravity of Pyrometer for regulating temperature in Wilfley fu	· 1189	Railway	Master Mechanics Association on screen 17: settle dust 109	3
nace Pyromorphite, specific gravity of Pyroxene, specific gravity of Pyrotite, hindered-settling test on settling velocity of specific gravity of	. 1548 . 1189 . 1189 17, 619	Ramsber	10	2
specific gravity of	66, 469	Pick	ing at	7
Q		Ramsey Rand, co	sludge tank	8
Quaker mine, Huntington mill atQuality of copper for plates	. 281 . 747	Sa	mpling in	9
rolls	. 47	W	ilings wheels in 865 eight of quartz 1160	0
product of Blake and Dodge breakers con	. 658	meta	l picking on the	9
work of classifiers	. 461	mill milli	G. A. and H. S. Denny	ĺ
trommels	. 100	mills ores,	on the	5
water for stamps in rectangular launders on circular slime tables	. 221 . 878	slime Randolpl	e treatment on the)
on circular slime tablesvanners	. 694	Bl	ake breaker at Clausthal	7
vanners Quart, equivalents of Quartering, coning and	. 1187 . 1577	dr	eakers 57 essing at Clausthal 1174 avity stamps 223	£
for sampling Quartz and galena, jig tests on	. 844 . 629 . 707	Fla	avity stamps 223 arz jigs at Clausthal 640 inted boxes at Clausthal 476)
used for film-sizing tests sphalerite, jig tests on angle of nip required to crush	. 628 . 94	roi	ls at Clausthal 109 oke of jigs 594 mmels at Clausthal 385)
free-settling velocity	. 707 . 471	_ mill,	acid water 173	3
hindered-settling test on	. 2017 17.622	Range of Rapid Ci	sizes fed to jigs 606 ty chlorination works, trommels at 354	į
in Banner mine mill, Bryan roller ore, capacity of Tremain stamp for	. 148 . 271	sta	Sizes teat to light Sizes Sizes	
pulsion jig test on	. 138 4, 625		Mill Company, Rapid Economy spring stamp	
ing Company	674 720	Rate of ti	all mill of Siller and Dubois	}
separation from gold by amalgamated coppe plate	4	tota	ween quartz and galena, hindered settling . 1460 al horse-power and that to overcome gravity	
settling velocity of	6, 469 1189	for c	n gravity stamps	3
in Mill 4	502	hinde	red settling 617	
weight of .1160 Quartzite, picked from gold in rock houses in the Rand, South Africa strength of	482 301	, t	rom experiment 1428 heoretical value for 1427 ncentration. See Individual Mills in Chaper XX. d to space between rolls 90	
Quebec ashestos dressing practice Queen & Co. Many colliery contributed a properties at	1159	gol	d to silver caught on successive plates 703	
Queen & Co. Mary colliery, centrifugal apparatus at 8: Quéhant, Ch. and O. Dupont, dressing lead and zin- in Belgium	10, 000 C 1185	cie	gyratory breakers	
Quenching for breaking rock after heating Quicklime in retorting mercury. Quicksilver. See Mercury. mill for	785	hin	Free settling	,
	79		forming or quarts and gardia 1720	

Pages 1-643, Vol. I.	ORE DRI	ESSING.	Pages 644-1197, Vol	l. II.
Ratios free to hindered settling, application t fier design	1429	products of slim stains on plates	e tables	689
table of free settling Rauft, T., gravity stamps	1426 225	wood at Mill 16 from ore prev Repairs. See also each	k points, etc	882 1607 1849
Huntington mill Ray Copper Company, the mines of the. A. Raymond automatic pulverizer George P., separation by decrepitatis	Hill 2036 236 on and	in vanners in mills, cost of on Blake breakers		50 663 1129 24
screening roller mill R. W. amalgamating pans Balch's magnetic separator	291	rolls, cost of Wetherill magne Reports	ttic separators, cost of	1525 1122
breakers Crocker's stamps double-cone classifier gravity stamps jaw plates	229 426 223	Repumping water Reserve capacity in mi Reservoirs, clarifying for water. See In	lls dividual Mills in Chapter XX.	1104
jaw plates mortars sampling in testing mills weathering at Meronitz, Bohemia Reaction wheel for sampling.	230 1175	Residue after reforting Residuum oil for separa for oil testing	ation	783 831 1155
Read, Thomas T., absorption of mercury by mating plates	amalga- 1515 1520 1516	smoking moulds Respirators Results at Mill 187 of classifying limo	nite ore	1094 784 1100 1920 405
Realgar, specific gravity of	643	film-sizing tests free-settling tests the tubular class Von Reytt's pow	sifier testsver and surface measurements.	719 466 613 306
Receiving cone for trommels floors	842 2025 177, 702	loss in		781 783 1519 781
gold in different parts of mill metals from skimmings in refuse waste in stamp mill	749 2025 2025 266	Mines Co., mill	oposed) at Mill 152xxv	1519 1814 931 i, 928 814
Rectangluar buddle Red Metal Mining Company River, Cornwall, tin washing tin works Reducing roast for magnetism	1182	for porosity previous to Revere Rubber Compan	magnetic separationny, conveyor belt at mills	829 1544 1706, 1819
Reduction, amount of, in rolls of iron ore to magnetic oxide ratio of, for gyratory breakers with rolls, diagram of percentage	92 813 1218	Revolutions. See speed and periphery speed	d of rolls	1707 87
Reed dry placer machine S. A., sampling Reese River process of amalgamation24 Refining at Mill 117	838 84 8, 1039, 1173 1674	slime tables steam stamps trommels Revolver for bottle tests	······································	88 696 128 349 1157
cost at Mill 106 plant of Mill 106 Reflectoscope for measuring mineral grains Re-grinding machines M. Schwerin	1643 1996 2014	convex slime tab convex slime tab devices used	ave slime tablesesle, Clark tablel	692 686 689 689
relative efficiency of . Regularity in feeding . Regular mill testing . Regulation of height of discharge in stamps .	1331 1114 1168 212	Schranz tab picking table cylindrical furnace distributor	le(Oxland) at Mill 137	689 689 490 1741 1418
temperature in Wilfley roasting furna pyrometer Regulators for water Reichenecker, A., amalgam dressing gold ores in Colorado	1548 858 788	driers	1746,	880 1762 328 334
gravity stamps Reifsnyder, Shimer and, sampling Reinforced concrete bins at Mill 160 Relation of angle of nip of rolls to feed an	224, 229 884 1834 l space 92	classification of cones, pyramids, Gates all-iron fra		1353 1353 361 1353 1356
rolls to angle of nip speed of current to size of grain in tanks surface to diameter of ore particle weight to surface of crushed product	settling 452 305	octagonal revolving grizzly Works Compas sectional	of the Denver Engineering	1353 1353 1353
gam as compared with hard amalgam on successive plates	7 amal~ 762]	strakes Rexroth coal jig Reynolds boilers		1355 725 641 997 1003
Reliance rolls at mills self-tightening cam Reluctance in magnetic field. Remedies for sickening of mercury. Remedios district, Colombia, mill in.	229 792 751	Edwin mill, fineness of ama Oscar, sealing amal Reytt, K. von	algam gam retorts	viii 764 1519 1185
Removal of amalgam from plates. coarse concentrates in jigs. concentrates on jigs.	757 576 586	gravity stamps	ssifying ss at Przibram	477 316 229 60
	80			

5 5 10 B

Pages 1199-1610, Vol. III.	IND	EX.	Pages 1611-2052, Vol. IV.
Reytt, K. von, Karlik gyrating screen screen and jig at Przibram Linkenbach tables mill machines moisture in drained ore- rolls versus other crushing machines Schranz mill Rheinpreussen colliery air blast at	729 1177 1185	Hidden Tr Premier m in the Tham	amation 787 Australia 788 stralia 788 stralia 788 easure mill, Colorado 788 easure mill, Colorado 788 es district, New Zealand 788 es district, New Zealand 788 aket tables; vanners and bump
Schranz mill Rheinpreussen colliery, air blast at 837 Rheinsh provinces, mills in Prussia, picking in Rhodesia, S. Africa, milling practice at. F. C. Roberts Rhodium, atomic weight of Rhodonite, specific gravity of Rhodonite, specific gravity of Rhyolite, weight of Rhyolite, weight of	816 1176 481	Colorado system copper mills of	n versus California system . 227, 1175 Lake Superior . 1419
erts Rhodium, atomic weight of Rhodochrosite, specific gravity of Rhodonite, specific gravity of Rhyolite, weight of	2044 1188 1189 1189 1190	gold milling in	Australia
Rhyolite, weight of Ribbon theory of roll capacity Ribbet aerial tramway at Mill 124 Rice, C. T., Kinkead mill at Goldfield, Nevada milling at Virginia City, Nevada	101 1696 2038 2038	Otago, N Thames, in Amador Gilpin C	1860 1860 1870
Rice, C. 1., Kinkead mill at Goldheld, Nevada	1382 1743, 1778, 1867 1886	gravity stamps	223, 224, 226, 228
classifiers at mills	1367 1898 393 884	narrow sluice pl	Mexico 2045 Superior 1997 o, Australia 788 104, 105 lates 788
stamps versus other crushers pocket vortex classifier pulsator classifier direct form 1388,		plates and traps	stamps 215 15 15 16 17 17 17 17 17 17 17
fourteen-day test at Mill 102	1391	pneumatic concernment	entration 788 entration 837
nine-day test at Mill 162 table of sizes, capacities etc., of iig	1456 1455 1456 1455	shoes and dies size of plates sluice plates stamp milling	56
Rapid Economy stamp R. H. and Locke, C. E., dressing of tin ores tests on a surface current box classifier A. E. Woodward, curves for free-settling		in United Zealand mills at Ballar	l States, Australia, and New 227 at. Victoria 226
edge runners	476 2047 295 640	in the Biack	[ew Zealand 226 New Zealand 226 [c Hills] 227
glass classifier and slime table gravity stamps Richards-Coggin classifier school laboratory work a free milling gold ore sieves classifiers and ilirs	223 476 2048 1175	stamps for differ steam stamps fo water used in sta Ricketts, L. D.	unty, Colorado 226 ent purposes 227 r gold in Black Hills 142 amp mills 222 1875
silver amalgam slime tables spitslutte study of the Wilfley table	787 728 470 1511	power tests by . Riddles	d at Grass Valley 1176 unity, Colorado 228 ent purposes 227 r gold in Black Hills 142 amp mills 222 1875 1875 1875 184 klies 341, 384 klies 345 vashers and wash trommels 335 1188, 1186
Richards-Coggin classifier. school laboratory work a free milling gold ore sieves, classifiers, and jigs silver amalgam slime tables spitchattle. study of the Wilfley table on different feeds testing a jig for a mill process jig typical methods of milling in Missouri undercurrent for saving black sands. 1419.	2022 1176 1183 1174 2040	versus trommels . Ries, Heinrich, basin v washing clays Riffle bars on revolving	vashers and wash trommels . 335
velocity of galena and quartz falling in water	1433, 2020	cast-rubber for	1409
hindered-settling classifier hydraulic classifier, estimated capacities of with different sizes of sorting columns	1384 405	for Delster con for New Standa	
sizing test of products of	1386	height of	## 1407 ## 1468 ## 1467 ## 1407 ## 1408 ## 140
Richardson automatic weighing scales	1872 1727 1276	tables	
Rich ore picked out for economy treated separately Rickerd T A across the San Juan mountains	481 1111 1923	bibliography for	723 721 721 727 729 729 720 720 720 720 720 720 720 720 720 720
adaptation of gold stamp mills. amalgamated plates735, 737, 745, 747, 762, 768 amalgamating pans	787 290	containing mercu	ry

rages 1-045, vol. 1.	Old Di	.UDDDIIT G.	1 4800 011 1101, 101. 11.
Differ containing managery adventages and	diend_	Distinger P R	von, movable and fixed sieve jigs,
Riffles containing mercury, advantages and		Kittinger, 1. K.	pumpe
vantages		pointed	i boxes, spitzlutt, runs 4.70
expanded metal	722	schleud	lermühle
for gold dredging	703	separat	ion by centrifugal force
mercury frams	772	settlers	787 npe and Harz jig 639
sampling	844, 1570	setzpun	npe and Harz jig 639
forms of	721	sieve so	cale, screens, riddles and trommels . 385
used in sluices	723 770	spannig	g and cobbing hammers 56 washers 334
Grass Valley		rectangular	washers
Hungarian	725	roll speeds	
Hungarian La Point suspended riffles	1509	round conve	ex buddle
on dredges	1012	rule for mid	dlings 1086
tables	675-679	runs	448
on dredges tables advantages of	679	separation b	by centrifugal force 827
Wilfley table	672	setzrad	478
plain transverse	$ \begin{array}{ccc} & 722 \\ & 644 \end{array} $	sieve scale	
principle ofrevolving strakes	725	for te	esting screens
Robinson	721	skimming si	ieves 577
rock	721	slope of jig	sieves 548
sluice	1464	tables .	667
timber riffle blocks	721	spalling	11
undercurrents		specific grav	rity test
use upon slimers	1498	spuzkasien.	433, 1367
Rigid rolls	1001 1006	shitzlutte	409
Denver Engineering Works Company de	scrin-	stay battery	229
tion of	1235	and ove	erflow battery 214
Right and left hand cams	195	stroke of jig	s 594
Ring and cone for sampling		sweening tal	hle 703
for amalgamating pan	244	table;	
stamp cams	192	compared	with willey 679
headsteam stamps	185 120	cruehin	vantage of jig over free settling 625
Rings, details of, from mills	122		g
Rinsing cylinder	335	thickness of	screen plate 372
table for hand picking	488	under-piston	i jig 520
Risdon Iron Works	viii, 1859	velocity of s	troke of jigs 595
amalgamating pan243, 244, 245, 24	6, 247, 249	wash tromm	nels 329
Blake breaker Bryan mills at Mill 173	22	Width of jig	sieves 591
clean-up pan	251	nebble phoc	or gold
crack-proof vanner belt	1503	Roasted blende a	phate
dredge	1653	Roasting and ma	ignetism
dredgeopen-connected type	1654	arsenopyrite	agnetism
vanner	651. 652	for friability	
weight of spider and driving cone made	e by. 247	leaching .	1168
Rittinger, beveled rolls	$$ $\frac{71}{507}$	magnetisn	1 790, 799, 800, 813, 1543, 1544, 1611
capacity of jigs coarsest size jigged concave buddle	597	hibliogr	148
concave buddle	706		f carbon in 1544
double trough classifier	416	experim	ents in roasting pyrite 1544
duck tables	702	in testin	ng
feeding rolls	71	mineral	s which become magnetic on roast-
figures on hand jig formula for amount of throw of jigs	49	ing .	le of, in mills 1995 800 828, 839, 890, 1611 e in tin ores 1081
free settling	595 471 1421	norosity	200 01, In Initis
free settling	11	wolframite	e in tin ores 1021
nand jigs	497. 499		
jig	643	at Friedric	chssegen, Germany
mechanism		mills	
plunger clearance	530	Dings	
length of jig sieves	592 507	Gaiena Howell W	
parabolic formula	471	at mi	hite
pointed boxes	411. 439	Mathey, a	t Mill 148
tables of sizes of	440	MCDouga.	Il type 1546
power for jigs	603	Oxland fu	rnace 1548
required for crushing	313	Trego	
principles of ore dressing	1050 1104	Wilden for	148
		iron ore	58
Blake breaker	56	ore, effect or	power required for crushing 313
breakers, hammers, and roasting for fria	bility 56	practice, Wis	sconsin 1548
buddles, percussion tables, slime tables	728	silver ores .	
Carr disintegrator	298 292	tin ores	1082
cone mill crushing machines	316	Robbine A C	alcium sulphate
details of hand picking	400	Dayton Nevoc	amalgamation and concentration at
edge runnerselevators, sand wheels, and conveyors	295	Robert, F. C. C.	ta
elevators, sand wheels, and conveyors	884	cost of cor	structing a 20-stamp mill 2049
fluted rolls	100	Huet and	Geyler's jig. 641 r stamp mill at Grass Valley. 1182
gravity stamps	223	North Sta	stamp mill at Grass Valley 1182
gravity stamps grist mill or buhrstone mill Harz jigs movable sieve jig	291		
Lenrouch	XX	Robins belt con-	MI 1183
magnetic congretore	200	at mille	.1636, 1637, 1661, 1797, 1750, 1805, 1806
mathematical discussion Cornish rolls.	109	1807.	031 1183 eyor805, 859, 1585, 1610, 2031, 2033 1636, 1637, 1661, 1727, 1750, 1805, 1806, 1808, 1809, 1810, 1811, 1812, 1813, 1821, 1823, 1824, 1825, 1826, 1828, 1876, 1913
mill schemes	1174	1822.	1823, 1824, 1825, 1826, 1828, 1876, 1913
	9	29	

Pages 1199-1610, Vol. III.	IND	EX. Pages 1611–2052, Vol. IV.
Robins belt conveyor in Blaisdell system	1602	Roll shells, truing with emery wheel 1243
stamp millspicking belt	2031 1438	wear of
at the West Aurora mill	2021	Rolls 62
Thomas, Jr., Robins belt, rollers, etc. Robinson coal washer (classifier) Deep Gold Mining Co., Ltd., mill of Diamond Mining Co. gold mine, mill at	88 4 478	action of on ores
Deep Gold Mining Co., Ltd., mill of	1648	
Diamond Mining Co	839 1184	an article on
jig	504	Argall rolls
jig mill, details of stamps riffle	$\frac{221}{721}$	as regrinding machine
washer for coal Roche-la-Molière colliery, coal washing at Rochelt, F., automatic slate picker for coal	447	1691, 1693, 1701, 1707, 1710, 1716, 1720, 1724, 1737,
Rochelt F automatic slate picker for coal	2050 493	1738, 1742, 1743, 1749, 1750, 1751, 1752, 1760, 1761, 1762, 1766, 1767, 1771, 1772, 1773, 1792, 1793, 1803
Rocheux, double discharge on jigs at	584	1806, 1807, 1808, 1819, 1822, 1824, 1825, 1828, 1829,
dle Breakers.		1832, 1833, 1837, 1838, 1843, 1844, 1853, 1854, 1857, 1859, 1864, 1865, 1866, 1867, 1868, 1869, 1877, 1878,
breakers	13	Reliance 82 an article on 2010 angle of nip for
Hathaway gyratory	1215	auxiliary spring 80-babbitting 73
in reserve	1109	babbitting 73 Becket Foundry & Machine Co. 76 belted 75
kinds of Krupp	1202	and geared 79
gyratory	1215	beveled
McCully gyratory	1210	Birmingham Iron Foundry
gyratory location of McCully gyratory method of operating separate motor for emery mill bibliography for horizontal	13	Bowers
emery mill	2, 253	Buchanan
bibliography for	291	capacity of
		Chicago Iron Works
house, picking in	482	choke and free crushing by
house, picking in	1419	coarse and fine. C. Blömeke 2010
riffles	$\frac{721}{722}$	Colorado Iron Works
Rocking stone mill	1084	and geared
table320,	1032	comparison between free and choke fed rolls 1229
Rodda, J. T., new form of stamp	228	core of
Roebling	1195	corrugated
screen gauge	173	table of sizes, capacities, and
powders, effect of water on. A. S. Cushman riffles. Rocker Rocking stone mill. table320, Rocky Mountain millxxix Rodda, J. T., new form of stamp Roebling. Roebling's gauge Screen gauge Rogers, A. N. Colorado versus California system of milling. data concerning slime tanks.	787 1174	power
data concerning slime tanks. gravity stamps 22: Rogers' dewatering screen at Mill 144	1408	remire on 104
Rogers' dewatering screen	*, 220 1591	diagram of percentage reduction in 122
at Mill 144	1592 642	diameter of
jig	293	discussion of
Rohrmühle Rolker, C. M., Allouez mill, Lake Superior Ball stamp. Collom jig at Lake Superior	1174	driving mechanism
Collom jig at Lake Superior	640	Eckart 111
concentration at Glasdir, Wales cross pieces on jigs Evans slime table and kieve	1183 551	Edison's
Evans slime table and kieve	728	giant 105
hog-trough classifier	476 1109	three high
milling in Utah	1174	efficiency of
hog-trough classifier mill capacity milling in Utah Rolled saw plates at Mill 180, life of steel for wearing parts of rolls.	1243	efficiency of 109 E. P. Allis Co. 72, 76 features and faults of 1229 feed to 63, 1224
Roller feeder	80%	feed to
C-16C-	000	feeding of
Huntington centrifugal Kent mill number used table of details of Kent mill Wild mill	276	fines produced by 308
number used	231	finger geared
table of details of Kent mill	1304	formula for angle of nip
table of sizes, capacities, power, weight,		vanners
etcquartz mills, Bryan	$\frac{1304}{271}$	Fort Scott Foundry & Machine Co
shells for Huntington mill	280	Fraser & Chalmers
Rollers for belt conveyors		geared
Roll jaw breaker. Sturtevant	32	Gates Economic
Blake breakers, Sturtevant	1205 2010	geared 75
L. H. Sturtevant	2010	and helted compared 88
shells	66 1716	Gever
cost of	69	graded crushing by
materials for	68	Hendy & Meyer 76
of chilled steeltruing of	2011	hexagonal cores 109 high-speed 88
device, Sturtevant	1243	sizing test of pulp from

Rolls, high-speed versus Bryan mills	1309	Rolls, Tuttle Manuf
hoppers and housing	83	types of
horse-power of	64	types of Union Iron Wo
Humboldt high-speed rolls	1241	use of for Dritti
Humphrey rolls	1234	used in brick m
hoppers and housing horse-power of Humboldt high-speed rolls Humplurey rolls table of sizes, power, speeds, weights, etc.	1235	velocity of appr versus ball mile
in stamp mill	1017	Chili millo fo
journal friction	90	Chili mills fo disintegrators
J. W. Jackson's), 111	gravity stamp
kept true	60	gravity staint
Krom belted	110	grinders Heberli mill.
Twen high aread	1238	Huntington r
table of sizes, power, speeds, weights, etc. in stamp mill journal friction J. W. Jackson's kept true Krom belted Gates, and other makes Logates, and other makes Lever and weight made by Power and Mining Machinery Company	73	stamps
made by Power and Mining Machinery Com-		steam stamps
Dany	1245	at Mill 1
material for wearing parts of	1243	Sturtevant m
materials cost, wear, etc.	66	Vezin, made by
material for wearing parts of materials cost, wear, etc. McFarlane 72 76, McEamahan and Stone single-roll crusher	1232	Walburn-Swens
McLanahan and Stone single-roll crusher	1241	Wall's corrugat W. F. Mosser
method of cleaning M. Hoagland Sons Co. Milburn's crusher Montana Iron Works	2011	W. F. Mosser
M. Hoagland Sons Co	.77	width of
Milburn's crusher	111	Wilds with flanges
Montana Iron Works	76	
Neuerbergs	770	fluted surface
Odell's	111 990	teeth
on native copper ore	88	sluggers and
	71	without springs
pillow blocks and alignment	ล่กั	Rompf jig screen.
Distabuse Foundry & Muchine Co	76	Roofs for mills
nower and wear	108	Root rotary pump .
pillow Blocks and alignment for Pittsburg Foundry & Machine Co. power and wear for 99 pressure exerted by of	5. 106	W. A., the Mac
pressure exerted by	311	Rope conveyors, pic
of	108	drive for sand
011	73	tramway
on	62	transmission
of roll crushing	1224	Ropes, L. S., mil
products crushed by	63	Creorgia
proper amount of reduction	92	Rosales, Henry, au
quality of crushing by	98	gravity stamp
principle and purpose of of roll crushing products crushed by proper amount of reduction quality of crushing by ram for ratio of feed to space	112	Rose, T. K amalgamatin
ratio of feed to space	$\frac{90}{1226}$	amalgamator
reduction	1,220	
relation of diameter, feed, space, and angle of	92	arrastra Blake and Sc
nipspeed to angle of nip	94	breakers .
	0.5	
Reliance ribbon theory of capacity rigid	111	clean-up pan Crawford mi
ribbon theory of capacity	101	Cyclops mill
rigid112,	1235	gold from pla
Roger's), 111	gravity stamı Harz jigs
running at different speeds	88	Harz jigs
Schellenbach Sons	76	Huntington 1
Schwarzmann's10	9, 110	Husband pn
scrapers for	75	spring stan
sectional shaft, journal speed, etc.	81	Jordan's cen Krom jig an
shaft, journal speed, etc	76	Krom jig am
SHRIES	65 74	rolls large steam s
shims for	71	lime for slim
side adjustmentsize of feed	ģô	metallurgy of
amond as positive at a	107	metallurgy of pointed boxe
sizes of	64	retorts
speeds, etc. treated by weights, and speeds sizing tests on	72	riddles versu.
treated by	63	size of stamp
weights, and speeds	79	Roseberry, B. C., c Rosenlecher, R., dr
sizing tests on9	9, 315	Rosenlecher, R., dr
test on pulp of coarse and fine rolls at Mill		Roskelly, I., stamp Ross, J., Jr., Wildr Rossland district, B Rotary breaker at I
162	, 1329	Ross, J., Ir., Wildr
spaces between	64, 89	Rossland district, B
special forms	104	Rotary breaker at I
speed of	09, 80	drier at Mill 18 percussion tabl
rolls and speed curves	70	percussion tabl
spring pressures on	06	Rotation of gravity
test on pulp or coarse and line rolls at Mill 162	79	Rothwell John E.
S R Krom's	72. 77	Rothwell, John E., rolls for chlo
Sturtevent balanced rolls	1232	R. P., Blake b
springs or weights for S. R. Krom's Sturtevant balanced rolls table of sizes, power, weight, dimensions,	-=	in Onta
etc	1234	Linkenbach
centrifugul rolls	1237	Ontario, Sil
Superior crushing rolls table of data from the mills value of forces acting at different angles	1231	mines in I
table of data from the mills	64	Rotter, Max
value of forces acting at different angles	94	Rough-crushing der
tests on work required for rolls	300	Roughing jig jigs at Mill 14
Thum's compound	. 110	jigs at Mill 14
Thum's compound	, 2010	plane, definitio
Triplex rolls	1920	Roughness, effect o Rough, unplaned p
	1200	avough unmailed b

Rolls, Tuttle Manufacturing & Supply Co	70
types of	. 76
Union Iron Works	72, 111
use of for brittle ores	. 314
used in brick manufacture	. 2011
types of Union Iron Works use of for brittle ores used in brick manufacture velocity of approach in versus ball mills at Mill 159 Chill mills for clays disintegrators	. 314 . 1830
Chili mills for clays	2010
disintegrators gravity stamps grinders Heberli mill Huntington mills	298
gravity stamps	. 222 . 110
grinders	. 110
Huntington mills	· 258
stamps	24. 314
stamps 22 steam stamps at Mill 179	. 110
at Mill 179	. 1900
Sturtevant mill Vezin, made by Colorado Iron Works Walburn-Swenson Co. Wall's corrugated finger gear W. F. Mosser & Co. width of Wilds	. 111 . 84
Walburn-Swenson Co	. 76
Wall's corrugated finger gear	. 111
W. F. Mosser & Co	. 76 . 83
width of	. 83
Wildswith flanges	. 72
fluted surfaces	. 110
knobs	. 106
teeth1	İ1, Î12
sluggers and knobs	. 104
without springs	. 74
Rope conveyors, picking on drive for sand wheels	1088
Root rotary pump	32. 989
W. A., the Macquisten flotation process	. 2030
Rope conveyors, picking on	. 489
drive for sand wheels	. 866 . 937 . 1094
transmission	1004
Ropes, L. S., mill of Isel Corundum Company	. 1001 !.
Georgia	. 1183
Rosales, Henry, auriferous quartz in Victoria	. 1176
gravity stamps	. 1183 . 1176 . 224 . 787
W. A., the Macquisten flotation process. Rope convevors, picking on drive for sand wheels tramway transmission Ropes, L. S., mill of Isel Corundum Company Georgia Rosales, Henry, auriferous quartz in Victoria gravity stamps Rose, T. K. amalgamating pans amalgamators arrastra	200
amalgamators	. 290 . 787
arrastra Blake and Schranz breakers, Dodge and Gate	. 290
breakers clean-up pan Crawford mill Cyclops mill gold from placer and vein rock gravity stamps Harz jigs Huntington mills Flushand pneumatic and Patterson elephan spring stamps	. 56
Crawford mill	. 291 . 295
Cyclors mill	294
gold from placer and vein rock	. 1174
gravity stamps	. 223
Harz jigs	. 639
Husband pneumatic and Patterson elephan	, 297
spring stamps	. 143
spring stamps Jordan's centrifugal grinder Krom jig and Clarkson-Stanfield machine	. 295 . 837 . 109
Krom jig and Clarkson-Stanfield machine	. 837
laws staam stamps	149
lime for slime settling	. 1419
rolls. large steam stamps lime for slime settling metallurgy of gold pointed boxes	. жх
pointed boxes	. 476
retoris	. 783
pointed boxes retorts riddles versus trommels size of stamp feed Roseberry, B. C., concentration at. A. W. Dyer Rosenlecher, R., dressing quicksilver in Tuscany Roskelly, I., stamp mill construction Ross, J., Jr., Wildman and Hector gold stamp mill Rossland district, B. C., milling in the. R. Hooke Rotary breaker at Mill 186 drier at Mill 180 percussion table, Bartsch pumps	385 207 2048
Roseberry, B. C., concentration at. A. W. Dyer .	2048
Rosenlecher, R., dressing quicksilver in Tuscany	. 1177
Roskelly, I., stamp mill construction	. 2048
Ross, J., Jr., Wildman and Hector gold stamp mill	s 1184 s 2046
Rotary breaker at Mill 186	. 1917
drier at Mill 180	. 1917
percussion table, Bartsch	. 1497
pumps Rotation of gravity stamps Rothwell, John E., belt elevators	. 871
Rothwell John E. helt elevators	. 884
rolls for chlorination process	. 111
R. P., Blake breaker	. 57
Rothwell, John E., belt elevators rolls for chlorination process R. P., Blake breaker in Ontario mill Linkenbach tables Ortein Collinguate allow	. 57
Linkenbach tables Ontario, Silver Reef, and California silver mines in Nevada	. 728
mines in Nevada	. 1174
Rotter, Max	. vii
Rotter, Max Rough-crushing department at Mill 152	. 180
Roughing jig	. 894
pigs at Mili 148	. 179: . 146
Roughness, effect of, in launders	. 146 87
Roughing jig jigs at Mill 148 plane, definition of Roughness, effect of, in launders Rough, unplaned pine board surfaces used as plate	s 75

1 ages 1155 1010, voi. 111.	2.,	1 agos 1011-2002, Vol. 1	r
Paulatta hall mill C Rlämeke	2016	Sahlin, A. Sturtevant mill	0
Roulette ball mill. C. Blömeke	4. 706	mills versus rolls	
holes compared with slotted holes in screens	169	sizing test on roll product	
tables, adjustments of	2023	Saint Andreasburg, sieve scale at	
tables, adjustments of	, 1908	David's Gold mine, New South Wales, milling at	
continuous surface	1500		4
Routine of managing heads and concaves on spindle		Dennis, Cornwall, tin dressing at	8
breakers	47	Eugene mill, B. C., milling at the. R. Stokes 20	4
Rowand incline screen	1345	Goar on the Khine, mill at	3
Roward incline screen 1345, 1762, 1763, 1764, 1805, 1808, 1809, 1810,	1000,	Johns River, Florida, pumps on 8 Joseph Lead Company mill xxvi, 924, 11	7
magnatic consentor	807	Hoffmann mill	έ.
magnetic separator. 1763, 1808 at mills 1763, 1808	1810	Just, Penzance, mill at	
tower drier at Mill 152	1813	Laurent-le-Minier, mill at	
tower drier at Mill 152	1746	Louis colliery, air blast at	
vertical drier at Mill 141	1765	exposition, the concentration plant of the 20	
Royal breaker	58	floor of the Anzin Co., air blast at	
Royal breaker California, the mill of the.		Smelting and Refining Company 17	
H. F. Brown	2044	mill	8
Rubber belt conveyors		Symphorien, Belgium, phosphate plant at 8	
for elevators vanners		Sala, stroke of jigs at	
belting in launders		Sal ammoniac used on amalgamated plates 7	
belts		Salberget, concentration plant at. G. Fagerberg 20	
tables	698	Salivation by mercury	
cushion for steam stamps	6. 127	Salkinson, A., use of steam for settling slines 20	12
for amalgamated plates	8, 760	Salt used in plate amalgamaton 7	5
riffle cleats	1487	settling test	4
roll springs		water	U
sheet for mortar blocks		effect of in concentration	e
surface for slime tablestable deck of Woodbury table		Salzburg tables	
gerge canvas for vanner helts	650	versus jigs	4
Rubidium, atomic weight of	1188	Samarium, atomic weight of	
versus canvas for vanner belts Rubidium, atomic weight of Ruby coal breaker, Colo., practice at the. R. M.		Sample, dipper or bucket 8	
riosea	2001	grab	
washing	2025	grinders	č
Rudorf, theory of flotation processes1555	290	bibliography for	
Rul, M., arrastra at Guanaxuato, Mexico	295	Nevada	Š
Rules for belting		Sturtevant 12	Š
ijaging	631	Complete 949 1E	$\tilde{7}$
mechanical sampler	846	are inaccurate, pipe and single split 20	U
mechanical sampler power consumed in mills	1093	at mills	17
used in crushing	309	are inaccurate, pipe and single split 20 at mills 1691, 1750, 1868, 1873, 18 Keewatin, Ontario. F. T. Snyder 20 Smuggler Union mill, an automatic. S. I.	l 3
used in crushing	9, 8 <u>0</u> 0	Hallett 20	19
jigs, labor for	604	Bridgman 8	
methods of	551	Brunton847, 15	2
sample	3. 845	oscillating mechanical	7
stamps	3, 224	Byrne automatic pulp 20	
Runs447, 476	, 1082	cheese-scoop	4
Russell process	1175	Clarkson	
Russia iron for jig screens	545	Collom	
Rusty gold	1014	essentials of	14
catching of	7776	essentials of	32
in dredging		hand sampling	7
Ruthenium, atomic weight of	. 1 188	hand sampling):
Rutile separated by magnets	. 790	in the mills	34
specific gravity of	. 1189	Johnson 20	ķ
Rutter breaker	. 45	Lamb automatic tailings sampler	
Ruttman, F. S	. 1175 . 57	pipe 8	
breakers	57	Snyder	,
Conkling jig		Snyder	57
Rverson pulverizer	. 236	riffle 15	i
bibliography for	. 200	Vezin	'n
		weaknesses of the Bridgman 20	Įį

S	S
Sachs, C., Neuhof mills at Beuthen	S
	55

Pages 1199-1610, Vol. III.

Johns River, Florida, pumps on	870
Jonns River, Pforda, pumps on Joseph Lead Company mill Hoffmann mil Just, Penzance, mill at Laurent-le-Minier, mill at. Louis colliery, air blast at exposition, the concentration plant of the floor of the Anzin Co., air blast at Smelting and Refining Company mill Symphorien, Belgium, phosphate plant at ala, stroke of jigs at alamander crucibles for melting al ammoniac used on amalgamated plates alberget, concentration plant at. G. Fagerberg alivation by mercury alkinson, A., use of steam for settling slines at used in plate amalgamaton settling test water	1175
romann mill	1706
Just, Penzance, mili at	1082
Tavia adliana sia blant at	1118
counscition the concentration plant of the	837
floor of the Angin Co. oir bloot of	017
Smalting and Defining Commons	977
Smening and Renning Company	1709
Complesion Relative phoenhote plant at	หดอก
Symphorien, Beigium, phosphate plant at	200
plamandan emisilan fan malting	704
alamander crucines for mening	740
all animoniae used on annaighmated plates	148
alivation by marcury	720
allyingon A use of green for settling climes	100
alt used in plate amalgamaton	750
cottling test	1147
water	1106
effect of in concentration	1700
alte effect on amalgamation	787
alzburg tables 682 1115	1185
versus iirs	641
amarium atomic weight of	1188
ample, dipper or bucket	245
grah	845
grinders 232 257 202	1284
settling test water effect of in concentration alts, effect on amalgamation alzburg tables versus jigs amarium, atomic weight of ample, dipper or bucket grab grinders bibliography for F. W. Braun Company Nevada	292
F. W. Braun Company	1323
Nevada	1284
Strintariont	1284
amplers	1570
are inaccurate, pipe and single split	2032
at mills	2032 1874
Keewatin, Ontario. F. T. Snyder	2031
Smuggler Union mill, an automatic. S. I.	
amplers	2032
Bridgman	884
Brunton847,	1527 1575
Bridgman Brunton. 847, oscillating mechanical Byrne automatic pulp	10/0
Byrne automatic pulp	2031 844
CHCCSC-SCOOD	884
Clarkson Collom different types essentials of. for tailings at Mill 160 hand sampling inaccuracies of the old Brunton	847
different types	2032
essentials of	846
for tailings at Mill 160	1834
hand sampling	1570
inaccuracies of the old Brunton	2032
in the mills Johnson Lamb automatic tailings sampler	040
Tohnson	2031 1573 1571
Lamb automatic tailings sampler	1573
mechanical	1571
pipe	845
Snyder846,	1572
Taylor and Brunton horizontal riffle sampler	1577
riffle	1578
Vezin846,	1572
weaknesses of the Bridgman	2032
amples moisture	840
storing samples	19/9
in the mills Johnson Lamb automatic tailings sampler mechanical pipe Snyder Snyder Taylor and Brunton horizontal riffie sampler riffie Vezin weaknesses of the Bridgman storing samples weight of samples taken in mechanical sampling sampling sampling a jig bed	1576
iampling	843
a jir bed	1171
and analyzing of slimes. L. Ehrmann	$\tilde{2}\hat{0}\hat{3}\hat{2}$
at mills	1912
Park City, Utah	2032
bibliography for	
busing the sample	884
bucking the sample	884 1578
by coning and quartering	884 1578 1577
by coning and quartering fractional selection	884 1578 1577 1570
by coning and quartering fractional selection hand	884 1578 1577 1570 1570
by coning and quartering fractional selection hand. 844, Jones sampler packings with circles of	884 1578 1577 1570 1570 1570
by coning and quartering fractional selection hand	1574
by coning and quartering fractional selection hand	1574 1570
ampling a jig bed and analyzing of slimes. L. Ehrmann at mills Park City, Utah bibliography for bucking the sample by coning and quartering fractional selection hand Jones sampler machines, principles of mechanical means riffles shovel	1574
machines, principles of mechanical means riffles shovel	1570 1570 1570 1570 1570
by coning and quartering fractional selection hand	1574 1570 1570 1570

Pages 1611-2052, Vol. IV.

		A 11 11 11 11 11 11 11 11 11 11 11 11 11
	1577	Sapphire washing
	1577	Sardinia, ore dressing in. N. Pellati
ground pulp	1078	Satelin, J. de, Hughes Daviot electromagnet 834
ground pulp department at mills1667, 1691, 1742,	1004	Saucon mine, movable sieve jig at
difficulties attending mechanical	1575	Sauer-Mayer riddle
general article on	4000	Sauvage, E., Plumb jig
general article on high-grade telluride gold ores with Vezin sam-	1573	Saving by canvas plant 1017
		Saving by canvas plant
in Colorado limit of error in mechanical sampling	1575	from scrap
machinical compliant	1577	in mills
mechanical sampling		gold mills
mechanical	2031	use of electricity
mill	1069	of water
S H Panros	2032	use of electricity
minimizing effect of air currents	1576	0f
moisture samples	1575	Saw blade for scraping plates
moisture samples notes on	2032	Saw blade for scraping plates
notes on of builton concentrating and slime tables. J. C. Bailor mill work ores. P. Argall plant of mills progrations in	784	Saxon mill, mercury traps in 774
concentrating and slime tables. J. C. Bailor	2032	wells in 770
mill work	1168	shoes and dies
ores. P. Argall	1609	Saxony, cobbing in
plant of mills	1872	mills in
precautions in	O A C	Scaife trough washer320, 335
principles of	849	Scales for weighing ore
requisites to accuracy		sieve
rules for	848	In American mans, table of
S. H. Pearce	2031 1576	Scandium stomic waight of
	1681	m American mins, table of
	1172	Company's plant Creenshard Pennsylvania 1170
trough for slime table	367	Schamberger, I. W., clay washing 1188
Sampson handrers 1202	1223	Schedules for calculating the value of zinc ores 1939
Samson breakers	1203	Joplin zinc ores
Mill 113	1659	western zinc ores
	1223	zinc ores, foreign
San Antonio de Vguana mill	1180	Scheelite, specific gravity of
San Antonio de Yguana mill Sanborn, J. A., amalgam	767	Schellenbuch Sons
temperature of water for amalgamation	789	rolls
Sand and slime concentrators	644	Schemes of mill treatment
	1464	Schemnitz, Hungary, settling tests at 1146
Wilfley table	1465	Schemnitz, Hungary, settling tests at
corundum	1078	Schiff, F., magnetic separators
corundum distributor, Blaisdell centrifugal flow of, in launders	1602	
flow of, in launders	873	bibliography for
for bedding false bottoms in mortar	180 759	Scaleuderseparator, description of the. L. Meritz
neated for sweating plates	1609	and O. Bilharz
	2031	Schmidt E halt tables 799
Condendary used in scouring conver plates	752	Schmidt, F., belt tables 728 Schmidt, F., belt tables 728 -Manderbach, Adolph, spiral sieves 385 spiral screen 363, 364, 385 Schnabel, Carl, bag rooms for zinc white 885
Sandpaper used in scouring copper plates Sand, preparation of moulding. J. Kraus pumps at Mill 182	2080	spiral screep
numps 868.	1587	Schnabel, Carl, bag rooms for zinc white 885
nt Mill 182	1911	Handbuch xx Huntington mill
Standard Consolidated mine	1588	Huntington mill
Prenier	OIL	separation processes
and Le Blanc	2031	silver amalgamation
ratio to water in pumping	869	by Washoe and Reese River processes 1174
Sands in classifiers and jigs, action of. G. G. Bring	2020	Scholl, G. P., modern gold milling 2035
mechanical settling and filtering of	2021	Schöne tubular classifier 478
moisture in	1107	School laboratory work, a free mining gold ore.
transported by water treatment at Mill 117	1070	Calcum buttons D. Calcum on the 1979
read for economy corpor plates	753	ctay exertian morter 1988
weeking in New Torsey glass	2020	Schrang brenker A6 57 60 61
used for scouring copper plates. washing in New Jersey, glass weight of wheels at mills 1587, 1668, 1669, 1677, 1715, 1893, Calumet and Hecla	1100	Scholl, (F. P., modern gold milling 2038 Schöne tubular classifier 476 School laboratory work, a free milling gold ore. R. H. Richards and E. E. Bugbee 2048 Schorr battery, R. Schorr on the 1278 Stay-overflow mortar 1266 Schranz breaker 56, 57, 60, 61 of Dodge type 31 section of 32 jig 503, 641 mill 235, 274, 292 bibliography for 296
wheels 864	1586	section of
et mills 1587, 1668, 1669, 1677, 1715, 1893,	1894	fig
Calumet and Hecla	2032	mill
	866	bibliography for 296
in the Transvaal	2031	bibliography for 296 products of, crushing Przibram ore 309 tests on work required for 300
mechanical efficiency of	1087	tests on work required for
on the Rand	1644	table
versus pumps in Witwatersrand	1645	Schubersatz
Wilfley middlings elevator	8081	Schulenburg, hand picking at
San Dimas, arrastras at	5, 290	sieve scale at
Sandstone, angle of nip required to crush	94 300	sieve scale at
compressive strength of	1100	nowite 470
Sandweroft standard came	215	W Huntington mill 907
Sandycroft standard cams San Francisco, cost of mill at Juan District, Colorado, cost of producing gold	1126	nowitz
Tuan District, Colorado, cost of producing gold	****	Schuttelherd, New Humboldt concentrator 1493
in1978, 1979,	1980	Schwarzmann's rolls
	1000	Schwerin, Martin, re-grinding machines
-4 1411 100	1980	
at 191111 100	1980 1626	relative efficiency of re-grinding machines 1831
Martin mill, Chihuahua, Mexico. K. Thomas.	1980 1626 2046	relative efficiency of re-grinding machines 1831 Scobey, J. C., economy in mill water 1419
Martin mill, Chihuahua, Mexico. K. Thomas. Sanna modified Ferraris screen	1626 2046 343	relative efficiency of re-grinding machines 1331 Scobey, J. C., economy in mill water 1419 sampler at Mill 173
Martin mill, Chihuahua, Mexico. K. Thomas. Sanna modified Ferraris screen Santa Barbara, oil-concentration plant, Van Meter	1980 1626 2046 343	relative efficiency of re-grinding machines. 1331 Scobey, J. C., economy in mill water 1419 sampler at Mill 173 1880 system of slime settling in Arizona 1411
Martin mill, Chihuahua, Mexico. K. Thomas. Sanna modified Ferraris screen. Santa Barbara, oil-concentration plant, Van Meter process at	1980 1626 2046 343 1993	Schutteinerd, New Humboldt concentrator Schwarzmann's rolls Schwarzmann's rolls Schwerin, Martin, re-grinding machines 1340 relative efficiency of re-grinding machines 1331 Scobey, J. C., economy in mill water 1419 sampler at Mill 173 1880 system of slime settling in Arizona 1411 Scoops for sampler 752
at Mill 100 Martin mill, Chihuahua, Mexico. K. Thomas. Sanna modified Ferraris screen Santa Barbara, oil-concentration plant, Van Meter process at Eduwiges mill Sapphire, North Carolina, corundum dressing at	1626 2046 343 1993 1184	relative efficiency of re-grinding machines. 1831 Scobey, J. C., economy in mill water 1419 sampler at Mill 173 1880 system of slime settling in Arizona 1411 Scoops for sampler 846 Scouring copper plate 752 Scow for dredging 1007, 1011

1 4503 1100 1010, 7 01. 111.	1-	1 ages 1011-2002, voi. 1v	•
Scrap iron recovered by magnets	790	Screens for gravity stamps 197	7 n
use of	1115	Screens for gravity stamps	ίĭ
use of Scraper conveyors at Mill 114	1662	Huntington mills	ĺŜ.
Mill 126	1709	at Mill 162 184	15
for belt conveyors	860	Huntington mills	2
hard amalgam on plates	762		£7
plates	75	removing sticks, bolts, pick points, etc	
slime tables		settling tanks	
Scraping conveyors	800	table of details of	έî
Scraping conveyors	1307	steam stamps 11	
and lamp chimney for sampling jig bed	1171	material, size, life, etc 12	
area on stamps	$\frac{209}{1012}$	testing	
for dredges	724	Tremain stamp	50
frames	176	unwatering	7Q
for jig	510	unwatering	
steam tamps	120	Gates all-iron frame revolving 135	
in gravity stamps	176	gravel 33	
gauges	1, 172	grizzlies	
meshes, tables of	894	gyrating	
openings	167	Hicks revolving grizzly	
measurements of		Impact screen	
plate, cost of sizing limit of	361	Imperial screen	
sizing limit of	1361	in gravity stamps 16	67
principles of	, 1361		10
Screening after decrepitation	829		89
at the Witkowitz collieryby trommels system of	2000		73 73
cost of	360	jig, details of	40
difficu ties of	372	Karop	86
difficu ties of economic limit of. P. Argall	1366	King screen	60
following disintegration	830	Klein moving grizzly	86
hot and cold ore	385 1566		46
separation by crushing and screening			68 47
tests		material, cost, life, etc	
tests	1340	for	84
wet	1138	jig 54	45
trommel	335	jig	66
wet versus dry	1139	meshes of	72
Screens	336	mill	
action of	2019	cost of maintenance of	
aluminum bronze cloth	174	ncedle gauge	72
plate	174	ncedle gauge	
analysis	2019	Newaygo separator	
arrangement of holes	168		72
at Mill 158	$\frac{1824}{2018}$	Oberegger gyrating	86 53
Truesdale coal washery, shaking	2018		26
Truesdale coal washery, shaking	2019	gun-metal at Mill 185	15
attachment of in trommels	355	plate or wire cloth	40
balancing of shaking	342	on a fixed shaft, rotary 20	
bar	336	opening in mortars	67 48
belt typebibliography for		percentage of opening in	68
blinding of		phosphor bronze cloth	74
blinding of	386	plate 17	74
brass cloth	174	placing of	70
Briart bar	346	plate, for gravity stamps	67 4 N
Callow belt screen	177	prevention of blinding	73
capacity of	341	pulsating	42
Centripact	1360	relation of thickness of plates and wires to diam-	
choice of	4, 371	eter of holes, in the mills	72
classified	. 336	to diameter of holes in punched	70
cloth	170	010 10	72
coal. F. W. Parsons		revolving	41
Columbian pulsating			69
comparison ofshaking and cylindrical	2019	versus slotted holes	69
copper plate	. 1/4	Rowand incline screen	45
corrosion of	354	Schmidt spiral 3	
Cost of per ton of ore crushed	174	sectional trommels	103 142
Denver Engineering Works Company revolving grizzly	1252		69
designation of holes	. 172	sieve scale for	366
dewatering	. 1591	sizes of needles for	172
different types of	. 2018	sieln a 936 12	45
Distl-Susky screw grate	. 386	Slope of	170
Dunlap perfect clay screen	. 1357	speed of shaking342, 3	77
Edison stationaryeffect of acid water	. 341 . 173	standardization of	161
size of holes in stamping	210	laboratory. W. S. Hutchinson 1366. 20	ງງິອີ
elongated punched holes	. 370	stationary	145
Ferraris hand	. 1360	standardization of 13 standardization of 1306, 20 stationary W. S. Hutchinson 1306, 20 stationary 3306, 13 of wire cloth or plate 3	140

Pages 1611-2052, Vol. IV.

Pages 1199-1610, Vol. III.

1 ages 1 040, Vol. 1.	10000 011 1101, 101. 11.
Screens suited for testing	Separation of molybdenite 1567
Screens suited for testing	three minerals on jigs
table of clear punched slotted	principles used in
thickness of	Separators at the Kalgoorlie mines, hydraulic 2034 Ball-Norton magnetic separator
plate	Buchanan magnetic 803
Traylor Centripact	Clarkson-Stanfield centrifugal 820
trommel, life, cost, and details of 352	classification of magnetic separators 1521
Tyler	Cleveland-Knowles magnetic separator
mining wire cloth	Conkling dry magnetic 809
mining wire cloth 1364 used for free-settling tests 465	Cranberry magnet 1530
in troumnels	Dellvik-Gröndal 804
variations in the percentage of opening of, in the	Ding's magnetic
mills	Edison magnetic
Vibracone separators	Eriksson's electromagnetic
Vibromotor	Eriksson's electromagnetic
won a of 100 170 356	separator, drum-type
screening surface 1305 wire cloth, of copper, brass, phosphor-bronze, galvanized and tinned 1365 wire, for gravity stamps 170	final
wire cloth, or copper, prass, phosphor-profize,	for fine materials
wire, for gravity stamps	Forsgren's electromagnetic separator
versus plate	Gröndal Nos. 2. 3, 4, and 5 magnetic 1537 Heberli magnetic 799
with round holes laid out in equilateral triangles 168	Heberli magnetic
squares	wet
Scraw conveyors 861 1582	Hughes Daviot electromagnet
at Mill 105	Humboldt magnetic
for removing jig tailings 588	Kessler magnetic
Screw conveyors 801, 1582 at Mill 105 1636, 1637 for removing jig tailings 588 table of sizes, capacities, and speeds of 1583	Kessler magnetic
tappets for stamps. 188, 225 Scrubber for cleaning copper plates 752 Scrubber for cleaning copper plates 752	Leighton magnetic
Scrubbing of amalgamated plates	Mechernich magnetic separator
Seager, T. B viii	Mechernich magnetic separator
Scriptonia Seager, J. B. Seager, J. B. Viii	Newaygo 1360
Sea water, use of	of the primary-magnet type
used in concentration 1182	secondary or induced-magnet type 1583
weight of	Pape-Henneberg
Sectional Blake breaker	Pape-Hennelberg 818 Payne magnetic 709 Peck centrifugal 828
breaker of Blake type	pneumatic
Sectional Blake breaker 20, 21	Sutton, Steele & Steele dry table 1479
mortage Tender 1267	principles of magnetic separators
for gravity stamps	Siemens magnetic
rolls	Ullrich magnetic 1535
stamp cams 192	Vibracone
mill	Wenström magnetic
trommels	Wetherill magnetic
ing grizzly	Series arrangement of machines
ing grizzly 1353 Sections in mills 1108 Seeman, L., centrifugal pumps 870, 885 classifier with helical current 478 478 478	Serpentine, specific gravity of
Seeman, L., centrifugal pumps	strength of 301
sizing, jigging, and wet stamping	Setting up a stamp 200 Wilfley tables 1408
sizing, jigging, and wet stamping	Settlers
Segregator (classifier), G. G. Gates 418	Settling, bibliography for
Seltz coal loading and screening machine 2018	Settling, bibliography for 475 beakers or jars 1146
Selenide silver mill	box for Johnston vanner concentrates 1502
Selenium, atomic weight of	concentrates in barrels
Self-tightening cams	dust 1099
manganese-steel mantles for McCully gyratory	clust 1099 fine slimes 1147, 1185, 1186 hindered 610, 1460 limit of 455
prenkers 1213	hindered
Sell, L., ball mills 293 Sellers, William & Co., steam hammer 12 Seminole mine ore, Krom air jig on 825	limit of
Seminole mine ore, Krom air jig on	pits for tin ores
Separating	pond in the Harz, a concrete
concentrating or washing	power of minerals, effect of
Separation by adhesion	rates in different mediums 826
centrifugal force	ratio, defined
crushing and screening	
and screening 1565	slimes1160, 1178, 1184
disintegration and screening	use of chemicals for
heavy solution	tanks
oil	at mills
weathering 830	Morenci, Arizona
combinations of principles of	and pits for clay. 1070 at mills . 1408, 1776, 1777, 1779 Morenci, Arizona 1413 baffle board 459 Berenger and Stingls slime tank 1407
case of	Berenger and Stingls slime tank
electrostatic	colculation of 454
in vanners, principle of	Callow cone
miscellaneous process of	Callow cone
in vanners, principle of 065 miscellaneous process of 700 of fluorspar, lead, and zinc. F. Julius 2028 galena-sphalerite ores at Broken Hill. 1611	Colorado Iron Works Company 1407
gaiena-sphaierne ores at Broken Hill 1011	data from the mills concerning 458 details of, in the mills
grease from diamond at Mill 188 1921 mixed sulphides. R. C. Canby 1923	details of, in the mills
•	88
	w 4r

ORE DRESSING.

Pages 1-643, Vol. I.

Pages 644-1197, Vol. II.

Pages 1199-1610, Vol. III.	INDI	$\mathbb{Z}X.$	Pages 1611-2	052, Vo	ol, IV	٧.
Pages 1199–1610, Vol. III. Settling tanks for graphite ores jig concentrates ore dressing, a kaolin. 1077, wanner concentrates hereill cylindrical clarifying tanks large cones practical limits of settling in relations of length and width to the settling speed of current to size of grain Scobey system in Arizona. Sherman system silme table of details of in the mills tests on fine silmes theory tube. 100 time and alum for tube of lime and alum for water setznad Severing minerels, methods of or detaching setznad Severing minerels, methods of or detaching shackeford's patent box-cleaning device. Shaft drier at mills furnaces for drying roasting furnace at mills 1663, 1769 for amalgamating pan jigs diameters of rolls steam stamps Tremain stamp trommels. Shafting in mills shaking amalgamating tables at mills 1645, 1650 in South Africa frame for Frue vanners grizzly at mills 1691, 1837, 1868 frame for Frue vanners at mills 1693, 1694, 1701 mercury trap plates screens at mills 1693, 1694, 1701 mercury trap plates screens at mills stamp shoes Shanks and butts of stamp shoes Shannon concentrator Copper Company, the use of lime for slim settling at stamps tromped stamps for a for dredges testing new spring for table for picking. Shalks and butts of stamp shoes Shannon concentrator Copper Company, the use of lime for slim settling at malgamated plates screen holes shannon concentrator Shannon concentrato	1075 586 2020 1406 452 1410 1406 452 1411 1406 1452 1411 1410 1452 1400 140	Sherman, F. W., systes slime treat wet concentration slime treat wet concentration of canvas for star shimer and Reifsnyde Shims for rolls	m of settling tanks ment at Mill 132 on by the Sherman or the state of the set of the se	pans. of 184, 1 r with ump uhrig in 1	144, 11 120 120 121 121 122 122 123 124 13885, 30 144, 11 144, 11 15885, 30 16645, 11 1750, 50 1750,	$\begin{array}{c} 49934784123641182989812421813777022081338449989857575997070644999922225 \\ 49934784712248118298981249113284912249113384989898989898989898989898989898989898$
separating and distributing tanks at Mill 132 settling tanks at Mill 132	1506	wires and price Siever coal jig				547 641
	-					

≾ieves	Silverton, Colorado, hammers used at
See also Screens, and plungers, sizes of in mills	mill at
and plungers, sizes of, in mills	Mining Co., mill
drop between, on jigs	Simmer and Jack mill, details of stamps
three-mineral separation 590	Deep Ltd. ore reduction plant of 1651
two-mineral separation	Simonds, E. H., place and value of small ore tests 2049 Simonnet and Chaumeis, American gold stamp mill-
life of in jigs 546	ing 1178
number of, on jigs	ing 1178 Simple-cylinder steam stamp at Mill 179 1897
skimming in jigs 576 slope of, in jigs 548	jigging mills 892 using power jigs 900 steam stamp at Mill 182 1909, 1912
width of, in jigs	steam stamp at Mill 1821909, 1912
Sifting and decrepitation	Simplex ore feeder
mill at	mills
Ems	Simpson pulverizer
Silesia, mill in. 1186 Silex liners for tube mills at Mill 143 1770	parison between
Silex liners for tube mills at Mill 143	issue
for melting	table of sizes, power, and weights 1241
Silicon, atomic weight of	spigot hydraulic classifier at Mill 180 1902
Sills and girders for steam stamps 114	stage crushing
for Nordberg steam stamps	versus double discharge on stamps 209
Silver Age mill xxv, 915 amalgam 730, 731, 747, 1512 preparation of 754 amalgamated plates 747	Sintering slimes at Mill 129
preparation of	Siphon separator 520 at Mechernich 421, 475, 477, 478 Sites for mills 1085, 1124
apparatus used for amargamation 131	Size and shape of mouth of breakers 54
assay for in Mill 55	of amalgamated plates
Mill 68. 303 atomic weight of 1188	feed to hydraulic classifiers
combination mills 1039 -copper ores, mills for	for film sizing 707
cost of producing	jig bed
Cup, British Columbia, handling of ore at the.	stamp screens, methods of designating 172
fineness in bullion	jig sieves and plungers
cost of producing 1960 Cup, British Columbia, handling of ore at the. G. Attwood 2039 fineness in bullion 785 horn, crushed in Harshaw mill 207	treated by amalgamating pans 248
Islet mill	needles for screens
in Lake Superior copper	needles for screens 172 sieve hole on jigs 573 slime tables 684, 696
Park City. Utah 2038	Sized feed for Wilfley tables
Park City, Utah 2038 H. L. J. Warren 2036 J. H. Steele 2044 Lake mill 1046, 1092, 1771 dewatering screen at Mill 139 1751 lead ever convoked by Black benefits 2017	Sizers Browne hydrometric conical
Lake mill	Keedy dry-ore sizer
dewatering screen at Mill 139 1751	ted to figs, range of
mill	vanners
ores, mills for	vanners' 658 Wilfley table 674 of Akron Chili mills, table of 1308
treated at Broken Hill by Collom jigs 515 mills 1039	Allis-Chalmers toothed and corrugated rolls,
settlers in 777	table of
milling, bibliography for	American Process Company driers 1598 Argall driers 1600 Austin gyratory breakers, table of 1210
ore, amalgamation of 1167 crushed at Geddes and Bertrand mill 100 by agreeting 100	Austin gyratory breakers, table of 1210
crushed at Geddes and Bertrand mill 100 by arrastras 238	Blake breakers 17, 21, 24 boxes for rolls 72
leaching and amalgamating	cam shaffs 101
loss of	Comet breaker
pan for testing 1157	diagram of 1218
separated by oil	diagram of. 1219 Denver Engineering Works Company's Blake breakers, table of 1204 Dodge breaker 30, 31
plated amalgamated plates	Dodge breaker 30 31
at Mill 143	double-come mydraulic classiners, table of 1381
comparison of with plain copper	Farrel Blake breakers, table of
plating as a preservative for copper plates	feed for gravity stamps
effect on fineness of amalgam	Gates ball mills, table of
method of	breakers
Plume, Colorado, description of two mills at 2043	breakers
products of stamping	grizzlies
in daily and hard amalgam	Hathaway gyratory breakers, table of 1217
Reef mill	Humphrey rolls, table of 1235 Imperial screens, table of 1350 improved Huntington mills, table of 1312 iron pice 455
removed by picking	improved Huntington mills, table of 1312
treated in mills 44, 46, 47, 48 486	iron pipe 405 Jeffrey swing hammer pulverizers, table of 1322 Kennedy gyratory breakers, table of 1214
per square foot of copper plates	Kennedy gyratory breakers, table of 1214 Kent roller mill
wet and dry crushing 224 Silverton Brand elevator belting at Mill 126 1707	Kent roller mill
	toble of

rages	1199-1010,	γ OI.	TTT.

Pages 1611-2052, Vol. IV.

Pages 1199–1610, Vol. III.	INDEX	ζ. Pa	ges 1611–2052, Vol. IV.
Sizes of La Point flour gold separators, table of McLanahan and Stone single-roll crush table of mortar blocks new Humboldt concentrator ore hand picked particles, effect on free settling Pilling air hoists, table of products of mills Richards' pulsator classifier, table of products of mills Richards' pulsator classifier, table of samples 182 samson breakers, table of screens 168 for free-settling tests 182 Stroud mills, tables of 182 Stroud mills, tables of 182 Stroud mills, tables of 182 Strutevant balanced rolls, table of 184 Sturtevant balanced rolls, table of 184 Sturtevant Dodge type breakers, table of trommel screens Wild roller mills, table of Wild roller mills, table of 182 Stroud mills, table of 183 Silme tables 185 Sizing 1		zing test on Schranz mill proper spigot products of at Mill 144 stamp mortar prod Sturtevant mill protailings and concern Lane Chili mill, tailings and concern for Mill 174. Tustin mill product Woodbury jig tailin tests, film, on quartz at from Mill 78 graphical representat on breaker products. Bryan mills. F. F. classifier products. Crushed ore products crushing machines gravity stamps hindered-settling products. products of Gates Richards' hydra quartz and galena. Richards' classifier roll products slimes and sands. stamp and Bryan stamped ore steam stamped ore steam stamped ore steam stamped ore steam stamps. Tremain steam stamped ore steam stamps or with mills and s vanner products. Dodge breaker two-stamp steam balkimming launders, in Bin of hand jig jigs wersus automatic dische kinner, H. R., elevators ak kips for ore licit boards for belt convey kylights and mechanical. A. H strength of weight of ledging by hand hammers. liding block mechanism for mechanism f	roduct dichards' vortex classifiers are dichards are di
Chill mill product cyanide tailings. Dodge pulverizer product feed and discharge of Abbé tube mill and products of Drake cone classifier of Huntington mills tube mills to flotation plant at Mill 130	107 262 1290 3 1668 1316	diding block mechanism to ore feeder	** 145
Woodbury slime classifier at Mill 1 Griffin mill product at Mill 105 Hancock jig feed and middlings Heberli mill product Huntington mill product mill feed at mills ore broken by hand and machine product of De Kalb's classifier fine grinding system at Mill 105 settling tanks at Mill 144	1636 1443 259 281, 1669 750, 1772 13 1402 1638 777, 1779 1406 777, 1778 33 and 1317 328, 1829 1720, 1724 1720, 1724	concentrators. classification of Dimmick slime table Horn. Geyer vanners definition of, W. A. Pri J. H. Collins M. P. Boss ig. ponds, the use of a dr Kosmann pressed and dried settling. H. S. Nichol E. A. H. Tays by aid of milk of lin the Sherman syste H. S. Nichols M. D. Stackpole relative efficiency of	044

Slime settling tanks with steam coils at Mill 144 1779	Slocan, British Columbia, treatment of ores by flota-
theory 1149	tion processes
use of chemical to promote 1413	Slope and length of trommels
heat to promote	angles, measurement of
tables	table of 1191
at Clausthal	
Mill 177 1893	of amalgamated plates
bibliography for	amalgamating plates at mills 1622, 1624, 1627
capacity of	in California
circular, quantity of water on	amalgamating plates at mills 1622, 1624, 1627 in California 1619 Argall drier 881 belt conveyor at mills 1607, 1631, 1707, 1708, 1709, 1710, 1759, 1760, 1762, 1763, 1764, 1828, 1831, 1851, 1860, 1861, 1862, 1863, 1863, 1869, 1882, 1883 tables 698, 700 bin apron at Mill 154
specific gravity of feed	belt conveyor at mills 1667, 1681, 1707, 1708,
classification of pulp for	1709, 1710, 1759, 1760, 1762, 1763, 1764, 1828,
slimes for	1831, 1851, 1860, 1861, 1862, 1863, 1868, 1869,
	1882, 1883
with belt film tables	tables
construction and operation	Din apron at Mill 104 1816
convex versus vanners	1797 1742 1756 1760 1764 1760 1769 1769
cost of	1721, 1745, 1750, 1760, 1761, 1762, 1763, 1802,
coupled with kieve	canvas, blanket and carpet tables
vanner tilo	tables 700 701
Wilfley table 1110	at mile 1897 1808 1755 1770
density of pulp on	chutes 942
diameter and working radius of	concentric trommel at Mill 154 1818
fixed circular convex	Cylindrical drier at Mill 135
for testing 1154	dewatering screens at Mill 107 1858 elevators at mills 1715, 1818
unwaterer 880	elevators at mills
investigation on	Evans classifiers at Mill 161 1838, 1839
operation of	slime tables at Mill 177 1893
revolving circular concave	feed chute at Mill 179 1897
convex	sole for classifiers
scrapers on 696 size of grains treated 693	spitzlutte
slope of	film sizing tables 707
speed of	floors in mills 1080
step form	Mill 161 1841
surface for	German sweeping table
testing	grizzlies
thickness of water film on 695	grizzlies
velocity of water current 719	100, 100, 100, 100, 1021, 1020, 1031, 1803,
water films on	1860, 1888, 1892, 1909, 1913 Hallett table
for	Hallett table
work, effect of shape of grains on 694 tanks, effect and Stingls 1407	Impact screens at Mill 151 1803
tanks, Berenger and Stingls 1407	
Colorado Iron works Company 1407	Screens 548
use of steam pipes in	launders 873 874 877
treatment at mills	at Mill 152
on the Rand	Linkenbach slime table
use of steam for settling. A Soll-inner.	
1410 1410	picking beits at mills
Slimers	rierce amaigamators
Akens and Evans	plates
	revolving driers at Mill 138
belt percussion table	revolving driers at Mill 138 1746 Roberts slime table 691 Robins belt conveyors at mills 1805, 1806, 1807, 1808, 1809, 1810, 1811, 1812, 1813, 1821, 1824, 1825, 1826, 1876 rotary driers at Mill 186. 1826
comparison of Woodbury and Evans slimers at	1808 1800 1810 1911 1919 1912 1901 1904
	1000, 1000, 1010, 1011, 1012, 1013, 1021, 1024,
	rotary driers at Mill 186
	round tables at Mill 180 1904, 1905
	Salzburg table
use of riffles on 1408 Wilfley 1504	Salzburg table
Slimes and sand separation at Mill 106	at Mill 158
at Tarnowitz, control of	at Mill 158 1824 shaking feeders at mills 1837, 1868, 1860
A. W Warwick, on finely ground 1490	
at Tarnowitz, control of	launders at Mill 152 1811 screens at Mill 111 1655
colloidal silicic acid in. W. A. Caldecott. 1410	sides of spilabastas
theory of Whitney and Ober 1419	sides of spilzkasten
definitions of	sides of spitzkasten 440 slime tables 684, 694, 719 sluices 723 splace plates 723
De Kalb on 1394, 1397 De Kalb on 1419 department at Mill 163 1419 effect of heat in cartling allowed. 1848	
department at Mill 163	splash plates 739 Stein, Bilharz, and Luhrig tables 670 tables in film sizing tests 707, 718, 719
	tables in film sizing tests 707 718 710
H. A. Megraw on	on dredges
in Cœur d'Alene, the saving of. W. C.	tower screen plates at Mill 158 1899 1894 1895
Clark	trays on Sherman slimer
partment of Agriculture 1400	trays on Sherman slimer
1107	trommels
	at milis 1000, 1081, 162'8 1685, 1690, 1691, 1692,
	1737 1749 1748 1740 1750 1754 1724 1725
settling of	1818 1828 1829 1829 1827 1000 1040 1040
1120	trommels
steel par rittles for gold	1882 1888 1809 1019
What constitutes A W W 1401	undercurrents
Slimy water affecting jig work	vanners
Slip	undercurrents
Or slime kaolin 1077	White Similer traves
Slipping of belts	Dioffed holes compared with round holes in sereons 160
	Sludge 901
92	
	•



Pages 1199-1610, Vol. III.	INL	EX.	Pages 1611-2052, Vol. IV.
Sludge from hand jigs mill practice of Missouri-Kansas district tank, Ramsey	2043	tables,	small mills, hand. A. W. Warwick 2032 Allis-Chalmers annular picking or sorting ble
Sluggers, rolls with Sluice, new Australian shaking plates	104 2029 740	at m Hun	1835 1892 1892 1892 1893 1894 1895 1895 1895 1895 1895 1895 1895 1895 1895 1895 1895 1895 1895 1895
article on riffles Sluices, Bowie's figures on sizes and carrying power of	1464	inves inves di	stigation of free settling
for corundum ore riffles on dredges 1007 1008	1078 723 1012	sp use ma	sults, fastest grains 466 slowest grains 466 ecific gravities of minerals used for tests 465 de of in mills 889
undercurrents Small steam stamps Smallite, specific gravity of Smartsville and Mooney Flat, arrastra at 23	726 136 1189 8 290	Source of w	rater 1105 a, diamond washing in 333, 1178 mills 1149 l picking in 482
Smith, F. C., stamping, amalgamating, and concentration telluride ore	1175	nills picki	eds in
O., gravity stamps gauges for wire and plate R. G., settling fine slimes Vaile filter press at Mill 101	1898	stam stam	n meshes 172 p practice 221 ps in 225 of lime for settling 459
specific gravity of	814 1189	weig Carolir wa	ht of quartz in
Smittem	1859 1700	stam Unit	, false bottoms in mortar
mill xxy Union mill, Telluride, Colorado 1176, Mining Co., mill Smyth mill, stamps at	i, 933 2043 1016 228	Spring Southwest	splash board
Snake River, Caribou riffle ondredges on	1509 1009	Space between	ecting rods in blende jigs in 530 s in Cooley jig in 532 een rolls 64, 89
Idaho, dredging on	1006	Spaced rolls Spadone co	s, product of, crushing Przibram ore 308 ncentrator belt, the 1503 ore dressing in 1176
discussion of costs, micrometer gauge for ore grains gyrating amalgamated plates vanner	1178 788	Spalling, de hamme Span of wir	finition of
importance of mill constants for the engineer magnetic separation	2048 1568 1362	J. von . critic	llar oscillating table. 691 xx ism of Rittinger's theory
metallurgical standards micrometer gauge mortar at Newton mill, Colorado sampler	2019 1138 227 884	surfa Spathic iror	ce sizing 729 t ore roasted for magnetism 814, 815 saration at Allevard 9, 492 ns of rolls 104
shoes and dies Snyder micrometer caliper	181 1366 2027	Specific gra ser chan	vity affecting momentum 4 paration 889 ged by roasting 828
sampier	1572 1832 657 1094	defin differ effect	ition of. 3 rence in for jigging. 609 ton cost of milling. 1128 free settling 404
Soapstone for lubricating Societé Minière du Gard, Ferraris ball mill at Sockets in stamp bosses	1097 1300 187	of co jig	slime tables 693 pper 3 beds 574
Soda for melting Sodium amalgam 730, for brightening mercury used in stamp mills	$\begin{array}{c} 785 \\ 752 \end{array}$	mi	rcury 730 nerals and metals 1188 effect of 3 ann water 3
atomic weight of phosphate for brightening mercury Soft rock phosphate.	1188 785 895 755	oil qu roc	s
Solution for silver plating Sondericker, J. Sorted products obtained by air Sorting	viii 819 892	settli test	1 water 1100 mg power 4 1159 1159 1111
before sizing belts at Mill 137 Robins sorting belt by free settling	1611	neigi	tamp
hand breaking for picking tables or belts for hindered settling.	1435 1435	kept co of Abb Akro	nstant
settling in air columns, area of. defined for Richards' classifier.	1611 403	sus va Alsiņ	- Chaimers Folis at Mill 179 1898 spended frame vanner 1508 nners at Mill 186 1739 g cylinder 267 gamating pan 248, 249 rican Blower Company fans at Mill 151 1804
for Richards' classifier. cost of hand sorting. followed by agitation suction	1438 891	amal Ame Arga arras	gamating pan
	9:		

Speed of Atwood amalgaments	1 1800 011 1101, 101. 11.
Speed of Atwood amalgamator 776 Austin gyratory breakers, table of 1210 ball mill 260 at Mill 159 1828 Ball-Norton magnet 798 Barlett shaking picking table 489 belt conveyors at mills 1667, 1670, 1690, 1691, 1707, 1707, 1708, 1709, 1710, 1759, 1700, 1762, 1763, 1704, 1771, 1772, 1819, 1828, 1831, 1853, 1838, 1831, 1853, 1838 1809, 1882, 1883, 1913 1809, 1882, 1883, 1913 1809, 1882, 1883, 1913 1523	Speed of Gates breakers at mills
ball mill	Gebrüder Sulzer centrifugal pump at Mill
Ball-Norton magnet 1828	0.1-1-0
Bartlett shaking picking table	Golden Gate table
1707, 1708, 1709, 1710, 1759, 1760, 1762, 1763	Gould centrifugal pumps at Mill 1391757
1764, 1771, 1772, 1819, 1828, 1831, 1853, 1868,	Golden Gate table
of Wetherill magnetic separator	mills at Mill 105
percussion tables	Gröndal magnetic separators at Mill 150 1720
belts	Hallett table
of Frue vanners at Mill 1271711, 1712	hand jigs at mills1710, 1846, 1869, 1930
Blake breakers	Harz jigs at mills1692, 1693, 1694, 1701, 1702
at Mill 139	Hardings at mills
Bradford iig	1855, 1877, 1878, 1879, 1885, 1913
Brink & Hübner disintegrator 286	Hathaway gyratory breakers, table of 1217 Heberli mill
of Wetherill magnetic separator 1523 percussion tables 1496 tables 698, 700 belts 698, 700 of Frue vanners at Mill 127 1711, 1712 Bilharz jig 504, 518 Blake breakers 17, 21, 24 at Mill 139 1749 Bogardus mill 260 Bradford jig 503 Briak & Hübner disintegrator 286 Bryan mill 272 mills at Mill 173 1879, 1928 Buchanan magnetic separator 803	Heberli mill
Buchanan magnetic separator 803 bucket conveyor 861 buckets on dredge 1902	and offer of stand paints at term 192 1910,
buckets on dredge	jigs at mills1902, 1903, 1904, 1905, 1909, 1910,
buckets on dredge	
Byron Jackson centrifugal pumps at mills 1674, 1677	Humphrey rolls, table of
1078	at mills 1669 1684 1686 1690 1694 170
Callow screens at mills	Hooper air jig
centrifugal pumps	Imlay table 681 Impact screens at Mill 151 681 Improved Huntington mills, table of 1312 International separators at Mill 138 1746, 1747
at milis 1094, 1095, 1711, 1712, 1890, 1899,	improved Huntington mills, table of
1904, 1905 1907 1908 1909 1	International separators at Mill 1381746, 1747,
mills at mills	Jeffrey conveyors at Mill 126
cleaner jigs at Mill 148	at mills . 1685, 1686, 1707, 1708, 1727, 1739, 1939
at Mill 111 265	1833, 1858, 1929
Cala about what at Mill 194	at Mill 167
Comet breaker	Kennedy gyratory breakers, table of 1214
pans 1006 Cole shovel-wheel at Mill 124 1693 Comet breaker 41, 46 concentric trommels at Mill 154 1816 cone mill 250 Conkling its 250	Knowles duplex vacuum pumps at Mill 117 1879
Conkling jig	New Century magnetic separators, table of 1542
conveying and draining belts at Mill 130 1721	Krogh centrifugal pumps at Will 173 1990
conveyors	Krom air jig 824
Crane log washer at Mill 95	gyratory breakers, table of
Crickboom wash trommel	Linkenbach slime table
cyclone pulverizer	at mills. 1685, 1686, 1707, 1708, 1737, 1738, 1832, 1833, 1858, 1929 Johnston vanners 1833, 1858, 1929 at Mill 167 1858 Kennedy gyratory breakers, table of 1214 Kent roller mill 1804 Knowles duplex vacuum pumps at Mill 117, 1673 New Century magnetic separators, table of 1542 triplex pump at Mill 117 1674 Krogh centrifugal pumps at Mill 173 1929 Krom air jig 824 Krupp ball mills at Mill 128 1714 gyratory breakers, table of 1215 Linkenbach slime table 691 log washer 327 washers at Mill 154 1815 machines 1097 McCully breaker 44
cylindrical driers. 880 De Laval cream separator 827 Denver Engineering Works Company's Blake breakers, table of 1204 dewatering wheels at Mill 144. 1772, 1773 disc conveyors. 1583 Dodge breaker	machines 1097 McCully breaker 1097 McCully breakers, table of 1212 McFarlane rolls at Mill 142 1706, 1767 magnetic separator used at Monteponi 810 May Brothers' jigs at Mill 128 1714 mechanical batea 083 Monadnock Chili mills at Mill 144 1775 mortar jigs at Mill 177 1892 movable sieve jig 500 Narod pulverizer 282 New Century jigs at Mill 141 1760 New Humboldt concentrators 1494 Overstrom tables at mills 1711, 1730, 1930 Pape-Henneberg dry separator 819
Denver Engineering Works Company's Blake	gyratory breakers, table of
dewatering wheels at Mill 144	McFarlane rolls at Mill 142 1766, 1767
Dodge breeker	May Brothers' jigs at Mill 128
Dodge breaker	Monadock Chili mills at Mill 144
dredges	mortar jigs at Mill 177 1892
at mills 1667, 1681, 1685, 1689, 1690, 1691.	movable sieve jig
1093, 1701, 1702, 1703, 1707, 1710, 1711, 1725, 1727, 1728, 1729, 1742, 1742, 1740, 1750, 1750, 1750,	New Century jigs at Mill 141
1758, 1755, 1759, 1760, 1761, 1762, 1763, 1771,	New Humboldt concentrators
1772, 1774, 1792, 1793, 1804, 1822, 1824, 1825, 1829, 1837, 1838, 1839, 1849, 1849, 1849, 1844,	Pape-Henneberg dry separator
1845, 1846, 1847, 1853, 1854, 1855, 1857, 1858,	Pape-Henneberg dry separator 819 Peck centrifugal separator 828 picking belts at mills . 1737, 1806, 1815, 1842, 1882
Dodge breaker 36 pulverizer. 262 dredges 1009 elevators. 802, 803 at mills 1667, 1681, 1685, 1689, 1690, 1690, 1691, 1792, 1793, 1707, 1710, 1711, 1725, 1727, 1728, 1729, 1742, 1743, 1749, 1750, 1752, 1753, 1755, 1759, 1760, 1761, 1762, 1763, 1771, 1772, 1774, 1792, 1793, 1804, 1822, 1824, 1825, 1820, 1837, 1838, 1839, 1840, 1842, 1843, 1844, 1845, 1846, 1847, 1853, 1854, 1855, 1857, 1858, 1866, 1867, 1809, 1871, 1877, 1880, 1883, 1888, 1886, 1807, 1809, 1871, 1877, 1880, 1883, 1888, 1889, 1890, 1898, 1910, 1928	1889
Ellenbecker table	tables
Ellenbecker table 681 Evans jigs at mills1837, 1838, 1843, 1844, 1845, 1930	1889 Conveyor
round tables at Mill 162 1846	plunger feeders at mills 1740 1750 1957
slime tables at Mill 177	pneumatic belt concentrator 818
Fans at Mill 186	push conveyors at Mill 105
feeders at Mill 125 1700 Ferraris magnetic separator 799	pumps 872 push conveyors at Mill 105 872 revolving driers at mills 1746, 1762 Riblet aerial tramway at Mill 124 1696 Rittinger toble
Ferruris magnetic separator 799 Frayer centrifugal pumps at Mill 159 Frayer cand pumps at Mill 159 Frayer cand pumps at Mill 159	Rittinger table
spiral sand pump	Robins belt conveyors at mills1750, 1805, 1806,
Frenier sand pumps at mills	Riblet aerial tramway at Mill 124
11129	
Garland disc conveyors at Mill 124	Robinson jig 504 Rock Emery mills 255
·	rolls64, 86
94	



eed of rolls and angle of nip 94	Speed of Wifley tables at mills 1708, 1715 172	9, 1738, 1739.
speed curves	Speed of Wifley tables at mills 1708, 1715 172: 1744, 1745, 1754, 1761, 1776, 1780, 1829, 1830, 1839, 1844 1858, 1867, 1868, 1870, 188 Woodbury-Benedict jigs at Mill 177	, 1777, 1779,
at mills 1667, 1685, 1688, 1690, 1691, 1693, 1701, 1707, 1710, 1714, 1716, 1720, 1724, 1727, 1737, 1738, 1742, 1743, 1749, 1750, 1751, 1752, 1760, 1761, 1762, 1771, 1773, 1792, 1803, 1806, 1807, 1808, 1810, 1822, 1824, 1825, 1828, 1829, 1832, 1832, 1833, 1834, 1844, 1844, 1844, 1845,	1780, 1829, 1830, 1839, 1844	, 1801, 1800, 14 1929 1940
1738, 1742, 1743, 1749, 1750, 1751, 1752, 1760,	Woodbury-Benedict jigs at Mill 177	1893
1761, 1762, 1771, 1773, 1792, 1803, 1806, 1807,	concentrators	1490
1833, 1837, 1838, 1843, 1844, 1851, 1857, 1858	at Mill 117	1800
1833, 1837, 1838, 1843, 1844, 1851, 1857, 1858, 1864, 1865, 1866, 1867, 1868, 1869, 1883, 1890, 1910, 1911, 1913, 1928	proper speeds for sand wheels of variou	s diam-
1910, 1911, 1913, 1928	eters	1587
rotary driers at Mill 186	Traylor centrifugal pumps Sperm oil Sperry . E. A., amalgamated plates plates for Tremain steam stamps mercury traps	1007
round tables at Mill 180	Sperry	138
Salzburg table	E. A., amalgamated plates	.745, 762, 763
sample grinder	plates for Tremain steam stamps	787
Samplers		
sand wheels	Tremain stamptrap in Cross mill	.136, 139, 142
at mills	trap in Cross mill	774
Sautter magnetic separator. 798 scraping conveyor at mills 1662, 1709 screw conveyors at Mill 105 1636, 1637	Sphalerite and quartz, jig tests on extraction plant at Mill 130 hindered-settling test on pulsion jig test on settling velocity of specific gravity of Spider in any logarity on specific gravity of spider in any logarity	628
screw conveyors at Mill 105	extraction plant at Mill 130	1721
table of 1583	hindered-settling test on	617, 620
settlers	settling velocity of	466 469
grizzlies at mills	specific gravity of	1189
launders at mills	Spider in amalgamating pan	247
screens	Spigots for classifiers 388 404	439 445 444
screens 342, 345 at Mill 175 1889 Sherman re-grinders at Mill 132 1728, 1729	Spiders for trommels Spigots for classifiers	
Sherman re-grinders at Mill 132 1728, 1729	spitzkasten	440
Siemens and Halske magnetic separator 798	Spilsbury, E. G., breakers	60
simple steam stamp at Mill 182	Dodge breaker Engis machine	838
magnetic separator. 804 simple steam stamp at Mill 182 1909 slime tables. 684, 696 sorting tables at Mill 177 1892 stamps at mills 1818 1820 1821 1834 1838 1832	jig riddles <i>versus</i> trommels	527
sorting tables at IVIII 177	riddles versus trommels	385
sorting tables at Mill 177 . 1892 stamps at mills . 1618, 1620, 1621, 1624, 1626, 1632, 1640, 1658, 1661, 1668, 1677, 1769, 1915	Spindle and jaw breakers, table of products	of 53
in California	breakers capacity of compared comparison with jaw continuous action of	52
steam stamps	compared	45, 46
Stein, Bilbarz, and Lubrig tables	continuous action of	01 55
Sturtevant-Dodge type breakers, table of 1205 emery mill at Mill 186	COSt OI	02
emery mill at Mill 188 1918	details in the mills	46
mill	distribution of crushing in the mill	54
rotary breakers at Mill 186 1917	friction	54
Sutton, Steele, and Steele dry tables at Mill	having greatest movement on smallest l	ump 36, 1207
take-off belts of Wetherill magnetic separators 1524	heads and concaves	47
Traylor centrifugal pump at Mill 114 1662	number used	51
jigs at Mill 170	power of	
Tremain stamp 138 Triumph vanners at Mill 101 1627	principle of action running cost size and shape of mouth	54
	size and shape of mouth	54
trommels	table of comparative tests of	45
1690, 1691, 1692, 1693, 1701, 1702, 1703, 1707,	cost of crushing bydetails of	46
1710, 1714, 1724, 1725, 1727, 1728, 1737, 1738,	sizing tests of product from	45
1742, 1743, 1749, 1750, 1751, 1752, 1760, 1766, 1767, 1771, 1772, 1773, 1774, 1792, 1803, 1818	taper	52
1828, 1829, 1832, 1837, 1838, 1842, 1843, 1846,	wear forweight of	
1828, 1829, 1832, 1837, 1838, 1842, 1843, 1846, 1853, 1854, 1855, 1857, 1864, 1866, 1867, 1869, 1876, 1877, 1882, 1890, 1898, 1913, 1928, 1930	with equal movement on large and	i small
effect of	greatest movement on largest lump	45 45
effect of	or gyrating breakers	1206
Tustin's mili	or gyrating breakers	1818
vanner belts	Spinel, specific gravity of	1189
vanners	the Schmidt	362
Vapart disintegrator	sand pump	870
750, 1772	washing pipe for slime tables	689
vibration of Sutton, Steele, & Steele dry table 1555	Spitzgerinne Spitzkasten. See Pointed Boxes.	
Wilfley table deck	Spilzkasten	439
wash trommels	at mills	1401, 1419
pans	Rittinger	433
water current to move sand and gravel 878 waves and thickness of films on amalgamated	slope, spigots, deflectors, etc	440
nlates 746	Spitzhitte. See Tubular Classifier. Spitzhitte.	476, 773, 1389
Wenström magnetic separator 802	Rittinger Splash board	422, 424
Wetherill magnetic separator	Splash board	739
Wheel agritator 790	for stamps plates	
Wilfley slimers	Splice for belt	1094
at Mill 132	Split shovel	1570
Wilfley slimers 1505-1506 at Mill 132 1729 tables 673, 675, 1469 at mills 1625, 1633, 1656, 1661, 1662, 1669, 1686, 1687, 1689, 1864, 1665, 1702, 1704	for sampling	1189
1898 1897 1890 1804 180K '1709 '1704'	Charles for hand and Th	000

Pages 1199-1610, Vol. III.	INDE	EX. Pages 1611–2052, Vol. IV.
Stamps screen for	120	Steam pipe for amalgamating pan 243
Stamps, screen for	128	pipes for drying
shoessizing tests on	$\frac{120}{315}$	power in mills. See Individual Mills in Chapter XX.
small steam	136	picssuic in mins
springstaves	141 120	on steam stamps 126 pumps 871
steam. See Steam Stamps.		separator 1091
steam	$\frac{113}{1250}$	separator
discharges for foundations, anvil blocks, mortar beds, sills,	1256	area of discharge
foundations, anvil blocks, mortar beds, sills, and girders of Nordberg steam stamp	1247	Ball. 114, 118, 119, 120, 121, 122, 123, 124, 126, 127, 128, 130, 131, 132, 133, 134 Cuyahoga. 114, 118, 119, 121, 122, 123, 126, 127,
indicator diagrams of tandem or steeple-com-	1271	Cuyahoga114, 118, 119, 121, 122, 123, 126, 127
pound	1255	128, 133
mortar jig discharge for Nordberg steeple-compound at Mill 181	1256	Fisher's
Nordberg steeple-compound at Mill 181 pneumatic and spring	$\frac{1254}{113}$	Fraser & Chalmers. 114, 116, 118, 119, 120, 121, 122, 123, 126, 127, 128, 131, 133, 101, 101, 101, 101, 101, 101
principles of action	1246	Indicated Delit.
single-cylinder at Mill 182	1254 135	Leavitt. 114, 115, 116, 118, 119, 120, 121, 122, 123, 124, 126, 127, 128, 131, 132, 133, 134
steam cylinder, valves, and valve gears of		nnings 120
Nordberg steam stamps	1249	mills in Montana 984
table of efficiency oftandem or steeple-compound	1250	at Lake Superior 990 mortar discharges 998
use of and quality of work of	134	Nordberg
table of details for screens	$\frac{121}{127}$	and girders 1247
foundations and mortar beds	118 118	single-cylinder stamp
sills and girders fortests on work required for	306	steeple-compound at Mill 181 1254 tandem compound at Tamarack and Osce-
their principle, purpose, and classification113, Traylor gravity	1246	ola mills
velocity of fall in	315	prospector's 2011 screens, material, size, life, etc. 1212 shaft, pulley, and guides 128
versus ball mills, as slime makers at Mill 185	1916	shaft, pulley, and guides
Bryan mill Griffin mill	273 284	Sharpneck 136 Tremain 136
rolls	314	Union Iron Works, 114, 117, 118, 119, 122, 128
weight of and effectiveness of blow	2013	Wilson's
Wellman, Seaver, Morgan gravity Stand pipes	1278	Wood
for Tamarack classifier	397	stamps
Standard Consolidated mill	228 766	at mills1892, 1895, 1897, 1899, 1901, 1906, 1909
mine, Frenier sand pumps at	1588	capacity of
Iron Works, Lane slow-speed mill	1308	cards of 131
mill	1183	clean-up
Idaho, milling at the. J. R. Finlay mine, tube mill lining at the	2033 2014	cylinder and compound stamps 1254
Bodie, Cal., slope of launder at	1549	cost of crushing by
Mining Co., mill	947 1267	cylinder clearance 123
ten-stamp battery Standardization of laboratory screens. W. S. Hutch-	1000	die, ring, staves, and shoes 120
insonscreens	1366 1361	different makes of
A. Whitby	2019	discharge of
report of committee on Standards, metallurgical. F. T. Snyder	2019 2019	efficiency of 131 energy, momentum, and efficiency 133 floors, bins, and feeding 128
Stanford, C. P. Stanwood gravity muller. 1279,	228	foundation, mortar beds, sills, and girders 114
Stapff, F. M., Stapff jig	1285 . 643	traine 118
Stapff, F. M., Stapff jig	824	indicator diagrams of single-cylinder Nord-
Ballarat, acid water	178	berg
mercury wells in	771	Krause discharge
Starch, settling of,	880	Leavitt differential cylinder
ley	1184	housing
screens	488 1345	jig discharge for
for dredges	1012 1189	piston, stroke, speed, water, capacity 126
Stausatz	214	piston rod, dash pot, flange, revolving pulley, stamp stem, stamp shoe
Staves, details of, from mills	123 120	power for 181
Stay battery	224	principle of
for stamps box for jigs	214 551	rubber cushion for
boxes for jig discharges	584	safety devices
overflow mortar, Schorr Steam cylinder for steam stamps	1266 122	single-cylinder at Mill 182 1254
of Nordberg steam stamps	1249	sizing tests 135 small 136
for heatingpower	1098 1091	spring timbers for
hammers	12	steam cylinder, valve, and valve motion 122 tandem or steeple-compound
jacket for amalgamating pan	243 519	tests on
	~_~	GLATAIL 104

Steam stamps, types of	Stokes, G. G., velocity of a sphere falling through
used for malleable minerals	a viscous liquid 1422
uses and sizing tests	R., asbestos milling in Canada
valve and valve gears of Nordberg steam stamps 1249	Britannia Copper Co. mill, B. C 2046
versus gravity stamps	Coniagas mill, Cobalt, Ontario 2046
rolls at Mill 179 1900	diamond washing in Africa
water used 129	milling at Broken Hill 2046
Wearing parts	Rossland district, B. C 2046
weights, life, etc., of shoes, dies, rings, staves 122	milling at Broken Hill
used for heating water for amalgamation 768	mili practice in Australia
versus electricity as a motive power 1927	tin industry of Tasmania 2046
Stearns-Roger Manufacturing Company, hoe con-	washing in the Malays 2046
veyor at Mill 141	tube milling in New Zealand 2014
Mill 152	Stolberg, jig eccentrics at
roll speeds	Stone, compressive strength of
scraping conveyor	effect of heat on strength
Wetherill magnetic separator 1521	riffles
Stedman's disintegrator	tests on at Watertown arsenal 300
bibliography for	Stoppages in mills 1115
capacity for clay	Storage bins
fertilizers	tanks for water
Steel cloth screens	Storehouse for mill
Steel cloth screens	Storing concentrates
for jig screens	canvas tables
roll shells	gold stamp mills in California 1181
springs	Story in mill building
shoes and dies	Stoves for heating
steam stamp wearing parts 122	Stoves for heating
frame for mills 1088	Yguana, Mexico
log washer 325	Strainer for classifiers
McLanahan's 325	water 858
plate screens	Strakes 725
receiving bins at Mill 174	Strainer for amalgam 781
scraper for amalgamated plates	Strands in wire rope
special gravity of	Strength of cubes and prisms, tested at Berlin 302
versus brass for jig screens	machines 1006
Steep end-shake vanner	rock, effect of, on power used
Steeple-compound or tandem steam stamps 1250	Sione
indicator diagrams	before and after heating, tested at Berlin 302
	parallel and perpendicular to bedding
mill	planes
mill 1177 Stein table 069, 698 Steinenbruck, mill at 1176	
Steinenbruck, mill at	Stretch of belt
Rittinger tables at	Stroh's jig
Stem for gravity stamps	Stroke of jigs
guides at Mill 96 1618	movable sieve jig 500
Stem Winder Millxxvi, 951	steam stamps
Stem Winder Mill. xxvi, 951 Stems, fatigue of stamp	on Wilfley table
	See also Throw.
removal of broken stamp	Strokes, number of, in jigs
Stephanite, specific gravity of	Strontianite apecific gravity of 1180
removal of broken stamp 2011 Stephanite, specific gravity of 1189 Stephen Lavagnino's arrastras xxviii, 1039 Stephens-Adamson Manufacturing Company, belt conveyors at Mill 171 1868, 1869	Strontium, atomic weight of
conveyor of Mill 171 Company, Delt	Stroud, E. H. and Company, disintegrator and pul-
elevator buckets at Mill 126 1707	verizer
self-oiling carrier for conveyor belt 1585	mili 1281, 1319
tripper for discharging conveyor belts 1586	tables of sizes, capacities, power, etc., of the 1320,
	Structure and fracture of minerals
Step roller crusher mill	Stubbs wire gauge
Steps on slime tables	
Step roller crusher mill 2017 Steps on slime tables 689 Steptoe Valley Smelting and Mining Company . 1852, 1865 Mill Ely, Nevada. W. R. Ingalls 2039 Sterling Iron & Zinc Co. mill	screen gauge
Mill Ely, Nevada. W. R. Ingalls 2039	Studying mills, method of
	Stuhl, L., Mumford and Moodie machine 839
magnetic separation 837	Stupakoff, S. H., on wire gauges 2019
Sterrett, D. B., monazite sand dressing in the Caro-	Sturm, Priedrich, separation processes
linas 2030 Stetefeldt, C. A., gravity crushers 229	Sturtevant, bag houses
etampe 229	balanced rolls, description of
stamps	table of sizes, power, weights, dimensions,
leaching silver with hyposulphita 1174	P. F. etc
leaching silver with hyposulphite	B. F., Co., heating apparatus 1099
of silver ores	breaker 1223
rolls	diagram of
Stewart jig in coal washing	centrifugal rolls
Intrivation	description of
Stewart's mill, wear of amalgamating pans 249	Dodge-type breaker
Stibilite, specific gravity of	fan at Mill 105
Stickes mill of the Utica Companyxxviii, 1034	fan at Mill 105
Stewart's mill, wear of amalgamating pans 2061	Mill Company, rolls 1245
Stiller pulpodess gravity of	rock emery mill 258
Stiles pulverizer	sample grinders 1284
Stirling boilers 994 Stirring arms in trough washers 320	sample grinders 1284 Sturtevant breaker 1223
in setting line slimes 1140	mill
Stirrin teader	details of
Stock house for ore	details of
Stock house for ore. 843, 1108 Stock, H. H., concentration of Mesabi ores 1344 Stokes, G. G., law of viscous resistance. 1423	versus rolls
Stokes, G. G., law of viscous resistance	data of sizes

Pages 1199–1610, Vol. III.	INDI	z_{X} .	Pages 1611-2052, Vol	. IV.
sturtevant roll jaw Blake breakers rolls at Mill 178 182 roll shell turning device, the rotary breaker at Mill 186 sample grinder toggle separator Stutz coal jig mechanism improvements on coal jigs jig ribbon theory of roll capacity S, link belt elevators and conveyors rolls for coal water separation Style "K." Gates' breakers Submerged trommels at mills 1356, 1703 Suckling's double discharge mortar Suction. Suckling's double discharge mortar Suction in jigging after sorting Bring's tests on suction jig cleaners at Mill 186 dredge effect of fans, for dust final conclusions on general principles of how avoided in jigs in jigs 49 Hoppe's tests investigated in the mills theory of use made of, in mills Sudbury, breakers at Sulsse, Mathet, De Gournay and Hochstrate apparatus Sulphide Corporation at Mill 130 separated by oil Sulphides, effect of, on amalgamated plates Sulphur, atomic weight of from coal by crushing, removal of . C. C. Upham Mines Company mill Virginia, mill at ore, mill for 90 specific gravity of Sulphurets treatment of Sulphurets treatment of Sulphurets treatment of Sulphurets used on revolving convex tables grizzlies and gravel screens principles of ore dressing Summerhayes vanner belt Summit County ore, Colorado, concentration of. D. H. Laurence Mining Co., results with Wilfley table Superior crushing rolls, description of rolls at Mill 167 supplementary principles in concentration Surface current box classifiers 433, 477, details of in the mills	1205 12010 1390 11910 12143 11911 12143 12143 12143 12184 2018 523 640 1207 1227 1611 1401 1401 1401 1401 1401 1402 1402 1402 1403 1404 1404 1404 1404 1404 1404 1405 1406 1407 1407 1408 1408 1409	Sutton, Steele and mills	at Steele pneumatic dry tables at 1765, 1803, eter ore sizer at Mill 151. 1803, table, description of the. R. C. separator, description of the. R. C. separator, description of the. C. Canby agnetic concentration at 835 at 1804 and 1804 at 1805 at 1804 at 1805 at	t , 1804 , 1804 , 1804 , 1804 , 1804 , 1804 , 1805 , 2027 , 1568 , 1185 , 1420 , 1569 , 1570 , 1569 , 1570 , 1556 , 1670 , 1556 , 1862 , 1870 , 1556 , 1862 , 1870
Virginia, mill at ore, mill for specific gravity of Sulphurets treatment of Sulphurets treatment of Sulphurets acid for leaching in settling tests used on plates Summary of devices used on revolving convex tables grizzlies and gravel screens principles of ore dressing Summerhayes vanner belt	905 905 4, 905 1189 781 1167 1147 1, 752 689 339	Castelnau Clark department at Dodd Ellenbecker Evans Ferraris belt for settling star testing German sweep Gilpin County glass, for film- Golden Gate	mills	689 1841 675 681 689 698 880 1155 703 680 707 681
Mining Co., results with Wilfley table Superior crushing rolls, description of rolls at Mill 167 Supplementary principles in concentration Surface current box classifiers. 433, 477, details of in the mills in the mills method of investigating laws of free settling particles in expenses	674 1231 1857 5 1401 442 440	Hendy concent Imlay Linkenbach sli of diameters ar velocitie effect of dis wagon voids in crus	rator me	683 681 689 2002, 2003 2005,
of slime tables of slime tables produced in crushing relation of to diameter of ore particle sizing on, used in mills tables continuous intermittent tension, relation to slime question theory of crushing work units of Suspended frame vanners, Allis-Chalmers	688 310 305 889 685 686 700 1414 305 1187 1503	Parsons revolving circul Rittinger Roberts slime rocking. Salzburg Schranz Sparre circular top, paint for Uren belt with riffles Wilfley	ar concave slime	668 692 667 691 1032 682 728 691 1483 698 770
Johnston Sorting or picking table, Krupp-type Sutter Creek, California, mill at 1023, Sutton, Steele and Steele, dialectric separator at Mill 151 electrostatic separator pneumatic dry tables 1479,	1501 1436 1184 1766 1804	Woodbury Tables. See also B Allis-Chalmers and belts for he spee belt	uddles, Table, and Slime Tables.	676 1435 1435 1438

Tables, blanket	Tailings plant at Vallogge Idaha
building type	Tailings plant at Kellogg, Idaho
bumping	of Calumet & Hecla Mining Co., Michigan 2046
700 1025 1464 1507	Mill 177 1894 preservation of 1114 removal of, from jigs 587 reservoirs 460 re-treatment plant at Mill 130 1723 reservoirs 1723
carpet and blanket	removal of, from jigs
carpet and blanket 703 carpet . 703, 1035, 1464, 1507 classification of Wilfley group 1465 cocca matting 702 concentrating, Bartlett Simplex concentrator 1487	re-treatment plant at Mill 130. 460
cocoa matting	
Bartisch rotary percussion table 1497	sampling of 845 sand and simes in the Witwatersrand, handling
belt-percussion table 1496	01. II. K. Skimler
capacity of Wilfley table	Sizes of in mills
Christensen concentrator 1484	treatment of
cleaned-ore plane in	used for filling 925 value of 1114
cleaning plane in	weight of
Deister concentrators	wheels 864
Dodd buddle	data on. Julian & Smart 1610 mechanical efficiency of 1609
feed box for Wilfley table	spokeless. L. H. Lavenstein
Ferraris	versus pumps in Witwatersrand
general comments on	and proper speed
head motion for Wilfley table	effect on mercury 94
investigation of Wilfley table work 1469	effect on mercury
James table	ground in buhrstone mill 253 specific gravity of
linoleum for deck cover 1467	Tallow
Luhrig-Buss concentrating table 1492 slimer 1496	for belts
McLeod concentrating table	mill, Burgan classifier at 1371 Nordberg tandem-compound stamps at 1254
new Humboldt concentrator	Nordberg tandem-compound stamps at 1254
operating conditions for Wilfley table 1469	Mining Company mill xxvii, 1000, 1181
Overstrom table	rigid rolls at
riffle cleats for Wilfley tables 1467	
roughing plane in	trommels 362 Tank for constant head 858
sized versus classified feed for	washing with hand picking 488
speeds for Wilfley table	house at Mill 161
tilting-frame for Wilfley table	system of working amalgamating pans 248 Tanks, Callow 2020
wash water for Wilfley table 1469	distributing
Wilfley	settling
Woodbury table	settling 450 Tantalum, atomic weight of 1188 Tange of beackers
Cornish frames 704	Taper of breakers 52 stamp stems 187, 188 Tappan pump 1046
end-bump	
fixed circular convex slime 689	the Boss wedge-grip 1272
for amalgamated plates	resetting 201
picking 488	screw type
greased 831 Humboldt picking 1437	Tarasca Gold Mining Company, Pinder concen-
intermittent surface type	trators at
investigation of film sizing	Tarnowitz, Büttgenbach's separator at 447
principle of	Heberli mill at
principle of 644 concentrating. C. W. Comstock 2023 principles of action of Wilfley group 1465	tanks at 479
revolving circular convex slime	Silesia, mill at
strakes 725 Salzburg 1115	stamps at 230
shaking amalgamating tables in South Africa 1513	Tasmania, costs of producing copper at 1957, 1958 mill in
side-bump	tallow for guides in
slime	tin milling in
tye	Tatum, L. W., amalgamating pans
versus jigs 606, 641 Wilfley group 1464	riffle for cutting down ground pulp 1577
Taft breaker 61 Tailboard for jigs 510, 525, 550	F. W., belts
height of 550	hand breaker
Tail-discharges for jigs	J. & Co., stamp mill 1137 mine of Idlewild Gold Mining Company, mill . xxvii
Kalgoorlie, disposal of 2032 the Arizona Copper Co., disposal of 2032	pipe sampler used by
definition of	portable stamp mill
definition of 494 disposal of 1113	W. W., sampling
	Tays, E. A. H., Bryan mill
handled by mechanical shoveler 879 launders 873	slime settlings 1419
or vanners, testing or	Teague on kieves
10	JU

Pages 1199–1610, Vol. III.	INDI	EX.	Pages 1611-2052, Vol	1 TV7
Tecolotes mill	. 1748	Tests of American I	·	
Tecolotes mill Telluride, Colorado, mill at. 1014, 101 milling practice at gold ore, cost of producing gold from	6, 1176		Process Company drier	
goldore cost of producing gold from	1014		on Butte copper slimes	
ore, cost of producing gold from tests on Tellurium, atomic weight of Temperature effect of or amplements. 788 151	1175	feed and disc	harge of Abbe tube mill	. 1489
		Gates and M	cCully breakers	. 1290
at Homestake. T. J. Grier settling slimes. 114	. 2024	grains in free Grill drier at	settling plant of Empire Portland Cemen	465
straining amalgam of heating for decrepitation	781 829	Company	paint of Empire Fortiand Cemen	1597
oil separation pan amalgamation	. 831	hindered settl	on Montana sulphide copper ore	1442
roasting for magnetism regulated by pyrometer in Wilfley roasting fu	. 814	McLeod, Wi	alley and Overstrom tables at	. 623
nace	. 1548	mill work	• • • • • • • • • • • • • • • • • • • •	. 1493
Template for stamp cams Templates	1097	ores ou wein	ion at Mill 172 erill magnetic separators	XOX
for gravity stamps	. 854	power at Mill Richards' pul	173sator jig	. 1927 . 1456
Tenacity, affecting separation and brittleness, effect of in dressing ores	. 2	roasting pyrite	e for magnetism	1544
		WIII 102 .		. 1909
Tennessee Copper Company, cost of producing copper at	6, 1957	steeple compo	and steam stamp at Mill 182	1254
		telluride gold	ores separation by crushing and	1555
Tenth U. S. Census, order of drop of stamps Tephroite, specific gravity of		trommel prod	ucts at Iron Mountain Missour	1567
Terrocad mill site	. 1188	woodbury lig	at Mili 102 1449, 1450	. 1451
washing china clay	1174	on absorption of	fiers	765
Test, directions for carrying out a concentration J. P. Porter	1.	compressive si	trength of stone	300
in Platteville, Wisconsin, results of a mill. H	3.	Haverstraw sa	ndstone at Watertown Arsenal.	707 . 300
jigging	. 1165	insterstitial cu	ingrrents	626
jigging of gold ore. lubricants.	1008	ugging mixed	Sizes	630
specific gravity	0, 1171	sands, regrind smooth and co	m stamps ing. C. Butters prrugated vanners	2014 650
a Frue vanner	6, 1988 . 1171	stone at Berli	1	301
Bardwell sorting tubebibliography for	. 1988			
by bottle amalgamation	. 1996	vanners		4, 666
oll	1155	screen sizing t		2049
suited for	. 1989	produc on classifi	is of Huntington mills	1317 1453
for a process	. 1562			
Delprat and Potter processes Elmore process Van Meter process	. 1998	feed to	ers Huntington mills flotation plant at Mill 1301721	1316 1724
Van Meier process 1991, 1995	2, 1993 . 1150	Ha Ha	ncock jig, also on middlings rz jigs at Mill 144 . 1772, 1773, bodbury slime classifier at Mill 162	1443
suited for	. 1989	w	oodbury slime classifier at Mill	1440
magnets, double-pole	. 1998	materia	l conveyed in pipe launder at	1449
of black sand. W. Fawcett	. 2048	mill fee	ajuato d at Mill 139 Mill 144.	1750
gold mill tailings. W. E. Darrowores. H. Van F. Furman	. 2048			
mill ore from mine	482	Br Br	yan mills yan mills, high-speed rolls and Huntington mills tree and fine rolls at Mill 162	1310
ores. M. Lenicque plant at Denver. G. R. Delamater	. 2048 . 1997	COE	Huntington mills	1317
1. Longe	. 2049	De	Kalb's classifier	1402
Mill 141 of H. E. Woods. A. Lakes the California Ore Testing Company	2048 2049	fine	grinding system, Mill 105	1638
roasting for magnetic separationscreens suited for	1995	grii	nding pans	1284
under water	1139	Hu	nding pans at Mill 130	1669
tools for	1127	Kid I	chards' vortex classifier at Mill 441775, 1776, d treatment at Mill 117	1778
Wilfley table suited for Tests, amalgamation at the Homestake mill in 1897. A. J. Clark	1156	san , sett	id treatment at Mill 117 ling tanks at Mill 1441776,	1777,
		She	arman settling tanks at Mill 132.	$1779 \\ 1406$
by Elmore vacuum oil process 1559 hand picking	, 1560 1163	<i>s∳i</i> stai	tzkasten at Mill 144 1777, mp mortar at Mill 180	1778
by Elmore vacuum oil process	1168	tailings and	and concentrates from stamps l Lane Chili mill, comparative.	1309
at Mill 162	1391 2049	from	Mill 174odbury jig at Mill 162 1449,	1887
sorting, at Mill 162				1451
meanurgical	101	sizing and assayii	ag	1102

		2 4800 022 2201, 101, 11.
Tests to show relative efficiency of regrinding machines	1331	Thyng, W. S., details of a hand jig 2021
See Sizing Tests.	1100	Ticonderoga, New York, graphite mill at 1078
Tetradymite, specific gravity of	1189	Tierra Seca gold separator
Tetrahedrite, specific gravity of Thallium, atomic weight of	1188	Tiger & Poorman mill
Thames district, amaigamated plates in	750	Tightener on belt conveyors
mills in	1111	Tighteners for belts 1004
plates in	788	stamp helts
New Zealand, mills atshoes and dies at		Tilly Foster mill. 195
stamps at	226	magnetic concentration at810, 830
Thatcher, Arthur Thayer portable one-stamp mill	viii	mine, costs at
Thayer portable one-stamp mill	1137	Timber for mortar blocks
Statup multiproperty	1191	TILLIE DIOCKS
Theoretical and actual crushing ribbons of rolls	101	Time of cleaning plates
capacity of trommels value for hindered settling ratio	377 1427	required by cyanide operations at Mill 117 1672
Of free-setting velocities		for magnetic roast
Theory of crushingelectromagnets	303	retorting
electromagnets	790	Tin amalgam 730
HOBITON Drocesses	1555	Tin amalgam
flow in launders	876	bronze plate screens
or said that water in landers 1002, 1000,	1595	dredging in New South Wales
slime settling	1149	dredging in New South Wales
suction	1462	dressing
tube mill action		at the old Clitters mine
work required for crushing	304	bibliography for
Thermo-electric couple with pyrometer in Wilfley	1540	1916
roasting furnace	1178	Tagmania D Stokes W. R. Lewis 2037
mill at	1079	Tasmania. R. Stokes 2046 the Malay Peninsula. W. H. Derrick 2039 industry of Tasmania. R. Stokes 2046
Thickness of amalgamated plates737	, 744	industry of Tasmania. R. Stokes 2046
mank in trommels	378	mining in Indo-China
bed on fine concentrators	644	ore concentration. J. B. Hill, D. A. MacAlister 2046 Cornish, crushed by Husband stamp 141
on vanners. bottom bed on jigs film in film-sizing tests	660 575	Cornish, crushed by Husband stamp 141
film in film-sizing tests	718	frames for 704 crushed by Sturtevant mill 228
on sime tables	697	gressing of R. H. Richards and C. E. Locke 1924
canvas tables	702	roasted for porosity
hard amalgam on plates	761	
ore on belts of magnetic separators stamp die	807	ring in Cornwall on
plate or wire	$\frac{207}{371}$	separation of, at Altenberg 9 worked at Irish Creek, Virginia 288 pellets, recovery of. M. Baldauf 2030
screens	341	worked at Irish Creek, Virginia 288 pellets, recovery of. M. Baldauf 2030
screens, effect on percentage of opening water film on amalgamated plates	369	
Thick pulp or tractor Autor	746	173 174 175 176 177
Thick pulp extractor, Ayton. Thics, A., and W. B. Phillips, stamp mill at Haile	1419	washing. J. H. D. James 2035
gold mine. North Carolina	1175	in Cornwall
gold mine, North Carolina method of chlorination at Mill 98	1622	Tiptic district Utah mills in 1040 1041 1048
I filte. A., gravity stamps 994	225	Tires of rolls
Thirion classifier Thomas breaker	475	Titanite, specific gravity of 1189 Titanium, atomic weight of 1189 Torgoles for Neuron 1289
	57	Titanium, atomic weight of
log washer 324, R. A., Dolcoath tin mill, Cornwall slag, mill for Thompson, experiments on magnet	228	Toggles, for Frue vanners 645 Tokit, F., chilled iron shells 111
R. A., Dolcoath tin mill, Cornwall	1183	Tomboy Gold Mines Company
slag, mill for	1177	Tomboy Gold Mines Company
Thompson, experiments on magnet	794	Tombstone, amalgamating pans at
H. N. dressing asbestos at Thetford, Quebec. pneumatic concentration at Thetford, Quebec	1178	Arizona, mill at
pneumatic concentration at Thefford Ouches	7110	silver milling at 1016
pulverizer	234	mill, jigs in 639 Ton, definition of vi, 883
bibliography for	294	equivalents of
pneumatic concentration at Thetford, Quebec pulverizer bibliography for. S. P., electromagnets xxx, on magnets	833	of water
Thomson-Houston dynamo	795	Tonge, Thomas, concentration from dumps at Lead-
Thorium, atomic weight of Thoulet, J., experiments on very fine kaolin	1188	ville, Colorado 1179
Thoulet, J., experiments on very fine kaolin	477	Tonorah Mining Company's mill S. A. Wongerlan 2007
on scume rates of the grains	474	ore testing plants
settling in water velocity of spheres of different density and size	1176	CHILLICYCL BUILLIO-ITALINE BL 1272
Thoulet's solution	477	rachuca stamp battery at 1272
Thoulet's solution Three-high rolls -mineral separation	107	Loois for testing
-mineral separation	ด์เก	Toothed rolls
-mineral separation	590	Toothed rolls 111, 112, 1080 description of Allis-Chalmers type 1242
Throw of Comet breaker	680	table of sizes, capacities, and power. 1243 Topaz, specific gravity of 1189 Top layer on jigs, defined 495
Gilpin County humping table	48	Topaz, specific gravity of
Hooper vanning jig	BOA.	Total cont
Hooper vanning jig	594	1123
Johnston vanner	503	Totten & Hogg, makers of Forster breaker 25 Toughness of minerals, effect of 2 Tourmaline, specific gravity of 189 Tower driers 160
The state of the s	608	Toughness of minerals, effect of
shaking plates	688 '	Tourmaline, specific gravity of
Stein, Bilharz, and Luhrio tables	741 670	Lower driers
		Tower driers 1807, 1813, 1860 at mills 1809, 1822, 1824, 1825, 1861, 1863 Screens at mills 1809, 1822, 1824, 1825, 1861, 1863 Trachyte, strength of 301 weight of 301
Thrust of gravity stamps	195	Trachyte, strength of
Thrust of gravity stamps	188	weight of 1190
secure a combounder tong	110	Weight of
		,

Pages 1199–1610, Vol. III.	IND	EX.	Pages 1611–2052, Vol. IV.
Trajectory, use made of, in mills	. 1123 . 1769	screens, cost of in	to space between rolls
Transporting power of water Transvaal, milling in the. J. H. Hammond	. 878 . 2033	wasning pia	eens
milling in the	225	Trommels	
Transylvania, Laszlo amalgamator in Trap rock, weight of	777 1190	action of arrangement of	378 364
Traps, bibliography forbox	773	1693, 1701, 1702 1725, 1727, 1728	581, 1682, 1685, 1690, 1691, 1692, 2, 1703, 1706, 1707, 1710, 1714, 1724, 3, 1737, 1738, 1742, 1743, 1749, 1750
transverse with gates	72–773 877	1751, 1752, 1760 1792, 1796, 1797	, 1766, 1767, 1771, 1772, 1773, 1774, , 1798, 1799, 1815, 1818, 1828, 1829,
flow of water	885 1197	1864, 1866, 1867	378 381, 1682, 1685, 1690, 1691, 1692, 2, 1703, 1706, 1707, 1710, 1714, 1724, 3, 1737, 1738, 1742, 1743, 1749, 1750, 3, 1766, 1767, 1771, 1772, 1773, 1774, 3, 1798, 1799, 1815, 1818, 1828, 1829, 1829, 4, 1838, 1842, 1843, 1846, 1851, 1857, 7, 1876, 1877, 1882, 1884, 1889, 1890, 1898, 1913, 1928, 1929, 1939, 1898, 1913, 1928, 1929, 1855
civil engineers' pocket-book xx coefficient of efflux strength of stone	, 1174 404 316	capacity or	377
Travel of belt vanners on Stein, Bilharz, and Luhrig tables	648 670	cones, pyramids, a	
vanners	2 657	construction of in	mills
Traylor all iron jig & Company, J. A. centrifugal pumps sand pumps. centrifugal pumps at Mill 114 capacities of	1610 1588	details of trommel	screens at Mill 125 1705
capacities of	1588 1589	dimensions and op	349 eration of 347 356
Centripact screen	$\frac{1352}{1865}$	effect of centrifuga diameter of	l force in
concentrator double-discharge mortar Engineering Company, Centripact screen	1266 1360	stope in	pe
Giroux mill Traylor gravity stamps high-speed rolls at Mill 158	1864	for dredges	
Imperial screenjigs at mills1864,	1348 1867	Gates all-iron fram	374 ae revolving screen
rolls at Mill 169 sectional mortar Trays for Wilfley slimer	1267	length of	
Treatment charge on zinc ores	781 1933	Neuerberg octagonal	
of middlings	750 750	pitch angle in	
slimes	1121 1613	power for principle of	
at Mill 148	1548 1792	rate of travel of or receiving cones for	346 e in 374 358
Tregoning pulverizer	297	Schmidt spiral scre sectional	een
details of	139 138	slope of	
Tremticz, Huntington mill at Trent Chili mill, sizing tests of Engineering & Machinery Company, Monad- nock Chili mills at Mill 144	282 271	speeds, pitch angle	349 ;, etc. 376 352
nock Chili mills at Mill 144 L. C. & Company, on Chili mill Trenton Iron Company	270	systems of	352 els at Mill 125 1350 at Mill 125 364 atric 362
gaugescreen gauge	1194 173	tests of work of in thickness of bank	mills
Mining and Development Company Trevarns (Camborn), tin mill Triangular gate spigot for jigs	1083	marene Rowand inc	Blömeke
Tributer's mill Trimountain Mining Company copper handbook	1039 1901	water for	
Triple discharge two-stamp mills	209 1091	without internal sh Trough classifiers	afts
pumping engine Triplex pump at Mill 117 rolls	$872 \\ 1674$	double or shallow-pocket	218 416 1371 1371 1319
description of	1239 1548	bibliography for washing for corun	
Tripolite, settling rate of Trippel, A., Krom jigs at the Manhattan mill Georgetown, Colorado	474 838 838	Troughs. See also La for mercury traps jerking	772
discharging conveyor belts	1586	Truesdale coal breaker	861 nts of 1187 2050 69
at mills	. 1499	Sturtevant rol with an emery	shell turning device 1248 wheel
at Mill 101 Trommel, an improved	1360 1700	Trunking machine	

Pages 1-643, Vol. I.	ORE	DRESSING	Pages 644-1197, Vol. II.
Trunking table for cleaning jig concentrates Trustedt magnetic separator		587 Tullock fe	eder for jigs
Tube mill, a double	2	017	Olis
crushing efficiency of. W. A. Calded S. H. Pearce	ott and	323 vanne	d in Bryan mills
S. H. Pearce experiences in El Oro, valuable. C. feeder, a special. W. H. Fox E. G. Banks grinding in New Zealand. on the Rand. installations, design of A. James liners, wear, cost. S. D. McNicken lining at the Standard mine. W. W. patents	Butters 2	016 Tumbler of Tumbler of Tungsten,	er
grinding in New Zealand.	20	013 in C 013 Wa	colorado, concentration of H. R. Van genen
installations, design of A. James liners, wear, cost. S. D. McNicken	20	014 ore co	incentrates, cost of producing in Colorado 1987
lining at the Standard mine. W. W. patents	Bradley 2	013 Wa 017	n Colorado, concentration of. H. R. Van genen
patents practice in S. Africa New Zealand S. Africa, K. L. Graham W. P. Dowling	2015, 20	515	treatment of
W. R. Dowling	2013, 20	014 Turbine w 013 Turbo log	
W. R. Dowling. results in S. Africa. H. Leupold Abbé.	233, 1	010 a 285 r	1089 Washer 1341 t Mill 154 1341, 1816 Ower required for 1816 Peelie gravity of 1816
Abbé. mill at Guanajuato capacity of. at Mill 103		290 Tuscany	1886 pecific gravity of 1189 mills in 1177 or quicksilver ores 1074 ll 1047
Alsing	0 1004 1	2/1 Tustin mi	ll
Allis-Chalmers an article on. A. H. Bromley at El Oro. E. Burt Guanajuato, Mexico. C. W. Van 1 mills the Gold King mill, Colorado. F. I ard	20	323 nur 013 pov	1027 1027
Guanajuato, Mexico. C. W. Van I)18 sizi	ng tests of products of, in Oro Plata, and Itica mines
the Gold King mill, Colorado. F. I ard	E. Shep-	Tustin's p	Ultica mines
ard the Walhi mines. R. Stokes. bibliography for. capacity of	20		The state of the s
classification of	12	291 285 Tutty, E.	slime table
classification of classification of consumption of pebbles and liners at Mill 118 cost of grinding by Davidsen	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	191 Twelve Ap 191 Two-curre	ostles mill, amalgam in
Davidsen Denver Engineering Works Company	1280, 12	197 -stam	p mills
direction of rotation for	1280, 12	196 Tyler Com	facturing & Supply Company, rolls 76 slime table 687 J., on capacity of jigs 602 osstles mill, amalgam in 767, 783 nt classifier 1144 p mills 209 ral separation on jigs 589 yan, W. S., wire cloth screens 1366 e-crimped screens 354 sining wire cloth 1364
discharge of the	12	87 m 15 screen	sining wire cloth 1364 cloth used at Mill 101 1626 ge 173
A. W. Warwick Cliciency of El Oro lining for feeding of	20	screen	ge
feeding of	12	888 tromm	171 d on Waddell Chili mills at Mill 174
feed opening for for cement grinding	12	87 d	ouble-crimped wire screens
feeding of . P. Argall feed opening for for cement grinding fine grinding. Davidsen foundations for Gates general notes	12000 12	15 to	sining wire cloth 1364 ble of screen meshes 1196 sting screens 1138 n material for screens 355
general notes Hardinge conical in S. Africa, work of. S. H. Pearce	1280, 12	96 Wire V	Works Company 1194
in S. Africa, work of. S. H. Pearce and A. Caldecott	ind W. 20	stear 13	olls
A. Caldecott liners for linings for, discussion by H. A. White	. 1839, 13	86 40	U
management of	16	พบ	gnetic separator
operation of. H. Fischer pebbles or flints for	19	40 Ultra-micro	Australian Metals Company's mill
quality of work done by tube mills	12	89 -violet 90 Tude	scope 1419 for the study of slimes 1401 rays for the detection of willemite. E. K. d 2048 nd A. Fraenkel, chemical-technical anal-
sizes best suited for feed to speed of rotation for theory of tube-mill action	. 1289, 13	88 Ulzer, F. a. 37 ysis	nd A. Fraenkel, chemical-technical anal-
versus grinding pans R. C. Clark	2014 20		Schone's tubular classifier
with central end discharge	20	14 Undercurre	
Tubular classifier	20	18 for say 21 Under-pisto	ring black sands. R. H. Richards 2020 on ligs
investigation of free settling on fine grains Richards'	4'	39 Undershot 78 Undersize,	water wheels
results of	6	28 in the pe 10 Unfinished 13 Union Bay	Consolidated Mining Company, Callow 1404
free-settling classifiers	159	96 Iron W	orks
Tuff, machine hest suited for emphine	· · · · · · · · · · · · · · · · · · ·	iii 10 Bi	249 ake breaker
Tullock concentrators, water used in	126 87	59 De 54 gri	odd tables at Mill 96
vor Branish ammin	18	104 iro	on battery frame

Vanners, side-shake versus end-shake 655	Vezin jig 1150
slope in degrees and inches	Vezin jig
Snyder 657	rolle O4
Spadone concentrator belt	sampler
Spadone concentrator belt	for sampling high-grade telluride gold ores 1573
steep end-shake	requisites to accuracy when using
testing	samples at mills1691, 1701, 1737, 1742, 1748, 1750
testing	1772
thickness of hed on DDU	springs for rolls
Triumph	Vial magnetic congretor 00F
Tulloch	Vibracone separator, the
concentrator 652	Vibrating grizzlies
Union Iron Works, iron frame	Vibracone separator, the. 1352, 1360 Vibrating grizzlies 341, 345 and riddles 1346
versus convex slime tables	Vibrations in vanners 658 Vibrometer screen. W. W. Beaumont 2018 Vibromotor screen 385
with tipping or undulating motion 1501	Vibrometer screen. W. W. Beaumont 2018
Johnston vanner	Vibromotor screen
suspended frame vanner 1503	Vickers-Maxim steel roll shells at Mill 128 1714
Woodbury 654 Vanning shovel 1152	Victor turbine wheel
Vanning shovel	Victoria mill
tests 1170	mills in
plaque	New Zealand, weight of ore
Vapart disintegrator	milling in
at Lintorf, Prussia	stamps in
bibliography for	
Varney amalgamating pan	Montagne Company 1116
Vats for electroplating copper plates	heating ore for friability 9
silver plating	mill 911
Vaucron mill 1178	separation of pyrite and blende 829
classifiers at	new Central mill
jigs in 641	Montagne Company 1116
number of sieves for jigs	
rolls at	mill at
sieve scale at	Virgilina, concentration at. E. K. Judd 2038
stroke of jigs at	Virginia City, Nevada, milling practice at. C. T.
V-box classifiers	Rice 2038 mill, amalgamated plates in 767 pyrite mills. R. H. Painter 2037 zunc ore, concentration of. T. L. Watson 2042 Viscosity of liquid effects of the cartillar of liquid fields. 2017
Vein quartz, weight of	mill, amalgamated plates in
Veitch, Alexander, on Hancock jig	pyrite mills. R. H. Painter
Velardeña Mining and Smelting Company 1742	zinc ore, concentration of. T. L. Watson 2042
V-box classifiers 419 Vein quartz, weight of 1190 Veitch, Alexander, on Hancock jig. 1441 Velardeña Mining and Smelting Company 1742 Velocities, application of free settling to classified design 1442 rade free to hindered settling to classifier 1423	
sign 1432	Vivianite, specific gravity of
ratio free to hindered settling to classifier	Vogt, G 1186
uchgu	Vivianite, specific gravity of 1189 Vogt, G 1186 Vogt, G, testing of clays 1185 Volts. See also Power.
full-teeter velocities of quartz and galena 1430	Volts. See also Power.
free settling	Volume of proken ore
of currents in classifier	units of
fall of minerals in water	units of 1187 Von Dessauer, H. A. 789 on amalgamated plates 767
settling curves of	on amaigamated plates
particles falling in water and in air 837	Hauer, J 838
water in film sizing tests	Reytt, K
Velocity card of steam stamp	breaking
curves of gravity stamps	moisture in ore
of a sphere falling through a viscous body. Sir G. C. Stokes	power and surface measurements, table of
	results of
	for stamps 205 used by rolls 98
fall of lead shot	used by rolls
galena and quartz falling in water. R. H.	sizing test of breaker product
Richards	Vortex classifiers, Richards' annular vortex classifiers 1382
pulsion in jigging	
	at mill 124 1602 1603 1604
rolls and stamps 314	at mill 124
rolls and stamps	at mill 124
rolls and stamps	at mill 124
rolls and stamps. 314 settling, effect of 4 of fine grains 473 grains 466	at mill 124
rolls and stamps 314 settling, effect of 4 of fine grains 473 grains 466 under free-settling conditions 1421	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403
rolls and stamps. 314 settling, effect of. 4 of fine grains. 473 grains 466 under free-settling conditions 1421 vibrations of Wilfley table deck. 1466	at mill 124
rolls and stamps	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W
rolls and stamps 314 settling, effect of 4 of fine grains 473 grains 466 under free-settling conditions 1421 vibrations of Wilfley table deck 1466 water on jigs 595 waves on amalgamated plates 746	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189
rolls and stamps. 314 settling, effect of. 4 of fine grains. 473 grains 466 under free-settling conditions 1421 vibrations of Wilfley table deck 1466 water on jigs 595 waves on amalgamated plates 746 Venezuela, mill in 1127	at mill 124
rolls and stamps	at mill 124 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886
rolls and stamps	at mill 124 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886
rolls and stamps	at mill 124 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886
rolls and stamps	at mill 124 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886
rolls and stamps	at mill 124 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886
rolls and stamps	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886 Wagemann, C., tin concentration at Ploermel, France 1177 Wage scale at mills . 1619, 1621, 1622, 1626, 1629, 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 1690, 1698, 1705, 1712, 17130, 1745, 1757, 1794, 1804, 1816, 1820, 1830, 1841, 1848, 1852, 1859, 1865, 1881, 1919 in the Sen Luan district of Colored
rolls and stamps	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886 Wagemann, C., tin concentration at Ploermel, France 1177 Wage scale at mills. 1619, 1621, 1622, 1626, 1629, 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 1690, 1698, 1705, 1712, 1730, 1745, 1757, 1794, 1804, 1816, 1820, 1830, 1841, 1848, 1852, 1859, 1865, 1881, 1919 in the San Juan district of Colorado 1980 Wages of labor 1100
rolls and stamps	at mill 124 . 1692, 1693, 1694 Richards' pocket vortex classifier . 1373 single-spigot . 1377 tank vortex classifier . 1379 for classifier . 403 W Wad, specific gravity of . 1189 Waddell Chili mill at Mill 174 . 1886 Wagemann, C., tin concentration at Ploermel, France 1177 Wage scale at mills . 1619, 1621, 1622, 1626, 1629, 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 1690, 1698, 1705, 1712, 1730, 1745, 1757, 1794, 1804, 1816, 1820, 1831, 1841, 1848, 1852, 1859, 1865, 1881, 1919 in the San Juan district of Colorado . 1980 Wages of labor . 1100 Wagner mica-plate static machine used with Blake-
rolls and stamps	at mill 124 . 1692, 1693, 1694 Richards' pocket vortex classifier . 1373 single-spigot . 1377 tank vortex classifier . 1379 for classifier . 403 W Wad, specific gravity of
rolls and stamps	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886 Wagemann, C., tin concentration at Ploernel, France 1177 Wage scale at mills. 1619, 1621, 1622, 1628, 1629, 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 1690, 1698, 1705, 1712, 1730, 1745, 1757, 1794, 1804, 1816, 1820, 1681, 1816, 1820, 1830, 1841, 1848, 1852, 1859, 1865, 1881, 1919 in the San Juan district of Colorado 1980 Wages of labor 1100 Wagner mica-plate static machine used with Blake- Morscher electrical ore separator 1551 Wagoner, L. 262
rolls and stamps	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886 Wagemann, C., tin concentration at Ploermel, France 1177 Wage scale at mills . 1619, 1621, 1622, 1626, 1629, 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 1690, 1698, 1705, 1712, 1773, 1744, 1757, 1794, 1804, 1816, 1820, 1830, 1841, 1848, 1852, 1859, 1865, 1881, 1919 in the San Juan district of Colorado 1980 Wagner mica-plate static machine used with Blake-Morscher electrical ore separator 1551 Wagoner, L. 262 Wagoner, L. 262 Gormula for free settling 472
rolls and stamps. 314 settling, effect of. 4 of fine grains. 473 grains 466 under free-settling conditions 1421 vibrations of Willey table deck 1466 water on jigs 595 waves on amalgamated plates 746 Venezuela, mill in 1127 Ventilation. 1009 Verdigris on amalgamated plates 750, 762 Vereim Chemischer Fabriken 1914 Vermilion hematite, action of Monarch breaker on 28 Vertical and horizontal shafts of amalgamating pans 241 mills 255 Vezin feeder for rolls 71 H. A., viii effect of strength and specific gravity on crushing power 316 on belts 1094 cost of mills 1126	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886 Wagemann, C., tin concentration at Ploermel, France 1177 Wage scale at mills . 1619, 1621, 1622, 1626, 1629, 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 1690, 1698, 1705, 1712, 1773, 1744, 1757, 1794, 1804, 1816, 1820, 1830, 1841, 1848, 1852, 1859, 1865, 1881, 1919 in the San Juan district of Colorado 1980 Wagner mica-plate static machine used with Blake-Morscher electrical ore separator 1551 Wagoner, L. 262 Wagoner, L. 262 Gormula for free settling 472
rolls and stamps. 314 settling, effect of. 4 of fine grains 473 grains 466 under free-settling conditions 1421 vibrations of Wilfley table deck 1466 water on jigs 5595 waves on amalgamated plates 746 Venezuela, mill in 1127 Ventilation 1099 Verdigris on amalgamated plates 750, 762 Verein Chemischer Fabriken 1914 Vermilion hematite, action of Monarch breaker on 28 Vertical and horizontal shafts of amalgamating pans 241 mills 255 Vezin feeder for rolls 71 H. A., viiii effect of strength and specific gravity on crushing power 316 on belts 1094 cost of mills 1126 dust prevention 1099	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886 Wagemann, C., tin concentration at Ploermel, France 1177 Wage scale at mills . 1619, 1621, 1622, 1626, 1629, 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 1690, 1698, 1705, 1712, 1773, 1744, 1757, 1794, 1804, 1816, 1820, 1830, 1841, 1848, 1852, 1859, 1865, 1881, 1919 in the San Juan district of Colorado 1980 Wagner mica-plate static machine used with Blake-Morscher electrical ore separator 1551 Wagoner, L. 262 Wagoner, L. 262 Gormula for free settling 472
rolls and stamps	at mill 124 . 1692, 1693, 1694 Richards' pocket vortex classifier . 1373 single-spigot . 1377 tank vortex classifier . 1379 for classifier . 403 W Wad, specific gravity of
rolls and stamps	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of Waddell Chili mill at Mill 174 1886 Wagemann, C., tin concentration at Ploermel, France 1177 Wage scale at mills. 1619, 1621, 1622, 1626, 1629, 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 1690, 1688, 1705, 1712, 1730, 1745, 1757, 1794, 1804, 1816, 1820, 1830, 1841, 1848, 1852, 1859, 1865, 1881, 1919 in the San Juan district of Colorado 1980 Wagner mica-plate static machine used with Blake- Morscher electrical ore separator 1551 Wagner, L. 262 formula for free settling 472 free settling in water 477 theory of power required in crushing 310 Tustin mill. 264, 294, 316 velocity of particles falling in water 478
rolls and stamps	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886 Wagemann, C., thi concentration at Ploermel, France 1177 Wage scale at mills . 1619, 1621, 1622, 1626, 1629, 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 1690, 1698, 1705, 1712, 1730, 1745, 1712, 1794, 1804, 1816, 1820, 1830, 1841, 1848, 1852, 1859, 1865, 1881, 1919 in the San Juan district of Colorado 1980 Wages of labor 1100 Wagner mica-plate static machine used with Blake- Morscher electrical ore separator 1551 Wagoner, L. 262 formula for free settling 472 free settling in water 477 theory of power required in crushing 377 theory of power required in crushing 364, 294, 316 Velocity of particles falling in water 478 Wagons for concentrates 1112
rolls and stamps	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1377 for classifier 403 W Wad, specific gravity of Waddell Chili mill at Mill 174 1886 Wagemann, C., tin concentration at Ploermel, France 1177 Wage scale at mills. 1619, 1621, 1622, 1626, 1629, 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 1890, 1698, 1705, 1712, 1730, 1745, 1757, 1794, 1804, 1816, 1820, 1830, 1841, 1848, 1852, 1859, 1865, 1881, 1919 in the San Juan district of Colorado 1980 Wages of labor 1100 Wagner mica-plate static machine used with Blake-Morscher electrical ore separator 1551 Wagoner, L. 262 formula for free settling 472 free settling in water 477 theory of power required in crushing 310 Tustin mill. 264, 294, 316 Wagons for concentrates 1112 Wagons for concentrates 1112 Waburn and Swensen Company 77
rolls and stamps	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886 Wagemann, C., tin concentration at Ploermel, France 1177 Wage scale at mills. 1619, 1621, 1622, 1626, 1629, 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 1690, 1698, 1705, 1712, 1730, 1745, 1757, 1794, 1804, 1816, 1820, 1830, 1841, 1848, 1852, 1859, 1865, 1881, 1919 in the San Juan district of Colorado 1980 Wages of labor 1100 Wagner mica-plate static machine used with Blake- Morscher electrical ore separator 1551 Wagoner, L. 262 formula for free settling 472 free settling in water 477 theory of power required in crushing 310 Tustin mill. 264, 294, 316 velocity of particles falling in water 478 Wagons for concentrates 1112 Walburn and Swensen Company 77 rolls 76 breaker of Blake type 238
rolls and stamps	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 4037 W Wad, specific gravity of W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886 Wagemann, C., tin concentration at Ploermel, France 1177 Wage scale at mills. 1619, 1621, 1622, 1628, 1629, 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 1690, 1698, 1705, 1712, 17730, 17745, 1775, 1774, 1804, 1816, 1820, 1830, 1841, 1848, 1852, 1859, 1865, 1881, 1919 in the San Juan district of Colorado 11980 Wages of labor 1100 Wagner mica-plate static machine used with Blake-Morscher electrical ore separator 1551 Wagoner, L. 262 formula for free settling 472 free settling in water 477 theory of power required in crushing 310 Tustin mill. 264, 294, 316 velocity of particles falling in water 478 Wagons for concentrates. 1112 Walburn and Swensen Company 77 rolls 564 rolls 761
rolls and stamps	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886 Wagemann, C., tin concentration at Ploermel, France 1177 Wage scale at mills. 1619, 1621, 1622, 1626, 1629, 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 1690, 1698, 1705, 1712, 1730, 1745, 1757, 1794, 1804, 1816, 1820, 1830, 1841, 1848, 1852, 1859, 1865, 1881, 1919 in the San Juan district of Colorado 11980 Wagner mica-plate static machine used with Blake-Morscher electrical ore separator 1551 Wagoner, L. 262 formula for free settling 472 free settling in water 477 theory of power required in crushing 310 Tustin mill 264, 294, 316 velocity of particles falling in water 478 Wagons for concentrates. 1112 Walburn and Swensen Company 77 rolls 564 rolls 721
rolls and stamps	at mill 124. 1692, 1693, 1694 Richards' pocket vortex classifier 1373 single-spigot 1377 tank vortex classifier 1379 for classifier 403 W Wad, specific gravity of 1189 Waddell Chili mill at Mill 174 1886 Wagemann, C., tin concentration at Ploermel, France 1177 Wage scale at mills 1619, 1621, 1622, 1626, 1629, 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 1690, 1698, 1705, 1712, 1730, 1745, 1757, 1794, 1804, 1816, 1820, 1830, 1841, 1848, 1852, 1859, 1865, 1881, 1919 in the San Juan district of Colorado 1980 Wages of labor 1100 Wagner mica-plate static machine used with Blake- Morscher electrical ore separator 1551 Wagoner, L 262 formula for free settling 472 free settling in water 477 theory of power required in crushing 310 Tustin mill 264, 294, 316 velocity of particles falling in water 478 Wagons for concentrates 77 rolls 76 breaker of Blake type 23

Wales, milling of lead and zinc in northern. E. Walker 2039	Wash water for trommels
Walker, E., the Elmore flotation process	on slime tables
bibliography for	pipes on slime table
Walker's patent stamp	Chaimers & Williams vanners at Mill 122 1087
Wall finger gear rolls	Frue vanners at mills1662, 1694, 1695, 1706,
jig	1755, 1880 Harz jigs at mills1744, 1751, 1752, 1753, 1877, 1878, 1879
Wallace, Idaho, mill at 947 steel breaker 2010 Wall's mill, Bingham Canyon, Utah 2038	1277 1278 at mins1744, 1751, 1752, 1755,
Wall's mill, Bingham Canyon, Utah	James slimer 1492
Waitl, V., Oberegger gyrating screens 380	James shmer
Wunderlich trough classifier for coal 478	New Standard concentrator 1479
Wann, E. E., discusses time grinding	picking belt at Mill 154
Wann, E. E., discusses fine grinding 2016 Wappler, A. F., Fröbel's mill 291 Ward, W. P., Hundt's settling tub, Rittinger's setzrad,	Richards' vortex classifier at Will 1/3 18/8
Rittinger's pointed boxes	1694, 1743, 1744, 1751, 1752, 1753, 1755.
Stapff and Cazin jigs	1775, 1776, 1778
Wardner, Idaho, mill at	rolls at Mill 173
Waring magnetic separator	round tables at Mill 1801904, 1905
pulverator 234	single-spigot classifier at Mill 1801902, 1903 trommels at mills1691, 1692, 1693, 1743, 1772, 1773, 1774, 1816, 1876, 1877
pulverator	1772 1773 1774 1816 1876 1877
system of magnetic separations, description of	
the	at mills 1661. 1662. 1687. 1706. 1744. 1745.
Warp and woof on canvas tables	1754. 1880
Warren, A. Sidney, free-settling velocities	Wasp No. 2 mill, Kirk, S. Dakota 2044
Warwick, A. W., definition of slime	Waste picked out in mine for stowing 481 Water, acid, effect of on screens 173 column, weight of 1188 consumption 2048 at Arizona mills 1831 Butte. C. W. Goodale 1420, 1997 Cananea O. P. Findley 1419 Eureka Hill. G. W. Riter 2036 Longfellow concentrator 1931
discussion of the tube mill 2015	column weight of
fine grinding 1340	consumption
discussion of the tube mill 2015 fine grinding 1340 in the tube mill 2015	at Arizona mills
finely ground slimes	Butte. C. W. Goodale
hand sorting in small mills	Cananea. O. P. Findley 1419
history of concentration 2049	Eureka Hill. G. W. Riter 2036
on slimes	Longiellow concentrator
etamp mill foundations 2044	1700 1706 1709 1712 1715 1730 1731 1746
the A. M. W. mill at Leadville. Colo 2043	1757, 1762, 1786, 1794, 1802, 1816, 1817, 1840,
Wascott, stamps in Gilpin County, Colorado 229	Longfellow concentrator 1931 mills 1413, 1622, 1640, 1648, 1664, 1698, 1699, 1700, 1706, 1709, 1712, 1715, 1730, 1731, 1746, 1787, 1762, 1786, 1794, 1802, 1816, 1817, 1840, 1848, 1853, 1856, 1859, 1865, 1875, 1882, 1887, 1891, 1894, 1897, 1912, 1932 Montana conpersulpide mills 1897, 1912, 1932
Washburn & Moen	1891, 1894, 1897, 1912, 1932
Washburn & Moen screen gauge	
history of concentration 2049 on slimes 2020 power for stamp mills 2044 stamp mill foundations 2044 the A. M. W. mill at Leadville, Colo. 2043 Wascott, stamps in Gilpin County, Colorado 229 Washburn & Moen. 171, 1196 Washburn & Moen screen gauge 173 Washburn & Moen screen gauge 194, 1364, 1999 Washers. See Log Washers. Dorr mechanical classifier 1343 for clay 1076	Northern Mexico mills 1931
Washers. See Log Washers.	Shannon concentrator 1931 Washington, Arizona, plant 1411 in Arizona, D. E. Woodbridge 1997
for clay	in Arizona. D. E. Woodbridge
for clay 1076 log 55, 320 preliminary 319, 1341 trough 319	
preliminary	on the Rand
trough	current in launders, speed necessary to carry
using rotating surrers	sand 878 economy in mill. J. C. Scobey 1419 stamp milling. A. W. Warwick 2011
Washing before hand picking	stamp milling. A. W. Warwick 2011
box before hand picking 488 canvas tables 701 702	effect of temperature on amalgamation 766
clay and kaolin	flow of
cocoa matting 703	for Atwood amalgamator
devices on slime tables	breaking rock after heating 9
diamonds	classifier
drum at Mill 95	calculation of 429 Conkling jig 503
machinery	dredging
ore at Elkton Mine	Ferraris belt table
pans 333	classifier
bibliography for	German sweeping table
for corundum	gravity stamps, amount and temperature 221 Hallett table
diamondiferous earth	Heberwasche 522
pits 335 placer gravel 723	jigs
preliminary, bibliography for	Lake Superior hog trough classifier 390
tank with hand picking	log washer 324 mills 1102
Washington, gold mill at Republic 2036	mills
Washington, gott initiat Republic	Parsons table
district 1105	& Fisher jig
Copper Company 1836 district 1105 plant of the Anaconda Copper Co. L. S. Aus-	Rittinger table
tin	Salzburg table
process	Schmidt spiral screen
of amalgamation	Schranz jig
smelter 2042 Montana 1924	sluices 723 spitzhutte 424
Wash trommels	
bibliography for	Stein, Bilharz, and Luhrig tables 670
Bradford	Tamarack classifier
Carnall	Tremain steam stamp
compared with log washers	trommels
Crickboom	wash tromnels
for disintegrating clay	gravity stamps, amount and temperature of 221
Krupp 1341	launders, mean velocities of 811
versus log washers	stamp pulp
water distributor for vanners	jet for disintegration
· · · · · · · · · · · · · · · · · · ·	
10	<i>u</i>

•	
Weathering process at Mill 188 1921	Weight of stamps at mills 1618, 1620, 1621, 1624, 1626,
Webb City, Missouri, mills at	1630,
Webb, H. H., and Pope Yeatman, hand picking in	1632, 1634, 1640, 1645, 1649, 1651, 1658, 1661, 1665, 1666, 1668, 1677, 1679, 1769, 1915
South Africa	1665, 1666, 1668, 1677, 1679, 1769, 1915
Webber, W. O., centrifugal and reciprocating pumps 885	in California 1619 Witwatersrand 1643
on pumps	Sturtevant balanced rolls, table of 1234
Wedding H xx	Dodge-type breakers, table of
concentrating Thomas slag	tappets at Mill 117
magnetic iron oxides 813	wearing parts, Blake breakers
Separation of iron ore	Dodge breaker
separators	Forster breaker
Mumford & Moodie's separator	Wetherill magnetic separators, table of 1522
processes of separation 835 Wetherill process 836 Wedgewood mortar for amalgam 780, 1025 We	Wild roller mills, table of
Wetherin process	table of measurements of
Weighing 1160	units of
Weighing 1160 conveyor, Richardson automatic 2032	Weights for rolls
devices	Weisbach, hydraulic power 239 P. J., manual xx
Avery automatic scales at Mill 105 1635	vater motors
Blake-Denison continuous weighers 1603	Weiss, picking at
Libra scales	sieve scale at
Libra scales 1605 machines, the Blake-Denison 1609 ore 883	sieve scale at
ore	arator at
Weight and power of steam stamps	mill at
of Akron Chili mills, table of	Welkenraedt, double discharge on jigs at 584
arrastra 237 238	mill at
amalgamating pan 243 arrastra 237, 238 Austin gyratory breakers, table of 1210	Weller pulp thickener 2010
Bartlett Simplex concentrator	Wellman-Seaver-Morgan, Company Akron Chili mill 1307
Bartlett Simplex concentrator	Weller pulp thickener 2019 Wellman-Seaver-Morgan, Company, Akron Chili mill 1307 Garfield Chili mill 1307
bosses at Mill 117	gravity stamps
broken ore	sectional guides for gravity stamps 1270
quartz	Walle T W molyhdanita dragging 1567
cobbing hammers at Mill 186 1917	mercury 708
Colorado Iron Works continuous grinding	Wendt, A. F., Wendt jig
Comet breaker	crushing and jigging at Crown Point mines,
pans	New York
breakers, table of	connecting rods on 520
	Mental M
dies in amalgamating pans 245 Ding's magnetic separators 1541	elliptical gear on
Dodge breaker	Wengler & Lowe's classifier
Farrel Blake breakers, table of 1200	hydraulic classifier
Ferraris ball mills, table of	Wenström magnetic separator 800
patent tables, table of	construction of
Gates pail mills, table of	products of
style "K" breakers, table of	Wentworth Company, mill
Gilpin County bumping table	Goldneids Company, snoe and die used in mill of 181
stamp mortars	stamps
hammers for breaking 11	mill, plates in 788 Wessinger, H. J., on breaking 60 crushing hematite at Minnesota Iron Mine 60
Hathaway gyratory breakers, table of 1217	crushing hematite at Minnesota Iron Mine 60
Humphrey rolls, table of	West Argentine Co., iron stamp frame
improved Huntington mills, table of 1312	West Argentine Co., iron stamp frame
International magnetic separators 1535	at the mill of the. R. B. Hosker 2045
Kennedy gyratory breakers, table of 1214	
Kent roller mills	Wheeled Scraper Co., jaw breaker 25
Knowles' New Century magnetic separators, table of	Westphalia, jigs in
Krupp gyratory breakers table of 1215	West Rand, slime settling at
La Point flour gold separators, table of 1510	West Waverly Gold Mining Company Limited, mill xxviii,
log washer	1026
log washer	Yankee concentrator of Detroit Copper Co.,
McCully breaker44	Bryan mills at
McCully breaker 44 gyratory breakers, table of 1212 McLanahan and Stone single-roll crushers, table of 1241 mills	effort to clarify water at
McLanahan and Stone single-roll crushers,	Wet concentration versus oil process
mills	magnetic separator, Conkling
moving parts of Nordherg steeple-compound	screening tests
mills 1126 moving parts of Nordberg steeple-compound steam stamp at Mill 180	screening tests 1138 silver mill 1039 water for 1105
muller and shoes for amalgamating pan 246	versus dry concentration, bibliography for 837
new and old jaw plates for Blake breakers at	Wetherill horizontal magnetic separator 805
Mill 100 1624 New Standard concentrators 1479	inclined magnetic separator
New Standard concentrators	inclined magnetic separator
Nissen stamps at Mill 165	cost of screens
ore for sampling	magnetic separators
Nissen stamps at Mill 165 1851 ore for sampling 851, 852 parts of stamp 189 Pilling hoists, table of 1609	results of tests of
roll shells	magnet piant at Frankun, New Jersey 835, 1181
samples in mechanical sampling 1575, 1576	magnet
Samson breakers, table of	magnetic concentrating plant. Sterling Iron and
rining iosiss, table of 1009 roll shells 66 samples in mechanical sampling	treatment by the
at Mill 117 1668	mill 1060
stamp parts	mill 1060 separator 804, 1521, 2025 A. Smits. 2026 at mills 1525, 1810, 1826, 1802, 1863, 1801
at Mill 118 1677	A. Smits
stem 187 stems at Mill 117 1668	at mills 1020, 1810, 1826, 1862, 1863, 1891,
	1010
stamps	attendance required 1505
stamps	attendance required 1505
stamps	attendance required

1 ages 1-045, vol. 1.	Old Di	2000 011 1101, VOI.	7.7.
Wetherill magnetic separator, electrical and me	echanical	Wilfley group, Ferraris patent table 1	490
energy required by	1525		
energy required by for separating molybdenite and	biotite. 1568	James sumer	490
Humboldt Engineering Work	IS Com-	McLeod concentrator	492 402
maximum size treated	1525	New Humboldt concentrator	493
pany	agnets of 1524	New Standard concentrator 1	478
results from	2026	Overstrom table	485
table of dimensions and weight	s 1522	Pinder concentrator 1- principles of action of 1- roughing plane in 1- Sutton, Steele & Steele dry table 1-	481
wear and tear on	1020	roughing plane in	400 465
helt speed for	1523	Sutton, Steele & Steele dry table.	479
belt speed fortake-off belt speed for	1524	Woodbury table	494
parallel magnetic separator	804	head-motion on shaking feeders at Mill 171.1868, 13	869
plant at Lohmannsfeld	2035		
separator in Arizona	2020	Impact screen. J. H. Collins	023
Germany	2029	at mills	765
Germany ores suited for the types of separators. F. Essen. Wethey, A. H., Chili mill.	2029	attendance required to operate	040
types of separators. F. Essen	2031	capacity of	548
Wethey, A. H., Chili mill	271, 1115	consumption of fuel in	548 547
improvements in concentration at But	1360 2018	fines in product sink in water	548
Pratt ore sizer removal of wood	1609	size of	$5\overline{48}$
Wilfley tablelifting magnet at Mill 164	729	size of	547
lifting magnet at Mill 164	1532	shaft roaster 20	029
Wetted perimeter in launders	876	slimers 1	004 003
W. F. Mosser and Company Wharton magnetic cobbers at Mill 157	1819 1820	A. R. Wilfley 20 at mills	856
Steel Company, concentrating plant of .		reed best suited for	ວບູວ
Wheal Grenville tin dressing	1082	head motion 1	504
Wheel agitator Wheeler amalgamating pan	780	on natural feed	505
H. A., on sizing tests of trommel produ		operation of	500 504
Dans	1282	shaking frame for	504
fine grinding in. W. Broadbridge	2015	sub-frame for 1	504
Zenas, tappet gib	188	trays or decks for	504
Wheels, dewatering	1590	table	119
Wilfley middlings return	1468	as a slimer	110
sand wheels	864, 1586	effect of appearance	vii
sand wheels. Whelpley & Storer pulverizer	236, 289	feed, proper consistency for 14	404
Dibliography for		for testing	153
whirling table		ran wheel on	721
White, F., fine crushing machines		4-4	771
H. A., formula for speed of revolution	a of ball	test	165
mills	1337	testing 12 tests of, at Parrott mill 12 tests of, at Parrott mill 1622, 1625, 1633, 164 1657, 1661, 1663, 1669, 1686, 1687, 1689, 1694, 16703, 1704, 1708, 1709, 1715, 1729, 1738, 1739, 1745, 1754, 1764, 1776, 1777, 1779, 1780, 1811, 1829, 1830, 1833, 1839, 1840, 1844, 1848, 1850, 1852, 1855, 1858, 1867, 1870, 1880, 1885, 1886, 1894, 1896, 1904, 1905, 1908, 1929, 16 capacity of	675
theory of tube-mill action	1323	tables at mills 1620, 1621, 1622, 1625, 1633, 16	656
tube-mill experiments	224	1703 1704 1708 1709 1715 1720 1738 1730 17	744
Whitehead, Cabell and T. M. Chatard, se	ttling of	1745, 1754, 1761, 1776, 1777, 1779, 1780, 1811, 18	312
T., gravity stamps. Whitehead, Cabell and T. M. Chatard, se slimes at Republic gold mine, Washington	1176	1829, 1830, 1833, 1839, 1840, 1844, 1848, 1850, 18	851
C., setting simes	1148	1852, 1855, 1858, 1867, 1870, 1880, 1885, 1886, 18	893
Whitney and Ober, colloidal theory of slime effect of surface tension in preventing se	ettling of	capacity of	480
slime	1414	consistency of pulp for	
slime precipitating agents	1416	deck for	467
W. R., chemicals for settling slimes	1419	description of	465
Whole bed on jigs, defined	495	elevator or raff wheel for	804
labyrinths and runs	447	feed box for 19 for reworking dumps T. Tonge 20 testing 1471, 19	022
table of details of	444	testing	990
means of getting	451	foundation for	465
Wickes boilers	737 740	head motion for 14	466
belt elevators	863	height of riffle cleats for	468
jig sieves	5 91	in California practice 16	619
rolls	83	Canadian mills	022
Wilbraham rotary pumpWild mill	1990 1904	investigation of work of	469
regrinding mill	2015, 2016	on different feeds, a study of the. R. H.	000
regrinding millroller mill, table of sizes, capacities,	power,	Richards	469
weights, etc	1304	riffle cleats for	467
rolls Wildman Gold Mining Company	72	"setting up" and "leveling up" 14	468
wildman Gold Mining Company	1023 1184	sized versus classified feeds for the 14 speeds of vibrations of deck 1465, 14 study of the R. H. Richards 1	4/8
Wiley, H. W., agricultural analysis	XX	study of the. R. H. Richards	511
settling in water	1174	tests on at Mill 162	493
Wilfley, A. R., Wilfley's slimer	2023	tilting frame of	467
Bartlett Simplex concentrator	1404	velocity of vibrations of deck	406 200
Card concentrator	1481	versus Card tables at Mill 159	679.
Christensen concentrator	1484	wash water required for	469
classification of	1465	Wilkens, H. A. J. and H. B. C. Nitze, plates at the Haile gold	224
cleaned-ore plane in	1485	and H. B. C. Nitze, plates at the Haile gold	787
Deigter concentrators	1422	Wetherill magnetic separators	R33
depth of bed in	1510	Wilkes, J. A., gold stamp mill	178
Dodd buddle	1481		997
	4 .	10	OF STREET

Pages 1199–1610, Vol. III.	ND	Pages 1611-2052, Vol. IV.
Willemite, phosphorescence of	1931	olverine mine, cost of mining and milling 1131
Williams, Albert, Ir., bottom discharge tanks for	1189	Wood and Laschinger, mechanical efficiency of sand
Setting sumes	476 459	wheel
on settling tanks. G. W., metallurgy at Broken Hill. hinged hammer pulverizer	$\frac{1568}{1322}$	for launders 872 mill buildings 1088
J. R., burnt lime for settling slimes cost of milling on the Rand		riffies
deniation of sames	1399	slime table surface 688 stamp guides 155
Patent Crusher Company, hinged hammer pul-	1416	frames for jigs
	$\frac{1322}{2015}$	grizzlies
pulverizer. Wills, J. L., Frisbee Lucop mill Wilson, E. B., stamps for different processes	294	picked out by hand 482 pipes for acid water 1106
steam stamp 142, steel for shoes and dies	143	removal of. A. H. Wethey
Willisee, P. A. and I. B. Hobeon apparety of Smarte-		from ore
ville and Mooney Flat. Wimmer's jig	290 643	removing device. A. H. Wethey
Wimmer's jig Windows Windsor cyanide plant, slime settling at Wine Harbor, Whelpley & Storer pulverizer at	1100 478	required for drying 899 retorting 782
	289 245	sieve frames for jigs 538 steam stamp 136, 2011
Winnowing ore dry	825	surface for slime tables
Winnowing ore dry Winslow, W. H., Ryerson pulverizer Winter, George W., Peck separator Wire cloth, brass	299 839	Woodbridge, D. E., Anaconda concentrator
copper	1364 1364	and Sonora 1923 concentration at Cananea, Mexico 1923, 2038
galvanized	136 5 1364	in Arizona
Manufacturers' Association standards 1 phosphor bronze	1364	ore dressing at Cananea
screens, cost of	361	Water consumption in Arizona 1925 Woodbury-Benedict jigs at Mill 177 1892, 1893
Tyler double-crimped	340 370	bull jigs
tinned 1	364 365	concentrators 1494
Tyler double-crimped mining wire cloth 1 versus plate for testing screens	.364 .138	at Mill 117
	354	distributor
gauges 1 S. H. Stupakoff 2	194	Imperial concentrator
in screens, use of bronze	019	jig systems. 1440 J. T. Glidden 2022
picking belt at Mill 137	012 740	jigs
rope elevators	.095	
Wisconsin, concentration in	568	slime classifiers 1447 at Mill 164 1850 system of ore concentration 1459 table 1270
Huff electrostatic separators in	552	system of ore concentration
Lead & Zinc Co., separation of blende and pyrite	829	table
practice at Mill 148	548	belt
zinc milling in	038 023	Woods dry placer machine
wiswell electric ore pulverizer	235 296	bibliography for 296 Woodward, A. E. 476
Witherbee, Sherman and Company mill. 1053, 1054, 10 1117, 1)59, 820	woolen blanket tables
	802	work. See Power.
Witkowitz coal washery. 11. Fillunger	052	done in crushing by rolls
Witwatersrand, cost of producing gold in . 1983, 1984, 19	836 85,	classifiers, quality of
general milling practice in	986 6 43	required for crushing
hydraulic stamp used in	$257 \\ 012$	ore. 308 Your Own Diggings mill 1021 Working of amalgamating pan 248
milling on the, H. H. Webb & P. Yeatman 20 practice on the. E. D. Chester	0 35 035	Worthington centrifugal pumps at mills . 1696, 1745, 1881 pump
	789	at Mill 175
Darien	788	Wrightson's coal-picking table. 2021 Wrought iron, specific gravity of. 1189 W. S. Tyler Company. 354-355, 370, 1138, 1196
concentration in the Vectores district D C 0	759 034	ugures on cost of screens
Espiritu Santo mill, Cana, Darien. 2 remedy for hard amalgam 2 Wolf breaker. 56 Wolff, D. D., Waugh & Bignell concentrator Wolframite, hindered-settling test on 613,	033 024	Wulfenite, specific gravity of
Wolf breaker	, 58 838	trough classifier
Wolframite, hindered-settling test on	617 829	w. Y. O. D. mili
settling velocity of 468	469	Wythe Lead & Zinc Co
specific gravity of	369	X
Wolhuter mill, details of stamps	221	Xenon, atomic weight of